PHASE I ENVIRONMENTAL SITE ASSESSMENT

Undeveloped, Wooded Land
320 Adams Drive
City of Coatesville, Chester County, Pennsylvania

December 21, 2018

Whitman Project No: 18-12-12T

Prepared For:
Baker Residential of PA LLC
One West Red Oak Lane
White Plains, New York 10604

Prepared By:
Whitman
7 Pleasant Hill Road
Cranbury, New Jersey 08512
Tel: (732) 390-5858
Fax: (732) 390-9496

WHITMAN
Creating Solutions. Exceeding Expectations.

TABLE OF CONTENTS

Page No.

EXECUTIVE SUMMARY 1

1.0 INTRODUCTION 4

1.1 Purpose and Scope of Services 4
1.2 Additional Services 5
1.3 Deviations to ASTM E1527-13 Standard 5

2.0 SITE DESCRIPTION 5

2.1 Site Improvements & Use 5
2.2 Physical Setting 6

3.0 USER PROVIDED INFORMATION 7

4.0 RECORDS REVIEW 7

4.1 Historical Use Information 7
4.2 Site and Adjoining and Surrounding Property History 9
4.2.1 Site Property History 9
4.2.2 Adjoining Property History 10
4.2.3 Surrounding Property History 10
4.3 Database Report & Environmental Record Review 10

5.0 SITE RECONNAISSANCE 12

5.1 Methodology and Limiting Conditions 12
5.2 Interior and Exterior Site Observations 12
5.2.1 Storm Water Discharges 13
5.3 Adjoining and Surrounding Properties Reconnaissance 13
5.3.1 Adjoining Properties 13
5.3.2 Surrounding Properties 14

6.0 INTERVIEWS 14

7.0 FINDINGS, OPINIONS AND CONCLUSIONS 15

7.1 Findings and Opinions 15
7.1.1 RECs 16
7.1.2 CRECs 16
7.1.3 HRECs 16
7.1.4 De Minimis Conditions 16
7.2 Data Gaps 16
7.3 Conclusions 18
7.4 Limiting Conditions and Deviations 19
7.4.1 Accuracy and Completeness 19
7.4.2 Warranties and Representations 20
7.4.3 Continued Validity/User Reliance 20
7.4.4 Significant Assumptions 20

8.0 ADDITIONAL SERVICES 21

Figures

Figure 1: Site Layout Plan

Appendices

Appendix A: Database Radius Report
Appendix B: User Questionnaire
Appendix C: Historical Research Documentation
Appendix D: Photograph Log
Appendix E: Other Reference Information
Appendix F: Whitman Staff and Environmental Professional Qualifications/Resumes
Appendix G: Environmental Professional Statement

EXECUTIVE SUMMARY

Subject to the qualifications and limitations stated in Section 1 of this report, Whitman was retained by Baker Residential of PA LLC (also known as "Client" or "User(s)") to perform a Phase I Environmental Site Assessment (Phase I ESA) of the property located at 320 Adams Drive (also known as Parcel ID No. 1601 00140000) in the City of Coatesville, Chester County, Pennsylvania (herein referred to as the "Site"). Whitman's assessment was conducted in connection with the Client's planned sale of the Site.

The Phase I ESA described in this report was performed in accordance with the scope and limitations of the American Society of Testing and Materials Practice E1527-13 *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM E1527-13). Limiting conditions and/or deviations from the ASTM E1527-13 standard are described in Sections 1.3, 5.1 and 7.4 of this report, as applicable.

Site Feature	Description
Approximate Site size	88.3 acres
Current Site operator	None identified
Site use	None – undeveloped, wooded land
Buildings (stories)	None – undeveloped, wooded land
Construction date(s)	Not applicable
Exterior areas	Undeveloped, wooded land with a large area of rock and soil stockpiled in the central portion of the Site and one gravel-covered vehicle parking and storage area
On-site roads/rail lines	None identified; however, online mapping sources depict Dulles Drive extending on the Site. The area of Dulles Drive comprised an unpaved pathway.
Other large equipment	None identified

As a result of the Phase I ESA, including but not limited to our visual observation of the Site; review of historical information, environmental databases, and information provided by the User(s); interviews with current Site representative(s); and Whitman's professional judgment, no evidence of *recognized environmental conditions* (RECs) or *controlled recognized environmental conditions* (CRECs) associated with the Site, as defined by the ASTM E1527-13 standard were identified:

Pursuant to the ASTM Phase I Standard, a data gap is defined as *a lack of or inability to obtain information required by [the ASTM Phase I Standard] despite good faith efforts by the environmental professional to gather such information*. Pursuant to the ASTM Phase I

Standard, *the report shall identify and comment on significant data gaps that affect the ability of the EP to identify RECs and identify the sources of information that were consulted to address the data gaps. A data gap is only significant if other information and/or professional experience raises reasonable concerns involving the data gap*. The term "significant data gap" does not necessarily imply that the relative liability or potential financial risk of the concern is significant. The following *significant* data gap was noted:

Data Gap No. 4 – 55-Gallon Drums

According to an April 5, 2004 Phase I Environmental Site Assessment prepared by Vollmer Associates LLP, 55-gallon drums were observed in several locations on the Site. The previous report indicated that there was no evidence of hazardous substances leaking from the drums; however, the drums were sealed, and the contents could not be verified. Vollmer Associates indicated that one drum was located in the southeastern portion of the Site; however, the location of the second drum was not reported. No visual evidence of the reported drums was observed during Whitman's December 14, 2018 Site visit, and no visual or olfactory evidence of a release of hazardous substances, such as staining, stressed vegetation, or odors, was observed during Whitman's Site visit. However, the contents of the drums remain unknown, and no information or documentation was identified that indicated when the drums were removed from the Site or where they were transported. Based on the condition of the drums apparent in the Vollmer Associates report, the drums may have leaked, and a potential exists for impact to the environmental condition of the Site. Therefore, this data gap is considered to be a *significant* data gap.

This Executive Summary is part of this complete report; any findings, opinions or conclusions in this Executive Summary are made in context with the complete report. Whitman recommends that the User(s) read the entire report for all supporting information related to findings, opinions, and conclusions.

Legal Notice

This document was prepared by Whitman solely for the benefit of the User(s). With regard to third-party recipients of this document, neither Whitman, nor the Client, nor the User(s), nor any of their respective parents, affiliates, or subsidiaries, nor any person acting on their behalf: (a) makes any warranty, expressed or implied, with respect to the use of any information or methods disclosed in this document; or (b) assumes any liability with respect to the use of any information or methods disclosed in this document. Any third-party recipient of this document, by its acceptance or use of this document, releases Whitman, the Client, the User, and their parents, affiliates, and subsidiaries, from any liability for direct, indirect, economic, incidental, consequential or special loss or damage whether arising in contract, warranty, express or implied, tort, or otherwise, and irrespective of fault, negligence, and strict liability.

This report is intended to be used in its entirety. No excerpts may be taken to be representative of the findings of this assessment.

1.0 INTRODUCTION

Whitman was retained by Baker Residential of PA LLC (also known as "Client(s)" or "User(s)") to perform a Phase I Environmental Site Assessment (Phase I ESA) of the property located at 320 Adams Drive (also known as Parcel ID No. 1601 00140000) in the City of Coatesville, Chester County, Pennsylvania (herein referred to as the "Site"). Whitman's assessment was conducted in connection with the Client's planned sale of the Site.

This report was prepared for and may be relied upon by User for the purposes set forth herein; it may not be relied on by any party other than the User and reliance may not be assigned without the express approval of Whitman. Authorization for third party reliance on this report will be considered by Whitman if requested by the User. Whitman reserves the right to deny reliance on this report by third parties.

1.1 Purpose and Scope of Services

This Phase I ESA has been prepared by Whitman in accordance with the American Society for Testing and Materials E1527-13 *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM E1527-13) and is intended for the sole use of the above-listed User(s).

The purpose of this assessment is to identify *Recognized Environmental Conditions* (RECs) at the Site, as defined by the ASTM E1527-13 standard. The completion of this Phase I ESA report may be used to satisfy one of the requirements for the User(s) to qualify for the *innocent landowner*, *contiguous property owner*, or *bona fide prospective purchaser* limitations pursuant to the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), thereby constituting *all appropriate inquiries into the previous ownership and uses of the property consistent with good commercial or customary practice* as defined by 42 U.S.C. §9601(35)(B) of CERCLA.

Whitman understands that this assessment is not funded with a federal grant awarded under the United States Environmental Protection Agency (U.S. EPA) Brownfields Assessment and Characterization program.

The Scope of Services for this Phase I ESA included the following tasks:

- Site and vicinity reconnaissance;
- Site and vicinity description and physical setting;
- Historical source review and description of historical Site conditions;
- Interviews with owners, operators, and/or occupants of the Site, and/or local officials;
- Review of environmental databases and regulatory agency records;
- Review of previous environmental reports/documentation, as applicable;

- Review of environmental liens, if provided or authorized to obtain by the User; and
- Preparation of a report summarizing findings, opinions, and conclusions.

Pursuant to the ASTM E1527-13 standard, recommendations to conduct Phase II sampling or other assessment activities are not required to be included in this report.

1.2 Additional Services

Items outside the scope of the ASTM E1527-13 standard include, but are not limited to, the following:

- Asbestos-containing building materials
- Radon
- Lead-based paint
- Lead in drinking water
- Wetlands
- Regulatory compliance
- Cultural and historic resources
- Industrial hygiene
- Health and safety
- Ecological resources
- Endangered species
- Indoor air quality unrelated to *releases* of *hazardous substances* or *petroleum products* into the environment
- Biological agents
- Mold

No additional tasks were performed as part of the preparation of the Phase I ESA.

1.3 Deviations to ASTM E1527-13 Standard

Notwithstanding additions to the ASTM E1527-13 standard, as listed in Sections 1.2 and 9, if applicable, and limiting conditions, as listed in Section 5.1, if applicable, no significant deviations or deletions to the ASTM standard were made during this Phase I ESA.

2.0 SITE DESCRIPTION

2.1 Site Improvements & Use

Current on-site improvements are listed in the following table: A Site layout plan is included as **Figure 1**.

Site Feature	Description
Approximate Site size	88.3 acres
Current Site operator	None identified
Site use	None – undeveloped, wooded land

Site Feature	Description
Buildings (stories)	None – undeveloped, wooded land
Construction date(s)	Not applicable
Exterior areas	Undeveloped, wooded land with a large area of rock and soil stockpiled in the central portion of the Site and one gravel-covered vehicle parking and storage area
On-site roads/rail lines	None identified; however, online mapping sources depict Dulles Drive extending on the Site. The area of Dulles Drive comprised an unpaved pathway.
Other large equipment	None identified on Site
Potable water supply	None identified on Site
Sewage disposal system(s) and age	None identified on Site
Heating/Cooling system fuel source(s)	None identified on Site
Back-up fuel source(s)	None identified on Site

2.2 Physical Setting

A current United States Geological Survey (USGS) topographic map depicting the Site area was reviewed. The topographic downward slope observed at the Site during the Site reconnaissance is to the north, south, east, and west from the center of the Site. Based on local topography and historical environmental reports provided to Whitman, as applicable, the assumed direction of shallow ground water flow is to the west. However, a subsurface investigation would be required to determine actual ground water flow direction.

According to Pennsylvania Department of Environmental Protection's (PADEP's) online mapping tool, eMapPA, the Site is underlain by the Chickies Formation and Antietam and Harpers Formations, undivided. The Chickies Formation consists of light-gray to white, hard, massive quartzite and quartz schist with thin interbedded dark slate dating to the Lower Cambrian period; the Antietam Formation consists of quartz sandstone with quartzite and quartz schist dating to the Cambrian period; and the Harpers Formation consists of schist, phyllite, and shale dating to the early Cambrian period.

According to the United States Department of Agriculture (USDA) Natural Resources Conservation Service (NRCS) Web Soil Survey, soils at the Site are identified as the Edgemont channery loam and Edgemont channery sandy loam.

3.0 USER PROVIDED INFORMATION

According to the ASTM E1527-13 standard, certain tasks that may help identify the presence of RECs associated with the Site are generally conducted by the Phase I ESA User(s). These tasks include: providing, or authorizing the *environmental professional* to obtain, recorded land title records for environmental liens or activity and land use limitations (AULs); providing specialized knowledge related to RECs at the Site (e.g., information about previous ownership or environmental litigation); providing commonly known or *reasonably ascertainable* information within the local community about the Site that is material to RECs in connection with the Site; and informing the *environmental professional* if, as believed by the User, the purchase price of the Site is lower than the fair market value due to contamination. A list of requested information was included in Whitman's signed proposal. A copy of a questionnaire with information provided by the User(s), as indicated below, is included in **Appendix B**

User Responsibility	User Response Provided (if No, see Section 7.2)	Description
Title & Judicial Records for Environmental Liens or Activity and Use Limitations	Yes	User was not aware of Title & Judicial Records for Environmental Liens or Activity and Use Limitations for the Site.
Specialized Knowledge	Yes	User was not aware of Specialized knowledge of the Site.
Property Value Reduction Issues	Yes	None
Commonly Known or Reasonably Ascertainable Information	Yes	User was not aware of Specialized knowledge of the Site
Reason for Conducting Phase I	Yes	Preparation of potential sale

Information provided by the User(s) has been incorporated in this report, as applicable.

4.0 RECORDS REVIEW

4.1 Historical Use Information

Information regarding Site and vicinity historical uses was obtained from various publicly available and practically reviewable sources including but not limited to aerial photographs; Sanborn fire insurance maps; topographic maps; city directories; local municipal records; an environmental database report; property tax files; recorded land title records; building department records; zoning/land use records; previous environmental reports; other historical sources; and/or interviews with Site representative(s) and regulatory agency official(s), as necessary. Information from these sources is incorporated in this report, as applicable.

Description/Title of Document(s) Received or Agency Contacted	Date Information Request Filled	Most Recent Update	Reference Source
EDR environmental database report (see **Appendix A**)	December 12, 2018	Same	Environmental Data Resources, Inc. (EDR)
Sanborn fire insurance maps – unmapped property (see **Appendix C**)	December 12, 2018	Same	EDR
Aerial photographs dated 1950, 1968, 1969, 1982, 1992, 1999, 2002, 2004, 2008, 2010, and 2013	December 12, 2018	N/A	www.historicaerials.com
Aerial photographs dated April 5, 1992, April 12, 1999, December 31, 2001, June 5, 2004, June 6, 2005, May 27, 2008, May 9, 2010, September 11, 2012, April 24, 2013, September 6, 2015, August 27, 2016, and February 26, 2018	December 18, 2018	N/A	Google Earth
Topographic maps dated 1906, 1910, 1917, 1921, 1923, 1929, 1936, 1943, 1944, 1956, 1960, 1965, 1969, 1974, 1975, 1992, 1999, 2013, and 2016	December 12, 2018	N/A	www.historicaerials.com
City directories dated 1977, 1982, 1987, 1992, 1995, 2000, 2005, 2010, 2014 (see **Appendix C**)	December 17, 2018	Same	EDR
PADEP on-line eMap database	December 12, 2018	Same	PADEP http://www.depgis.state.pa.us/emappa/
April 5, 2004 Phase I Environmental Site Assessment prepared by Vollmer Associates LLP (see **Appendix E**)	December 12, 2018	Same	User
June 11, 2004 Geotechnical Investigation prepared by Advanced GeoServices Corp. (see **Appendix E**)	December 12, 2018	Same	User
December 12, 2018 Standard Detail Report for Complaint ID No. 234314 (see **Appendix E**)	December 13, 2018	Same	PADEP

4.2 Site and Adjoining and Surrounding Property History

Past uses and conditions of the Site, and adjoining and surrounding properties, that were visually and/or physically observed during the Site reconnaissance, or to the extent that they were identified during interviews (see Section 6) or the records review (see Section 4) are summarized below:

4.2.1 Site Property History

Prior to 1950, the Site comprised undeveloped, wooded and vegetated land with unpaved roads in the southern and central portions and unpaved trails in the western, central, and southern portions. Construction of the northerly- and westerly-adjoining State Highway 82 began sometime between 1950 and 1968. Stockpiling of soil and rock cuttings from the roadway construction was apparent on the central portion of the Site, and additional unpaved roads were apparent in the northern and southern portions of the Site. Stockpiling of soil and rock cuttings from the roadway construction continued until sometime between 1969 and 1982, and the soil and rock cuttings were left in place on the Site. Once stockpiling activities were completed, the stockpiled soil and rock and unpaved roadways and trails became revegetated and wooded. No additional development activities were apparent through to 2013.

Historical ownership is summarized in the following table:

Date(s)	Owner Name
Prior to May 13, 1932, July 14, 1944, and March 20, 1953*	Unknown (see Section 7.2)
May 13, 1932 to February 12, 1959*	George D. and Elizabeth Spackman
July 14, 1944 to September 22, 1955*	David S. and Edith C. Landis
March 20, 1953 to December 6, 1955*	Paul L.A. Keiser
February 12, 1959, September 22, 1955, and December 6, 1955, to December 18, 1987	Miller Hill Corp.
December 18, 1987 to April 15, 2004	Tarlecky Enterprises Corp.
April 15, 2004 to present	Baker Residential of PA

* - Based on the information reviewed, it appears that the Site previously comprised separate lots that were sold to Miller Hill Corp. on separate dates.

According to the review of the topographic maps, the elevation of the central portion of the Site increased by at least 20 feet sometime between 1944 and 1956. This coincides with the stockpiling of soil and rock cuttings activities observed during the aerial review.

4.2.2 Adjoining Property History

The northern-adjoining properties comprised undeveloped, wooded land and single-family residences since prior to 1950. Sometime between 1950 and 1968, State Highway 82 was constructed.

The southern-adjoining properties comprised undeveloped, vegetated land with unpaved roads and a portion of the Amtrak rail line since prior to 1950. Construction of single- and multi-family residences began sometime between 1950 and 1968. Additional single-family residences were constructed sometime between 1969 and 1982 and between 1992 and 1999.

The eastern-adjoining properties comprised undeveloped, wooded and vegetated land and single-family residences since prior to 1950. Construction of single-family residences began sometime between 1950 and 1968. Additional single-family residences were constructed sometime between 2002 and 2004.

The western-adjoining properties comprised undeveloped, wooded land, a public thoroughfare, and single-family residences since prior to 1950 to the present. Sometime between 1950 and 1968, State Highway 82 was constructed.

4.2.3 Surrounding Property History

The surrounding properties to the north, east, and west comprised undeveloped, wooded land, agricultural farmland, and single-family residences since prior to 1950. Additional single-family residences were constructed to the west sometime between 1950 and 1968 and between 1999 and 2004; and multi-family residences were constructed to the west sometime between 1969 and 1982 and between 1999 and 2004.

Surrounding properties to the south comprised mixed-use commercial, industrial, single-family residential, and schools from prior to 1950 to the present. Industrial facilities common in the area are steel mills.

4.3 Database Report & Environmental Record Review

A database search report that identifies properties listed on state and federal databases within the ASTM-required radii of the Site was obtained from EDR and is included in **Appendix A**. The purpose of the regulatory file review is to obtain sufficient information to assist the *environmental professional* in determining if a REC, CREC, HREC, and/or de minimis condition exists at the Site in connection with the listing. Pertinent and/or alternative regulatory files and/or records reviewed are listed in Section 4.1 and are summarized in Section 7, as applicable.

	Listed in one or more databases?	Were pertinent regulatory files and/or records associated with the listing(s) reviewed?	Were alternate files and/or records associated with the listing(s) reviewed?	Were RECs/HRECs/ CRECs/de minimis conditions identified in connection with the Site
Site	Yes	Yes	No	See below
Adjoining property(ies)	No	N/A	N/A	N/A

According to the EDR database report, the Site was not identified in any databases. However, during a review of the PADEP's eMap online database, a complaint was filed on June 11, 2003 for land contamination (Complaint ID No. 234314). A records request was submitted to PADEP for the complaint, and a copy was obtained on December 13, 2018. According to the complaint, a spill of 100 gallons of hydraulic oil occurred due to a broken hydraulic line, the spill was contained to pavement, and clean-up was underway. Based on the information reported on the complaint, it does not appear that this spill occurred at the Site, as there are no paved surfaces present, and the location of the complaint is incorrect on eMap.

Whitman evaluated the following factors to determine whether environmental records should be reviewed with respect to the potential for contaminant migration from the surrounding properties:

(1) Whether the property is up-gradient or down-gradient of the Site vis-à-vis **ground water migration** based on the local topography, and the assumed ground water depth and shallow ground water flow direction identified in Section 2.2;

(2) Whether the property is up-gradient or down-gradient of the Site vis-à-vis **vapor migration** based on readily available information pursuant to the ASTM E1527-13 standard including soil and geological characteristics; contaminant characteristics; contaminated plume migration data; and significant conduits that might provide preferential pathways for vapor migration such as major utility corridors, sanitary sewers, storm sewers, and significant natural conduits such as Karst terrain (vapor migration may also be influenced by the age and design of infrastructure features associated with these conduits);

(3) Property case status (i.e., whether the [state environmental agency or [an] applicable regulatory authority] has issued a No Further Action letter [or other similar closure document]);

(4) Type of database and whether the presence of contamination is known; and

(5) The distance between the listed property and the Site.

Based on the above-described regulatory file review, conditions or evidence indicative of a REC, CREC, HREC and/or de minimis condition at the Site were not identified, and no further regulatory file review was conducted.

Unless otherwise noted, the information obtained from the files/records review was sufficient to evaluate the existence of RECs, HRECs, CRECs, and/or de minimis conditions in connection with the Site.

5.0 SITE RECONNAISSANCE

5.1 Methodology and Limiting Conditions

Site reconnaissance performed by	Ms. Sheila Innella, Whitman Senior Scientist I Ms. Alexa Fiumarelli, Whitman Staff Scientist Ms. Emily Dallas, Whitman Junior Scientist
Methodology	Walkthrough Site reconnaissance (a photograph log is included as **Appendix D**)
Reconnaissance date	December 14, 2018
Site representative name	N/A
Site representative title	N/A
Site representative company	N/A
Limiting condition(s)	The soil surface beneath the observed debris piles at the Site could not be inspected (see Section 7.2).

5.2 Interior and Exterior Site Observations

Unless otherwise noted, the items listed in the table below appeared in good condition with no visual evidence of staining, deterioration, or a discharge of hazardous materials and/or petroleum products; and there are no records of a release in these areas. Items where further description is warranted are discussed in the section(s) following the table.

Item	Identified (Y/N)	Currently Present	Historically Present	Description
Hazardous material storage or handling areas	**N**			
Aboveground storage tanks (ASTs) and associated piping	**N**		**X**	See Section 7.2

Item	Identified (Y/N)	Currently Present	Historically Present	Description
Underground storage tanks (USTs) and associated piping	**N**			
Drums & containers (≥5 gallons)	**Y**		**X**	See Section 7.2
Odors	**N**			
Pools of liquid, including surface water bodies and sumps (handling hazardous substances or substances likely to be hazardous only)	**N**			
Polychlorinated Biphenyls (PCBs) / Transformers	**N**			
Stains or corrosion	**N**			
Drains & sumps	**N**			
Pits, ponds & lagoons	**N**			
Stressed vegetation	**N**			
Solid waste, historic fill or any other fill material	**Y**	**X**	**X**	See Section 7.2
Wastewater (including storm water or any discharge into a drain, ditch, underground injection system, or stream on or adjacent to the Site)	**Y**	**X**		See Section 5.2.1
Wells (including dry wells, irrigation wells, injection wells, abandoned wells, or other wells)	**N**			
Septic systems or cesspools	**N**			
Debris Piles	**Y**	**X**	**X**	See Section 7.2

5.2.1 Storm Water Discharges

During Whitman's December 14, 2018 Site visit, storm water discharge pipes measuring approximately one-foot in diameter were observed along the western property boundary. It appeared that the storm water discharge pipes collected stormwater from catch basins on the eastern/southern-adjoining properties and discharged collected storm water to the soil surface and catch basins along State Highway 82. No visual or olfactory evidence, such as staining or odors, was observed in the vicinity of the storm water discharge pipes, storm water discharge points, or storm water catch basins on the adjoining properties.

5.3 Adjoining and Surrounding Properties Reconnaissance

5.3.1 Adjoining Properties

During the Site reconnaissance, Whitman viewed the adjoining properties from the Site and publicly accessible areas (e.g., public roadways, etc.).

Direction from Site	Current Land Use Description
North	Undeveloped, wooded land and State Highway 82, proceeded by single-family residences
East	Undeveloped, wooded land and single-family residences
South	Single-family residences and portion of Amtrak rail line
West	State Highway 82, proceeded by undeveloped, wooded land and single-family residences

5.3.2 Surrounding Properties

The surrounding properties to the north, east, and west comprised undeveloped, wooded land and single- and multi-family residences. Surrounding properties to the south comprised mixed-use commercial, industrial (steel mills), single-family residential, and schools.

6.0 INTERVIEWS

Ms. Sheila Innella, Whitman Senior Scientist, conducted interviews (either in person, by telephone, and/or in writing) to obtain historically and/or environmentally-pertinent information regarding RECs associated with the Site. Interviews were conducted with the User(s), key Site manager, Site owner(s), Site operator(s), Site occupants, and/or State, and/or local agency officials, as necessary. The information provided by each has been incorporated in this report, as applicable.

In those instances where answers were not received, or were only partially received (other than from the User(s) – see Section 3.0), written records were kept of the person to whom the questions were addressed and of the responses received (i.e., if questions were asked [or attempted to be asked] in person, by electronic mail, or by telephone), or at least one reasonable follow up (telephone call or written request) was made again asking for responses (i.e., if the questions were asked in writing and sent by first class mail or by private, commercial carrier).

Individuals interviewed and the duration of their occupancy, if applicable, as well as others interviewed during the preparation of this Phase I ESA, are listed in the following table:

Name	Position/Title	Duration of Occupancy
Mr. John Dolan	Vice President and General Manager for Baker Residential (Key Site Manager)	N/A
Ms. Elaine Henderson	Clerk for Pennsylvania Department of Environmental Protection	N/A

Name	Position/Title	Duration of Occupancy
Ms. Sandra Warner	Open Records Officer for Chester County	N/A
Ms. Patty Counes	Open Records Officer for Chester County Health Department	N/A
Ms. Ruthann Mowday	Open Records Officer for City of Coatesville	N/A

7.0 FINDINGS, OPINIONS AND CONCLUSIONS

7.1 Findings and Opinions

Potential findings can include known or suspect RECs, historical RECs (HRECs), controlled RECs (CRECs) and *de minimis* conditions, pursuant to the ASTM E1527-13 standard.

RECs are defined as the presence or likely presence of any *hazardous substances* or *petroleum products* in, on, or at a *property*: (1) due to any *release* to the environment; (2) under conditions indicative of a *release* to the *environment*; or (3) under conditions that pose a *material threat* of a future *release* to the *environment*.

CRECs are defined as a REC resulting from a past *release* of *hazardous substances* or *petroleum products* that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with *hazardous substances* or *petroleum products* allowed to remain in place subject to the implementation of required controls (for example, *property* use restrictions, *activity and use limitations, institutional controls*, or *engineering controls*).

HRECs are defined as a past *release* of any *hazardous substances* or *petroleum products* that has occurred in connection with the *property* and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the *property* to any required controls (for example, *property* use restrictions, *activity and use limitations, institutional controls*, or *engineering controls*).

De minimis conditions are defined as a condition that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be *de minimis conditions* are not RECs nor CRECs.

Unless otherwise noted, the information obtained during the files/records review of this Phase I ESA was sufficient to evaluate the existence of RECs, HRECs, CRECs, and *de minimis* conditions. The Environmental Professional who prepared this Phase I report was Ms. Sheila

Innella, Whitman Senior Scientist, see **Appendices F and G**. Deviations from this standard are described in Sections 1.3, 5.1, and 7.4 of this report, as applicable.

7.1.1 RECs

No known or suspected RECs in connection with the Site were identified during this Phase I.

7.1.2 CRECs

No known or suspected CRECs in connection with the Site were identified during this Phase I.

7.1.3 HRECs

No known or suspected HRECs in connection with the Site were identified during this Phase I.

7.1.4 *De Minimis* Conditions

No known or suspected *de minimis conditions* in connection with the Site were identified during this Phase I.

7.2 Data Gaps

Pursuant to the ASTM Phase I Standard, a data gap is defined as *a lack of or inability to obtain information required by [the ASTM Phase I Standard] despite good faith efforts by the environmental professional to gather such information*. Pursuant to the ASTM Phase I Standard, *the report shall identify and comment on significant data gaps that affect the ability of the EP to identify RECs and identify the sources of information that were consulted to address the data gaps. A data gap is only significant if other information and/or professional experience raises reasonable concerns involving the data gap*. The term "significant data gap" does not necessarily imply that the relative liability or potential financial risk of the concern is significant.

Whitman has made an appropriate inquiry into the commonly known and reasonably ascertainable resources concerning the historical ownership and use of the Site back to the first development per 40 CFR Part 312.24 (*Reviews of Historical Sources of Information*). Data gaps identified during this assessment include the following:

<u>Data Gap No. 1 – Historical Information</u>
Historical information was unavailable in five-year increments between 1910 and 1917, 1923 and 1929, 1936 and 1943, and 1944 and 1950. Additionally, historical ownership prior to May 13, 1932, July 14, 1944, and March 20, 1953 was unavailable. Based on the absence of development during these time periods, this data gap is not considered to be a *significant* data gap.

Data Gap No. 2 – Soil and Rock Piles

Based on the review of historical aerials, apparent stockpiling in the center of the Site of soil and rock cuttings from the construction of State Highway 82 began sometime between 1950 and 1968 and continued until sometime between 1969 and 1982. During Whitman's December 14, 2018 Site visit, the stockpiled soil and rock appeared to have become heavily vegetated with trees and brush, and the stockpiled soil and rock measured approximately 850 feet long by 250 feet wide by 20 feet in height. Based on the approximate measurements, the amount of material stockpiled would be 200,000 tons or greater. No visual or olfactory evidence of a release of hazardous substances, such as staining, stressed vegetation, or odors, was observed during Whitman's Site visit. The stockpiled soil and rock are not expected to have impacted the environmental condition of the Site. Therefore, this data gap is not considered to be a *significant* data gap. However, should this material be removed during redevelopment activities, sampling in accordance with applicable disposal guidelines is necessary to determine how the material can be disposed.

Data Gap No. 3 – Former Tank

According to an April 5, 2004 Phase I Environmental Site Assessment prepared by Vollmer Associates LLP (see **Appendix D**), an empty tank was observed on the northern portion of the Site, however, the previous report indicated that there was no evidence of hazardous substances leaking from the tank. In another section of the report, an interview with Mr. Bob Tarlecky, the Site owner at the time, indicated that the large tank was located on the northern-adjacent property and not the Site. According to the report, Mr. Tarlecky indicated that the tank was owned by a previous owner of the northern-adjoining property and had been intended for use as an oil storage tank; however, the owner passed prior to installation of the tank.

Based on Whitman's review of the photographs taken during Vollmer Associates' Site visit, the tank in question appears to have been a large (possibly 2,000-gallon or greater) steel underground storage tank (UST). It is apparent from the photographs that the tank was located south of State Highway 82; however, it is unclear if this was located on the Site or the northern-adjoining property. No evidence of the tank was observed during Whitman's December 14, 2018 Site visit in this area or elsewhere on the Site. Additionally, no visual or olfactory evidence of a release of hazardous substances, such as staining, stressed vegetation, or odors, was observed during Whitman's Site visit, at the location where the tank had reportedly been located. It is unknown when the tank was removed from the Site and disposed; however, based on Vollmer Associates' photographs, the former presence of the empty tank dumped on or near the Site is not expected to have impacted the environmental condition of the Site. Therefore, this data gap is not considered to be a *significant* data gap.

Data Gap No. 4 – 55-Gallon Drums

According to the April 5, 2004 Phase I, 55-gallon drums were observed in several locations on the Site. The previous report indicated that there was no evidence of hazardous substances leaking from the drums; however, the drums were sealed, and the contents could not be verified. Vollmer Associates indicated that one drum was located in the southeastern portion of

the Site; however, the location of the second drum was not reported. No visual evidence of the reported drums was observed during Whitman's December 14, 2018 Site visit, and no visual or olfactory evidence of a release of hazardous substances, such as staining, stressed vegetation, or odors, was observed during Whitman's Site visit. However, the contents of the drums remain unknown, and no information or documentation was identified that indicated when the drums were removed from the Site or where they were transported. Based on the condition of the drums apparent in the Vollmer Associates report, the drums may have leaked, and a potential exists for impact to the environmental condition of the Site. Therefore, this data gap is considered to be a *significant* data gap.

Data Gap No. 5 – Debris Piles

According to the April 5, 2004 Phase I, numerous piles of debris, trash, and tires were observed on the Site. According to Vollmer Associates' photographs, the debris also consisted of metal trash cans, plastic tarpaulin, vinyl siding, metal appliances, plastic and metal five-gallon containers, concrete, wood pallets, sheet metal, and scrap metal. During Whitman's December 14, 2018 Site visit, evidence debris was observed throughout the Site, including the following:

- Metal and plastic containers, concrete, automotive parts, and pressure-treated lumber in the central portion of the Site;
- Tires, concrete, automotive parts, shingles, floor tile, wood window frame, rebar, and a hot tub in the northern portion of the Site;
- Tires in the northeastern portion of the Site;
- Concrete in the eastern portion of the Site; and
- Tires, plastic playground equipment, plastic household waste, televisions, concrete, and asphalt millings in the southern portion of the Site

No visual or olfactory evidence of a release of hazardous substances, such as staining, stressed vegetation, or odors, was observed in the vicinity of the observed debris; however, the soil surface beneath the materials could not be inspected. Based on the observations made during the Site visit, the debris piles are not expected to have negatively impacted the environmental condition of the Site. Therefore, this data gap is not considered to be a *significant* data gap. However, it is necessary to dispose of these materials in accordance with applicable laws and regulations. Additionally, sampling for polychlorinated biphenyls (PCBs) in the concrete is necessary to ensure that the dumped concrete is not hazardous, and sampling of the dumped shingles and floor tile is necessary to determine if these are asbestos containing materials.

7.3 Conclusions

Whitman has performed a Phase I ESA in conformance with the scope and limitations of ASTM E1527-13 at the property located at **320 Adams Drive, City of Coatesville, Chester County, Pennsylvania** (Site).

This assessment has revealed no evidence of RECs (including CRECs) in connection with the Site.

7.4 Limiting Conditions and Deviations

7.4.1 Accuracy and Completeness

The ASTM E1527-13 standard recognizes inherent limitations for Phase I ESAs that apply to this report, including:

- Uncertainty Not Eliminated – No Phase I ESA can wholly eliminate uncertainty regarding the potential for RECs in connection with a property. Data gaps identified during this Phase I ESA are listed in Section 7.2.

- Not Exhaustive – A Phase I ESA is not an exhaustive investigation.

- Past Uses of the Property – A review of standard historical sources at intervals less than five years is not required.

The Client is advised that the Phase I ESA conducted at the Site is a limited inquiry into a property's environmental status, cannot wholly eliminate uncertainty, and is not an exhaustive assessment to discover every potential source of environmental liability at the Site. Therefore, Whitman does not make a statement of warranty or guarantee, express or implied for any specific use that i) the Site is free of RECs or environmental impairment; ii) that the Site is "clean"; or iii) that impairments, if any, are limited to those that were discovered while Whitman was performing the Phase I ESA. This limiting statement is not meant to compromise the findings of this report; rather, it is meant as a statement of limitations within the ASTM standard and intended scope of this assessment. Specific limiting conditions identified during the Site reconnaissance are described in Section 5.1. Subsurface conditions may differ from the conditions implied by surface observations, and can be evaluated more thoroughly through intrusive techniques that may be beyond the scope of this assessment. Information in this report is not intended to be used as a construction document, and should not be used for demolition, renovation, or other construction purposes.

This report presents Whitman's site reconnaissance observations, findings, and conclusions as they existed at the time of the Site reconnaissance. Whitman makes no representation or warranty that the past or current operations at the property are, or have been, in compliance with all applicable federal, state, and local laws, regulations and codes. Whitman makes no guarantees as to the accuracy or completeness of information obtained from others during the course of this Phase I ESA report. It is possible that information exists beyond the scope of this assessment, or that information was not provided to Whitman. Additional information subsequently provided, discovered, or produced may alter findings or conclusions made in this Phase I ESA report. Whitman is under no obligation to update this report to reflect such

subsequent information. The findings presented in this report are based upon reasonably ascertainable information and observed Site conditions at the time of the assessment.

This report does not warrant against future operations or conditions, nor does it warrant against operations or conditions present of a type or at a location not assessed. Regardless of the findings stated in this report, Whitman is not responsible for consequences or conditions arising from facts that were not fully disclosed to Whitman during the assessment.

An independent data research company provided the government agency database referenced in this report. Information regarding surrounding area properties was requested for approximate minimum search distances and was assumed to be correct and complete unless obviously contradicted by Whitman's observations or other credible referenced sources reviewed during the assessment.

Whitman is not a professional title insurance or land surveyor firm and makes no guarantee, explicit or implied, that any land title records acquired or reviewed, or any physical descriptions or depictions of the property in this report, represent a comprehensive definition or precise delineation of property ownership or boundaries.

7.4.2 Warranties and Representations

This report does not warrant against: (1) operations or conditions which were not evident from visual observations or historical information provided; (2) conditions which could only be determined by physical sampling or other intrusive investigation techniques, if no such activities were conducted during this assessment; (3) locations other than the client-provided addresses and/or legal parcel description; or (4) information regarding off-site location(s) (with possible impact to the Site) not published in publicly available records.

7.4.3 Continued Validity/User Reliance

This report is presumed to be valid, in accordance with, and subject to, the limitations specified in the ASTM E1527-13 standard, for a period of 180 days from completion, or until the Client obtains specific information that may materially alter a finding, opinion, or conclusion in this report, or until the Client is notified by Whitman that it has obtained specific information that may materially alter a finding, opinion, or conclusion in this report. Additionally, pursuant to the ASTM E1527-13 standard, this report is presumed valid if completed less than 180 days prior to the date of acquisition of the property or (for transactions not involving an acquisition) the date of the intended transaction.

7.4.4 Significant Assumptions

During this Phase I ESA, Whitman relied on database information; interviews with Site representatives, regulatory officials, and other individuals having knowledge of Site operations;

and information provided by the User(s) as requested in our authorized Scope of Work. Whitman has assumed that the information provided is true and accurate. Reliance on electronic database search reports is subject to the limitations set forth in those reports. Whitman did not independently verify the information provided. Whitman found no reason to question the validity of the information received unless explicitly noted elsewhere in this report. If other information is discovered and/or if previous reports exist that were not provided to Whitman, our conclusions may not be valid.

8.0 ADDITIONAL SERVICES

No additional services were performed during this Phase I ESA.

FIGURES



Source: ChescoViews R3.1

Site Layout Plan	
Baker Residential of PA LLC 320 Adams Drive Coatesville, Chester County, Pennsylvania	
Whitman Project No. 18-12-12T	
December 20, 2018	**Figure 1**
WHITMAN	**7 Pleasant Hill Road** **Cranbury, New Jersey 08512** **Tel: (732) 390-5858**

APPENDIX A:

Database Radius Report

Baker Residential
320 Adams Drive
Coatesville, PA 19320

Inquiry Number: 5509910.2s
December 12, 2018

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	310
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

320 ADAMS DRIVE
COATESVILLE, PA 19320

COORDINATES

Latitude (North):	39.9881250 - 39° 59' 17.25''
Longitude (West):	75.8214080 - 75° 49' 17.06''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	429870.4
UTM Y (Meters):	4426552.5
Elevation:	483 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5947569 COATESVILLE, PA
Version Date:	2013
North Map:	5948171 WAGONTOWN, PA
Version Date:	2013

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150815
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
320 ADAMS DRIVE
COATESVILLE, PA 19320

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
1	ELMWOOD GARDENS APAR	100 HARLAN DR	PA ARCHIVE UST	Lower	297, 0.056, ESE
A2	LAMBS AUTO SVC	101 E CHESTNUT ST	PA UNREG LTANKS, PA UST, PA ARCHIVE UST	Lower	358, 0.068, SW
A3	LAMB SERVICE STATION	101 E CHESTNUT ST	EDR Hist Auto	Lower	358, 0.068, SW
A4	LAMB PAUL H	101 N FIRST AVE	EDR Hist Auto	Lower	471, 0.089, SSW
B5	LIPKINS FURNITURE WH	139 E CHESTNUT ST	PA AUL, PA VCP	Lower	476, 0.090, SSW
C6	TUTTLE & MANET	399C FLEETWOOD RD	RCRA NonGen / NLR	Lower	574, 0.109, SE
7	GREAT VALLEY MATERIA	RTE 82	RCRA-CESQG	Lower	616, 0.117, West
D8	OLIVET UNITED METH C	310 E CHESTNUT ST	PA ARCHIVE UST	Lower	665, 0.126, SSE
B9	COATESVILLE CITY AUT	103 E DIAMOND ST	PA ARCHIVE UST	Lower	671, 0.127, SSW
C10	MCFALLS COLLISION IN	400 FLEETWOOD ST	RCRA-CESQG, FINDS, ECHO	Lower	814, 0.154, ESE
11	PARCEL 16-5-16, LUKE	115 WEST LINCOLN HIG	US BROWNFIELDS, FINDS	Lower	845, 0.160, SSW
D12	KANE EDWIN W DDS	7 N 3RD AVE	RCRA-CESQG, FINDS, ECHO	Lower	866, 0.164, SSE
D13	CHURCH OF THE TRINIT	323 E LINCOLN HWY	PA ARCHIVE UST	Lower	869, 0.165, SSE
E14	PARKS AIRPORT CLNR S	107 E LINCOLN HWY	RCRA-SQG, FINDS, ECHO	Lower	897, 0.170, SSW
E15	PARKS AIRPORT CLNR/C	107 E LINCOLN HWY	PA AIRS, PA DRYCLEANERS	Lower	897, 0.170, SSW
E16	ONE HOUR CLEANERS DB	107 EAST LINCOLN HIG	PA MANIFEST	Lower	897, 0.170, SSW
E17	PARKS AIRPORT CLEANE	107 E LINCOLN HWY	PA MANIFEST	Lower	897, 0.170, SSW
E18	LOCKWOOD ESTATE	50 E LINCOLN HWY	PA UNREG LTANKS	Lower	935, 0.177, SSW
F19	COATESVILLE TOWERS	339 E LINCOLN HWY	PA VCP	Lower	952, 0.180, SSE
F20	RITE AID NO 992	320 E LINCOLN HWY	RCRA-CESQG, FINDS, ECHO	Lower	1044, 0.198, SSE
F21	RITE AID # 00992	320 EAST LINCOLN HIG	PA MANIFEST	Lower	1044, 0.198, SSE
G22	DEVITTS HDWR STORE S	26 S 1ST AVE	PA VCP, PA ACT 2-DEED	Lower	1057, 0.200, SSW
G23	SMS MILL SVC/COATESV	S 1ST AVE	RCRA-CESQG, ICIS, US AIRS, FINDS	Lower	1143, 0.216, SSW
H24	PRESB CH OF COATESVI	FOURTH AVE & E LINCO	PA ARCHIVE UST	Lower	1156, 0.219, SE
I25	G. O. CARLSON INC	135 WEST LINCOLN HIG	RCRA-CESQG, NJ MANIFEST	Lower	1208, 0.229, SW
I26	GO CARLSON	135 W LINCOLN HWY	PA MANIFEST	Lower	1208, 0.229, SW
H27	FAMILY DOLLAR STORES	400 E LINCOLN HWY	RCRA-CESQG, FINDS, ECHO	Lower	1272, 0.241, SE
J28	COATESVILLE CTL OFC	500 E CHESTNUT ST	PA AUL	Lower	1292, 0.245, SE
J29	COATESVILLE CTL OFC	500 CHESTNUT ST	PA ARCHIVE UST	Lower	1292, 0.245, SE
J30	COATESVILLE CTL OFC	500 E CHESTNUT ST	PA LUST, PA AST	Lower	1292, 0.245, SE
I31	THE COATESVILLE GAS	WAGONTOWN RD (BRIDGE	EDR MGP	Lower	1296, 0.245, SW
K32	NEWLIN BROS	340 HARMONY ST	PA LUST	Lower	1302, 0.247, SSE
K33	NEWLIN BROS	340 HARMONY ST	PA ARCHIVE UST	Lower	1302, 0.247, SSE
34	FLAMER RES	553 E CHESTNUT ST	PA VCP	Lower	1356, 0.257, ESE
35	LUKENS WEST SIDE SLA	50 S. 1ST. AVENUE	PA HIST LF	Lower	1378, 0.261, South
36	GORDON JR HIGH SCH	351 KERSEY	PA UNREG LTANKS	Lower	1573, 0.298, SSE
37	BETH ISRAEL	5TH & HARMONY ST	PA UNREG LTANKS	Lower	1616, 0.306, SE
38	CARL O BENNER ELEM S	545 E LINCOLN HWY	PA LUST, PA ARCHIVE UST, PA MANIFEST	Lower	1720, 0.326, SE
L39	LEE RESIDENCE	224 W LINCOLN HWY	PA UNREG LTANKS	Lower	1883, 0.357, SW

MAPPED SITES SUMMARY

Target Property Address:
320 ADAMS DRIVE
COATESVILLE, PA 19320

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
40	PARCEL 16-5-302, BET	76 MAPLE STREET	US BROWNFIELDS, FINDS	Lower	1884, 0.357, South
M41	PARCEL 16-5-271, BET	97 SOUTH FIRST AVENU	US BROWNFIELDS, FINDS	Lower	1888, 0.358, South
M42	SIDHU PROP	99 S 1ST AVE	PA LUST, PA UST, PA AUL, PA ARCHIVE UST	Lower	2004, 0.380, South
L43	ANDY KUPERSTEIN	305 W LINCOLN HWY	PA LUST, PA ARCHIVE UST	Lower	2038, 0.386, SW
M44	PARCEL 16-5-298, BET	151 SOUTH FIRST AVEN	US BROWNFIELDS, FINDS	Lower	2089, 0.396, South
45	POLISH AMER CITIZENS	15 STRODE AVE	PA LUST, PA ARCHIVE UST	Lower	2167, 0.410, SW
46	HILL FARM	BLACKHORSE HILL RD	PA VCP	Higher	2240, 0.424, NE
N47	DUPONT OF COATESVILL	17 NORTH 7TH ST.	PA HIST LF	Lower	2272, 0.430, ESE
N48	DUPONT COATESVILLE	17 N 7TH AVE	SEMS-ARCHIVE	Lower	2272, 0.430, ESE
N49	DUPONT COATESVILLE	17 N 7TH AVE	PA INST CONTROL	Lower	2272, 0.430, ESE
50	COATSVILLE LANDFILL	MT AIRY RD	SEMS-ARCHIVE	Lower	2280, 0.432, NNW
51	GAS STOP	652 E LINCOLN HWY	PA LUST, PA AUL	Lower	2281, 0.432, ESE
52	WHITELAND AVE. SEWER	19 WHITELAND AVE. &	SEMS-ARCHIVE	Lower	2295, 0.435, ESE
53	JEROME H RHOADS INC	356 W MAIN ST	PA LUST	Lower	2525, 0.478, SW
54	736-738 E LINCOLN HW	736-738 E LINCOLN HW	PA VCP, PA ACT 2-DEED	Lower	2635, 0.499, ESE
55	ARCELORMITTAL PLATE	139 MODENA RD	SEMS, CORRACTS, RCRA-TSDF, RCRA-LQG, PA UNREG...	Lower	4768, 0.903, SSE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State- and tribal - equivalent NPL

PA SHWS ---------- Hazardous Sites Cleanup Act Site List
PA HSCA ---------- HSCA Remedial Sites Listing

State and tribal landfill and/or solid waste disposal site lists

PA SWF/LF ---------- Operating Facilities

State and tribal leaking storage tank lists

PA LAST ---------- Storage Tank Release Sites
INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

EXECUTIVE SUMMARY

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

PA ENG CONTROLS ---------- Engineering Controls Site Listing

State and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

PA BROWNFIELDS ---------- Brownfields Sites

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
US CDL ---------- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

PA ARCHIVE AST ---------- Archived Aboveground Storage Tank Sites

Local Land Records

LIENS 2 ---------- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System

Other Ascertainable Records

FUDS ---------- Formerly Used Defense Sites
DOD ---------- Department of Defense Sites
SCRD DRYCLEANERS ---------- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---------- Financial Assurance Information
EPA WATCH LIST ---------- EPA WATCH LIST
TRIS ---------- Toxic Chemical Release Inventory System
SSTS ---------- Section 7 Tracking Systems
ROD ---------- Records Of Decision

RMP Risk Management Plans
RAATS RCRA Administrative Action Tracking System
PRP Potentially Responsible Parties
PADS PCB Activity Database System
FTTS FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS Material Licensing Tracking System
COAL ASH DOE Steam-Electric Plant Operation Data
COAL ASH EPA Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER PCB Transformer Registration Database
RADINFO Radiation Information Database
HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS Incident and Accident Data
CONSENT Superfund (CERCLA) Consent Decrees
INDIAN RESERV Indian Reservations
FUSRAP Formerly Utilized Sites Remedial Action Program
UMTRA Uranium Mill Tailings Sites
LEAD SMELTERS Lead Smelter Sites
US MINES Mines Master Index File
ABANDONED MINES Abandoned Mines
DOCKET HWC Hazardous Waste Compliance Docket Listing
UXO Unexploded Ordnance Sites
FUELS PROGRAM EPA Fuels Program Registered Listing
PA ASBESTOS ASBESTOS
PA MINES MINES
PA UIC Underground Injection Wells

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

PA RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
PA RGA LF Recovered Government Archive Solid Waste Facilities List
PA RGA LUST Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 11/14/2018 has revealed that there are 3 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DUPONT COATESVILLE Site ID: 0300882 EPA Id: PAD021962006	17 N 7TH AVE	ESE 1/4 - 1/2 (0.430 mi.)	N48	113
COATSVILLE LANDFILL	MT AIRY RD	NNW 1/4 - 1/2 (0.432 mi.)	50	115
WHITELAND AVE. SEWER Site ID: 0305083 EPA Id: PA0001091784	19 WHITELAND AVE. &	ESE 1/4 - 1/2 (0.435 mi.)	52	120

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 03/01/2018 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARCELORMITTAL PLATE EPA ID:: PAD002326908	***139 MODENA RD***	***SSE 1/2 - 1 (0.903 mi.)***	***55***	***124***

Federal RCRA generators list

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/01/2018 has revealed that there is 1

RCRA-SQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PARKS AIRPORT CLNR S EPA ID:: PAD981731482	***107 E LINCOLN HWY***	***SSW 1/8 - 1/4 (0.170 mi.)***	***E14***	***28***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 7 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
GREAT VALLEY MATERIA EPA ID:: PAD987345659	RTE 82	W 0 - 1/8 (0.117 mi.)	7	17
MCFALLS COLLISION IN EPA ID:: PAD987352028	***400 FLEETWOOD ST***	***ESE 1/8 - 1/4 (0.154 mi.)***	***C10***	***20***
KANE EDWIN W DDS EPA ID:: PAR000025643	***7 N 3RD AVE***	***SSE 1/8 - 1/4 (0.164 mi.)***	***D12***	***26***
RITE AID NO 992 EPA ID:: PAR000536797	***320 E LINCOLN HWY***	***SSE 1/8 - 1/4 (0.198 mi.)***	***F20***	***39***
SMS MILL SVC/COATESV EPA ID:: PAD060057320	***S 1ST AVE***	***SSW 1/8 - 1/4 (0.216 mi.)***	***G23***	***49***
G. O. CARLSON INC EPA ID:: PAR000506899	***135 WEST LINCOLN HIG***	***SW 1/8 - 1/4 (0.229 mi.)***	***I25***	***74***
FAMILY DOLLAR STORES EPA ID:: PAR000553016	***400 E LINCOLN HWY***	***SE 1/8 - 1/4 (0.241 mi.)***	***H27***	***78***

State and tribal leaking storage tank lists

PA LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Resources' List of Confirmed Releases.

A review of the PA LUST list, as provided by EDR, and dated 09/10/2018 has revealed that there are 8 PA LUST sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
COATESVILLE CTL OFC Facility Id: 585972	***500 E CHESTNUT ST***	***SE 1/8 - 1/4 (0.245 mi.)***	***J30***	***82***
NEWLIN BROS Facility Id: 585861	340 HARMONY ST	SSE 1/8 - 1/4 (0.247 mi.)	K32	84
CARL O BENNER ELEM S	***545 E LINCOLN HWY***	***SE 1/4 - 1/2 (0.326 mi.)***	***38***	***87***

Facility Id: 586451				
SIDHU PROP Facility Id: 585829	***99 S 1ST AVE***	***S 1/4 - 1/2 (0.380 mi.)***	***M42***	***97***
ANDY KUPERSTEIN Facility Id: 586995	***305 W LINCOLN HWY***	***SW 1/4 - 1/2 (0.386 mi.)***	***L43***	***104***
POLISH AMER CITIZENS Facility Id: 587022	***15 STRODE AVE***	***SW 1/4 - 1/2 (0.410 mi.)***	***45***	***109***
GAS STOP Facility Id: 586067	***652 E LINCOLN HWY***	***ESE 1/4 - 1/2 (0.432 mi.)***	***51***	***116***
JEROME H RHOADS INC Facility Id: 586129	356 W MAIN ST	SW 1/4 - 1/2 (0.478 mi.)	53	121

PA UNREG LTANKS: Leaking storage tank cases from unregulated storage tanks.

A review of the PA UNREG LTANKS list, as provided by EDR, and dated 04/12/2002 has revealed that there are 5 PA UNREG LTANKS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LAMBS AUTO SVC	***101 E CHESTNUT ST***	***SW 0 - 1/8 (0.068 mi.)***	***A2***	***9***
LOCKWOOD ESTATE	50 E LINCOLN HWY	SSW 1/8 - 1/4 (0.177 mi.)	E18	38
GORDON JR HIGH SCH Closed: 6/25/2001	351 KERSEY	SSE 1/4 - 1/2 (0.298 mi.)	36	86
BETH ISRAEL	5TH & HARMONY ST	SE 1/4 - 1/2 (0.306 mi.)	37	87
LEE RESIDENCE	224 W LINCOLN HWY	SW 1/4 - 1/2 (0.357 mi.)	L39	91

State and tribal registered storage tank lists

PA UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Resources' Regulated Underground Storage Tank Listing.

A review of the PA UST list, as provided by EDR, and dated 09/04/2018 has revealed that there is 1 PA UST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LAMBS AUTO SVC Site ID: 569125 Tank Status: Currently In Use	***101 E CHESTNUT ST***	***SW 0 - 1/8 (0.068 mi.)***	***A2***	***9***

PA AST: The Aboveground Storage Tank database contains registered ASTs from the Department of Environmental Protection's Listing of Pennsylvania Regulated Aboveground Storage Tanks.

A review of the PA AST list, as provided by EDR, and dated 09/04/2018 has revealed that there is 1 PA AST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
COATESVILLE CTL OFC	***500 E CHESTNUT ST***	***SE 1/8 - 1/4 (0.245 mi.)***	***J30***	***82***

Site ID: 569240
Tank Status: C

State and tribal institutional control / engineering control registries

PA INST CONTROL: Under Act 2 and the accompanying regulations, Administration of Land Recycling Program, persons who perform a site cleanup using a site-specific standard or affect a special industrial area cleanup may use engineering or institutional controls to attain the cleanup. The sites listed had either an engineering control and/or an instituitional control used in the remediation of the site.

A review of the PA INST CONTROL list, as provided by EDR, and dated 05/15/2008 has revealed that there is 1 PA INST CONTROL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DUPONT COATESVILLE Primary Facility Id: 616960	17 N 7TH AVE	ESE 1/4 - 1/2 (0.430 mi.)	N49	114

PA AUL: A listing of sites with environmental covenants.

A review of the PA AUL list, as provided by EDR, and dated 10/16/2018 has revealed that there are 4 PA AUL sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LIPKINS FURNITURE WH Facility Id: 758308	***139 E CHESTNUT ST***	***SSW 0 - 1/8 (0.090 mi.)***	***B5***	***14***
COATESVILLE CTL OFC Facility Id: 585972	500 E CHESTNUT ST	SE 1/8 - 1/4 (0.245 mi.)	J28	81
SIDHU PROP Facility Id: 585829	***99 S 1ST AVE***	***S 1/4 - 1/2 (0.380 mi.)***	***M42***	***97***
GAS STOP Facility Id: 586067	***652 E LINCOLN HWY***	***ESE 1/4 - 1/2 (0.432 mi.)***	***51***	***116***

State and tribal voluntary cleanup sites

PA VCP: The VCP listings included Completed Sites, Sites in Progress and Act 2 Non-Use Aquifer Determinations Sites. Formerly known as the Act 2, the Land Recycling Program encourages the voluntary cleanup and reuse of contaminated commercial and industrial sites.

A review of the PA VCP list, as provided by EDR, and dated 10/09/2018 has revealed that there are 6 PA VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HILL FARM Activity ID: 617121	BLACKHORSE HILL RD	NE 1/4 - 1/2 (0.424 mi.)	46	112

Lower Elevation	Address	Direction / Distance	Map ID	Page
LIPKINS FURNITURE WH	***139 E CHESTNUT ST***	***SSW 0 - 1/8 (0.090 mi.)***	***B5***	***14***

Activity ID: 758308				
COATESVILLE TOWERS Activity ID: 740484	339 E LINCOLN HWY	SSE 1/8 - 1/4 (0.180 mi.)	F19	39
DEVITTS HDWR STORE S Activity ID: 616974	***26 S 1ST AVE***	***SSW 1/8 - 1/4 (0.200 mi.)***	***G22***	***49***
FLAMER RES Activity ID: 803437	553 E CHESTNUT ST	ESE 1/4 - 1/2 (0.257 mi.)	34	86
736-738 E LINCOLN HW Activity ID: 680476	***736-738 E LINCOLN HW***	***ESE 1/4 - 1/2 (0.499 mi.)***	***54***	***123***

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 09/18/2018 has revealed that there are 4 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PARCEL 16-5-16, LUKE ACRES property ID: 12458	***115 WEST LINCOLN HIG***	***SSW 1/8 - 1/4 (0.160 mi.)***	***11***	***23***
PARCEL 16-5-302, BET ACRES property ID: 12454	***76 MAPLE STREET***	***S 1/4 - 1/2 (0.357 mi.)***	***40***	***91***
PARCEL 16-5-271, BET ACRES property ID: 12456	***97 SOUTH FIRST AVENU***	***S 1/4 - 1/2 (0.358 mi.)***	***M41***	***94***
PARCEL 16-5-298, BET ACRES property ID: 12455	***151 SOUTH FIRST AVEN***	***S 1/4 - 1/2 (0.396 mi.)***	***M44***	***106***

Local Lists of Landfill / Solid Waste Disposal Sites

PA HIST LF: The report provides facility information recorded in the Pennsylvania Department of Environmental Protection ALI database. Some of this information has been abstracted from old records and may not accurately reflect the current conditions and status at these facilities.

A review of the PA HIST LF list, as provided by EDR, has revealed that there are 2 PA HIST LF sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LUKENS WEST SIDE SLA Database: HIST LF INACTIVE, Date of Government Version: 12/20/1994 permitno: 300176	50 S. 1ST. AVENUE	S 1/4 - 1/2 (0.261 mi.)	35	86
DUPONT OF COATESVILL Database: HIST LF INVENTORY, Date of Government Version: 06/02/1999	17 NORTH 7TH ST.	ESE 1/4 - 1/2 (0.430 mi.)	N47	113

Facility Status: INACTIVE
Site ID: 1-106

Local Lists of Registered Storage Tanks

PA ARCHIVE UST: The list includes tanks storing highly hazardous substances that were removed from the DEP's Storage Tank Information database because of the Department's policy on sensitive information. The list also may include tanks that are removed or permanently closed.

A review of the PA ARCHIVE UST list, as provided by EDR, and dated 09/04/2018 has revealed that there are 8 PA ARCHIVE UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ELMWOOD GARDENS APAR Facility Id: 15-43452	100 HARLAN DR	ESE 0 - 1/8 (0.056 mi.)	1	8
LAMBS AUTO SVC Status: Closed Without a Permit Facility Id: 15-06586	***101 E CHESTNUT ST***	***SW 0 - 1/8 (0.068 mi.)***	***A2***	***9***
OLIVET UNITED METH C Facility Id: 15-41268	310 E CHESTNUT ST	SSE 1/8 - 1/4 (0.126 mi.)	D8	19
COATESVILLE CITY AUT Status: Closed Without a Permit Facility Id: 15-45652	103 E DIAMOND ST	SSW 1/8 - 1/4 (0.127 mi.)	B9	20
CHURCH OF THE TRINIT Facility Id: 15-42769	323 E LINCOLN HWY	SSE 1/8 - 1/4 (0.165 mi.)	D13	27
PRESB CH OF COATESVI Status: Closed Without a Permit Facility Id: 15-45523	FOURTH AVE & E LINCO	SE 1/8 - 1/4 (0.219 mi.)	H24	73
COATESVILLE CTL OFC Status: Closed Without a Permit Facility Id: 15-17725	500 CHESTNUT ST	SE 1/8 - 1/4 (0.245 mi.)	J29	81
NEWLIN BROS Status: Closed Without a Permit Facility Id: 15-10149	340 HARMONY ST	SSE 1/8 - 1/4 (0.247 mi.)	K33	85

Local Land Records

PA ACT 2-DEED: This listing pertains to sites where the Department has approved a cleanup requiring a deed acknowledgment under Act 2. This list includes sites remediated to a non-residential Statewide health standard (Section 303(g)); all sites demonstrating attainment of a Site-specific standard (Section 304(m)); and sites being remediated as a special industrial area (Section 305(g)). Persons who remediated a site to a standard that requires a deed acknowledgment shall comply with the requirements of the Solid Waste Management Act or the Hazardous Sites Cleanup Act, as referenced in Act 2. These statutes require a property description section in the deed concerning the hazardous substance disposal on the site. The location of disposed hazardous substances and a description of the type of hazardous substances disposed on the site shall be included in the deed acknowledgment. A deed acknowledgment is required at the time of conveyance of the property.

A review of the PA ACT 2-DEED list, as provided by EDR, and dated 04/23/2010 has revealed that there

are 2 PA ACT 2-DEED sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
DEVITTS HDWR STORE S	***26 S 1ST AVE***	***SSW 1/8 - 1/4 (0.200 mi.)***	***G22***	***49***
736-738 E LINCOLN HW	***736-738 E LINCOLN HW***	***ESE 1/4 - 1/2 (0.499 mi.)***	***54***	***123***

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/01/2018 has revealed that there is 1 RCRA NonGen / NLR site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TUTTLE & MANET EPA ID:: PAR000026930	399C FLEETWOOD RD	SE 0 - 1/8 (0.109 mi.)	C6	15

PA DRYCLEANERS: A listing of drycleaning facilities.

A review of the PA DRYCLEANERS list, as provided by EDR, and dated 09/18/2018 has revealed that there is 1 PA DRYCLEANERS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PARKS AIRPORT CLNR/C PF ID: 638731	***107 E LINCOLN HWY***	***SSW 1/8 - 1/4 (0.170 mi.)***	***E15***	***30***

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there are 4 PA MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ONE HOUR CLEANERS DB Generator EPA Id: PAD981731482	107 EAST LINCOLN HIG	SSW 1/8 - 1/4 (0.170 mi.)	E16	31
PARKS AIRPORT CLEANE Generator EPA Id: PAD981731482	107 E LINCOLN HWY	SSW 1/8 - 1/4 (0.170 mi.)	E17	36
RITE AID # 00992 Generator EPA Id: PAR000536797	320 EAST LINCOLN HIG	SSE 1/8 - 1/4 (0.198 mi.)	F21	44
GO CARLSON Generator EPA Id: PAR000506899	135 W LINCOLN HWY	SW 1/8 - 1/4 (0.229 mi.)	I26	77

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there is 1 NJ MANIFEST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
G. O. CARLSON INC EPA Id: PAR000506899	***135 WEST LINCOLN HIG***	***SW 1/8 - 1/4 (0.229 mi.)***	***I25***	***74***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
THE COATESVILLE GAS	WAGONTOWN RD (BRIDGE	SW 1/8 - 1/4 (0.245 mi.)	I31	83

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 2 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LAMB SERVICE STATION	101 E CHESTNUT ST	SW 0 - 1/8 (0.068 mi.)	A3	13
LAMB PAUL H	101 N FIRST AVE	SSW 0 - 1/8 (0.089 mi.)	A4	14

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 1 records.

Site Name	Database(s)
SOUTH COATESVILLE FILL	SEMS-ARCHIVE

OVERVIEW MAP - 5509910.2S

0 1/4 1/2 1 Miles

Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

Power transmission lines

Pipelines

100-year flood zone

500-year flood zone

National Wetland Inventory

State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Baker Residential	CLIENT:	Whitman
ADDRESS:	320 Adams Drive Coatesville PA 19320	CONTACT:	Sheila Innella
		INQUIRY #:	5509910.2s
LAT/LONG:	39.988125 / 75.821408	DATE:	December 12, 2018 11:58 am

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 5509910.2S



0 1/8 1/4 1/2 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Pipelines
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Baker Residential	CLIENT: Whitman
ADDRESS: 320 Adams Drive Coatesville PA 19320	CONTACT: Sheila Innella INQUIRY #: 5509910.2s
LAT/LONG: 39.988125 / 75.821408	DATE: December 12, 2018 12:02 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	0.001		0	NR	NR	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	3	NR	NR	3
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	1	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-CESQG	0.250		1	6	NR	NR	NR	7
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
State- and tribal - equivalent NPL								
PA SHWS	1.000		0	0	0	0	NR	0
PA HSCA	1.000		0	0	0	0	NR	0
State and tribal landfill and/or solid waste disposal site lists								
PA SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
PA LUST	0.500		0	2	6	NR	NR	8
PA LAST	0.500		0	0	0	NR	NR	0
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PA UNREG LTANKS	0.500		1	1	3	NR	NR	5
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
PA UST	0.250		1	0	NR	NR	NR	1
PA AST	0.250		0	1	NR	NR	NR	1
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
PA ENG CONTROLS	0.500		0	0	0	NR	NR	0
PA INST CONTROL	0.500		0	0	1	NR	NR	1
PA AUL	0.500		1	1	2	NR	NR	4
State and tribal voluntary cleanup sites								
PA VCP	0.500		1	2	3	NR	NR	6
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
PA BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	1	3	NR	NR	4
Local Lists of Landfill / Solid Waste Disposal Sites								
PA HIST LF	0.500		0	0	2	NR	NR	2
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
PA ARCHIVE UST	0.250		2	6	NR	NR	NR	8
PA ARCHIVE AST	0.001		0	NR	NR	NR	NR	0
Local Land Records								
LIENS 2	0.001		0	NR	NR	NR	NR	0
PA ACT 2-DEED	0.500		0	1	1	NR	NR	2
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
PA SPILLS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		1	0	NR	NR	NR	1
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	0.001		0	NR	NR	NR	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.001		0	NR	NR	NR	NR	0
FINDS	0.001		0	NR	NR	NR	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	0.001		0	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PA AIRS	0.001		0	NR	NR	NR	NR	0
PA ASBESTOS	0.001		0	NR	NR	NR	NR	0
PA DRYCLEANERS	0.250		0	1	NR	NR	NR	1
PA MANIFEST	0.250		0	4	NR	NR	NR	4
RI MANIFEST	0.250		0	0	NR	NR	NR	0
NJ MANIFEST	0.250		0	1	NR	NR	NR	1
PA MINES	0.500		0	0	0	NR	NR	0
PA NPDES	0.001		0	NR	NR	NR	NR	0
PA UIC	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	1	0	0	NR	1

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
EDR Hist Auto	0.125		2	NR	NR	NR	NR	2
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
PA RGA HWS	0.001		0	NR	NR	NR	NR	0
PA RGA LF	0.001		0	NR	NR	NR	NR	0
PA RGA LUST	0.001		0	NR	NR	NR	NR	0
- Totals --		0	10	29	24	1	0	64

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

1
ESE
< 1/8
0.056 mi.
297 ft.

ELMWOOD GARDENS APARTMENT
100 HARLAN DR
COATESVILLE, PA 19324

PA ARCHIVE UST **S111110007**
N/A

Relative:
Lower

Actual:
402 ft.

ARCHIVE UST:

Facility Id:	15-43452
Site ID:	Not reported
Municipality:	Not reported
Client Date:	Not reported
Owner Id:	16865
Owner Name:	PARK RUN ASSOC
Owner Address:	238 CHESTNUT ST
Owner Address 2:	Not reported
Owner City,St,Zip:	DOWNINGTOWN, PA 19335
Owner Phone:	2152693856
Owner County Code:	15
Resp Party Name:	Not reported
RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	003
Tank Id:	88139
Status:	Not reported
Status Code End Date:	Not reported
Capacity:	0
Substance:	UNKNOWN
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	Not reported
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	Not reported
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	Not reported
Contact Name:	Not reported
Company:	Not reported
Tank Sequence #:	004
Tank Id:	88140
Status:	Not reported
Status Code End Date:	Not reported
Capacity:	0
Substance:	UNKNOWN
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	Not reported
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	Not reported
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported

ELMWOOD GARDENS APARTMENT (Continued) **S111110007**

Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	Not reported
Contact Name:	Not reported
Company:	Not reported
Tank Sequence #:	005
Tank Id:	88141
Status:	Not reported
Status Code End Date:	Not reported
Capacity:	0
Substance:	UNKNOWN
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	Not reported
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	Not reported
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	Not reported
Contact Name:	Not reported
Company:	Not reported

A2 **LAMBS AUTO SVC** **PA UNREG LTANKS** **U002317717**
SW **101 E CHESTNUT ST** **PA UST** **N/A**
< 1/8 **COATESVILLE, PA 19320** **PA ARCHIVE UST**
0.068 mi.
358 ft. **Site 1 of 3 in cluster A**

Relative: **Lower**
Actual: **328 ft.**

UNREG LTANKS:

Region:	South East
Contaminant:	Not reported
Closed:	**Not reported**
Class:	Cleanup of Tanks using authorities other than Act 32

UST:

Site ID:	569125
Other Id:	15-06586
Client Id Number:	179531
Municipality Name:	Coatesville
Region:	EP SE Rgnl Off Norristown
Mailing Name:	PAUL H LAMB JR
Mailing Address:	101 E CHESTNUT ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	COATESVILLE, PA 19320-3230
Registration Expiration Date:	02/04/2019
Tank Seq No:	009
Tank Status:	**Currently In Use**
Capacity:	10000
Substance:	Gasoline
Date Installed:	12/14/1994
Tank Code:	UST
Inspection Code:	Facility Operation Inspection
Tank Last Dt Inspected:	05/30/2018

LAMBS AUTO SVC (Continued) **U002317717**

Decode for Tstatus: Currently In Use
Decode for Substance: Gasoline

Tank Seq No: 010
Tank Status: Currently In Use
Capacity: 10000
Substance: Gasoline
Date Installed: 12/14/1994
Tank Code: UST
Inspection Code: Facility Operation Inspection
Tank Last Dt Inspected: 05/30/2018
Decode for Tstatus: Currently In Use
Decode for Substance: Gasoline

ARCHIVE UST:
Facility Id: 15-06586
Site ID: Not reported
Municipality: Coatesville City
Client Date: Not reported
Owner Id: Not reported
Owner Name: PAUL H LAMB JR
Owner Address: 101 E CHESTNUT ST
Owner Address 2: Not reported
Owner City,St,Zip: COATESVILLE, PA 19320-3230
Owner Phone: Not reported
Owner County Code: Not reported
Resp Party Name: Not reported
RP Address: Not reported
RP Address 2: Not reported
RP City,St,Zip: Not reported
Region Code Name: Not reported
Regulated Expire Date: Not reported

Tank Sequence #: 003
Tank Id: Not reported
Status: Closed Without a Permit
Status Code End Date: Not reported
Capacity: 2000
Substance: Gasoline
Tank Substance End Date: Not reported
Install Date: Not reported
Tank Code: UST
Inspection Code: Not reported
Last Inspection: Not reported
Substance Type: P
CASRN for Hazardous Substances: Not reported
Chemical Name: Not reported
Other Information Regarding The Tank Substance: Not reported
Undeliverable Address Ind.: N
Contact Name: UNKNOWN
Company: Not reported

Tank Sequence #: 008
Tank Id: Not reported
Status: Closed Without a Permit

LAMBS AUTO SVC (Continued) **U002317717**

Status Code End Date:	Not reported
Capacity:	550
Substance:	Used Oil (all forms)
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	007
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	550
Substance:	Kerosene
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	005
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	1000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

LAMBS AUTO SVC (Continued) **U002317717**

Tank Sequence #:	004
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	4000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	002
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	3000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	001
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	6000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	02/01/1984
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN

LAMBS AUTO SVC (Continued) **U002317717**

Company:	Not reported
Tank Sequence #:	006
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	1000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

A3 **LAMB SERVICE STATION** **EDR Hist Auto** **1021607660**
SW **101 E CHESTNUT ST** **N/A**
< 1/8 **COATESVILLE, PA 19320**
0.068 mi.
358 ft. **Site 2 of 3 in cluster A**

Relative: EDR Hist Auto
Lower

Actual: **328 ft.**

Year:	Name:	Type:
2001	LAMB PAUL H	Convenience Stores
2002	LAMB SERVICE STATION	Convenience Stores
2003	LAMB SERVICE STATION	Convenience Stores
2004	LAMB SERVICE STATION	Convenience Stores
2005	LAMB SERVICE STATION	Convenience Stores
2006	LAMB SERVICE STATION	Convenience Stores
2007	LAMB SERVICE STATION	Convenience Stores
2008	LAMB SERVICE STATION	Convenience Stores
2009	LAMB SERVICE STATION	Convenience Stores
2010	LAMB SERVICE STATION	Convenience Stores
2011	LAMB SERVICE STATION	Convenience Stores
2012	LAMB SERVICE STATION	Convenience Stores
2013	LAMB SERVICE STATION	Convenience Stores
2014	COATESVILLE SHELL	Gasoline Service Stations, NEC
2014	LAMB SERVICE STATION	Convenience Stores

A4
SSW
< 1/8
0.089 mi.
471 ft.

LAMB PAUL H
101 N FIRST AVE
COATESVILLE, PA 19320

Site 3 of 3 in cluster A

EDR Hist Auto **1020625163**
N/A

Relative:
Lower

Actual:
323 ft.

EDR Hist Auto

Year:	Name:	Type:
1975	LAMB PAUL H	Gasoline Service Stations
1976	LAMB PAUL H	Gasoline Service Stations
1977	LAMB PAUL H	Gasoline Service Stations
1978	LAMB PAUL H	Gasoline Service Stations
1979	LAMB PAUL H	Gasoline Service Stations
1980	LAMB PAUL H	Gasoline Service Stations
1982	LAMB PAUL H	Gasoline Service Stations
1983	LAMB PAUL H	Gasoline Service Stations
1985	LAMB PAUL H	Gasoline Service Stations
1986	LAMB PAUL H	Gasoline Service Stations
1987	LAMB PAUL H	Gasoline Service Stations
1988	LAMB PAUL H	Gasoline Service Stations
1989	LAMB PAUL H	Gasoline Service Stations
1990	LAMB PAUL H	Gasoline Service Stations
1991	LAMB PAUL H	Gasoline Service Stations
1992	LAMB PAUL H	Gasoline Service Stations
1993	LAMB PAUL H	Gasoline Service Stations
1996	LAMB PAUL H	Gasoline Service Stations
1997	LAMB PAUL H	Gasoline Service Stations

B5
SSW
< 1/8
0.090 mi.
476 ft.

LIPKINS FURNITURE WHSE BLDG
139 E CHESTNUT ST
COATESVILLE, PA 19320

Site 1 of 2 in cluster B

PA AUL **S112430112**
PA VCP **N/A**

Relative:
Lower

Actual:
339 ft.

AUL:

Faciility Id:	758308
Primary Facility Type:	Land Recycling and Cleanup Locator
Latitude:	Not reported
Longitude:	Not reported
Region:	Southeast Region
Client Id:	Not reported
Client Name:	Not reported
Incident Id / Name Description:	Not reported
Remediation Id:	42717
Remediation Received Date:	2012-11-08 00:00:00
Address:	139 E CHESTNUT ST COATESVILLE, PA 19320-3230
AUL Code:	ENVIRONMENTAL COVENANT
Received Date:	10/07/2013
Action Date:	11/07/2013
Action:	DEP SIGNED
Recorded Date:	12/04/2013
Terminated Date:	Not reported
Amended Date:	Not reported
Activity Use Limitation Code:	Not reported
Activity Use Limitation Desc:	Not reported
Aul Comment:	Not reported
Internal Use EDR Field:	Not reported

LIPKINS FURNITURE WHSE BLDG (Continued) **S112430112**

VCP:

Cleanup Records:

Municipality:	Coatesville City
Region:	Southeast Region
Category Desc:	Unleaded Gasoline
Type:	Complete Sites
LRP Activity Number:	44470
Remediation:	Site-Specific Standard
Activity:	NO
Date Approved:	09/17/2013
Date Received:	Not reported
Date Nonuse:	Not reported
ICS Code:	Not reported
Media:	Soil
Latitude:	39.984524
Longitude:	-75.823645

Activity:

Activity ID:	758308, 758308,
Municipality:	Coatesville City
Region:	Southeast Region
Category Desc:	Unleaded Gasoline
Type:	Complete Sites
LRP Activity Number:	44469
Remediation:	Statewide Health Standard
Activity:	NO
Date Approved:	09/17/2013
Date Received:	Not reported
Date Nonuse:	Not reported
ICS Code:	Not reported
Media:	Soil
Latitude:	39.984524
Longitude:	-75.823645

C6 **TUTTLE & MANET** **RCRA NonGen / NLR** **1001125414**
SE **399C FLEETWOOD RD** **PAR000026930**
< 1/8 **COATESVILLE, PA 19350**
0.109 mi.
574 ft. **Site 1 of 2 in cluster C**

Relative: **Lower**

Actual: **367 ft.**

RCRA NonGen / NLR:

Date form received by agency:	10/29/2007
Facility name:	TUTTLE & MANET
Facility address:	399C FLEETWOOD RD COATESVILLE, PA 19350
EPA ID:	PAR000026930
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	03
Land type:	Other land type
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

TUTTLE & MANET (Continued) **1001125414**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/06/2005
Site name: TUTTLE & MANET
Classification: Not a generator, verified

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: PA01
. Waste name: PA01

Date form received by agency: 01/13/1997
Site name: TUTTLE & MANET
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: PA01
. Waste name: PA01

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/11/2005
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported

TUTTLE & MANET (Continued) **1001125414**

Date achieved compliance: Not reported
Evaluation lead agency: State

7
West
< 1/8
0.117 mi.
616 ft.

GREAT VALLEY MATERIAL INC **RCRA-CESQG** **1000570187**
RTE 82 **PAD987345659**
COATESVILLE, PA 19320

Relative:
Lower

Actual:
338 ft.

RCRA-CESQG:
Date form received by agency: 07/31/1991
Facility name: GREAT VALLEY MATERIAL INC
Facility address: RTE 82
COATESVILLE, PA 19320
EPA ID: PAD987345659
Contact: JOSEPH_E CRAFT
Contact address: RTE 82
COATESVILLE, PA 19320
Contact country: US
Contact telephone: 215-296-2880
Contact email: Not reported
EPA Region: 03
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: OPERNAME
Owner/operator address: OPERSTREET
OPERCITY, AK 99999
Owner/operator country: Not reported
Owner/operator telephone: 215-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MYERS ALLAN A
Owner/operator address: PO BOX 98 BERKS RD
WORCHESTER, PA 19490
Owner/operator country: Not reported
Owner/operator telephone: 215-584-6020

GREAT VALLEY MATERIAL INC (Continued) **1000570187**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:
Regulation violated: SR - 261.5(d) (260.2a,f)
Area of violation: Generators - General
Date violation determined: 05/25/1994
Date achieved compliance: 09/29/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 05/25/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/29/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported

GREAT VALLEY MATERIAL INC (Continued) **1000570187**

Evaluation lead agency: State

Evaluation date: 05/25/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/29/1994
Evaluation lead agency: State

D8 **OLIVET UNITED METH CHURCH** **PA ARCHIVE UST** **S111114309**
SSE **310 E CHESTNUT ST** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.126 mi.
665 ft. **Site 1 of 3 in cluster D**

Relative: **Lower**

Actual: **348 ft.**

ARCHIVE UST:

Facility Id:	15-41268
Site ID:	Not reported
Municipality:	Not reported
Client Date:	Not reported
Owner Id:	2409
Owner Name:	OLIVET UN METHODIST CH
Owner Address:	310 E CHESTNUT ST
Owner Address 2:	Not reported
Owner City,St,Zip:	COATESVILLE, PA 19320-3203
Owner Phone:	2153845828
Owner County Code:	15
Resp Party Name:	Not reported
RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	001
Tank Id:	17092
Status:	Not reported
Status Code End Date:	Not reported
Capacity:	5000
Substance:	HEATING OIL
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	Not reported
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	Not reported
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	Not reported
Contact Name:	Not reported
Company:	Not reported

B9 **COATESVILLE CITY AUTH ANNEX** **PA ARCHIVE UST** **S119698227**
SSW **103 E DIAMOND ST** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.127 mi.
671 ft. **Site 2 of 2 in cluster B**

Relative: **Lower**
Actual: **328 ft.**

ARCHIVE UST:

Facility Id:	15-45652
Site ID:	Not reported
Municipality:	Coatesville City
Client Date:	Not reported
Owner Id:	Not reported
Owner Name:	PA AMER COATESVILLE
Owner Address:	114 E LINCOLN HWY
Owner Address 2:	Not reported
Owner City,St,Zip:	COATESVILLE, PA 19320-3406
Owner Phone:	Not reported
Owner County Code:	Not reported
Resp Party Name:	Not reported
RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	001
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	1000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	KEVIN C SHELTON OPR ASST CHF
Company:	Not reported

C10 **MCFALLS COLLISION INC** **RCRA-CESQG** **1004774781**
ESE **400 FLEETWOOD ST** **FINDS** **PAD987352028**
1/8-1/4 **COATESVILLE, PA 19320** **ECHO**
0.154 mi.
814 ft. **Site 2 of 2 in cluster C**

Relative: **Lower**
Actual: **357 ft.**

RCRA-CESQG:

Date form received by agency:	10/03/1991
Facility name:	MCFALLS COLLISION INC
Facility address:	400 FLEETWOOD ST COATESVILLE, PA 19320
EPA ID:	PAD987352028
Contact:	MARK MCFALL
Contact address:	400 FLEETWOOD ST COATESVILLE, PA 19320
Contact country:	US

MCFALLS COLLISION INC (Continued) **1004774781**

Contact telephone: 215-384-2620
Contact email: Not reported
EPA Region: 03
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: OPERNAME
Owner/operator address: OPERSTREET
OPERCITY, AK 99999
Owner/operator country: Not reported
Owner/operator telephone: 215-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MCFALL COLLISION INC
Owner/operator address: 400 FLEETWOOD ST
COATESVILLE, PA 19320
Owner/operator country: Not reported
Owner/operator telephone: 215-384-2620
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

MCFALLS COLLISION INC (Continued) **1004774781**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110000921628

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PA-EFACTS (Pennsylvania - Environmental Facility Application Compliance Tracking System) is a Department-wide database that provides a holistic view of clients and sites (including facilities) that DEP regulates.

MCFALLS COLLISION INC (Continued) **1004774781**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004774781
Registry ID:	110000921628
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000921628

11
SSW
1/8-1/4
0.160 mi.
845 ft.

PARCEL 16-5-16, LUKENS STEEL COMPANY - THE FLATS **US BROWNFIELDS** **1023620390**
115 WEST LINCOLN HIGHWAY **FINDS** **N/A**
COATESVILLE, PA 19320

Relative:
Lower

Actual:
305 ft.

US BROWNFIELDS:

Property Name:	PARCEL 16-5-16, LUKENS STEEL COMPANY - THE FLATS
Recipient Name:	Chester County
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	6.2
Latitude:	39.982458
Longitude:	-75.827175
HCM Label:	Address Matching-House Number
Map Scale:	100000
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	12458
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Not reported
Accomplishment Count:	0
Cooperative Agreement Number:	98355101
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Bethlehem Steel Corporation
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported

PARCEL 16-5-16, LUKENS STEEL COMPANY - THE FLATS (Continued) **1023620390**

IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported

PARCEL 16-5-16, LUKENS STEEL COMPANY - THE FLATS (Continued) **1023620390**

Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Steel facility
Below Poverty Number:	1324
Below Poverty Percent:	28.4%
Meidan Income:	3707
Meidan Income Number:	2469
Meidan Income Percent:	53.0%
Vacant Housing Number:	274
Vacant Housing Percent:	13.3%
Unemployed Number:	214
Unemployed Percent:	4.6%

FINDS:

Registry ID: 110060823140

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

D12 **KANE EDWIN W DDS** **RCRA-CESQG** **1004777282**
SSE **7 N 3RD AVE** **FINDS** **PAR000025643**
1/8-1/4 **COATESVILLE, PA 19320** **ECHO**
0.164 mi.
866 ft. **Site 2 of 3 in cluster D**

Relative:
Lower

Actual:
342 ft.

RCRA-CESQG:

Date form received by agency:	11/22/1996
Facility name:	KANE EDWIN W DDS
Facility address:	7 N 3RD AVE COATESVILLE, PA 19320
EPA ID:	PAR000025643
Contact:	EDWIN KANE
Contact address:	7 N 3RD AVE COATESVILLE, PA 19320
Contact country:	US
Contact telephone:	610-384-5891
Contact email:	Not reported
EPA Region:	03
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	KANE EDWIN W
Owner/operator address:	7 N 3RD AVE COATESVILLE, PA 19320
Owner/operator country:	Not reported
Owner/operator telephone:	610-384-5891
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No

KANE EDWIN W DDS (Continued) **1004777282**

Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110001002968

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PA-EFACTS (Pennsylvania - Environmental Facility Application Compliance Tracking System) is a Department-wide database that provides a holistic view of clients and sites (including facilities) that DEP regulates.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004777282
Registry ID: 110001002968
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110001002968

D13 **CHURCH OF THE TRINITY** **PA ARCHIVE UST** **S111108721**
SSE **323 E LINCOLN HWY** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.165 mi.
869 ft. **Site 3 of 3 in cluster D**

Relative:
Lower

Actual:
345 ft.

ARCHIVE UST:
Facility Id: 15-42769
Site ID: Not reported
Municipality: Not reported
Client Date: Not reported
Owner Id: 16830
Owner Name: CHURCH OF THE TRINITY
Owner Address: 323 E LINCOLN HWY
Owner Address 2: Not reported
Owner City,St,Zip: COATESVILLE, PA 19320
Owner Phone: 2153844771
Owner County Code: 15
Resp Party Name: Not reported

CHURCH OF THE TRINITY (Continued) **S111108721**

RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	001
Tank Id:	87811
Status:	Not reported
Status Code End Date:	Not reported
Capacity:	6000
Substance:	HEATING OIL
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	Not reported
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	Not reported
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	Not reported
Contact Name:	Not reported
Company:	Not reported

E14 **PARKS AIRPORT CLNR SVC** **RCRA-SQG 1000117385**
SSW **107 E LINCOLN HWY** **FINDS PAD981731482**
1/8-1/4 **COATESVILLE, PA 19320** **ECHO**
0.170 mi.
897 ft. **Site 1 of 5 in cluster E**

Relative: **Lower**
Actual: **325 ft.**

RCRA-SQG:

Date form received by agency:	08/21/1986
Facility name:	PARKS AIRPORT CLEANERS INC
Facility address:	107 E LINCOLN HWY COATESVILLE, PA 19320
EPA ID:	PAD981731482
Contact:	SUN PARK
Contact address:	107 E LINCOLN HWY COATESVILLE, PA 19320
Contact country:	US
Contact telephone:	215-384-8688
Contact email:	Not reported
EPA Region:	03
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	OPERNAME
Owner/operator address:	OPERSTREET OPERCITY, AK 99999
Owner/operator country:	Not reported
Owner/operator telephone:	215-555-1212

PARKS AIRPORT CLNR SVC (Continued) **1000117385**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: GENERAL PARTNERSHIP B B & Z A
Owner/operator address: PO BOX 7
GAP, PA 17527
Owner/operator country: Not reported
Owner/operator telephone: 717-442-9221
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110001048624

PARKS AIRPORT CLNR SVC (Continued) **1000117385**

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

PA-EFACTS (Pennsylvania - Environmental Facility Application Compliance Tracking System) is a Department-wide database that provides a holistic view of clients and sites (including facilities) that DEP regulates.

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000117385
Registry ID:	110001048624
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001048624

E15 **PARKS AIRPORT CLNR/COATESVILLE** **PA AIRS** **S106935492**
SSW **107 E LINCOLN HWY** **PA DRYCLEANERS** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.170 mi.
897 ft. **Site 2 of 5 in cluster E**

Relative: **Lower**
Actual: **325 ft.**

AIRS:

Address 2:	Not reported
Primary Facility ID:	638731
Contact Name:	Not reported
Contact Phone:	Not reported
Contact Email:	Not reported
Status:	Inactive
Region:	Southeast Regional Office
Site ID:	516075
Client ID:	210458
Client Name:	PARKS AIRPORT CLNR INC
NAICS Code:	812320
Client Address:	107 E LINCOLN HWY
Client Address 2:	Not reported
Client City:	COATESVILLE

PARKS AIRPORT CLNR/COATESVILLE (Continued) **S106935492**

Client State:	PA
Client Zip:	19320-3405
Client Type:	NON-GOVERNMENT
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
Latitude:	Not reported
Longitude:	Not reported

DRYCLEANERS:

Regional Office:	1
District Office:	12
County #:	15
Site Id:	516075
PF ID:	638731
EPA Compliance Data System #:	4202995041
EPA Class:	Not reported
Get Sic:	Not reported
Naics Number:	812320
AFS Id:	Not reported
PF Other Id:	00-1200038-1
Municipality Name:	Coatesville City
Date Last Modified:	06/06/2003
Latitude Degrees:	Not reported
Latitude Minutes:	Not reported
Latitude Seconds:	Not reported
Longitude Degrees:	Not reported
Longitude Minutes:	Not reported
Longitude Seconds:	Not reported
Clint ID:	210458
Regulatory Program:	MACT
Subpar:	Subpart M--National Perchloroethylene Air Emission Standards for Dry Cleaning Facilities
Region:	Southeast Regional Office
Primary Facility Status:	Inactive
Contact Name:	Not reported
Contact Phone:	Not reported
Contact Email:	Not reported
Client:	PARKS AIRPORT CLNR INC
Client Type:	Not reported
Client Address1:	107 E LINCOLN HWY
Client Address2:	Not reported
Client City:	COATESVILLE
Client State:	PA
Client Zip:	19320-3405
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
Latitude:	Not reported
Longitude:	Not reported

E16 **ONE HOUR CLEANERS DBA PARKS AIRPORT CLEANERS** **PA MANIFEST** **S109246809**
SSW **107 EAST LINCOLN HIGHWAY** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.170 mi.
897 ft. **Site 3 of 5 in cluster E**

Relative: **Lower**

Actual: **325 ft.**

Manifest Details:

Year:	2013
Manifest Number:	011613111JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482

ONE HOUR CLEANERS DBA PARKS AIRPORT CLEANERS (Continued) **S109246809**

Generator Date:	12/28/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES RECYLEX EXPERT INC
TSD Facility Address:	8381 PLACE MARTEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	F002
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	130
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	CDX761010010
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	011613111JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	12/28/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES RECYLEX EXPERT INC
TSD Facility Address:	8381 PLACE MARTEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D039
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	130
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	CDX761010010
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	011613111JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	12/28/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported

ONE HOUR CLEANERS DBA PARKS AIRPORT CLEANERS (Continued) **S109246809**

Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES RECYLEX EXPERT INC
TSD Facility Address:	8381 PLACE MARTEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	F002
Container Number:	6
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	400
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	CDX761010010
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	011613111JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	12/28/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES RECYLEX EXPERT INC
TSD Facility Address:	8381 PLACE MARTEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D039
Container Number:	6
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	400
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	CDX761010010
Date TSP Sig:	Not reported

Year:	2012
Manifest Number:	010181445JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	12/20/2012
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported

ONE HOUR CLEANERS DBA PARKS AIRPORT CLEANERS (Continued) **S109246809**

TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES RECYLEX EXPERT INC
TSD Facility Address:	8381 PLACE MARTEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	F002
Container Number:	6
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	200
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	CDX761010010
Date TSP Sig:	Not reported
Year:	2012
Manifest Number:	010181445JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	12/20/2012
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES RECYLEX EXPERT INC
TSD Facility Address:	8381 PLACE MARTEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D039
Container Number:	6
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	200
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	CDX761010010
Date TSP Sig:	Not reported
Year:	2011
Manifest Number:	008374957JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	04/30/2011
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	CDX761010010
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES RECYLEX EXPERT INC
TSD Facility Address:	8381 PLACE MARTEN

ONE HOUR CLEANERS DBA PARKS AIRPORT CLEANERS (Continued) **S109246809**

TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	F002
Container Number:	6
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	400
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2011
Manifest Number:	008374957JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	04/30/2011
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	CDX761010010
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES RECYLEX EXPERT INC
TSD Facility Address:	8381 PLACE MARTEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D039
Container Number:	6
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	400
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	006662753JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	03/18/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	CNRRR8381PLA
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES DE RECYCLAGE EXPERTS INC
TSD Facility Address:	8381 PLACE MARIEN
TSD Facility City:	MONTREAL EST QUEBEC
TSD Facility State:	CN
Facility Telephone:	Not reported

ONE HOUR CLEANERS DBA PARKS AIRPORT CLEANERS (Continued) **S109246809**

Page Number:	1
Line Number:	2
Waste Number:	D039
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	130
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	006662753JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	03/18/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	CNRRR8381PLA
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES DE RECYCLAGE EXPERTS INC
TSD Facility Address:	8381 PLACE MARIEN
TSD Facility City:	MONTREAL EST QUEBEC
TSD Facility State:	CN
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D039
Container Number:	4
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	240
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access
6 additional PA_MANIFEST: record(s) in the EDR Site Report.

E17 **PARKS AIRPORT CLEANERS** **PA MANIFEST** **S118890837**
SSW **107 E LINCOLN HWY** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.170 mi.
897 ft. **Site 4 of 5 in cluster E**

Relative: Manifest Details:
Lower

Year:	2015
Manifest Number:	013917140JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	07/20/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported

Actual:
325 ft.

PARKS AIRPORT CLEANERS (Continued) **S118890837**

TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES DE RECYCLAGE EXPERT
TSD Facility Address:	8381 PLACE MARIEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	F002
Container Number:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	260
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	MIK814262374
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	013917140JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	07/20/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES DE RECYCLAGE EXPERT
TSD Facility Address:	8381 PLACE MARIEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D039
Container Number:	5
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	400
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	MIK814262374
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	013917140JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	07/20/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES DE RECYCLAGE EXPERT
TSD Facility Address:	8381 PLACE MARIEN

PARKS AIRPORT CLEANERS (Continued) **S118890837**

TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	F002
Container Number:	5
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	400
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	MIK814262374
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	013917140JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD981731482
Generator Date:	07/20/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	215-384-8688
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	SERVICES SANITAIRES DE RECYCLAGE EXPERT
TSD Facility Address:	8381 PLACE MARIEN
TSD Facility City:	MONTREAL
TSD Facility State:	QE
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D039
Container Number:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	260
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	MIK814262374
Date TSP Sig:	Not reported

E18 **LOCKWOOD ESTATE** **PA UNREG LTANKS** **S105918633**
SSW **50 E LINCOLN HWY** **N/A**
1/8-1/4 **EAST WHITELAND TWP., PA**
0.177 mi.
935 ft. **Site 5 of 5 in cluster E**

Relative: **Lower**
Actual: **322 ft.**

UNREG LTANKS:

Region:	South East
Contaminant:	BTEX
Closed:	**Not reported**
Class:	Cleanup of Tanks using authorities other than Act 32

F19 **COATESVILLE TOWERS** **PA VCP** **S111074214**
SSE **339 E LINCOLN HWY** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.180 mi.
952 ft. **Site 1 of 3 in cluster F**

Relative: **Lower**

Actual: **340 ft.**

VCP:

Cleanup Records:

Municipality:	Coatesville City
Region:	Southeast Region
Category Desc:	Fuel Oil No 2
Type:	Complete Sites
LRP Activity Number:	42307
Remediation:	Statewide Health Standard
Activity:	NO
Date Approved:	12/26/2011
Date Received:	Not reported
Date Nonuse:	Not reported
ICS Code:	Not reported
Media:	Soil
Latitude:	39.98385
Longitude:	-75.819066

Activity:

Activity ID:	740484, 740484,
Municipality:	Coatesville City
Region:	Southeast Region
Category Desc:	Fuel Oil No 2
Type:	Complete Sites
LRP Activity Number:	42307
Remediation:	Statewide Health Standard
Activity:	NO
Date Approved:	12/26/2011
Date Received:	Not reported
Date Nonuse:	Not reported
ICS Code:	Not reported
Media:	Groundwater
Latitude:	39.98385
Longitude:	-75.819066

F20 **RITE AID NO 992** **RCRA-CESQG** **1016144769**
SSE **320 E LINCOLN HWY** **FINDS** **PAR000536797**
1/8-1/4 **COATESVILLE, PA 19320** **ECHO**
0.198 mi.
1044 ft. **Site 2 of 3 in cluster F**

Relative: **Lower**

Actual: **343 ft.**

RCRA-CESQG:

Date form received by agency:	07/15/2016
Facility name:	RITE AID NO 992
Facility address:	320 E LINCOLN HWY COATESVILLE, PA 19320
EPA ID:	PAR000536797
Mailing address:	30 HUNTER LN CAMP HILL, PA 17011
Contact:	DAVID W CROZIER
Contact address:	30 HUNTER LN CAMP HILL, PA 17011
Contact country:	US
Contact telephone:	717-975-8643

RITE AID NO 992 (Continued) **1016144769**

Contact email: EHS@RITEAID.COM
EPA Region: 03
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: RITE AID OF PENNSYLVANIA INC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/15/1993
Owner/Op end date: Not reported

Owner/operator name: RAUF R MANAGEMENT
Owner/operator address: 209-43 27TH AVE
BAYSIDE, NY 11360
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/15/1993
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No

RITE AID NO 992 (Continued) **1016144769**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

RITE AID NO 992 (Continued) **1016144769**

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)-

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P081
. Waste name: NITROGLYCERINE (R)

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U044
. Waste name: CHLOROFORM

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO-

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA,2ALPHA,3BETA,4ALPHA,5ALPHA,6BETA)-

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U205
. Waste name: SELENIUM SULFIDE

. Waste code: U211
. Waste name: CARBON TETRACHLORIDE

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279

RITE AID NO 992 (Continued) **1016144769**

. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Historical Generators:
Date form received by agency: 01/03/2013
Site name: RITE AID NO 992
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

Violation Status: No violations found

FINDS:

Registry ID: 110055472439

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RITE AID NO 992 (Continued) **1016144769**

PA-EFACTS (Pennsylvania - Environmental Facility Application Compliance Tracking System) is a Department-wide database that provides a holistic view of clients and sites (including facilities) that DEP regulates.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016144769
Registry ID:	110055472439
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055472439

F21 **RITE AID # 00992** **PA MANIFEST** **S116738949**
SSE **320 EAST LINCOLN HIGHWAY** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.198 mi.
1044 ft. **Site 3 of 3 in cluster F**

Relative: **Lower**

Actual: **343 ft.**

Manifest Details:

Year:	2013
Manifest Number:	012068132JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	11/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D018
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	012068132JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	11/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported

RITE AID # 00992 (Continued) **S116738949**

TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D009
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	010266251JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	08/12/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P075
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	010266251JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	08/12/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc

RITE AID # 00992 (Continued) **S116738949**

TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D024
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	012068132JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	11/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U002
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	012068132JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	11/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA

RITE AID # 00992 (Continued) **S116738949**

Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported
Year:	2013
Manifest Number:	012068132JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	11/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D035
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported
Year:	2013
Manifest Number:	012068132JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	11/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3

RITE AID # 00992 (Continued) **S116738949**

Waste Number:	P001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported
Year:	2013
Manifest Number:	010266251JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	08/12/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	P042
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD010154045
Date TSP Sig:	Not reported
Year:	2013
Manifest Number:	010266251JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000536797
Generator Date:	08/12/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Envirite of Pennsylvania Inc
TSD Facility Address:	730 Vogelsong Rd
TSD Facility City:	York
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D026
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs

RITE AID # 00992 (Continued) **S116738949**

Waste Quantity: 1
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: PAD010154045
Date TSP Sig: Not reported

Click this hyperlink while viewing on your computer to access
1 additional PA_MANIFEST: record(s) in the EDR Site Report.

G22 **DEVITTS HDWR STORE SITE** **PA VCP** **S105832506**
SSW **26 S 1ST AVE** **PA ACT 2-DEED** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.200 mi.
1057 ft. **Site 1 of 2 in cluster G**

Relative: Lower
Actual: 316 ft.

VCP:

Activity:
Activity ID: 616974,

Cleanup Records:
Municipality: Coatesville City
Region: Southeast Region
Category Desc: Not reported
Type: Complete Sites
LRP Activity Number: 25
Remediation: Special Industrial Area
Activity: NO
Date Approved: Not reported
Date Received: Not reported
Date Nonuse: Not reported
ICS Code: Not reported
Media: Soil
Latitude: 39.989444
Longitude: -75.823888

ACT 2-DEED:
Region: 4100
Municipality: Coatesville
Site Size: Not reported
Cleanup Standard: Special Industrial Area
Cleanup Indicator: Not reported
Response Date: 2/22/2000
Category Description: Not reported
Land Designation Code: Not reported

G23 **SMS MILL SVC/COATESVILLE** **RCRA-CESQG** **1000216668**
SSW **S 1ST AVE** **ICIS** **PAD060057320**
1/8-1/4 **COATESVILLE, PA 19320** **US AIRS**
0.216 mi. **FINDS**
1143 ft. **Site 2 of 2 in cluster G**

Relative: Lower
Actual: 317 ft.

RCRA-CESQG:
Date form received by agency: 05/22/2014
Facility name: HECKETT MULTISERV PLT 64
Facility address: S FIRST AVE GATE 9
COATESVILLE, PA 19320

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

EPA ID:	PAD060057320
Contact:	Not reported
Contact address:	Not reported
	Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	03
Land type:	Other land type
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D001
. Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Historical Generators:

Date form received by agency:	11/09/2004
Site name:	HECKETT MULTISERV PLT 64
Classification:	Conditionally Exempt Small Quantity Generator

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 05/26/1989
Site name: HECKETT MULTISERV PLT 64
Classification: Small Quantity Generator

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/18/2004
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

ICIS:
Enforcement Action ID: PA000A0000E00000000260285
FRS ID: 110008054880
Action Name: Not reported
Facility Name: SMS MILL SVC/COATESVILLE
Facility Address: S 1ST AVE

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

	COATESVILLE, PA 19320
Enforcement Action Type:	Administrative Order
Facility County:	CHESTER
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	5093
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	39.969167
Longitude in Decimal Degrees:	-75.808333
Permit Type Desc:	Not reported
Program System Acronym:	PA000562980
Facility NAICS Code:	327999
Tribal Land Code:	Not reported

Enforcement Action ID:	PA000A0000E00000000245074
FRS ID:	110008054880
Action Name:	Not reported
Facility Name:	SMS MILL SVC/COATESVILLE
Facility Address:	S 1ST AVE
	COATESVILLE, PA 19320
Enforcement Action Type:	Notice of Violation
Facility County:	CHESTER
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	5093
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	39.969167
Longitude in Decimal Degrees:	-75.808333
Permit Type Desc:	Not reported
Program System Acronym:	PA000562980
Facility NAICS Code:	327999
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1000216668
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
D and B Number:	Not reported
Primary SIC Code:	5093
NAICS Code:	327999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	NON
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	2001-01-19 00:00:00

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2001-03-20 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2003-03-22 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2005-11-01 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2008-02-13 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2008-03-26 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2008-04-15 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2009-04-02 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2009-04-16 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2009-04-30 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	2009-07-13 00:00:00
Activity Status Date:	2016-02-11 00:00:00
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	2011-05-31 00:00:00
Activity Status Date:	2016-02-11 00:00:00
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1990-06-28 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1991-06-07 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1992-06-22 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2010-07-16 00:00:00
Activity Status Date: 2010-07-16 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Resolved

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2009-04-14 00:00:00
Activity Status Date: 2009-04-14 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-01-19 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-03-20 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-03-22 00:00:00

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-11-01 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-02-13 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-03-26 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-04-15 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-02 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-16 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-30 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-07-13 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-05-31 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-04-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-08-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-09-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-05-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1985-09-25 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1986-04-24 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1986-09-16 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1986-11-26 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1987-09-29 00:00:00

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-04-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-05-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-10-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-06-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-06-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1993-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-07-16 00:00:00
Activity Status Date: 2010-07-16 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Resolved

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-14 00:00:00
Activity Status Date: 2009-04-14 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

US AIRS MINOR:
Envid: 1000216668
Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
D and B Number: Not reported
Primary SIC Code: 5093
NAICS Code: 327999
Default Air Classification Code: MIN
Facility Type of Ownership Code: NON
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2001-01-19 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2001-03-20 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2003-03-22 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2005-11-01 00:00:00

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2008-02-13 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2008-03-26 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2008-04-15 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2009-04-02 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2009-04-16 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2009-04-30 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2009-07-13 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2011-05-31 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 1990-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1991-06-07 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1992-06-22 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	2010-07-16 00:00:00
Activity Status Date:	2010-07-16 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Resolved

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	2009-04-14 00:00:00
Activity Status Date:	2009-04-14 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2001-01-19 00:00:00
Activity Status Date:	2016-02-11 00:00:00
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2001-03-20 00:00:00
Activity Status Date:	2016-02-11 00:00:00
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2003-03-22 00:00:00
Activity Status Date:	2016-02-11 00:00:00
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2005-11-01 00:00:00
Activity Status Date:	2016-02-11 00:00:00
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2008-02-13 00:00:00
Activity Status Date:	2016-02-11 00:00:00
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2008-03-26 00:00:00

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-04-15 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-02 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-16 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-30 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-07-13 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-05-31 00:00:00
Activity Status Date: 2016-02-11 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-04-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-08-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-09-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-05-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-09-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-09-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1986-11-26 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1987-09-29 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1988-04-12 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1988-05-26 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1989-10-24 00:00:00

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-06-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-06-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1993-06-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000562980
Facility Registry ID: 110008054880
Air Operating Status Code: OPR

SMS MILL SVC/COATESVILLE (Continued) **1000216668**

Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2010-07-16 00:00:00
Activity Status Date:	2010-07-16 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Resolved
Region Code:	03
Programmatic ID:	AIR PA000562980
Facility Registry ID:	110008054880
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2009-04-14 00:00:00
Activity Status Date:	2009-04-14 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

FINDS:

Registry ID: 110060049166

Environmental Interest/Information System
PA-EFACTS (Pennsylvania - Environmental Facility Application Compliance Tracking System) is a Department-wide database that provides a holistic view of clients and sites (including facilities) that DEP regulates.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

H24 **PRESB CH OF COATESVILLE** **PA ARCHIVE UST** **S119698216**
SE **FOURTH AVE & E LINCOLN HWY** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.219 mi.
1156 ft. **Site 1 of 2 in cluster H**

Relative: **Lower**
Actual: **336 ft.**

ARCHIVE UST:

Facility Id:	15-45523
Site ID:	Not reported
Municipality:	Coatesville City
Client Date:	Not reported
Owner Id:	Not reported
Owner Name:	PRESB CH OF COATESVILLE
Owner Address:	FOURTH AVE & E LINCOLN HWY
Owner Address 2:	Not reported
Owner City,St,Zip:	COATESVILLE, PA 19320
Owner Phone:	Not reported
Owner County Code:	Not reported
Resp Party Name:	Not reported
RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported

PRESB CH OF COATESVILLE (Continued) **S119698216**

Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	001
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	8000
Substance:	Heating Oil
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	Y
Contact Name:	UNKNOWN
Company:	Not reported

I25 **G. O. CARLSON INC** **RCRA-CESQG 1007113966**
SW **135 WEST LINCOLN HIGHWAY** **NJ MANIFEST PAR000506899**
1/8-1/4 **COATESVILLE, PA 19320**
0.229 mi.
1208 ft. **Site 1 of 3 in cluster I**

Relative: **Lower**

Actual: **308 ft.**

RCRA-CESQG:

Date form received by agency:	02/14/2002
Facility name:	G. O. CARLSON INC
Facility address:	135 WEST LINCOLN HIGHWAY COATESVILLE, PA 19320
EPA ID:	PAR000506899
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	03
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

G. O. CARLSON INC (Continued) **1007113966**

Owner/Operator Summary:
- Owner/operator name: Not reported
- Owner/operator address: Not reported
- Not reported
- Owner/operator country: Not reported
- Owner/operator telephone: Not reported
- Owner/operator email: Not reported
- Owner/operator fax: Not reported
- Owner/operator extension: Not reported
- Legal status: Not reported
- Owner/Operator Type: Owner
- Owner/Op start date: Not reported
- Owner/Op end date: Not reported

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Violation Status: No violations found

Evaluation Action Summary:
- Evaluation date: 02/14/2002
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Not reported
- Date achieved compliance: Not reported
- Evaluation lead agency: State

NJ MANIFEST:
- EPA Id: PAR000506899
- Mail Address: 135 W LINCOLN HWY
- Mail City/State/Zip: COATESVILLE 19320
- Facility Phone: 6104662333
- Emergency Phone: Not reported
- Contact: GUNARD TRAVAGLINI
- Comments: Not reported
- SIC Code: Not reported
- County: 00
- Municipal: 00
- Previous EPA Id: Not reported
- Gen Flag: X
- Trans Flag: Not reported
- TSDF Flag: Not reported
- Name Change: Not reported

G. O. CARLSON INC (Continued) **1007113966**

Date Change:	Not reported

Manifest:

Manifest Number:	NJA5110505
EPA ID:	PAR000506899
Date Shipped:	09/22/2004
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	PAR000043752
Transporter 2 EPA ID:	PAD014286009
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/22/2004
Date Trans2 Transported Waste:	09/22/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/23/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	10190421
Was Load Rejected:	COATESVILLE 19320
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5124670
EPA ID:	PAR000506899
Date Shipped:	09/22/2004
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	PAR000043752
Transporter 2 EPA ID:	NJD000692061
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported

G. O. CARLSON INC (Continued) **1007113966**

Date Trans1 Transported Waste:	09/22/2004
Date Trans2 Transported Waste:	09/30/2004
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/30/2004
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	11040425
Was Load Rejected:	COATESVILLE 19320
Reason Load Was Rejected:	Not reported

I26 **GO CARLSON** **PA MANIFEST** **S111773472**
SW **135 W LINCOLN HWY** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.229 mi.
1208 ft. **Site 2 of 3 in cluster I**

Relative: **Lower**

Actual: **308 ft.**

Manifest Details:

Year:	2004
Manifest Number:	NJA5124670
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000506899
Generator Date:	09/22/2004
Mailing Address:	135 W LINCOLN HWY
Mailing City,St,Zip:	COATESVILLE, PA 19320
Contact Name:	Not reported
Contact Phone:	610-46-2333
TSD EPA Id:	NJD980536593
TSD Date:	09/30/2004
TSD Facility Name:	ONYX ENVIRONMENTAL SERVICE
TSD Facility Address:	ONE EDEN LN
TSD Facility City:	FLANDERS
TSD Facility State:	NJ
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	12
Container Type:	Cylinders
Waste Quantity:	500

GO CARLSON (Continued) **S111773472**

Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	NJD000692061
Date TSP Sig:	09/30/2004
Year:	2004
Manifest Number:	NJA5124670
Manifest Type:	TSD Copy
Generator EPA Id:	PAR000506899
Generator Date:	09/22/2004
Mailing Address:	135 W LINCOLN HWY
Mailing City,St,Zip:	COATESVILLE, PA 19320
Contact Name:	Not reported
Contact Phone:	610-46-2333
TSD EPA Id:	NJD980536593
TSD Date:	09/30/2004
TSD Facility Name:	ONYX ENVIRONMENTAL SERVICE
TSD Facility Address:	ONE EDEN LN
TSD Facility City:	FLANDERS
TSD Facility State:	NJ
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	12
Container Type:	Cylinders
Waste Quantity:	500
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAR000043752
Date TSP Sig:	09/22/2004

H27 **FAMILY DOLLAR STORES OF PA NO 11095** **RCRA-CESQG** **1018281833**
SE **400 E LINCOLN HWY** **FINDS** **PAR000553016**
1/8-1/4 **COATESVILLE, PA 19320** **ECHO**
0.241 mi.
1272 ft. **Site 2 of 2 in cluster H**

Relative: **Lower**
Actual: **332 ft.**

RCRA-CESQG:

Date form received by agency:	05/16/2016
Facility name:	FAMILY DOLLAR STORES OF PA NO 11095
Facility address:	400 E LINCOLN HWY COATESVILLE, PA 19320-3412
EPA ID:	PAR000553016
Mailing address:	PO BOX 1017 CHARLOTTE, NC 28201-1017
Contact:	KELVIN DAVIS
Contact address:	PO BOX 1017 CHARLOTTE, NC 28201-1017
Contact country:	US
Contact telephone:	704-708-1649
Contact email:	KDAVIS@FAMILYDOLLAR.COM
EPA Region:	03
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous

FAMILY DOLLAR STORES OF PA NO 11095 (Continued) **1018281833**

waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	FAMILY DOLLAR STORES OF PA LLC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/05/2016
Owner/Op end date:	Not reported

Owner/operator name:	FAMILY DOLLAR STORES OF PA LLC
Owner/operator address:	PO BOX 1017
	CHARLOTTE, NC 28201
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/05/2016
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001

FAMILY DOLLAR STORES OF PA NO 11095 (Continued) **1018281833**

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: U002
. Waste name: ACETONE (I)

Violation Status: No violations found

FINDS:

Registry ID: 110069287587

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

FAMILY DOLLAR STORES OF PA NO 11095 (Continued) **1018281833**

ECHO:
Envid: 1018281833
Registry ID: 110069287587
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069287587

J28 **COATESVILLE CTL OFC** **PA AUL** **S120839551**
SE **500 E CHESTNUT ST** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.245 mi.
1292 ft. **Site 1 of 3 in cluster J**

Relative: **Lower**
Actual: **343 ft.**

AUL:
Faciility Id: 585972
Primary Facility Type: Storage Tank Locator
Latitude: Not reported
Longitude: Not reported
Region: Southeast Region
Client Id: Not reported
Client Name: Not reported
Incident Id / Name Description: 10 BELL COATESVILLE CTL OFC 21016
Remediation Id: Not reported
Remediation Received Date: Not reported
Address: 500 E CHESTNUT ST COATESVILLE, PA 19320-3214
AUL Code: ENVIRONMENTAL COVENANT
Received Date: 09/27/2013
Action Date: 03/07/2014
Action: DEP SIGNED
Recorded Date: 05/01/2014
Terminated Date: Not reported
Amended Date: Not reported
Activity Use Limitation Code: Not reported
Activity Use Limitation Desc: Not reported
Aul Comment: Not reported
Internal Use EDR Field: Not reported

J29 **COATESVILLE CTL OFC** **PA ARCHIVE UST** **S119697895**
SE **500 CHESTNUT ST** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.245 mi.
1292 ft. **Site 2 of 3 in cluster J**

Relative: **Lower**
Actual: **343 ft.**

ARCHIVE UST:
Facility Id: 15-17725
Site ID: Not reported
Municipality: Coatesville City
Client Date: Not reported
Owner Id: Not reported
Owner Name: VERIZON PA LLC
Owner Address: 1500 MACCORKLE AVE SE
Owner Address 2: Not reported
Owner City,St,Zip: CHARLESTON, WV 25396-0001
Owner Phone: Not reported
Owner County Code: Not reported
Resp Party Name: Not reported
RP Address: Not reported
RP Address 2: Not reported

COATESVILLE CTL OFC (Continued) **S119697895**

RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	002
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	1500
Substance:	Diesel Fuel
Tank Substance End Date:	Not reported
Install Date:	01/01/1959
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	PAUL L GEBHARD ENV MGR
Company:	Not reported
Tank Sequence #:	001
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	3000
Substance:	Diesel Fuel
Tank Substance End Date:	Not reported
Install Date:	12/01/1958
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	PAUL L GEBHARD ENV MGR
Company:	Not reported

J30 **COATESVILLE CTL OFC** **PA LUST** **S102733885**
SE **500 E CHESTNUT ST** **PA AST** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.245 mi.
1292 ft. **Site 3 of 3 in cluster J**

Relative: LUST:
Lower

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	585972
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	04/01/2003
Confirmed Date:	08/06/1994
Program Other Id:	15-17725

Actual:
343 ft.

COATESVILLE CTL OFC (Continued) **S102733885**

Client: VERIZON PENNSYLVANIA LLC
Incident Id: 10
Incident Desc: BELL COATESVILLE CTL OFC 21016
Suspect Date: Not reported
Source Of Notification: Not reported
Release Discovered: Not reported
Source Cause Of Release: Not reported
Tank: Not reported
Impact Desc: Ground Water
Substance: Fuel Oil No 2
CAS RN: Not reported
Chemical: Not reported
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.98523
Longitude: -75.81629

AST:
Site ID: 569240
Client Id: 87568
Other Id: 15-17725
Mailing Name: VERIZON PENNSYLVANIA LLC
Mailing Address: 966 S MATLACK ST
Mailing Address: Not reported
Mailing City,St,Zip: WEST CHESTER, PA 19380
Municipality: Coatesville
Region Name: EP SE Rgnl Off Norristown

Tank Seq Num: 001A
Tank Status: Currently In Use
Tank Capacity: 1500
Substance: Diesel Fuel
Date Installed: 01/01/1993
Tank Code: AST
Inspection Code: Not reported
Tank Last Inspected: Not reported
Registration Expiration Date: 02/04/2019
Decode for Tstatus: Currently In Use
Decode for Substance: Diesel Fuel

I31 **THE COATESVILLE GAS CO** **EDR MGP** **1008408529**
SW **WAGONTOWN RD (BRIDGE ST) AND W LINCOLN HWY (W MAIN STREET)** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.245 mi.
1296 ft. **Site 3 of 3 in cluster I**

Relative: Manufactured Gas Plants:
Lower No additional information available

Actual:
307 ft.

K32 **NEWLIN BROS** **PA LUST** **S105800118**
SSE **340 HARMONY ST** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.247 mi.
1302 ft. **Site 1 of 2 in cluster K**

Relative: LUST:
Lower

Actual:
340 ft.

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	585861
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	11/19/2002
Confirmed Date:	09/30/1992
Program Other Id:	15-10149
Client:	JEROME H RHOADS INC
Incident Id:	12
Incident Desc:	NEWLINS AUTO SVC
Suspect Date:	Not reported
Source Of Notification:	INSTL
Release Discovered:	CLOS
Source Cause Of Release:	INFNP
Tank:	Not reported
Impact Desc:	Soil
Substance:	Leaded Gasoline
CAS RN:	Not reported
Chemical:	Not reported
Comments:	Not reported
Horizontal Ref Datum:	WGS84
Altitude Datum:	Not reported
Latitude:	39.983106
Longitude:	-75.819083

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	585861
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	11/19/2002
Confirmed Date:	09/30/1992
Program Other Id:	15-10149
Client:	JEROME H RHOADS INC
Incident Id:	12
Incident Desc:	NEWLINS AUTO SVC
Suspect Date:	Not reported
Source Of Notification:	INSTL
Release Discovered:	CLOS
Source Cause Of Release:	INFNP
Tank:	Not reported
Impact Desc:	Soil
Substance:	Unleaded Gasoline
CAS RN:	Not reported
Chemical:	Not reported
Comments:	Not reported
Horizontal Ref Datum:	WGS84
Altitude Datum:	Not reported
Latitude:	39.983106
Longitude:	-75.819083

K33 **NEWLIN BROS** **PA ARCHIVE UST** **S119697847**
SSE **340 HARMONY ST** **N/A**
1/8-1/4 **COATESVILLE, PA 19320**
0.247 mi.
1302 ft. **Site 2 of 2 in cluster K**

Relative:
Lower

Actual:
340 ft.

ARCHIVE UST:

Facility Id:	15-10149
Site ID:	Not reported
Municipality:	Coatesville City
Client Date:	Not reported
Owner Id:	Not reported
Owner Name:	JEROME H RHOADS INC
Owner Address:	PO BOX 1198
Owner Address 2:	Not reported
Owner City,St,Zip:	LANCASTER, PA 17601
Owner Phone:	Not reported
Owner County Code:	Not reported
Resp Party Name:	Not reported
RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported

Tank Sequence #:	002
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	550
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	001
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	550
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported

NEWLIN BROS (Continued) **S119697847**

Other Information Regarding The Tank Substance: Not reported
Undeliverable Address Ind.: N
Contact Name: UNKNOWN
Company: Not reported

34
ESE
1/4-1/2
0.257 mi.
1356 ft.

FLAMER RES **PA VCP** **S122431854**
553 E CHESTNUT ST **N/A**
COATESVILLE, PA 19320

Relative:
Lower

Actual:
355 ft.

VCP:

Activity:
Activity ID: 803437,

Cleanup Records:
Municipality: Coatesville City
Region: Southeast Region
Category Desc: Fuel Oil No 2
Type: Complete Sites
LRP Activity Number: 48453
Remediation: Statewide Health Standard
Activity: NO
Date Approved: 07/31/2018
Date Received: Not reported
Date Nonuse: Not reported
ICS Code: Not reported
Media: Soil
Latitude: 39.985647
Longitude: -75.814738

35
South
1/4-1/2
0.261 mi.
1378 ft.

LUKENS WEST SIDE SLAG DUMP **PA HIST LF** **S106934777**
50 S. 1ST. AVENUE **N/A**
COATESVILLE, PA 19355

Relative:
Lower

Actual:
321 ft.

HIST LF INACTIVE:
Size Acres: Not reported
Cont ID: Not reported
Contact Name: Not reported
Contact Tele: Not reported

36
SSE
1/4-1/2
0.298 mi.
1573 ft.

GORDON JR HIGH SCH **PA UNREG LTANKS** **S105918583**
351 KERSEY **N/A**
COATESVILLE, PA

Relative:
Lower

Actual:
328 ft.

UNREG LTANKS:
Region: South East
Contaminant: FUEL OIL NO. 2
Closed: **6/25/2001**
Class: Cleanup of Tanks using authorities other than Act 32

37
SE
1/4-1/2
0.306 mi.
1616 ft.

BETH ISRAEL
5TH & HARMONY ST
COATESVILLE, PA

PA UNREG LTANKS **S105918510**
N/A

Relative:
Lower

Actual:
323 ft.

UNREG LTANKS:

Region:	South East
Contaminant:	PHC's
Closed:	**Not reported**
Class:	Cleanup of Tanks using authorities other than Act 32

38
SE
1/4-1/2
0.326 mi.
1720 ft.

CARL O BENNER ELEM SCH
545 E LINCOLN HWY
COATESVILLE, PA 19320

PA LUST **S105145063**
PA ARCHIVE UST **N/A**
PA MANIFEST

Relative:
Lower

Actual:
337 ft.

LUST:

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	586451
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	03/25/1992
Confirmed Date:	03/25/1992
Program Other Id:	15-40559
Client:	COATESVILLE AREA SCH DIST
Incident Id:	36
Incident Desc:	CARL O BENNER ELEM SCH
Suspect Date:	Not reported
Source Of Notification:	Not reported
Release Discovered:	Not reported
Source Cause Of Release:	Not reported
Tank:	Not reported
Impact Desc:	Soil
Substance:	Fuel Oil No 2
CAS RN:	Not reported
Chemical:	Not reported
Comments:	Not reported
Horizontal Ref Datum:	WGS84
Altitude Datum:	Not reported
Latitude:	39.984167
Longitude:	-75.814444

ARCHIVE UST:

Facility Id:	15-40559
Site ID:	Not reported
Municipality:	Not reported
Client Date:	Not reported
Owner Id:	622
Owner Name:	COATESVILLE AREA SCH DIST
Owner Address:	1515 E LINCOLN HWY
Owner Address 2:	Not reported
Owner City,St,Zip:	COATESVILLE, PA 19320
Owner Phone:	6103833790
Owner County Code:	15
Resp Party Name:	Not reported
RP Address:	Not reported

CARL O BENNER ELEM SCH (Continued) **S105145063**

RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	001
Tank Id:	16894
Status:	Not reported
Status Code End Date:	Not reported
Capacity:	5000
Substance:	HEATING OIL
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	Not reported
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	Not reported
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	Not reported
Contact Name:	Not reported
Company:	Not reported
Tank Sequence #:	002
Tank Id:	16895
Status:	Not reported
Status Code End Date:	Not reported
Capacity:	5000
Substance:	HEATING OIL
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	Not reported
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	Not reported
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	Not reported
Contact Name:	Not reported
Company:	Not reported

Manifest Details:

Year:	2006
Manifest Number:	NJA5311474
Manifest Type:	TSD Copy
Generator EPA Id:	PADEP0012351
Generator Date:	06/03/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	NJD002200046
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC

CARL O BENNER ELEM SCH (Continued) **S105145063**

TSD Facility Address: 217 SOUTH FIRST STREET
TSD Facility City: ELIZABETH
TSD Facility State: NJ
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: U036
Container Number: 2
Container Type: Wooden boxes, cartons, cases
Waste Quantity: 529
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2006
Manifest Number: NJA5311471
Manifest Type: TSD Copy
Generator EPA Id: PADEP0012351
Generator Date: 06/03/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: NJD002200046
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 217 SOUTH FIRST STREET
TSD Facility City: ELIZABETH
TSD Facility State: NJ
Facility Telephone: Not reported
Page Number: 1
Line Number: 4
Waste Number: D001
Container Number: 2
Container Type: Metal drums, barrels, kegs
Waste Quantity: 806
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2006
Manifest Number: NJA5311474
Manifest Type: TSD Copy
Generator EPA Id: PADEP0012351
Generator Date: 06/03/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: NJD002200046
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 217 SOUTH FIRST STREET
TSD Facility City: ELIZABETH
TSD Facility State: NJ

CARL O BENNER ELEM SCH (Continued) **S105145063**

Facility Telephone: Not reported
Page Number: 1
Line Number: 3
Waste Number: D001
Container Number: 1
Container Type: Metal drums, barrels, kegs
Waste Quantity: 51
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2006
Manifest Number: NJA5311476
Manifest Type: TSD Copy
Generator EPA Id: PADEP0012351
Generator Date: 06/03/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: NJD002200046
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 217 SOUTH FIRST STREET
TSD Facility City: ELIZABETH
TSD Facility State: NJ
Facility Telephone: Not reported
Page Number: 1
Line Number: 1
Waste Number: D001
Container Number: 1
Container Type: Fiberboard or plastic drums, barrels, kegs
Waste Quantity: 8
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2006
Manifest Number: NJA5311474
Manifest Type: TSD Copy
Generator EPA Id: PADEP0012351
Generator Date: 06/03/2006
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: Not reported
TSD EPA Id: NJD002200046
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 217 SOUTH FIRST STREET
TSD Facility City: ELIZABETH
TSD Facility State: NJ
Facility Telephone: Not reported
Page Number: 1
Line Number: 1

CARL O BENNER ELEM SCH (Continued) **S105145063**

Waste Number:	U061
Container Number:	2
Container Type:	Wooden boxes, cartons, cases
Waste Quantity:	529
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

L39 **LEE RESIDENCE** **PA UNREG LTANKS** **S105918625**
SW **224 W LINCOLN HWY** **N/A**
1/4-1/2 **COATESVILLE, PA**
0.357 mi.
1883 ft. **Site 1 of 2 in cluster L**

Relative: **Lower**
Actual: **328 ft.**

UNREG LTANKS:

Region:	South East
Contaminant:	FUEL OIL #2
Closed:	**Not reported**
Class:	Cleanup of Tanks using authorities other than Act 32

---

40 **PARCEL 16-5-302, BETHLEHEM STEEL MAPLE ST.** **US BROWNFIELDS** **1023620394**
South **76 MAPLE STREET** **FINDS** **N/A**
1/4-1/2 **COATESVILLE, PA 19320**
0.357 mi.
1884 ft.

Relative: **Lower**
Actual: **315 ft.**

US BROWNFIELDS:

Property Name:	PARCEL 16-5-302, BETHLEHEM STEEL MAPLE ST.
Recipient Name:	Chester County
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.7
Latitude:	39.967843
Longitude:	-75.855723
HCM Label:	Address Matching-House Number
Map Scale:	100000
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	12454
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported

PARCEL 16-5-302, BETHLEHEM STEEL MAPLE ST. (Continued) **1023620394**

Grant Type:	N/A
Accomplishment Type:	Not reported
Accomplishment Count:	0
Cooperative Agreement Number:	98355101
Start Date:	Not reported
Ownership Entity:	Private
Completion Date:	Not reported
Current Owner:	Bethelehem Steel Corporation
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported

PARCEL 16-5-302, BETHLEHEM STEEL MAPLE ST. (Continued) **1023620394**

Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Steel facility
Below Poverty Number:	1999
Below Poverty Percent:	32.6%
Meidan Income:	3566
Meidan Income Number:	3675
Meidan Income Percent:	59.9%
Vacant Housing Number:	337
Vacant Housing Percent:	13.6%
Unemployed Number:	405
Unemployed Percent:	6.6%

FINDS:

Registry ID: 110060823435

Environmental Interest/Information System

PARCEL 16-5-302, BETHLEHEM STEEL MAPLE ST. (Continued) **1023620394**

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

M41 **PARCEL 16-5-271, BETHLEHEM STEEL S. FIRST AVE. LOT** **US BROWNFIELDS** **1023620392**
South **97 SOUTH FIRST AVENUE** **FINDS** **N/A**
1/4-1/2 **COATESVILLE, PA 19320**
0.358 mi.
1888 ft. **Site 1 of 3 in cluster M**

Relative: **Lower**
Actual: **319 ft.**

US BROWNFIELDS:

Property Name:	PARCEL 16-5-271, BETHLEHEM STEEL S. FIRST AVE. LOT
Recipient Name:	Chester County
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.8
Latitude:	39.980284
Longitude:	-75.821407
HCM Label:	Address Matching-House Number
Map Scale:	100000
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	12456
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported
Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Not reported
Accomplishment Count:	0
Cooperative Agreement Number:	98355101
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Bethlehem Steel Corporation
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported

PARCEL 16-5-271, BETHLEHEM STEEL S. FIRST AVE. LOT (Continued) **1023620392**

IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported

PARCEL 16-5-271, BETHLEHEM STEEL S. FIRST AVE. LOT (Continued) **1023620392**

mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Steel facility
Below Poverty Number:	1962
Below Poverty Percent:	33.1%
Meidan Income:	3158
Meidan Income Number:	3543
Meidan Income Percent:	59.7%
Vacant Housing Number:	348
Vacant Housing Percent:	14.5%
Unemployed Number:	366
Unemployed Percent:	6.2%

FINDS:

Registry ID: 110060823293

Environmental Interest/Information System

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

M42 **SIDHU PROP** **PA LUST** **U003919313**
South **99 S 1ST AVE** **PA UST** **N/A**
1/4-1/2 **COATESVILLE, PA 19320** **PA AUL**
0.380 mi. **PA ARCHIVE UST**
2004 ft. **Site 2 of 3 in cluster M**

Relative: **Lower**

Actual: **313 ft.**

LUST:

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	585829
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	04/22/1997
Confirmed Date:	11/30/1995
Program Other Id:	15-08398
Client:	SIDHU PROP LP
Incident Id:	35
Incident Desc:	15-08398 ROBT BARNETT SVC STA
Suspect Date:	10/2/1995
Source Of Notification:	INSTL
Release Discovered:	CLOS
Source Cause Of Release:	TANK
Tank:	Not reported
Impact Desc:	Soil
Substance:	Unleaded Gasoline
CAS RN:	Not reported
Chemical:	Not reported
Comments:	Not reported
Horizontal Ref Datum:	WGS84
Altitude Datum:	Not reported
Latitude:	39.980461
Longitude:	-75.821297

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	585829
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	02/16/2016
Confirmed Date:	07/05/2011
Program Other Id:	15-08398
Client:	SIDHU PROP LP
Incident Id:	42717
Incident Desc:	15-08398 LEW SVC CTR
Suspect Date:	Not reported
Source Of Notification:	INSTL
Release Discovered:	SAMPL, TTEST
Source Cause Of Release:	PUST
Tank:	Not reported
Impact Desc:	Ground Water
Substance:	Unleaded Gasoline
CAS RN:	91-20-3
Chemical:	NAPHTHALENE
Comments:	Not reported
Horizontal Ref Datum:	WGS84
Altitude Datum:	Not reported
Latitude:	39.980461
Longitude:	-75.821297

SIDHU PROP (Continued) **U003919313**

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 585829
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: **Cleanup Completed**
Status Date: 02/16/2016
Confirmed Date: 07/05/2011
Program Other Id: 15-08398
Client: SIDHU PROP LP
Incident Id: 42717
Incident Desc: 15-08398 LEW SVC CTR
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: SAMPL, TTEST
Source Cause Of Release: PUST
Tank: Not reported
Impact Desc: Ground Water
Substance: Unleaded Gasoline
CAS RN: 95-63-6
Chemical: TRIMETHYLBENZENE, 1,3,4- (TRIMETHYLBENZENE, 1,2,4-)
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980461
Longitude: -75.821297

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 585829
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: **Cleanup Completed**
Status Date: 02/16/2016
Confirmed Date: 07/05/2011
Program Other Id: 15-08398
Client: SIDHU PROP LP
Incident Id: 42717
Incident Desc: 15-08398 LEW SVC CTR
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: SAMPL, TTEST
Source Cause Of Release: PUST
Tank: Not reported
Impact Desc: Ground Water
Substance: Unleaded Gasoline
CAS RN: 108-67-8
Chemical: TRIMETHYLBENZENE, 1,3,5-
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980461
Longitude: -75.821297

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 585829
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: **Cleanup Completed**

SIDHU PROP (Continued) **U003919313**

Status Date: 02/16/2016
Confirmed Date: 07/05/2011
Program Other Id: 15-08398
Client: SIDHU PROP LP
Incident Id: 42717
Incident Desc: 15-08398 LEW SVC CTR
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: SAMPL, TTEST
Source Cause Of Release: PUST
Tank: Not reported
Impact Desc: Soil
Substance: Unleaded Gasoline
CAS RN: 71-43-2
Chemical: BENZENE
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980461
Longitude: -75.821297

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 585829
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: Cleanup Completed
Status Date: 02/16/2016
Confirmed Date: 07/05/2011
Program Other Id: 15-08398
Client: SIDHU PROP LP
Incident Id: 42717
Incident Desc: 15-08398 LEW SVC CTR
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: SAMPL, TTEST
Source Cause Of Release: PUST
Tank: Not reported
Impact Desc: Soil
Substance: Unleaded Gasoline
CAS RN: 1634-04-4
Chemical: METHYL TERT-BUTYL ETHER (MTBE)
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980461
Longitude: -75.821297

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 585829
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: Cleanup Completed
Status Date: 02/16/2016
Confirmed Date: 07/05/2011
Program Other Id: 15-08398
Client: SIDHU PROP LP
Incident Id: 42717

SIDHU PROP (Continued) **U003919313**

Incident Desc: 15-08398 LEW SVC CTR
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: SAMPL, TTEST
Source Cause Of Release: PUST
Tank: Not reported
Impact Desc: Soil
Substance: Unleaded Gasoline
CAS RN: 91-20-3
Chemical: NAPHTHALENE
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980461
Longitude: -75.821297

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 585829
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: Cleanup Completed
Status Date: 02/16/2016
Confirmed Date: 07/05/2011
Program Other Id: 15-08398
Client: SIDHU PROP LP
Incident Id: 42717
Incident Desc: 15-08398 LEW SVC CTR
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: SAMPL, TTEST
Source Cause Of Release: PUST
Tank: Not reported
Impact Desc: Soil
Substance: Unleaded Gasoline
CAS RN: 95-63-6
Chemical: TRIMETHYLBENZENE, 1,3,4- (TRIMETHYLBENZENE, 1,2,4-)
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980461
Longitude: -75.821297

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 585829
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: Cleanup Completed
Status Date: 02/16/2016
Confirmed Date: 07/05/2011
Program Other Id: 15-08398
Client: SIDHU PROP LP
Incident Id: 42717
Incident Desc: 15-08398 LEW SVC CTR
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: SAMPL, TTEST
Source Cause Of Release: PUST

SIDHU PROP (Continued) **U003919313**

Tank: Not reported
Impact Desc: Soil
Substance: Unleaded Gasoline
CAS RN: 108-67-8
Chemical: TRIMETHYLBENZENE, 1,3,5-
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980461
Longitude: -75.821297

UST:
Site ID: 569149
Other Id: 15-08398
Client Id Number: 307982
Municipality Name: Coatesville
Region: EP SE Rgnl Off Norristown
Mailing Name: SIDHU PROP LP
Mailing Address: 99 S 1ST AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: COATESVILLE, PA 19320-3419
Registration Expiration Date: 02/04/2019

Tank Seq No: 006
Tank Status: **Currently In Use**
Capacity: 10000
Substance: Gasoline
Date Installed: 09/18/1995
Tank Code: UST
Inspection Code: Facility Operation Inspection
Tank Last Dt Inspected: 05/24/2017
Decode for Tstatus: Currently In Use
Decode for Substance: Gasoline

Tank Seq No: 007
Tank Status: **Currently In Use**
Capacity: 6000
Substance: Gasoline
Date Installed: 09/18/1995
Tank Code: UST
Inspection Code: Facility Operation Inspection
Tank Last Dt Inspected: 05/24/2017
Decode for Tstatus: Currently In Use
Decode for Substance: Gasoline

Tank Seq No: 008
Tank Status: **Currently In Use**
Capacity: 4000
Substance: Diesel Fuel
Date Installed: 10/28/2003
Tank Code: UST
Inspection Code: Facility Operation Inspection
Tank Last Dt Inspected: 05/24/2017
Decode for Tstatus: Currently In Use
Decode for Substance: Diesel Fuel

SIDHU PROP (Continued) **U003919313**

AUL:

Faciility Id:	585829
Primary Facility Type:	Storage Tank Locator
Latitude:	Not reported
Longitude:	Not reported
Region:	Southeast Region
Client Id:	Not reported
Client Name:	Not reported
Incident Id / Name Description:	42717 15-08398 LEW SVC CTR
Remediation Id:	Not reported
Remediation Received Date:	Not reported
Address:	99 S 1ST AVE COATESVILLE, PA 19320-3419
AUL Code:	ENVIRONMENTAL COVENANT
Received Date:	01/15/2016
Action Date:	02/18/2016
Action:	DEP SIGNED
Recorded Date:	05/19/2016
Terminated Date:	Not reported
Amended Date:	Not reported
Activity Use Limitation Code:	Not reported
Activity Use Limitation Desc:	Not reported
Aul Comment:	Not reported
Internal Use EDR Field:	Not reported

ARCHIVE UST:

Facility Id:	15-08398
Site ID:	Not reported
Municipality:	Coatesville City
Client Date:	Not reported
Owner Id:	Not reported
Owner Name:	SIDHU PROP LP
Owner Address:	99 S 1ST AVE
Owner Address 2:	Not reported
Owner City,St,Zip:	COATESVILLE, PA 19320
Owner Phone:	Not reported
Owner County Code:	Not reported
Resp Party Name:	Not reported
RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	002
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	4000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	12/01/1967
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported

SIDHU PROP (Continued) **U003919313**

Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	RAJBIR S SIDHU OWNER
Company:	Not reported

Tank Sequence #:	003
Tank Id:	Not reported
Status:	Removed
Status Code End Date:	Not reported
Capacity:	500
Substance:	Kerosene
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	RAJBIR S SIDHU OWNER
Company:	Not reported

Tank Sequence #:	001
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	4000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	12/01/1967
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	RAJBIR S SIDHU OWNER
Company:	Not reported

Tank Sequence #:	005
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	4000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	09/11/1995
Tank Code:	UST
Inspection Code:	Not reported

SIDHU PROP (Continued) **U003919313**

Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	RAJBIR S SIDHU OWNER
Company:	Not reported

Tank Sequence #:	004
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	500
Substance:	Used Oil (all forms)
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	RAJBIR S SIDHU OWNER
Company:	Not reported

L43 **ANDY KUPERSTEIN** **PA LUST S119698158**
SW **305 W LINCOLN HWY** **PA ARCHIVE UST N/A**
1/4-1/2 **COATESVILLE, PA 19320**
0.386 mi.
2038 ft. **Site 2 of 2 in cluster L**

Relative: LUST:
Lower

Actual:
342 ft.

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	586995
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Interim or Remedial Actions Initiated**
Status Date:	06/13/1991
Confirmed Date:	06/13/1991
Program Other Id:	15-44829
Client:	ANDY KUPERSTEIN
Incident Id:	38
Incident Desc:	KUPERSTEIN PROP
Suspect Date:	Not reported
Source Of Notification:	Not reported
Release Discovered:	Not reported
Source Cause Of Release:	Not reported
Tank:	Not reported
Impact Desc:	Ground Water
Substance:	Unleaded Gasoline
CAS RN:	Not reported
Chemical:	Not reported
Comments:	Not reported
Horizontal Ref Datum:	WGS84

ANDY KUPERSTEIN (Continued) **S119698158**

Altitude Datum:	Not reported
Latitude:	39.981408
Longitude:	-75.830603

ARCHIVE UST:

Facility Id:	15-44829
Site ID:	Not reported
Municipality:	Coatesville City
Client Date:	Not reported
Owner Id:	Not reported
Owner Name:	ANDY KUPERSTEIN
Owner Address:	15 RAMBIEWOOD DR
Owner Address 2:	Not reported
Owner City,St,Zip:	COATESVILLE, PA 19320
Owner Phone:	Not reported
Owner County Code:	Not reported
Resp Party Name:	Not reported
RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported
Tank Sequence #:	001
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	500
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	003
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	500
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported

ANDY KUPERSTEIN (Continued) **S119698158**

Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	002
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	500
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

M44 **PARCEL 16-5-298, BETHLEHEM STEEL MAPLE STREET** **US BROWNFIELDS** **1023620393**
South **151 SOUTH FIRST AVENUE** **FINDS** **N/A**
1/4-1/2 **COATESVILLE, PA 19320**
0.396 mi.
2089 ft. **Site 3 of 3 in cluster M**

Relative: **Lower**
Actual: **311 ft.**

US BROWNFIELDS:

Property Name:	PARCEL 16-5-298, BETHLEHEM STEEL MAPLE STREET
Recipient Name:	Chester County
Grant Type:	Assessment
Property Number:	Not reported
Parcel size:	.6
Latitude:	39.980095
Longitude:	-75.821218
HCM Label:	Address Matching-House Number
Map Scale:	100000
Point of Reference:	Entrance Point of a Facility or Station
Highlights:	Not reported
Datum:	North American Datum of 1983
Acres Property ID:	12455
IC Data Access:	Not reported
Start Date:	Not reported
Redev Completition Date:	Not reported
Completed Date:	Not reported
Acres Cleaned Up:	Not reported
Cleanup Funding:	Not reported
Cleanup Funding Source:	Not reported
Assessment Funding:	Not reported
Assessment Funding Source:	Not reported
Redevelopment Funding:	Not reported
Redev. Funding Source:	Not reported
Redev. Funding Entity Name:	Not reported
Redevelopment Start Date:	Not reported

PARCEL 16-5-298, BETHLEHEM STEEL MAPLE STREET (Continued) **1023620393**

Assessment Funding Entity:	Not reported
Cleanup Funding Entity:	Not reported
Grant Type:	N/A
Accomplishment Type:	Not reported
Accomplishment Count:	0
Cooperative Agreement Number:	98355101
Start Date:	Not reported
Ownership Entity:	Not reported
Completion Date:	Not reported
Current Owner:	Bethlehem Steel Corporation
Did Owner Change:	N
Cleanup Required:	U
Video Available:	Not reported
Photo Available:	Not reported
Institutional Controls Required:	Not reported
IC Category Proprietary Controls:	Not reported
IC Cat. Info. Devices:	Not reported
IC Cat. Gov. Controls:	Not reported
IC Cat. Enforcement Permit Tools:	Not reported
IC in place date:	Not reported
IC in place:	U
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported

PARCEL 16-5-298, BETHLEHEM STEEL MAPLE STREET (Continued) **1023620393**

Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Surface Water:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
Nickel Cleaned Up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Property Description:	Steel facility
Below Poverty Number:	1969
Below Poverty Percent:	33.0%
Meidan Income:	3333
Meidan Income Number:	3554
Meidan Income Percent:	59.6%
Vacant Housing Number:	349
Vacant Housing Percent:	14.5%
Unemployed Number:	371
Unemployed Percent:	6.2%

FINDS:

Registry ID: 110060823364

PARCEL 16-5-298, BETHLEHEM STEEL MAPLE STREET (Continued) **1023620393**

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

45 SW 1/4-1/2 0.410 mi. 2167 ft. **POLISH AMER CITIZENS CLUB**
15 STRODE AVE
COATESVILLE, PA 19320

PA LUST **S119698170**
PA ARCHIVE UST **N/A**

Relative: Lower

Actual: 336 ft.

LUST:

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	587022
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	02/10/1992
Confirmed Date:	07/23/1991
Program Other Id:	15-44995
Client:	POLISH AMER CITIZENS CLUB
Incident Id:	50217
Incident Desc:	NORWI
Suspect Date:	Not reported
Source Of Notification:	OWNER
Release Discovered:	CLOS
Source Cause Of Release:	INFNP
Tank:	Not reported
Impact Desc:	Soil
Substance:	Leaded Gasoline
CAS RN:	Not reported
Chemical:	Not reported
Comments:	Not reported
Horizontal Ref Datum:	WGS84
Altitude Datum:	Not reported
Latitude:	39.980759
Longitude:	-75.830998

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	587022
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	02/10/1992
Confirmed Date:	07/23/1991
Program Other Id:	15-44995
Client:	POLISH AMER CITIZENS CLUB
Incident Id:	50217
Incident Desc:	NORWI
Suspect Date:	Not reported
Source Of Notification:	OWNER
Release Discovered:	CLOS
Source Cause Of Release:	INFNP
Tank:	Not reported

POLISH AMER CITIZENS CLUB (Continued) **S119698170**

Impact Desc: Soil
Substance: Unleaded Gasoline
CAS RN: Not reported
Chemical: Not reported
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980759
Longitude: -75.830998

ARCHIVE UST:

Facility Id:	15-44995
Site ID:	Not reported
Municipality:	Coatesville City
Client Date:	Not reported
Owner Id:	Not reported
Owner Name:	POLISH AMER CITIZENS CLUB
Owner Address:	15 STRODE AVE
Owner Address 2:	Not reported
Owner City,St,Zip:	COATESVILLE, PA 19320-3027
Owner Phone:	Not reported
Owner County Code:	Not reported
Resp Party Name:	Not reported
RP Address:	Not reported
RP Address 2:	Not reported
RP City,St,Zip:	Not reported
Region Code Name:	Not reported
Regulated Expire Date:	Not reported

Tank Sequence #:	006
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	4000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	001
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	550
Substance:	Unknown
Tank Substance End Date:	Not reported
Install Date:	Not reported

POLISH AMER CITIZENS CLUB (Continued) **S119698170**

Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	H
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	005
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	4000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	003
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	4000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	004
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	4000

POLISH AMER CITIZENS CLUB (Continued) **S119698170**

Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

Tank Sequence #:	002
Tank Id:	Not reported
Status:	Closed Without a Permit
Status Code End Date:	Not reported
Capacity:	1000
Substance:	Gasoline
Tank Substance End Date:	Not reported
Install Date:	Not reported
Tank Code:	UST
Inspection Code:	Not reported
Last Inspection:	Not reported
Substance Type:	P
CASRN for Hazardous Substances:	Not reported
Chemical Name:	Not reported
Other Information Regarding The Tank Substance:	Not reported
Undeliverable Address Ind.:	N
Contact Name:	UNKNOWN
Company:	Not reported

46
NE
1/4-1/2
0.424 mi.
2240 ft.

HILL FARM **PA VCP** **S106983457**
BLACKHORSE HILL RD **N/A**
COATESVILLE, PA 19320

Relative:
Higher

Actual:
580 ft.

VCP:

Cleanup Records:

Municipality:	Caln Twp
Region:	Southeast Region
Category Desc:	Pesticides
Type:	Complete Sites
LRP Activity Number:	356
Remediation:	Statewide Health Standard
Activity:	NO
Date Approved:	05/30/2002
Date Received:	Not reported
Date Nonuse:	Not reported
ICS Code:	Not reported
Media:	Soil
Latitude:	39.995833
Longitude:	-75.813333

HILL FARM (Continued) **S106983457**

Activity:
- Activity ID: 617121, 617121,
- Municipality: Caln Twp
- Region: Southeast Region
- Category Desc: Inorganics
- Type: Complete Sites
- LRP Activity Number: 356
- Remediation: Statewide Health Standard
- Activity: NO
- Date Approved: 05/30/2002
- Date Received: Not reported
- Date Nonuse: Not reported
- ICS Code: Not reported
- Media: Soil
- Latitude: 39.995833
- Longitude: -75.813333

N47 **DUPONT OF COATESVILLE** **PA HIST LF** **S105954688**
ESE **17 NORTH 7TH ST.** **N/A**
1/4-1/2 **COATESVILLE, PA**
0.430 mi.
2272 ft. **Site 1 of 3 in cluster N**

Relative: **Lower**
Actual: **343 ft.**

HIST LF INVENTORY:
- Site ID: 1-106
- Inspect Date: 07/31/00
- Facility Status: INACTIVE
- Facility Type: Not reported

N48 **DUPONT COATESVILLE** **SEMS-ARCHIVE** **1003864882**
ESE **17 N 7TH AVE** **PAD021962006**
1/4-1/2 **COATESVILLE, PA 19320**
0.430 mi.
2272 ft. **Site 2 of 3 in cluster N**

Relative: **Lower**
Actual: **343 ft.**

SEMS Archive:
- Site ID: 300882
- EPA ID: PAD021962006
- Cong District: 5
- FIPS Code: 42029
- FF: N
- NPL: Not on the NPL
- Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information
- Latitude: 40.116667
- Longitude: -75.825000000000003

SEMS Archive Detail:
- Region: 3
- Site ID: 300882
- EPA ID: PAD021962006
- Site Name: DUPONT COATESVILLE
- NPL: N
- FF: N
- OU: 0
- Action Code: VS
- Action Name: ARCH SITE

DUPONT COATESVILLE (Continued) **1003864882**

SEQ:	1
Start Date:	Not reported
Finish Date:	1980-06-01 00:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse
Region:	3
Site ID:	300882
EPA ID:	PAD021962006
Site Name:	DUPONT COATESVILLE
NPL:	N
FF:	N
OU:	0
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1980-06-01 00:00:00
Qual:	N
Current Action Lead:	EPA Perf
Region:	3
Site ID:	300882
EPA ID:	PAD021962006
Site Name:	DUPONT COATESVILLE
NPL:	N
FF:	N
OU:	0
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1979-11-01 00:00:00
Finish Date:	1979-11-01 00:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

N49 **DUPONT COATESVILLE** **PA INST CONTROL** **S109029862**
ESE **17 N 7TH AVE** **N/A**
1/4-1/2 **COATESVILLE, PA 19320**
0.430 mi.
2272 ft. **Site 3 of 3 in cluster N**

Relative:
Lower

Actual:
343 ft.

INST CONTROL:

Municipality Name:	Coatesville
Primary Facility Id:	616960
Address 2:	Not reported
Land Designation Code:	DEEDR
Region:	SE-1

50
NNW
1/4-1/2
0.432 mi.
2280 ft.

COATSVILLE LANDFILL
MT AIRY RD
COATSVILLE, PA 19320

SEMS-ARCHIVE

1000421170
PAD000414730

Relative:
Lower

Actual:
474 ft.

SEMS Archive:

Site ID:	300438
EPA ID:	PAD000414730
Cong District:	5
FIPS Code:	42029
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information
Latitude:	40.136111
Longitude:	-75.826667

SEMS Archive Detail:

Region:	3
Site ID:	300438
EPA ID:	PAD000414730
Site Name:	COATSVILLE LANDFILL
NPL:	N
FF:	N
OU:	0
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1981-02-01 00:00:00
Finish Date:	1981-02-01 00:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	3
Site ID:	300438
EPA ID:	PAD000414730
Site Name:	COATSVILLE LANDFILL
NPL:	N
FF:	N
OU:	0
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	Not reported
Finish Date:	1990-03-07 00:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	3
Site ID:	300438
EPA ID:	PAD000414730
Site Name:	COATSVILLE LANDFILL
NPL:	N
FF:	N
OU:	0
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1981-04-01 00:00:00

COATSVILLE LANDFILL (Continued) **1000421170**

Qual: L
Current Action Lead: St Perf

51
ESE
1/4-1/2
0.432 mi.
2281 ft.

GAS STOP **PA LUST S119007951**
652 E LINCOLN HWY **PA AUL N/A**
COATESVILLE, PA 19320

Relative:
Lower

Actual:
339 ft.

LUST:

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	586067
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	07/11/2016
Confirmed Date:	10/18/1993
Program Other Id:	15-23149
Client:	KRSF LLC
Incident Id:	39
Incident Desc:	HESS 38291
Suspect Date:	Not reported
Source Of Notification:	Not reported
Release Discovered:	Not reported
Source Cause Of Release:	Not reported
Tank:	Not reported
Impact Desc:	Ground Water
Substance:	Unleaded Gasoline
CAS RN:	71-43-2
Chemical:	BENZENE
Comments:	Not reported
Horizontal Ref Datum:	WGS84
Altitude Datum:	Not reported
Latitude:	39.984722
Longitude:	-75.810833

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	586067
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	07/11/2016
Confirmed Date:	10/18/1993
Program Other Id:	15-23149
Client:	KRSF LLC
Incident Id:	39
Incident Desc:	HESS 38291
Suspect Date:	Not reported
Source Of Notification:	Not reported
Release Discovered:	Not reported
Source Cause Of Release:	Not reported
Tank:	Not reported
Impact Desc:	Ground Water
Substance:	Unleaded Gasoline
CAS RN:	98-82-8
Chemical:	CUMENE
Comments:	Not reported

GAS STOP (Continued) **S119007951**

Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.984722
Longitude: -75.810833

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 586067
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: **Cleanup Completed**
Status Date: 07/11/2016
Confirmed Date: 10/18/1993
Program Other Id: 15-23149
Client: KRSF LLC
Incident Id: 39
Incident Desc: HESS 38291
Suspect Date: Not reported
Source Of Notification: Not reported
Release Discovered: Not reported
Source Cause Of Release: Not reported
Tank: Not reported
Impact Desc: Ground Water
Substance: Unleaded Gasoline
CAS RN: 100-41-4
Chemical: ETHYL BENZENE
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.984722
Longitude: -75.810833

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 586067
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: **Cleanup Completed**
Status Date: 07/11/2016
Confirmed Date: 10/18/1993
Program Other Id: 15-23149
Client: KRSF LLC
Incident Id: 39
Incident Desc: HESS 38291
Suspect Date: Not reported
Source Of Notification: Not reported
Release Discovered: Not reported
Source Cause Of Release: Not reported
Tank: Not reported
Impact Desc: Ground Water
Substance: Unleaded Gasoline
CAS RN: 1634-04-4
Chemical: METHYL TERT-BUTYL ETHER (MTBE)
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.984722
Longitude: -75.810833

GAS STOP (Continued) **S119007951**

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 586067
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: **Cleanup Completed**
Status Date: 07/11/2016
Confirmed Date: 10/18/1993
Program Other Id: 15-23149
Client: KRSF LLC
Incident Id: 39
Incident Desc: HESS 38291
Suspect Date: Not reported
Source Of Notification: Not reported
Release Discovered: Not reported
Source Cause Of Release: Not reported
Tank: Not reported
Impact Desc: Ground Water
Substance: Unleaded Gasoline
CAS RN: 91-20-3
Chemical: NAPHTHALENE
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.984722
Longitude: -75.810833

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 586067
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: **Cleanup Completed**
Status Date: 07/11/2016
Confirmed Date: 10/18/1993
Program Other Id: 15-23149
Client: KRSF LLC
Incident Id: 39
Incident Desc: HESS 38291
Suspect Date: Not reported
Source Of Notification: Not reported
Release Discovered: Not reported
Source Cause Of Release: Not reported
Tank: Not reported
Impact Desc: Ground Water
Substance: Unleaded Gasoline
CAS RN: 108-88-3
Chemical: TOLUENE
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.984722
Longitude: -75.810833

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 586067
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: **Cleanup Completed**

GAS STOP (Continued) **S119007951**

Status Date: 07/11/2016
Confirmed Date: 10/18/1993
Program Other Id: 15-23149
Client: KRSF LLC
Incident Id: 39
Incident Desc: HESS 38291
Suspect Date: Not reported
Source Of Notification: Not reported
Release Discovered: Not reported
Source Cause Of Release: Not reported
Tank: Not reported
Impact Desc: Ground Water
Substance: Unleaded Gasoline
CAS RN: 1330-20-7
Chemical: XYLENES (TOTAL)
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.984722
Longitude: -75.810833

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 586067
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: Interim or Remedial Actions Initiated
Status Date: 02/15/2018
Confirmed Date: 02/15/2018
Program Other Id: 15-23149
Client: KRSF LLC
Incident Id: 51572
Incident Desc: NOC
Suspect Date: 2/15/2018
Source Of Notification: INSTL, OWNER
Release Discovered: TTEST
Source Cause Of Release: PUST
Tank: Not reported
Impact Desc: Soil
Substance: Unleaded Gasoline
CAS RN: Not reported
Chemical: Not reported
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.984722
Longitude: -75.810833

AUL:
Faciility Id: 586067
Primary Facility Type: Storage Tank Locator
Latitude: Not reported
Longitude: Not reported
Region: Southeast Region
Client Id: Not reported
Client Name: Not reported
Incident Id / Name Description: 40 COATESVILLE HESS
Remediation Id: Not reported

GAS STOP (Continued) **S119007951**

Remediation Received Date:	Not reported
Address:	652 E LINCOLN HWY COATESVILLE, PA 19320-3532
AUL Code:	ENVIRONMENTAL COVENANT
Received Date:	12/13/2016
Action Date:	09/19/2017
Action:	DEP SIGNED
Recorded Date:	10/09/2017
Terminated Date:	Not reported
Amended Date:	Not reported
Activity Use Limitation Code:	Not reported
Activity Use Limitation Desc:	Not reported
Aul Comment:	Not reported
Internal Use EDR Field:	Not reported

---

52 **WHITELAND AVE. SEWER** **SEMS-ARCHIVE** **1003867287**
ESE **19 WHITELAND AVE. & BUSINESS RT. 30** **PA0001091784**
1/4-1/2 **DOWNINGTOWN, PA 19335**
0.435 mi.
2295 ft.

Relative: **Lower**

Actual: **331 ft.**

SEMS Archive:

Site ID:	305083
EPA ID:	PA0001091784
Cong District:	5
FIPS Code:	42029
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information
Latitude:	40.083333000000003
Longitude:	-75.700000000000003

SEMS Archive Detail:

Region:	3
Site ID:	305083
EPA ID:	PA0001091784
Site Name:	WHITELAND AVE. SEWER
NPL:	N
FF:	N
OU:	0
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1999-06-16 00:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	3
Site ID:	305083
EPA ID:	PA0001091784
Site Name:	WHITELAND AVE. SEWER
NPL:	N
FF:	N
OU:	0
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1996-08-12 00:00:00

WHITELAND AVE. SEWER (Continued) **1003867287**

Finish Date:	1996-08-12 00:00:00
Qual:	N
Current Action Lead:	EPA Perf
Region:	3
Site ID:	305083
EPA ID:	PA0001091784
Site Name:	WHITELAND AVE. SEWER
NPL:	N
FF:	N
OU:	0
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1995-03-13 00:00:00
Finish Date:	1995-03-13 00:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	3
Site ID:	305083
EPA ID:	PA0001091784
Site Name:	WHITELAND AVE. SEWER
NPL:	N
FF:	N
OU:	0
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	1995-03-14 00:00:00
Finish Date:	1995-03-21 00:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

53
SW
1/4-1/2
0.478 mi.
2525 ft.

JEROME H RHOADS INC
356 W MAIN ST
COATESVILLE, PA 19320

PA LUST **S102733886**
N/A

Relative:
Lower

Actual:
358 ft.

LUST:

Region:	EP SE Rgnl Off Norristown
Municipality:	Coatesville City
Facility Id:	586129
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	**Cleanup Completed**
Status Date:	07/06/1995
Confirmed Date:	06/30/1994
Program Other Id:	15-25526
Client:	JEROME H RHOADS INC
Incident Id:	17
Incident Desc:	JEROME H RHOADS INC
Suspect Date:	Not reported
Source Of Notification:	INSTL
Release Discovered:	CLOS
Source Cause Of Release:	INFNP
Tank:	Not reported

JEROME H RHOADS INC (Continued) **S102733886**

Impact Desc: Soil
Substance: Diesel Fuel
CAS RN: Not reported
Chemical: Not reported
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980763
Longitude: -75.832566

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 586129
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: Cleanup Completed
Status Date: 07/06/1995
Confirmed Date: 06/30/1994
Program Other Id: 15-25526
Client: JEROME H RHOADS INC
Incident Id: 17
Incident Desc: JEROME H RHOADS INC
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: CLOS
Source Cause Of Release: INFNP
Tank: Not reported
Impact Desc: Soil
Substance: Kerosene
CAS RN: Not reported
Chemical: Not reported
Comments: Not reported
Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980763
Longitude: -75.832566

Region: EP SE Rgnl Off Norristown
Municipality: Coatesville City
Facility Id: 586129
Facility Type: Underground Storage Tank Containing Petroleum
Facility Status: Cleanup Completed
Status Date: 07/06/1995
Confirmed Date: 06/30/1994
Program Other Id: 15-25526
Client: JEROME H RHOADS INC
Incident Id: 17
Incident Desc: JEROME H RHOADS INC
Suspect Date: Not reported
Source Of Notification: INSTL
Release Discovered: CLOS
Source Cause Of Release: INFNP
Tank: Not reported
Impact Desc: Soil
Substance: Unleaded Gasoline
CAS RN: Not reported
Chemical: Not reported
Comments: Not reported

JEROME H RHOADS INC (Continued) **S102733886**

Horizontal Ref Datum: WGS84
Altitude Datum: Not reported
Latitude: 39.980763
Longitude: -75.832566

54
ESE
1/4-1/2
0.499 mi.
2635 ft.

736-738 E LINCOLN HWY SITE **PA VCP** **S108055516**
736-738 E LINCOLN HWY **PA ACT 2-DEED** **N/A**
COATESVILLE, PA 19320

Relative:
Lower

Actual:
339 ft.

VCP:

Cleanup Records:
Municipality: Coatesville City
Region: Southeast Region
Category Desc: Unleaded Gasoline
Type: Complete Sites
LRP Activity Number: 36497
Remediation: Statewide Health Standard
Activity: NO
Date Approved: 05/18/2006
Date Received: Not reported
Date Nonuse: Not reported
ICS Code: Not reported
Media: Soil
Latitude: 39.985277
Longitude: -75.809444

Activity:
Activity ID: 680476, 680476,
Municipality: Coatesville City
Region: Southeast Region
Category Desc: Leaded Gasoline
Type: Complete Sites
LRP Activity Number: 36497
Remediation: Statewide Health Standard
Activity: NO
Date Approved: 05/18/2006
Date Received: Not reported
Date Nonuse: Not reported
ICS Code: Not reported
Media: Soil
Latitude: 39.985277
Longitude: -75.809444

ACT 2-DEED:
Region: 4100
Municipality: Coatesville
Site Size: Not reported
Cleanup Standard: Statewide Health
Cleanup Indicator: LOW
Response Date: 5/18/2006
Category Description: Diesel Fuel, Kerosene, Leaded Gasoline, Unleaded Gasoline, Used Motor Oil
Land Designation Code: Not reported

55
SSE
1/2-1
0.903 mi.
4768 ft.

Relative:
Lower

Actual:
366 ft.

ARCELORMITTAL PLATE LLC
139 MODENA RD
COATESVILLE, PA 19320

SEMS **1000208280**
CORRACTS **PAD002326908**
RCRA-TSDF
RCRA-LQG
PA UNREG LTANKS
PA ACT 2-DEED
PA SPILLS
2020 COR ACTION
TSCA
ICIS
US AIRS
FINDS
ECHO
PA MANIFEST
RI MANIFEST
PA NPDES

SEMS:

Site ID:	300565
EPA ID:	PAD002326908
Cong District:	16
FIPS Code:	42029
Latitude:	40.116667
Longitude:	-75.825000000000003
FF:	N
NPL:	Not on the NPL
Non NPL Status:	Other Cleanup Activity: State-Lead Cleanup

SEMS Detail:

Region:	3
Site ID:	300565
EPA ID:	PAD002326908
Site Name:	LUKENS STEEL CO
NPL:	N
FF:	N
OU:	0
Action Code:	SI
Action Name:	SI
SEQ:	3
Start Date:	1995-11-06 00:00:00
Finish Date:	1/29/1996
Qual:	H
Current Action Lead:	EPA Perf

Region:	3
Site ID:	300565
EPA ID:	PAD002326908
Site Name:	LUKENS STEEL CO
NPL:	N
FF:	N
OU:	0
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1980-08-01 00:00:00
Finish Date:	8/1/1980
Qual:	Not reported
Current Action Lead:	EPA Perf

Region: 3

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Site ID:	300565
EPA ID:	PAD002326908
Site Name:	LUKENS STEEL CO
NPL:	N
FF:	N
OU:	0
Action Code:	VA
Action Name:	OTHR CLEANUP
SEQ:	1
Start Date:	1999-10-17 00:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	St Ovrsght

Region:	3
Site ID:	300565
EPA ID:	PAD002326908
Site Name:	LUKENS STEEL CO
NPL:	N
FF:	N
OU:	0
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	1987-08-07 00:00:00
Finish Date:	8/7/1987
Qual:	N
Current Action Lead:	St Perf

CORRACTS:

EPA ID:	PAD002326908
EPA Region:	3
Area Name:	ENTIRE FACILITY
Actual Date:	20050615
Action:	CA100 - RFI Imposition
NAICS Code(s):	33111 332811 Iron and Steel Mills and Ferroalloy Manufacturing Metal Heat Treating
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	PAD002326908
EPA Region:	3
Area Name:	ENTIRE FACILITY
Actual Date:	20050615
Action:	CA725YE - Current Human Exposures Under Control, Yes, Current Human Exposures Under Control has been verified
NAICS Code(s):	33111 332811 Iron and Steel Mills and Ferroalloy Manufacturing Metal Heat Treating
Original schedule date:	Not reported
Schedule end date:	Not reported

EPA ID:	PAD002326908
EPA Region:	3
Area Name:	ENTIRE FACILITY

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Actual Date: 20000714
Action: CA210SF - CA Responsibility Referred To A Non-RCRA Federal Authority, Corrective Action at the facility or area referred to CERCLA
NAICS Code(s): 33111 332811
Iron and Steel Mills and Ferroalloy Manufacturing
Metal Heat Treating
Original schedule date: Not reported
Schedule end date: Not reported

EPA ID: PAD002326908
EPA Region: 3
Area Name: ENTIRE FACILITY
Actual Date: 19911201
Action: CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority
NAICS Code(s): 33111 332811
Iron and Steel Mills and Ferroalloy Manufacturing
Metal Heat Treating
Original schedule date: Not reported
Schedule end date: Not reported

RCRA-TSDF:
Date form received by agency: 01/20/2016
Facility name: ARCELORMITTAL PLATE LLC
Facility address: 139 MODENA RD
COATESVILLE, PA 19320
EPA ID: PAD002326908
Mailing address: MODENA RD
COATESVILLE, PA 19320
Contact: REZA (RAY) AJALLI
Contact address: MODENA RD
COATESVILLE, PA 19320
Contact country: US
Contact telephone: 610-383-2097
Contact email: RAY.AJALLI@ARCELORMITTAL.COM
EPA Region: 03
Land type: Private
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: ARCELORMITTAL PLATE LLC

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Owner/operator address: MODENA RD
COATESVILLE, PA 19320
Owner/operator country: US
Owner/operator telephone: 610-383-2000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/11/2007
Owner/Op end date: Not reported

Owner/operator name: ARCELORMITTAL PLATE LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/11/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Historical Generators:
Date form received by agency: 01/23/2014
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Date form received by agency: 04/03/2012
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: P022
. Waste name: CARBON DISULFIDE

. Waste code: P098
. Waste name: POTASSIUM CYANIDE

. Waste code: U077
. Waste name: ETHANE, 1,2-DICHLORO-

. Waste code: U134
. Waste name: HYDROFLUORIC ACID (C,T)

. Waste code: U154
. Waste name: METHANOL (I)

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste code: U188
. Waste name: PHENOL

Date form received by agency: 03/16/2010
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Date form received by agency: 02/25/2008
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 11/13/2007
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 11/05/2007
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 02/03/2006
Site name: ISG PLATE
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Date form received by agency: 06/21/2004
Site name: ISG PLATE LLC COATESVILLE

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 02/06/2004
Site name: ISG PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D011
. Waste name: SILVER

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K064
. Waste name: ACID PLANT BLOWDOWN SLURRY/SLUDGE RESULTING FROM THE THICKENING OF BLOWDOWN SLURRY FROM PRIMARY COPPER PRODUCTION.

Date form received by agency: 02/04/2002
Site name: BETHLEHEM LUKENS PLATE COATESVILLE
Classification: Large Quantity Generator

Date form received by agency: 03/22/2001
Site name: BETHLEHEM LUKENS PLATE COATESVILLE
Classification: Large Quantity Generator

Date form received by agency: 02/27/1998
Site name: LUKENS INC COATESVILLE FAC
Classification: Large Quantity Generator

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Date form received by agency: 01/25/1996
Site name: LUKENS INC COATESVILLE FAC
Classification: Large Quantity Generator

Date form received by agency: 02/21/1994
Site name: LUKENS STEEL CO - COATSVILLE
Classification: Large Quantity Generator

Date form received by agency: 02/21/1992
Site name: LUKENS STEEL CO.
Classification: Large Quantity Generator

Date form received by agency: 03/01/1990
Site name: LUKENS STEEL CO.
Classification: Large Quantity Generator

Date form received by agency: 11/19/1980
Site name: LUKENS STEEL CO
Classification: Not a generator, verified

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 07/31/1980
Site name: LUKENS STEEL CO
Classification: Large Quantity Generator

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 01/01/1979
Site name: LUKENS STEEL CO
Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 1500

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 82070

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 1000

Waste code: K061
Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.
Amount (Lbs): 20476380

Waste code: LABP
Waste name: LAB PACK
Amount (Lbs): 127

Corrective Action Summary:
Event date: 12/01/1991
Event: CA PRIORITIZATION-HIGH CA PRIORITY

Event date: 07/14/2000
Event: REFERRED TO A NON-RCRA AUTHORITY-REFERRED TO CERCLA

Event date: 06/15/2005
Event: HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE

Event date: 06/15/2005
Event: INVESTIGATION IMPOSITION

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 04/08/2015
Date achieved compliance: 04/09/2015
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/2015
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.20(a)(g),262.23(b)(h)
Area of violation: Generators - Manifest

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Date violation determined: 02/23/1999
Date achieved compliance: 01/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/12/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - ACT 97 SEC. 6018.401(a)
Area of violation: Generators - Pre-transport
Date violation determined: 09/13/1994
Date achieved compliance: 07/13/1995
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/29/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.11
Area of violation: Generators - General
Date violation determined: 03/31/1992
Date achieved compliance: 09/13/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - ACT 97 610 (3)
Area of violation: TSD - Landfill Standards
Date violation determined: 03/18/1992
Date achieved compliance: 03/31/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.20(g)
Area of violation: Generators - Manifest
Date violation determined: 03/09/1992

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Date achieved compliance: 03/31/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 268.7
Area of violation: Generators - Manifest
Date violation determined: 03/09/1992
Date achieved compliance: 03/31/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.42
Area of violation: Generators - General
Date violation determined: 08/28/1991
Date achieved compliance: 03/09/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/24/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.23
Area of violation: Generators - Manifest
Date violation determined: 08/28/1991
Date achieved compliance: 03/31/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/24/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 08/28/1990
Date achieved compliance: 10/18/1990

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/08/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 08/28/1990
Date achieved compliance: 10/18/1990
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 10/18/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 500
Final penalty amount: 500
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 07/13/1988
Date achieved compliance: 10/16/1989
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 10/16/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 1000
Final penalty amount: 1000
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 08/14/1987
Date achieved compliance: 10/16/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/14/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 04/08/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 04/09/2015

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Evaluation lead agency: EPA

Evaluation date: 10/23/2013
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/08/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/25/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/17/2001
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/31/2000
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/23/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 01/31/2000
Evaluation lead agency: State

Evaluation date: 09/27/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/13/1995
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/13/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 07/13/1995
Evaluation lead agency: State

Evaluation date: 04/28/1992

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/13/1994
Evaluation lead agency: State

Evaluation date: 03/31/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/13/1994
Evaluation lead agency: State

Evaluation date: 03/18/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Landfill Standards
Date achieved compliance: 03/31/1992
Evaluation lead agency: State

Evaluation date: 03/09/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 03/31/1992
Evaluation lead agency: State

Evaluation date: 08/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 03/31/1992
Evaluation lead agency: State

Evaluation date: 08/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/09/1992
Evaluation lead agency: State

Evaluation date: 08/28/1990
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 10/18/1990
Evaluation lead agency: State

Evaluation date: 07/13/1988
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: TSD - General
Date achieved compliance: 10/16/1989
Evaluation lead agency: State

Evaluation date: 08/14/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 10/16/1989
Evaluation lead agency: State

Evaluation date: 02/09/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Evaluation lead agency: State

RCRA-LQG:
Date form received by agency: 01/20/2016
Facility name: ARCELORMITTAL PLATE LLC
Facility address: 139 MODENA RD
COATESVILLE, PA 19320
EPA ID: PAD002326908
Mailing address: MODENA RD
COATESVILLE, PA 19320
Contact: REZA (RAY) AJALLI
Contact address: MODENA RD
COATESVILLE, PA 19320
Contact country: US
Contact telephone: 610-383-2097
Contact email: RAY.AJALLI@ARCELORMITTAL.COM
EPA Region: 03
Land type: Private
Classification: TSDF
Description: Handler is engaged in the treatment, storage or disposal of hazardous waste
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: ARCELORMITTAL PLATE LLC
Owner/operator address: MODENA RD
COATESVILLE, PA 19320
Owner/operator country: US
Owner/operator telephone: 610-383-2000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/11/2007
Owner/Op end date: Not reported

Owner/operator name: ARCELORMITTAL PLATE LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/11/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Historical Generators:
Date form received by agency: 01/23/2014
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Date form received by agency: 04/03/2012
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: P022
. Waste name: CARBON DISULFIDE

. Waste code: P098
. Waste name: POTASSIUM CYANIDE

. Waste code: U077
. Waste name: ETHANE, 1,2-DICHLORO-

. Waste code: U134
. Waste name: HYDROFLUORIC ACID (C,T)

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U188
. Waste name: PHENOL

Date form received by agency: 03/16/2010
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Date form received by agency: 02/25/2008
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 11/13/2007
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 11/05/2007
Site name: ARCELORMITTAL PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 02/03/2006
Site name: ISG PLATE
Classification: Large Quantity Generator

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Date form received by agency: 06/21/2004
Site name: ISG PLATE LLC COATESVILLE
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 02/06/2004
Site name: ISG PLATE LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D011
. Waste name: SILVER

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K064
. Waste name: ACID PLANT BLOWDOWN SLURRY/SLUDGE RESULTING FROM THE THICKENING OF BLOWDOWN SLURRY FROM PRIMARY COPPER PRODUCTION.

Date form received by agency: 02/04/2002
Site name: BETHLEHEM LUKENS PLATE COATESVILLE
Classification: Large Quantity Generator

Date form received by agency: 03/22/2001
Site name: BETHLEHEM LUKENS PLATE COATESVILLE
Classification: Large Quantity Generator

Date form received by agency: 02/27/1998
Site name: LUKENS INC COATESVILLE FAC
Classification: Large Quantity Generator

Date form received by agency: 01/25/1996
Site name: LUKENS INC COATESVILLE FAC
Classification: Large Quantity Generator

Date form received by agency: 02/21/1994
Site name: LUKENS STEEL CO - COATSVILLE
Classification: Large Quantity Generator

Date form received by agency: 02/21/1992
Site name: LUKENS STEEL CO.
Classification: Large Quantity Generator

Date form received by agency: 03/01/1990
Site name: LUKENS STEEL CO.
Classification: Large Quantity Generator

Date form received by agency: 11/19/1980

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Site name: LUKENS STEEL CO
Classification: Not a generator, verified

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 07/31/1980
Site name: LUKENS STEEL CO
Classification: Large Quantity Generator

. Waste code: F007
. Waste name: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS

. Waste code: K061
. Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

. Waste code: K062
. Waste name: SPENT PICKLE LIQUOR GENERATED BY STEEL FINISHING OPERATIONS OF FACILITIES WITHIN THE IRON AND STEEL INDUSTRY (SIC CODES 331 AND 332).

Date form received by agency: 01/01/1979
Site name: LUKENS STEEL CO
Classification: Large Quantity Generator

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:
Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 1500

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 82070

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 1000

Waste code: K061
Waste name: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

ELECTRIC FURNACES.
Amount (Lbs): 20476380

Waste code: LABP
Waste name: LAB PACK
Amount (Lbs): 127

Corrective Action Summary:
Event date: 12/01/1991
Event: CA PRIORITIZATION-HIGH CA PRIORITY

Event date: 07/14/2000
Event: REFERRED TO A NON-RCRA AUTHORITY-REFERRED TO CERCLA

Event date: 06/15/2005
Event: HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE

Event date: 06/15/2005
Event: INVESTIGATION IMPOSITION

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 04/08/2015
Date achieved compliance: 04/09/2015
Violation lead agency: EPA
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/09/2015
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.20(a)(g),262.23(b)(h)
Area of violation: Generators - Manifest
Date violation determined: 02/23/1999
Date achieved compliance: 01/31/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/12/1999
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - ACT 97 SEC. 6018.401(a)
Area of violation: Generators - Pre-transport
Date violation determined: 09/13/1994
Date achieved compliance: 07/13/1995
Violation lead agency: State

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Enforcement action: WRITTEN INFORMAL
Enforcement action date: 09/29/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.11
Area of violation: Generators - General
Date violation determined: 03/31/1992
Date achieved compliance: 09/13/1994
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - ACT 97 610 (3)
Area of violation: TSD - Landfill Standards
Date violation determined: 03/18/1992
Date achieved compliance: 03/31/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.20(g)
Area of violation: Generators - Manifest
Date violation determined: 03/09/1992
Date achieved compliance: 03/31/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 268.7
Area of violation: Generators - Manifest
Date violation determined: 03/09/1992
Date achieved compliance: 03/31/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Enforcement action date: 07/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.42
Area of violation: Generators - General
Date violation determined: 08/28/1991
Date achieved compliance: 03/09/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/24/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.23
Area of violation: Generators - Manifest
Date violation determined: 08/28/1991
Date achieved compliance: 03/31/1992
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/24/1991
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 08/28/1990
Date achieved compliance: 10/18/1990
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/08/1990
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 08/28/1990
Date achieved compliance: 10/18/1990
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 10/18/1990

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 500
Final penalty amount: 500
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 07/13/1988
Date achieved compliance: 10/16/1989
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 10/16/1989
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: 1000
Final penalty amount: 1000
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: TSD - General
Date violation determined: 08/14/1987
Date achieved compliance: 10/16/1989
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/14/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 04/08/2015
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 04/09/2015
Evaluation lead agency: EPA

Evaluation date: 10/23/2013
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/08/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/25/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/17/2001
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/31/2000
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/23/1999
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 01/31/2000
Evaluation lead agency: State

Evaluation date: 09/27/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/13/1995
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/13/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 07/13/1995
Evaluation lead agency: State

Evaluation date: 04/28/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/13/1994
Evaluation lead agency: State

Evaluation date: 03/31/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/13/1994
Evaluation lead agency: State

Evaluation date: 03/18/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - Landfill Standards
Date achieved compliance: 03/31/1992
Evaluation lead agency: State

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Evaluation date: 03/09/1992
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 03/31/1992
Evaluation lead agency: State

Evaluation date: 08/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 03/31/1992
Evaluation lead agency: State

Evaluation date: 08/28/1991
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/09/1992
Evaluation lead agency: State

Evaluation date: 08/28/1990
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 10/18/1990
Evaluation lead agency: State

Evaluation date: 07/13/1988
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: TSD - General
Date achieved compliance: 10/16/1989
Evaluation lead agency: State

Evaluation date: 08/14/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: TSD - General
Date achieved compliance: 10/16/1989
Evaluation lead agency: State

Evaluation date: 02/09/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

UNREG LTANKS:
Region: South East
Contaminant: FUEL OIL #2
Closed: **Not reported**
Class: Cleanup of Tanks using authorities other than Act 32

ACT 2-DEED:
Region: 4100
Municipality: Coatesville
Site Size: Not reported
Cleanup Standard: Statewide Health
Cleanup Indicator: Not reported
Response Date: 2/1/2007
Category Description: Diesel Fuel, Kerosene, Leaded Gasoline, Unleaded Gasoline, Used Motor Oil

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Land Designation Code: Not reported

SPILLS:
Id No: 247804
Latitude: 39 58 25.1616
Longitude: -75 48 54.018
Material Involved: Petroleum Based
Substance: Unknown Sheen 0 Each
Date Received: 02/20/2007
Municipality: South Coatesville Boro
Description: Sheen observed on gibbons creek by ISG Plate LLC.
Complaint Type: Not reported
Responsible Party: Not reported

2020 COR ACTION:
EPA ID: PAD002326908
Region: 3
Action: Not reported

ICIS:
Enforcement Action ID: PA000A0000E00000000193132
FRS ID: 110005981928
Action Name: Not reported
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Notice of Violation
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000E00000000117684
FRS ID: 110005981928
Action Name: Not reported
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Notice of Violation
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000E00000000049423
FRS ID: 110005981928
Action Name: Not reported
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Notice of Violation
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000E00000000045267
FRS ID: 110005981928
Action Name: Not reported
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Notice of Violation
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500057
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500057
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Administrative Order
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3312
Federal Facility ID: Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500052
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500052
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Notice of Violation
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500048
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500048
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Administrative Order
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500038
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500038
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Administrative Order
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

EA Type Code: SCAAAO
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500037
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500037
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Notice of Violation
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500034
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500034
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Notice of Violation
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500030
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500030
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Administrative Order

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500016
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500016
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Administrative Order
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500015
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500015
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address: 139 MODENA RD
COATESVILLE, PA 19320-4036
Enforcement Action Type: Administrative Order
Facility County: CHESTER
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3312
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 39.983013
Longitude in Decimal Degrees: -75.827911
Permit Type Desc: Not reported
Program System Acronym: PA000483776
Facility NAICS Code: 331110
Tribal Land Code: Not reported

Enforcement Action ID: PA000A0000420290001500013
FRS ID: 110005981928
Action Name: ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500013
Facility Name: ARCELORMITTAL PLATE LLC/COATESVILLE

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Facility Address:	139 MODENA RD COATESVILLE, PA 19320-4036
Enforcement Action Type:	Administrative Order
Facility County:	CHESTER
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	3312
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	39.983013
Longitude in Decimal Degrees:	-75.827911
Permit Type Desc:	Not reported
Program System Acronym:	PA000483776
Facility NAICS Code:	331110
Tribal Land Code:	Not reported

Enforcement Action ID:	PA000A0000420290001500011
FRS ID:	110005981928
Action Name:	ARCELORMITTAL PLATE LLC/COATESVILLE 420290001500011
Facility Name:	ARCELORMITTAL PLATE LLC/COATESVILLE
Facility Address:	139 MODENA RD COATESVILLE, PA 19320-4036
Enforcement Action Type:	Administrative Order
Facility County:	CHESTER
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	3312
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	39.983013
Longitude in Decimal Degrees:	-75.827911
Permit Type Desc:	Not reported
Program System Acronym:	PA000483776
Facility NAICS Code:	331110
Tribal Land Code:	Not reported

Enforcement Action ID:	03-1989-N017
FRS ID:	110005981928
Action Name:	ISG PLATE - COATESVILLE (Permit PA0011568) Administrative Order
Facility Name:	ARCELORMITTAL PLATE COATESVILLE
Facility Address:	139 MODENA ROAD COATESVILLE, PA 19320
Enforcement Action Type:	CWA 309A AO For Compliance
Facility County:	CHESTER
Program System Acronym:	NPDES
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	309A
Facility SIC Code:	3312
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	39.98301
Longitude in Decimal Degrees:	-75.82791
Permit Type Desc:	NPDES Individual Permit
Program System Acronym:	PA0011568
Facility NAICS Code:	331110
Tribal Land Code:	Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

US AIRS (AFS):
Envid: 1000208280
Region Code: 03
County Code: PA029
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
D and B Number: Not reported
Facility Site Name: ARCELORMITTAL PLATE LLC/COATESVILLE
Primary SIC Code: 3312
NAICS Code: 331110
Default Air Classification Code: MAJ
Facility Type of Ownership Code: NON
Air CMS Category Code: TVM
HPV Status: Not reported

US AIRS (AFS):
Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1997-07-09 00:00:00
Activity Status Date: 2016-02-11 16:51:51
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1997-07-30 00:00:00
Activity Status Date: 2016-02-11 16:52:07
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1998-08-28 00:00:00
Activity Status Date: 2016-02-11 16:53:51
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1998-09-11 00:00:00
Activity Status Date: 2016-02-11 16:52:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1998-10-06 00:00:00
Activity Status Date: 2016-02-11 16:54:05
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1998-11-03 00:00:00
Activity Status Date: 2016-02-11 16:52:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-01-05 00:00:00
Activity Status Date: 2016-02-11 16:53:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-03-26 00:00:00
Activity Status Date: 2016-02-11 16:53:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-07-20 00:00:00
Activity Status Date: 2016-02-11 16:53:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-08-27 00:00:00
Activity Status Date: 2016-02-11 16:53:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-12-17 00:00:00
Activity Status Date: 2016-02-11 16:54:32
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-08-15 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-08-16 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-08-17 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-06-11 00:00:00
Activity Status Date: 2016-02-11 16:58:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-06-28 00:00:00
Activity Status Date: 2016-02-11 17:14:50
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-10-03 00:00:00
Activity Status Date: 2016-02-11 17:14:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-10-03 00:00:00
Activity Status Date: 2016-02-11 17:14:49
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2002-10-15 00:00:00
Activity Status Date:	2016-02-11 17:14:49
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2002-11-14 00:00:00
Activity Status Date:	2016-02-11 16:59:03
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2003-03-17 00:00:00
Activity Status Date:	2016-02-11 16:59:32
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2003-04-10 00:00:00
Activity Status Date:	2016-02-11 17:14:50
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date:	2003-10-08 00:00:00
Activity Status Date:	2016-02-11 17:14:52
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2004-03-05 00:00:00
Activity Status Date:	2016-02-11 17:01:24
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2004-06-22 00:00:00
Activity Status Date:	2016-02-11 17:01:47
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2004-10-14 00:00:00
Activity Status Date:	2016-02-11 17:14:55
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2004-10-20 00:00:00
Activity Status Date:	2016-02-11 17:14:55
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-03-17 00:00:00
Activity Status Date: 2016-02-11 17:02:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-04-25 00:00:00
Activity Status Date: 2016-02-11 17:03:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-04-27 00:00:00
Activity Status Date: 2016-02-11 17:03:12
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-06-16 00:00:00
Activity Status Date: 2016-02-11 17:03:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-07-12 00:00:00
Activity Status Date: 2016-02-11 17:04:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-11-05 00:00:00
Activity Status Date: 2016-02-11 17:04:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-11-30 00:00:00
Activity Status Date: 2016-02-11 17:04:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-02-01 00:00:00
Activity Status Date: 2016-02-11 17:04:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-02-28 00:00:00
Activity Status Date: 2016-02-11 17:15:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-03-30 00:00:00
Activity Status Date: 2016-02-11 17:04:58
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-09-11 00:00:00
Activity Status Date: 2016-02-11 17:15:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-11-08 00:00:00
Activity Status Date: 2016-02-11 17:15:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-01-24 00:00:00
Activity Status Date: 2016-02-11 17:06:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-03-15 00:00:00
Activity Status Date: 2016-02-11 17:06:16
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2007-04-16 00:00:00
Activity Status Date: 2016-02-11 17:06:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-04-17 00:00:00
Activity Status Date: 2016-02-11 17:06:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-05-15 00:00:00
Activity Status Date: 2016-02-11 17:07:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-08-28 00:00:00
Activity Status Date: 2016-02-11 17:06:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-09-26 00:00:00
Activity Status Date: 2016-02-11 17:07:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-11-15 00:00:00
Activity Status Date: 2016-02-11 17:15:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-12-13 00:00:00
Activity Status Date: 2008-03-20 17:03:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-02-13 00:00:00
Activity Status Date: 2016-02-11 17:07:37
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-03-18 00:00:00
Activity Status Date: 2016-02-11 17:07:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-04-25 00:00:00
Activity Status Date: 2016-02-11 17:07:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-09 00:00:00
Activity Status Date: 2016-02-11 17:08:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-16 00:00:00
Activity Status Date: 2016-02-11 17:08:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-07-17 00:00:00
Activity Status Date: 2016-02-11 17:08:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-08-11 00:00:00
Activity Status Date: 2016-02-11 17:15:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-10-07 00:00:00
Activity Status Date: 2016-02-11 17:08:29
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2008-10-14 00:00:00
Activity Status Date: 2016-02-11 17:09:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-01-12 00:00:00
Activity Status Date: 2016-02-11 17:08:45
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-03-20 00:00:00
Activity Status Date: 2016-02-11 17:09:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-03-30 00:00:00
Activity Status Date: 2016-02-11 17:09:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date:	2009-04-01 00:00:00
Activity Status Date:	2016-02-11 17:09:08
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-04-02 00:00:00
Activity Status Date:	2016-02-11 17:09:08
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-04-06 00:00:00
Activity Status Date:	2016-02-11 17:09:08
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-04-13 00:00:00
Activity Status Date:	2016-02-11 17:15:08
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-04-21 00:00:00
Activity Status Date:	2016-02-11 17:09:11
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-04-30 00:00:00
Activity Status Date:	2016-02-11 17:09:13
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active

Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-05-28 00:00:00
Activity Status Date:	2016-02-11 17:09:21
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active

Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-08-13 00:00:00
Activity Status Date:	2016-02-11 17:09:34
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active

Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-09-21 00:00:00
Activity Status Date:	2016-02-11 17:09:41
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active

Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2009-11-04 00:00:00
Activity Status Date:	2016-02-11 17:09:46
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-01-21 00:00:00
Activity Status Date: 2016-02-11 17:09:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-02-23 00:00:00
Activity Status Date: 2016-02-11 17:10:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-04-14 00:00:00
Activity Status Date: 2016-02-11 17:15:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-06-01 00:00:00
Activity Status Date: 2016-02-11 17:10:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-07-27 00:00:00
Activity Status Date: 2016-02-11 17:10:27
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-08-09 00:00:00
Activity Status Date: 2016-02-11 17:10:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-08-12 00:00:00
Activity Status Date: 2016-02-11 17:10:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2010-09-27 00:00:00
Activity Status Date: 2016-02-11 17:10:35
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-02-14 00:00:00
Activity Status Date: 2016-02-11 17:10:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2011-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-04-13 00:00:00
Activity Status Date: 2016-02-11 17:11:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-04-14 00:00:00
Activity Status Date: 2016-02-11 17:15:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-05-06 00:00:00
Activity Status Date: 2016-02-11 17:11:09
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-05-25 00:00:00
Activity Status Date: 2016-02-11 17:11:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-06-22 00:00:00
Activity Status Date: 2016-02-11 17:11:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-06-30 00:00:00
Activity Status Date: 2016-02-11 17:11:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-07-07 00:00:00
Activity Status Date: 2016-02-11 17:11:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-08-01 00:00:00
Activity Status Date: 2016-02-11 17:11:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-08-02 00:00:00
Activity Status Date: 2016-02-11 17:11:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-08-29 00:00:00
Activity Status Date: 2016-02-11 17:11:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-09-13 00:00:00
Activity Status Date: 2011-09-14 15:50:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-09-13 00:00:00
Activity Status Date: 2016-02-11 17:11:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-10-12 00:00:00
Activity Status Date: 2016-02-11 17:12:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-10-24 00:00:00
Activity Status Date: 2016-02-11 17:11:29
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-11-16 00:00:00
Activity Status Date: 2016-02-11 17:11:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-02-28 00:00:00
Activity Status Date: 2016-02-11 17:11:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-03-30 00:00:00
Activity Status Date: 2016-02-11 17:15:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2012-04-06 00:00:00
Activity Status Date: 2016-02-11 17:15:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date:	2012-05-01 00:00:00
Activity Status Date:	2016-02-11 17:11:57
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2012-05-18 00:00:00
Activity Status Date:	2016-02-11 17:11:59
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2012-06-05 00:00:00
Activity Status Date:	2016-02-11 17:12:01
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2012-09-24 00:00:00
Activity Status Date:	2016-02-11 17:12:17
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2012-12-31 00:00:00
Activity Status Date:	2016-02-11 17:12:27
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-01-02 00:00:00
Activity Status Date: 2016-02-11 17:12:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-02-25 00:00:00
Activity Status Date: 2016-02-11 17:12:37
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-02-28 00:00:00
Activity Status Date: 2016-02-11 17:12:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-03-28 00:00:00
Activity Status Date: 2016-02-11 17:15:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-04-10 00:00:00
Activity Status Date: 2016-02-11 17:12:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-04-11 00:00:00
Activity Status Date: 2016-02-11 17:15:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-07-18 00:00:00
Activity Status Date: 2016-02-11 17:13:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-08-22 00:00:00
Activity Status Date: 2016-02-11 17:13:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-09-10 00:00:00
Activity Status Date: 2016-02-11 17:13:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-09-13 00:00:00
Activity Status Date: 2016-02-11 17:13:08
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-10-01 00:00:00
Activity Status Date: 2016-02-11 17:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-10-18 00:00:00
Activity Status Date: 2016-02-11 17:13:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-02-14 00:00:00
Activity Status Date: 2016-02-11 17:13:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2014-04-23 00:00:00
Activity Status Date: 2016-02-11 17:13:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-05-19 00:00:00
Activity Status Date: 2016-02-11 17:15:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-05-29 00:00:00
Activity Status Date: 2016-02-11 17:13:39
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-09-10 00:00:00
Activity Status Date: 2016-02-11 17:13:53
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-09-26 00:00:00
Activity Status Date: 2016-02-11 17:13:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2014-12-02 00:00:00
Activity Status Date: 2016-02-11 17:14:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-02-11 17:14:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-03-26 00:00:00
Activity Status Date: 2016-02-11 17:15:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-04-23 00:00:00
Activity Status Date: 2016-02-11 17:14:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-08-14 00:00:00
Activity Status Date: 2016-02-11 17:14:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-09-28 00:00:00
Activity Status Date: 2016-02-11 17:14:30
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-10-02 00:00:00
Activity Status Date: 2016-02-11 17:14:31
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2015-10-30 00:00:00
Activity Status Date: 2016-02-11 17:14:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-02-16 00:00:00
Activity Status Date: 2016-02-16 17:15:02
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-03-08 00:00:00
Activity Status Date: 2016-03-09 16:54:09
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-03-17 00:00:00
Activity Status Date: 2016-03-23 18:17:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-06-01 00:00:00
Activity Status Date: 2016-06-15 13:52:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-08-16 00:00:00
Activity Status Date: 2016-08-24 00:33:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2016-09-26 00:00:00
Activity Status Date: 2016-10-05 00:43:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2016-10-03 00:00:00
Activity Status Date: 2016-10-05 00:43:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-12-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2007-12-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2011-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-08-12 00:00:00
Activity Status Date: 1999-08-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-02-04 00:00:00
Activity Status Date: 2000-02-04 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2003-04-07 00:00:00
Activity Status Date: 2003-04-07 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2005-05-06 00:00:00
Activity Status Date: 2005-05-06 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1997-07-09 00:00:00
Activity Status Date: 2016-02-11 16:51:51
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1997-07-30 00:00:00
Activity Status Date: 2016-02-11 16:52:07
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1998-08-28 00:00:00
Activity Status Date: 2016-02-11 16:53:51
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1998-09-11 00:00:00
Activity Status Date: 2016-02-11 16:52:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1998-10-06 00:00:00
Activity Status Date: 2016-02-11 16:54:05
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1998-11-03 00:00:00
Activity Status Date: 2016-02-11 16:52:55
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1999-01-05 00:00:00
Activity Status Date: 2016-02-11 16:53:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1999-03-26 00:00:00
Activity Status Date: 2016-02-11 16:53:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1999-07-20 00:00:00
Activity Status Date: 2016-02-11 16:53:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1999-08-27 00:00:00
Activity Status Date: 2016-02-11 16:53:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 1999-12-17 00:00:00
Activity Status Date: 2016-02-11 16:54:32
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2000-08-15 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2000-08-16 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2000-08-17 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-06-11 00:00:00
Activity Status Date: 2016-02-11 16:58:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-06-28 00:00:00
Activity Status Date: 2016-02-11 17:14:50
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-10-03 00:00:00
Activity Status Date: 2016-02-11 17:14:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-10-03 00:00:00
Activity Status Date: 2016-02-11 17:14:49
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-10-15 00:00:00
Activity Status Date: 2016-02-11 17:14:49
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2002-11-14 00:00:00
Activity Status Date: 2016-02-11 16:59:03
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-03-17 00:00:00
Activity Status Date: 2016-02-11 16:59:32
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-04-10 00:00:00
Activity Status Date: 2016-02-11 17:14:50
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-10-08 00:00:00
Activity Status Date: 2016-02-11 17:14:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-03-05 00:00:00
Activity Status Date: 2016-02-11 17:01:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-06-22 00:00:00
Activity Status Date: 2016-02-11 17:01:47
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-10-14 00:00:00
Activity Status Date: 2016-02-11 17:14:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2004-10-20 00:00:00
Activity Status Date: 2016-02-11 17:14:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-03-17 00:00:00
Activity Status Date: 2016-02-11 17:02:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-04-25 00:00:00
Activity Status Date: 2016-02-11 17:03:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2005-04-27 00:00:00
Activity Status Date: 2016-02-11 17:03:12
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-06-16 00:00:00
Activity Status Date: 2016-02-11 17:03:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-07-12 00:00:00
Activity Status Date: 2016-02-11 17:04:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-11-05 00:00:00
Activity Status Date: 2016-02-11 17:04:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-11-30 00:00:00
Activity Status Date: 2016-02-11 17:04:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-02-01 00:00:00
Activity Status Date: 2016-02-11 17:04:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-02-28 00:00:00
Activity Status Date: 2016-02-11 17:15:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-03-30 00:00:00
Activity Status Date: 2016-02-11 17:04:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-09-11 00:00:00
Activity Status Date: 2016-02-11 17:15:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2006-11-08 00:00:00
Activity Status Date: 2016-02-11 17:15:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-01-24 00:00:00
Activity Status Date: 2016-02-11 17:06:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-03-15 00:00:00
Activity Status Date: 2016-02-11 17:06:16
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-04-16 00:00:00
Activity Status Date: 2016-02-11 17:06:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-04-17 00:00:00
Activity Status Date: 2016-02-11 17:06:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-05-15 00:00:00
Activity Status Date: 2016-02-11 17:07:22
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-08-28 00:00:00
Activity Status Date: 2016-02-11 17:06:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-09-26 00:00:00
Activity Status Date: 2016-02-11 17:07:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-11-15 00:00:00
Activity Status Date: 2016-02-11 17:15:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-02-13 00:00:00
Activity Status Date: 2016-02-11 17:07:37
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2008-03-18 00:00:00
Activity Status Date: 2016-02-11 17:07:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-04-25 00:00:00
Activity Status Date: 2016-02-11 17:07:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-07-09 00:00:00
Activity Status Date: 2016-02-11 17:08:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-07-16 00:00:00
Activity Status Date: 2016-02-11 17:08:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-07-17 00:00:00
Activity Status Date: 2016-02-11 17:08:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-08-11 00:00:00
Activity Status Date: 2016-02-11 17:15:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-10-07 00:00:00
Activity Status Date: 2016-02-11 17:08:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2008-10-14 00:00:00
Activity Status Date: 2016-02-11 17:09:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-01-12 00:00:00
Activity Status Date: 2016-02-11 17:08:45
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-03-20 00:00:00
Activity Status Date: 2016-02-11 17:09:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-03-30 00:00:00
Activity Status Date: 2016-02-11 17:09:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-04-01 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-04-02 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-04-06 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-04-13 00:00:00
Activity Status Date: 2016-02-11 17:15:08
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-04-21 00:00:00
Activity Status Date: 2016-02-11 17:09:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-04-30 00:00:00
Activity Status Date: 2016-02-11 17:09:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-05-28 00:00:00
Activity Status Date: 2016-02-11 17:09:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-08-13 00:00:00
Activity Status Date: 2016-02-11 17:09:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2009-09-21 00:00:00
Activity Status Date: 2016-02-11 17:09:41
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2009-11-04 00:00:00
Activity Status Date: 2016-02-11 17:09:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-01-21 00:00:00
Activity Status Date: 2016-02-11 17:09:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-02-23 00:00:00
Activity Status Date: 2016-02-11 17:10:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-04-14 00:00:00
Activity Status Date: 2016-02-11 17:15:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-06-01 00:00:00
Activity Status Date: 2016-02-11 17:10:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-07-27 00:00:00
Activity Status Date: 2016-02-11 17:10:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-08-09 00:00:00
Activity Status Date: 2016-02-11 17:10:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-08-12 00:00:00
Activity Status Date: 2016-02-11 17:10:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2010-09-27 00:00:00
Activity Status Date: 2016-02-11 17:10:35
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-02-14 00:00:00
Activity Status Date: 2016-02-11 17:10:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-04-13 00:00:00
Activity Status Date: 2016-02-11 17:11:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-04-14 00:00:00
Activity Status Date: 2016-02-11 17:15:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-05-06 00:00:00
Activity Status Date: 2016-02-11 17:11:09
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-05-25 00:00:00
Activity Status Date: 2016-02-11 17:11:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-06-22 00:00:00
Activity Status Date: 2016-02-11 17:11:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-06-30 00:00:00
Activity Status Date: 2016-02-11 17:11:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-07-07 00:00:00
Activity Status Date: 2016-02-11 17:11:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2011-08-01 00:00:00
Activity Status Date: 2016-02-11 17:11:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-08-02 00:00:00
Activity Status Date: 2016-02-11 17:11:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-08-29 00:00:00
Activity Status Date: 2016-02-11 17:11:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-09-13 00:00:00
Activity Status Date: 2016-02-11 17:11:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-10-12 00:00:00
Activity Status Date: 2016-02-11 17:12:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-10-24 00:00:00
Activity Status Date: 2016-02-11 17:11:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2011-11-16 00:00:00
Activity Status Date: 2016-02-11 17:11:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-02-28 00:00:00
Activity Status Date: 2016-02-11 17:11:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-03-30 00:00:00
Activity Status Date: 2016-02-11 17:15:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-04-06 00:00:00
Activity Status Date: 2016-02-11 17:15:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-05-01 00:00:00
Activity Status Date: 2016-02-11 17:11:57
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-05-18 00:00:00
Activity Status Date: 2016-02-11 17:11:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-06-05 00:00:00
Activity Status Date: 2016-02-11 17:12:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-09-24 00:00:00
Activity Status Date: 2016-02-11 17:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2012-12-31 00:00:00
Activity Status Date: 2016-02-11 17:12:27
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-01-02 00:00:00
Activity Status Date: 2016-02-11 17:12:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-02-25 00:00:00
Activity Status Date: 2016-02-11 17:12:37
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-02-28 00:00:00
Activity Status Date: 2016-02-11 17:12:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-03-28 00:00:00
Activity Status Date: 2016-02-11 17:15:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2013-04-10 00:00:00
Activity Status Date: 2016-02-11 17:12:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-04-11 00:00:00
Activity Status Date: 2016-02-11 17:15:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-07-18 00:00:00
Activity Status Date: 2016-02-11 17:13:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-08-22 00:00:00
Activity Status Date: 2016-02-11 17:13:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-09-10 00:00:00
Activity Status Date: 2016-02-11 17:13:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-09-13 00:00:00
Activity Status Date: 2016-02-11 17:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-10-01 00:00:00
Activity Status Date: 2016-02-11 17:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2013-10-18 00:00:00
Activity Status Date: 2016-02-11 17:13:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-02-14 00:00:00
Activity Status Date: 2016-02-11 17:13:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-04-23 00:00:00
Activity Status Date: 2016-02-11 17:13:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-05-19 00:00:00
Activity Status Date: 2016-02-11 17:15:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-05-29 00:00:00
Activity Status Date: 2016-02-11 17:13:39
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-09-10 00:00:00
Activity Status Date: 2016-02-11 17:13:53
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-09-26 00:00:00
Activity Status Date: 2016-02-11 17:13:55
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2014-12-02 00:00:00
Activity Status Date: 2016-02-11 17:14:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-02-11 17:14:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-03-26 00:00:00
Activity Status Date: 2016-02-11 17:15:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2015-04-23 00:00:00
Activity Status Date: 2016-02-11 17:14:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-08-14 00:00:00
Activity Status Date: 2016-02-11 17:14:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-09-28 00:00:00
Activity Status Date: 2016-02-11 17:14:30
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-10-02 00:00:00
Activity Status Date: 2016-02-11 17:14:31
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2015-10-30 00:00:00
Activity Status Date: 2016-02-11 17:14:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-02-16 00:00:00
Activity Status Date: 2016-02-16 17:15:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-03-08 00:00:00
Activity Status Date: 2016-03-09 16:54:09
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-03-17 00:00:00
Activity Status Date: 2016-03-23 18:17:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-06-01 00:00:00
Activity Status Date: 2016-06-15 13:52:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-08-16 00:00:00
Activity Status Date: 2016-08-24 00:33:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-09-26 00:00:00
Activity Status Date: 2016-10-05 00:43:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2016-10-03 00:00:00
Activity Status Date: 2016-10-05 00:43:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1990-09-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1991-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1992-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1992-10-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1993-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1994-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1995-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 1996-09-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-12-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2007-12-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 1999-08-12 00:00:00
Activity Status Date: 1999-08-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2000-02-04 00:00:00
Activity Status Date: 2000-02-04 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2003-04-07 00:00:00
Activity Status Date: 2003-04-07 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: New Source Performance Standards
Activity Date: 2005-05-06 00:00:00
Activity Status Date: 2005-05-06 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Operating Permits
Activity Date: 2007-12-13 00:00:00
Activity Status Date: 2008-03-20 17:03:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Operating Permits
Activity Date: 2011-09-13 00:00:00
Activity Status Date: 2011-09-14 15:50:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1997-07-09 00:00:00
Activity Status Date: 2016-02-11 16:51:51
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1997-07-30 00:00:00
Activity Status Date: 2016-02-11 16:52:07
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-08-28 00:00:00
Activity Status Date: 2016-02-11 16:53:51
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-09-11 00:00:00
Activity Status Date: 2016-02-11 16:52:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-10-06 00:00:00
Activity Status Date: 2016-02-11 16:54:05
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-11-03 00:00:00
Activity Status Date: 2016-02-11 16:52:55
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-01-05 00:00:00
Activity Status Date: 2016-02-11 16:53:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-03-26 00:00:00
Activity Status Date: 2016-02-11 16:53:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-07-20 00:00:00
Activity Status Date: 2016-02-11 16:53:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-08-27 00:00:00
Activity Status Date: 2016-02-11 16:53:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 1999-12-17 00:00:00
Activity Status Date: 2016-02-11 16:54:32
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-08-15 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-08-16 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-08-17 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-06-11 00:00:00
Activity Status Date: 2016-02-11 16:58:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-06-28 00:00:00
Activity Status Date: 2016-02-11 17:14:50
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-10-03 00:00:00
Activity Status Date: 2016-02-11 17:14:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-10-03 00:00:00
Activity Status Date: 2016-02-11 17:14:49
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-10-15 00:00:00
Activity Status Date: 2016-02-11 17:14:49
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-11-14 00:00:00
Activity Status Date: 2016-02-11 16:59:03
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-03-17 00:00:00
Activity Status Date: 2016-02-11 16:59:32
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-04-10 00:00:00
Activity Status Date: 2016-02-11 17:14:50
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-10-08 00:00:00
Activity Status Date: 2016-02-11 17:14:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-03-05 00:00:00
Activity Status Date: 2016-02-11 17:01:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-06-22 00:00:00
Activity Status Date: 2016-02-11 17:01:47
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-10-14 00:00:00
Activity Status Date: 2016-02-11 17:14:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-10-20 00:00:00
Activity Status Date: 2016-02-11 17:14:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-03-17 00:00:00
Activity Status Date: 2016-02-11 17:02:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-04-25 00:00:00
Activity Status Date: 2016-02-11 17:03:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2005-04-27 00:00:00
Activity Status Date: 2016-02-11 17:03:12
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-06-16 00:00:00
Activity Status Date: 2016-02-11 17:03:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-07-12 00:00:00
Activity Status Date: 2016-02-11 17:04:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-11-05 00:00:00
Activity Status Date: 2016-02-11 17:04:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-11-30 00:00:00
Activity Status Date: 2016-02-11 17:04:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-02-01 00:00:00
Activity Status Date: 2016-02-11 17:04:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-02-28 00:00:00
Activity Status Date: 2016-02-11 17:15:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-03-30 00:00:00
Activity Status Date: 2016-02-11 17:04:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-09-11 00:00:00
Activity Status Date: 2016-02-11 17:15:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-11-08 00:00:00
Activity Status Date: 2016-02-11 17:15:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-01-24 00:00:00
Activity Status Date: 2016-02-11 17:06:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-03-15 00:00:00
Activity Status Date: 2016-02-11 17:06:16
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-04-16 00:00:00
Activity Status Date: 2016-02-11 17:06:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-04-17 00:00:00
Activity Status Date: 2016-02-11 17:06:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-05-15 00:00:00
Activity Status Date: 2016-02-11 17:07:22
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-08-28 00:00:00
Activity Status Date: 2016-02-11 17:06:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-09-26 00:00:00
Activity Status Date: 2016-02-11 17:07:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-11-15 00:00:00
Activity Status Date: 2016-02-11 17:15:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-12-13 00:00:00
Activity Status Date: 2008-03-20 17:03:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2008-02-13 00:00:00
Activity Status Date: 2016-02-11 17:07:37
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-03-18 00:00:00
Activity Status Date: 2016-02-11 17:07:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-04-25 00:00:00
Activity Status Date: 2016-02-11 17:07:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-09 00:00:00
Activity Status Date: 2016-02-11 17:08:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-16 00:00:00
Activity Status Date: 2016-02-11 17:08:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-07-17 00:00:00
Activity Status Date: 2016-02-11 17:08:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-08-11 00:00:00
Activity Status Date: 2016-02-11 17:15:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-10-07 00:00:00
Activity Status Date: 2016-02-11 17:08:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-10-14 00:00:00
Activity Status Date: 2016-02-11 17:09:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-01-12 00:00:00
Activity Status Date: 2016-02-11 17:08:45
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-03-20 00:00:00
Activity Status Date: 2016-02-11 17:09:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-03-30 00:00:00
Activity Status Date: 2016-02-11 17:09:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-01 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-02 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-06 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-13 00:00:00
Activity Status Date: 2016-02-11 17:15:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-21 00:00:00
Activity Status Date: 2016-02-11 17:09:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-30 00:00:00
Activity Status Date: 2016-02-11 17:09:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-05-28 00:00:00
Activity Status Date: 2016-02-11 17:09:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2009-08-13 00:00:00
Activity Status Date: 2016-02-11 17:09:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-09-21 00:00:00
Activity Status Date: 2016-02-11 17:09:41
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-11-04 00:00:00
Activity Status Date: 2016-02-11 17:09:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-01-21 00:00:00
Activity Status Date: 2016-02-11 17:09:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-02-23 00:00:00
Activity Status Date: 2016-02-11 17:10:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-04-14 00:00:00
Activity Status Date: 2016-02-11 17:15:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-06-01 00:00:00
Activity Status Date: 2016-02-11 17:10:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-07-27 00:00:00
Activity Status Date: 2016-02-11 17:10:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-08-09 00:00:00
Activity Status Date: 2016-02-11 17:10:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-08-12 00:00:00
Activity Status Date: 2016-02-11 17:10:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-09-27 00:00:00
Activity Status Date: 2016-02-11 17:10:35
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-02-14 00:00:00
Activity Status Date: 2016-02-11 17:10:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-04-13 00:00:00
Activity Status Date: 2016-02-11 17:11:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-04-14 00:00:00
Activity Status Date: 2016-02-11 17:15:14
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-05-06 00:00:00
Activity Status Date: 2016-02-11 17:11:09
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-05-25 00:00:00
Activity Status Date: 2016-02-11 17:11:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-06-22 00:00:00
Activity Status Date: 2016-02-11 17:11:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-06-30 00:00:00
Activity Status Date: 2016-02-11 17:11:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2011-07-07 00:00:00
Activity Status Date: 2016-02-11 17:11:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-08-01 00:00:00
Activity Status Date: 2016-02-11 17:11:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-08-02 00:00:00
Activity Status Date: 2016-02-11 17:11:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-08-29 00:00:00
Activity Status Date: 2016-02-11 17:11:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-09-13 00:00:00
Activity Status Date: 2016-02-11 17:11:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-10-12 00:00:00
Activity Status Date: 2016-02-11 17:12:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-10-24 00:00:00
Activity Status Date: 2016-02-11 17:11:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-11-16 00:00:00
Activity Status Date: 2016-02-11 17:11:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-02-28 00:00:00
Activity Status Date: 2016-02-11 17:11:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-03-30 00:00:00
Activity Status Date: 2016-02-11 17:15:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-04-06 00:00:00
Activity Status Date: 2016-02-11 17:15:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-05-01 00:00:00
Activity Status Date: 2016-02-11 17:11:57
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-05-18 00:00:00
Activity Status Date: 2016-02-11 17:11:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-06-05 00:00:00
Activity Status Date: 2016-02-11 17:12:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-09-24 00:00:00
Activity Status Date: 2016-02-11 17:12:17
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-12-31 00:00:00
Activity Status Date: 2016-02-11 17:12:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-01-02 00:00:00
Activity Status Date: 2016-02-11 17:12:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-02-25 00:00:00
Activity Status Date: 2016-02-11 17:12:37
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-02-28 00:00:00
Activity Status Date: 2016-02-11 17:12:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2013-03-28 00:00:00
Activity Status Date: 2016-02-11 17:15:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-04-10 00:00:00
Activity Status Date: 2016-02-11 17:12:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-04-11 00:00:00
Activity Status Date: 2016-02-11 17:15:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-07-18 00:00:00
Activity Status Date: 2016-02-11 17:13:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-08-22 00:00:00
Activity Status Date: 2016-02-11 17:13:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-09-10 00:00:00
Activity Status Date: 2016-02-11 17:13:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-09-13 00:00:00
Activity Status Date: 2016-02-11 17:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-10-01 00:00:00
Activity Status Date: 2016-02-11 17:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-10-18 00:00:00
Activity Status Date: 2016-02-11 17:13:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-02-14 00:00:00
Activity Status Date: 2016-02-11 17:13:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-04-23 00:00:00
Activity Status Date: 2016-02-11 17:13:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-05-19 00:00:00
Activity Status Date: 2016-02-11 17:15:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-05-29 00:00:00
Activity Status Date: 2016-02-11 17:13:39
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-09-10 00:00:00
Activity Status Date: 2016-02-11 17:13:53
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-09-26 00:00:00
Activity Status Date: 2016-02-11 17:13:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-12-02 00:00:00
Activity Status Date: 2016-02-11 17:14:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-02-11 17:14:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-03-26 00:00:00
Activity Status Date: 2016-02-11 17:15:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2015-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-04-23 00:00:00
Activity Status Date: 2016-02-11 17:14:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-08-14 00:00:00
Activity Status Date: 2016-02-11 17:14:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-09-28 00:00:00
Activity Status Date: 2016-02-11 17:14:30
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-10-02 00:00:00
Activity Status Date: 2016-02-11 17:14:31
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-10-30 00:00:00
Activity Status Date: 2016-02-11 17:14:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-02-16 00:00:00
Activity Status Date: 2016-02-16 17:15:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-03-08 00:00:00
Activity Status Date: 2016-03-09 16:54:09
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-03-17 00:00:00
Activity Status Date: 2016-03-23 18:17:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-06-01 00:00:00
Activity Status Date: 2016-06-15 13:52:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-08-16 00:00:00
Activity Status Date: 2016-08-24 00:33:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-09-26 00:00:00
Activity Status Date: 2016-10-05 00:43:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-10-03 00:00:00
Activity Status Date: 2016-10-05 00:43:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-05-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-09-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-06-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-05-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-10-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 1986-05-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-11-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-05-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-11-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-01-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-06-29 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-11-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-07-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-09-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-10-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1993-09-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1994-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1995-09-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1996-09-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-12-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2007-12-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-06-03 00:00:00
Activity Status Date: 1988-06-03 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 1988-06-20 00:00:00
Activity Status Date: 1988-06-20 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-07-12 00:00:00
Activity Status Date: 1988-07-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-07-12 00:00:00
Activity Status Date: 1989-07-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-05-31 00:00:00
Activity Status Date: 1991-05-31 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-10-08 00:00:00
Activity Status Date: 1991-10-08 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-04-03 00:00:00
Activity Status Date: 1992-04-03 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-02-08 00:00:00
Activity Status Date: 1990-02-08 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-05-01 00:00:00
Activity Status Date: 1991-05-01 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-01-14 00:00:00
Activity Status Date: 1992-01-14 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-08-12 00:00:00
Activity Status Date: 1999-08-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-02-04 00:00:00
Activity Status Date: 2000-02-04 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-04-07 00:00:00
Activity Status Date: 2003-04-07 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-05-06 00:00:00
Activity Status Date: 2005-05-06 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1997-07-09 00:00:00
Activity Status Date: 2016-02-11 16:51:51
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1997-07-30 00:00:00
Activity Status Date: 2016-02-11 16:52:07
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits
Activity Date:	1998-08-28 00:00:00
Activity Status Date:	2016-02-11 16:53:51
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits
Activity Date:	1998-09-11 00:00:00
Activity Status Date:	2016-02-11 16:52:46
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits
Activity Date:	1998-10-06 00:00:00
Activity Status Date:	2016-02-11 16:54:05
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits
Activity Date:	1998-11-03 00:00:00
Activity Status Date:	2016-02-11 16:52:55
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Active
Region Code:	03
Programmatic ID:	AIR PA000483776
Facility Registry ID:	110005981928
Air Operating Status Code:	OPR
Default Air Classification Code:	MAJ
Air Program:	Title V Permits

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 1999-01-05 00:00:00
Activity Status Date: 2016-02-11 16:53:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1999-03-26 00:00:00
Activity Status Date: 2016-02-11 16:53:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1999-07-20 00:00:00
Activity Status Date: 2016-02-11 16:53:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1999-08-27 00:00:00
Activity Status Date: 2016-02-11 16:53:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1999-12-17 00:00:00
Activity Status Date: 2016-02-11 16:54:32
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-08-15 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-08-16 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-08-17 00:00:00
Activity Status Date: 2016-02-11 16:55:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-06-11 00:00:00
Activity Status Date: 2016-02-11 16:58:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-06-28 00:00:00
Activity Status Date: 2016-02-11 17:14:50
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-10-03 00:00:00
Activity Status Date: 2016-02-11 17:14:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-10-03 00:00:00
Activity Status Date: 2016-02-11 17:14:49
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-10-15 00:00:00
Activity Status Date: 2016-02-11 17:14:49
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2002-11-14 00:00:00
Activity Status Date: 2016-02-11 16:59:03
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-03-17 00:00:00
Activity Status Date: 2016-02-11 16:59:32
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-04-10 00:00:00
Activity Status Date: 2016-02-11 17:14:50
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-10-08 00:00:00
Activity Status Date: 2016-02-11 17:14:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-03-05 00:00:00
Activity Status Date: 2016-02-11 17:01:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-06-22 00:00:00
Activity Status Date: 2016-02-11 17:01:47
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2004-10-14 00:00:00
Activity Status Date: 2016-02-11 17:14:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2004-10-20 00:00:00
Activity Status Date: 2016-02-11 17:14:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-03-17 00:00:00
Activity Status Date: 2016-02-11 17:02:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-04-25 00:00:00
Activity Status Date: 2016-02-11 17:03:52
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-04-27 00:00:00
Activity Status Date: 2016-02-11 17:03:12
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-06-16 00:00:00
Activity Status Date: 2016-02-11 17:03:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-07-12 00:00:00
Activity Status Date: 2016-02-11 17:04:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-11-05 00:00:00
Activity Status Date: 2016-02-11 17:04:43
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-11-30 00:00:00
Activity Status Date: 2016-02-11 17:04:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-02-01 00:00:00
Activity Status Date: 2016-02-11 17:04:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-02-28 00:00:00
Activity Status Date: 2016-02-11 17:15:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-03-30 00:00:00
Activity Status Date: 2016-02-11 17:04:58
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-09-11 00:00:00
Activity Status Date: 2016-02-11 17:15:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2006-11-08 00:00:00
Activity Status Date: 2016-02-11 17:15:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-01-24 00:00:00
Activity Status Date: 2016-02-11 17:06:19
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-03-15 00:00:00
Activity Status Date: 2016-02-11 17:06:16
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-04-16 00:00:00
Activity Status Date: 2016-02-11 17:06:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-04-17 00:00:00
Activity Status Date: 2016-02-11 17:06:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-05-15 00:00:00
Activity Status Date: 2016-02-11 17:07:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2007-08-28 00:00:00
Activity Status Date: 2016-02-11 17:06:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-09-26 00:00:00
Activity Status Date: 2016-02-11 17:07:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-11-15 00:00:00
Activity Status Date: 2016-02-11 17:15:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-02-13 00:00:00
Activity Status Date: 2016-02-11 17:07:37
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-03-18 00:00:00
Activity Status Date: 2016-02-11 17:07:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-04-25 00:00:00
Activity Status Date: 2016-02-11 17:07:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-07-09 00:00:00
Activity Status Date: 2016-02-11 17:08:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-07-16 00:00:00
Activity Status Date: 2016-02-11 17:08:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-07-17 00:00:00
Activity Status Date: 2016-02-11 17:08:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-08-11 00:00:00
Activity Status Date: 2016-02-11 17:15:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-10-07 00:00:00
Activity Status Date: 2016-02-11 17:08:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2008-10-14 00:00:00
Activity Status Date: 2016-02-11 17:09:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-01-12 00:00:00
Activity Status Date: 2016-02-11 17:08:45
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-03-20 00:00:00
Activity Status Date: 2016-02-11 17:09:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-03-30 00:00:00
Activity Status Date: 2016-02-11 17:09:04
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-04-01 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-04-02 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-04-06 00:00:00
Activity Status Date: 2016-02-11 17:09:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-04-13 00:00:00
Activity Status Date: 2016-02-11 17:15:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2009-04-21 00:00:00
Activity Status Date: 2016-02-11 17:09:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-04-30 00:00:00
Activity Status Date: 2016-02-11 17:09:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-05-28 00:00:00
Activity Status Date: 2016-02-11 17:09:21
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-08-13 00:00:00
Activity Status Date: 2016-02-11 17:09:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-09-21 00:00:00
Activity Status Date: 2016-02-11 17:09:41
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2009-11-04 00:00:00
Activity Status Date: 2016-02-11 17:09:46
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-01-21 00:00:00
Activity Status Date: 2016-02-11 17:09:56
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-02-23 00:00:00
Activity Status Date: 2016-02-11 17:10:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-04-14 00:00:00
Activity Status Date: 2016-02-11 17:15:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-06-01 00:00:00
Activity Status Date: 2016-02-11 17:10:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-07-27 00:00:00
Activity Status Date: 2016-02-11 17:10:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-08-09 00:00:00
Activity Status Date: 2016-02-11 17:10:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-08-12 00:00:00
Activity Status Date: 2016-02-11 17:10:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2010-09-27 00:00:00
Activity Status Date: 2016-02-11 17:10:35
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-02-14 00:00:00
Activity Status Date: 2016-02-11 17:10:52
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-04-13 00:00:00
Activity Status Date: 2016-02-11 17:11:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-04-14 00:00:00
Activity Status Date: 2016-02-11 17:15:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-05-06 00:00:00
Activity Status Date: 2016-02-11 17:11:09
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2011-05-25 00:00:00
Activity Status Date: 2016-02-11 17:11:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-06-22 00:00:00
Activity Status Date: 2016-02-11 17:11:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-06-30 00:00:00
Activity Status Date: 2016-02-11 17:11:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-07-07 00:00:00
Activity Status Date: 2016-02-11 17:11:19
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-08-01 00:00:00
Activity Status Date: 2016-02-11 17:11:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-08-02 00:00:00
Activity Status Date: 2016-02-11 17:11:22
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-08-29 00:00:00
Activity Status Date: 2016-02-11 17:11:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-09-13 00:00:00
Activity Status Date: 2016-02-11 17:11:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-10-12 00:00:00
Activity Status Date: 2016-02-11 17:12:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-10-24 00:00:00
Activity Status Date: 2016-02-11 17:11:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-11-16 00:00:00
Activity Status Date: 2016-02-11 17:11:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-02-28 00:00:00
Activity Status Date: 2016-02-11 17:11:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-03-30 00:00:00
Activity Status Date: 2016-02-11 17:15:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-04-06 00:00:00
Activity Status Date: 2016-02-11 17:15:18
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-05-01 00:00:00
Activity Status Date: 2016-02-11 17:11:57
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-05-18 00:00:00
Activity Status Date: 2016-02-11 17:11:59
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-06-05 00:00:00
Activity Status Date: 2016-02-11 17:12:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-09-24 00:00:00
Activity Status Date: 2016-02-11 17:12:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-12-31 00:00:00
Activity Status Date: 2016-02-11 17:12:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2013-01-02 00:00:00
Activity Status Date: 2016-02-11 17:12:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-02-25 00:00:00
Activity Status Date: 2016-02-11 17:12:37
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-02-28 00:00:00
Activity Status Date: 2016-02-11 17:12:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-03-28 00:00:00
Activity Status Date: 2016-02-11 17:15:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-04-10 00:00:00
Activity Status Date: 2016-02-11 17:12:48
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-04-11 00:00:00
Activity Status Date: 2016-02-11 17:15:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-07-18 00:00:00
Activity Status Date: 2016-02-11 17:13:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-08-22 00:00:00
Activity Status Date: 2016-02-11 17:13:04
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-09-10 00:00:00
Activity Status Date: 2016-02-11 17:13:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-09-13 00:00:00
Activity Status Date: 2016-02-11 17:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-10-01 00:00:00
Activity Status Date: 2016-02-11 17:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-10-18 00:00:00
Activity Status Date: 2016-02-11 17:13:10
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-02-14 00:00:00
Activity Status Date: 2016-02-11 17:13:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-04-23 00:00:00
Activity Status Date: 2016-02-11 17:13:34
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-05-19 00:00:00
Activity Status Date: 2016-02-11 17:15:29
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-05-29 00:00:00
Activity Status Date: 2016-02-11 17:13:39
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-09-10 00:00:00
Activity Status Date: 2016-02-11 17:13:53
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2014-09-26 00:00:00
Activity Status Date: 2016-02-11 17:13:55
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2014-12-02 00:00:00
Activity Status Date: 2016-02-11 17:14:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-02-04 00:00:00
Activity Status Date: 2016-02-11 17:14:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-03-26 00:00:00
Activity Status Date: 2016-02-11 17:15:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-03-31 00:00:00
Activity Status Date: 2016-02-11 17:15:33
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-04-23 00:00:00
Activity Status Date: 2016-02-11 17:14:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-08-14 00:00:00
Activity Status Date: 2016-02-11 17:14:26
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-09-28 00:00:00
Activity Status Date: 2016-02-11 17:14:30
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-10-02 00:00:00
Activity Status Date: 2016-02-11 17:14:31
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-10-30 00:00:00
Activity Status Date: 2016-02-11 17:14:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-02-16 00:00:00
Activity Status Date: 2016-02-16 17:15:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-03-08 00:00:00
Activity Status Date: 2016-03-09 16:54:09
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-03-17 00:00:00
Activity Status Date: 2016-03-23 18:17:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-06-01 00:00:00
Activity Status Date: 2016-06-15 13:52:34
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-08-16 00:00:00
Activity Status Date: 2016-08-24 00:33:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-09-26 00:00:00
Activity Status Date: 2016-10-05 00:43:04
Activity Group: Compliance Monitoring

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-10-03 00:00:00
Activity Status Date: 2016-10-05 00:43:11
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-12-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2007-12-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2011-08-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Activity Date: 2011-09-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 1999-08-12 00:00:00
Activity Status Date: 1999-08-12 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2000-02-04 00:00:00
Activity Status Date: 2000-02-04 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2003-04-07 00:00:00
Activity Status Date: 2003-04-07 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 03
Programmatic ID: AIR PA000483776
Facility Registry ID: 110005981928
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2005-05-06 00:00:00
Activity Status Date: 2005-05-06 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

FINDS:

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Registry ID: 110059230112

Environmental Interest/Information System
TSCA SUBMITTER

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000208280
Registry ID:	110059230112
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110059230112

Manifest Details:

Year:	2006
Manifest Number:	000011373FLE
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	09/15/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD002395887
TSD Date:	Not reported
TSD Facility Name:	HORSEHEAD RESOURCE DEVELOPMENT CO INC
TSD Facility Address:	900 DELAWARE AVENUE
TSD Facility City:	PALMERTON
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	K061
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	37360
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Year:	2006
Manifest Number:	000011761FLE
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	11/03/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD002395887
TSD Date:	Not reported
TSD Facility Name:	HORSEHEAD RESOURCE DEVELOPMENT CO INC
TSD Facility Address:	900 DELAWARE AVENUE
TSD Facility City:	PALMERTON
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	K061
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	36660
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	000011762FLE
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	10/18/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD002395887
TSD Date:	Not reported
TSD Facility Name:	HORSEHEAD RESOURCE DEVELOPMENT CO INC
TSD Facility Address:	900 DELAWARE AVENUE
TSD Facility City:	PALMERTON
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	D006
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	36840
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	000011763FLE
Manifest Type:	TSD Copy

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Generator EPA Id:	PAD002326908
Generator Date:	10/17/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD002395887
TSD Date:	Not reported
TSD Facility Name:	HORSEHEAD RESOURCE DEVELOPMENT CO INC
TSD Facility Address:	900 DELAWARE AVENUE
TSD Facility City:	PALMERTON
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	K061
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	34780
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	000011764FLE
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	10/11/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD002395887
TSD Date:	Not reported
TSD Facility Name:	HORSEHEAD RESOURCE DEVELOPMENT CO INC
TSD Facility Address:	900 DELAWARE AVENUE
TSD Facility City:	PALMERTON
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	38400
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	000011766FLE
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	10/09/2006
Mailing Address:	Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD002395887
TSD Date:	Not reported
TSD Facility Name:	HORSEHEAD RESOURCE DEVELOPMENT CO INC
TSD Facility Address:	900 DELAWARE AVENUE
TSD Facility City:	PALMERTON
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	41420
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	000011769FLE
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	10/06/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD002395887
TSD Date:	Not reported
TSD Facility Name:	HORSEHEAD RESOURCE DEVELOPMENT CO INC
TSD Facility Address:	900 DELAWARE AVENUE
TSD Facility City:	PALMERTON
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	K061
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	39140
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2006
Manifest Number:	000011771FLE
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	10/10/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

TSD EPA Id:	PAD002395887
TSD Date:	Not reported
TSD Facility Name:	HORSEHEAD RESOURCE DEVELOPMENT CO INC
TSD Facility Address:	900 DELAWARE AVENUE
TSD Facility City:	PALMERTON
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	D006
Container Number:	1
Container Type:	Cargo tanks (tank trucks)
Waste Quantity:	39220
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2006
Manifest Number:	000011779FLE
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	09/19/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD010154045
TSD Date:	Not reported
TSD Facility Name:	ENVIRITE OF PENNSYLVANIA INC
TSD Facility Address:	730 VOGELSONG ROAD
TSD Facility City:	YORK
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	1
Waste Number:	D007
Container Number:	1
Container Type:	Metal boxes, cartons, cases (including roll-offs)
Waste Quantity:	8500
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2006
Manifest Number:	000341314JJK
Manifest Type:	TSD Copy
Generator EPA Id:	PAD002326908
Generator Date:	11/20/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	610-383-2000
Page Number:	1
Line Number:	2
Waste Number:	NONE
Container Number:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	750
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access
2361 additional PA_MANIFEST: record(s) in the EDR Site Report.

RI MANIFEST:

EPA Id:	PAD002326908
GEN Cert Date:	1/26/2009
Manifest Document Number:	001349075SKS
Waste Description:	USED CLEANING COMPOUNDS NOIBN
TSDF Id:	Not reported
TSDF Name:	Not reported
Qty:	75
WT/Vol Units:	G
TSDF Date:	Not reported
Transporter 2 Id:	NJD071629976
Item Number:	1
Transporter 2 Name:	2/5/2009
Transporter Name 2:	SAFETY KLEEN
Transporter EPAID:	TXR000050930
Transporter Receipt Date:	1/26/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	3/24/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001788843SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	75
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	3/24/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	3/27/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

Transporter Receipt Date:	4/20/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001788974SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	62
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/20/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	4/24/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

Transporter Receipt Date:	6/15/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001813269SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	75
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	6/15/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	6/19/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/24/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001356277SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	25
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/24/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	3/6/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	6/15/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001813269SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	75
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	6/15/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	6/19/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/24/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001356277SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Transporter Contact Name:	Not reported
Quantity:	25
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/24/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	3/6/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/26/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001349075SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	75
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/26/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	2/5/2009

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	3/24/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001788843SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	75
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	3/24/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	3/27/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	4/20/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001788974SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	62
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/20/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	4/24/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/26/2009
Number Of Containers:	3
Container Type:	DM
Waste Code1:	R015
Waste Code2:	Not reported
Waste Code3:	Not reported
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	Not reported
TSDF Id:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	PAD002326908
Manifest Docket Number:	001349075SKS
Quarter:	Not reported
Waste Description:	USED CLEANING COMPOUNDS NOIBN
Transporter Contact Name:	Not reported
Quantity:	75
Transporter Contact Email:	Not reported
WT/Vol Units:	G
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1

ARCELORMITTAL PLATE LLC (Continued) **1000208280**

Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/26/2009
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	2/5/2009
Manifest Created Date:	Not reported
TSDF Receipt Date:	Not reported
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

Click this hyperlink while viewing on your computer to access additional RI_MANIFEST: detail in the EDR Site Report.

NPDES:

Permit Number:	PAR600113
Permit Name:	SMS MILL SVC COATESVILLE LLC
Effective Date:	09/01/2015
Expiration Date:	08/31/2020
Receiving Waters:	West Branch Brandywine Creek
Current Major Minor Status:	Minor
Total App. Design Flow (MGD):	0
Cognizant Official:	Not reported
Cognizant Official Telephone:	Not reported
Permit Street Address:	P.O. BOX 2859
Permit City/State/Zip:	CHESTERTON, IN 46304

Permit Number:	PAR800076
Permit Name:	MITTAL STEEL USA RAILWAYS INC
Effective Date:	09/01/2012
Expiration Date:	08/31/2017
Receiving Waters:	West Branch Brandywine Creek
Current Major Minor Status:	Minor
Total App. Design Flow (MGD):	Not reported
Cognizant Official:	Not reported
Cognizant Official Telephone:	Not reported
Permit Street Address:	139 MODENA ROAD
Permit City/State/Zip:	COATESVILLE, PA 19320

Permit Number:	PA0011568
Permit Name:	ARCELORMITTAL PLATE LLC
Effective Date:	12/01/2015
Expiration Date:	11/30/2020
Receiving Waters:	Not reported
Current Major Minor Status:	Major
Total App. Design Flow (MGD):	0.9729
Cognizant Official:	RAY AJALLI/MANAGER
Cognizant Official Telephone:	610-383-2097
Permit Street Address:	139 MODENA RD
Permit City/State/Zip:	COATESVILLE, PA 19320-4036

Count: 1 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SOUTH COATESVILLE	1003865787	SOUTH COATESVILLE FILL	MODENA RD	19320	SEMS-ARCHIVE

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/27/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 11/27/2018
Next Scheduled EDR Contact: 01/14/2019
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/27/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 11/27/2018
Next Scheduled EDR Contact: 01/14/2019
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/27/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 11/27/2018
Next Scheduled EDR Contact: 01/14/2019
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/06/2018
Next Scheduled EDR Contact: 10/15/2018
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/27/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 10

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 11/27/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 11/14/2018
Date Data Arrived at EDR: 11/28/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 9

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 11/28/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 10/17/2018
Date Data Arrived at EDR: 10/25/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 43

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 10/15/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 07/31/2018
Date Data Arrived at EDR: 08/28/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/28/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 07/31/2018
Date Data Arrived at EDR: 08/28/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/28/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/24/2018
Date Data Arrived at EDR: 09/25/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 45

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 09/25/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

State- and tribal - equivalent NPL

SHWS: Hazardous Sites Cleanup Act Site List

The Hazardous Sites Cleanup Act Site List includes sites listed on PA Priority List, sites delisted from PA Priority List, Interim Response Completed sites, and Sites Being Studied or Response Being Planned.

Date of Government Version: 10/16/2018
Date Data Arrived at EDR: 10/17/2018
Date Made Active in Reports: 11/27/2018
Number of Days to Update: 41

Source: Department Environmental Protection
Telephone: 717-783-7816
Last EDR Contact: 10/17/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Quarterly

HSCA: HSCA Remedial Sites Listing

A list of remedial sites on the PA Priority List. This is the PA state equivalent of the federal NPL superfund list.

Date of Government Version: 08/01/2017
Date Data Arrived at EDR: 01/23/2018
Date Made Active in Reports: 02/05/2018
Number of Days to Update: 13

Source: Department of Environmental Protection
Telephone: 717-783-7816
Last EDR Contact: 10/19/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Operating Facilities

The listing includes Municipal Waste Landfills, Construction/Demolition Waste Landfills and Waste-to-Energy Facilities.

Date of Government Version: 08/21/2018
Date Data Arrived at EDR: 08/22/2018
Date Made Active in Reports: 09/26/2018
Number of Days to Update: 35

Source: Department of Environmental Protection
Telephone: 717-787-7564
Last EDR Contact: 11/19/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LUST: Storage Tank Release Sites

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 09/10/2018
Date Data Arrived at EDR: 09/13/2018
Date Made Active in Reports: 09/26/2018
Number of Days to Update: 13

Source: Department of Environmental Protection
Telephone: 717-783-7509
Last EDR Contact: 09/13/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Quarterly

LAST: Storage Tank Release Sites

Leaking Aboveground Storage Tank Incident Reports.

Date of Government Version: 09/10/2018
Date Data Arrived at EDR: 09/13/2018
Date Made Active in Reports: 09/26/2018
Number of Days to Update: 13

Source: Department of Environmental Protection
Telephone: 717-783-7509
Last EDR Contact: 09/13/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Quarterly

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/10/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/25/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/24/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/01/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/08/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

UNREG LTANKS: Unregulated Tank Cases
Leaking storage tank cases from unregulated storage tanks.

Date of Government Version: 04/12/2002
Date Data Arrived at EDR: 08/14/2003
Date Made Active in Reports: 08/29/2003
Number of Days to Update: 15
Source: Department of Environmental Protection
Telephone: 717-783-7509
Last EDR Contact: 08/14/2003
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 10/10/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Varies

UST: Listing of Pennsylvania Regulated Underground Storage Tanks
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 09/04/2018
Date Data Arrived at EDR: 09/13/2018
Date Made Active in Reports: 09/27/2018
Number of Days to Update: 14
Source: Department of Environmental Protection
Telephone: 717-772-5599
Last EDR Contact: 09/13/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Varies

AST: Listing of Pennsylvania Regulated Aboveground Storage Tanks
Registered Aboveground Storage Tanks.

Date of Government Version: 09/04/2018
Date Data Arrived at EDR: 09/13/2018
Date Made Active in Reports: 09/27/2018
Number of Days to Update: 14
Source: Department of Environmental Protection
Telephone: 717-772-5599
Last EDR Contact: 09/13/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/25/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/01/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/08/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/10/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/24/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Engineering Controls Site Listing

Under the Land Recycling Act (Act 2) persons who perform a site cleanup using the site-specific standard or the special industrial area standard may use engineering or institutional controls as part of the response action. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/15/2008
Date Data Arrived at EDR: 05/16/2008
Date Made Active in Reports: 06/12/2008
Number of Days to Update: 27

Source: Department of Environmental Protection
Telephone: 717-783-9470
Last EDR Contact: 10/16/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: No Update Planned

INST CONTROL: Institutional Controls Site Listing

Under the Land Recycling Act (Act 2) persons who perform a site cleanup using the site-specific standard or the special industrial area standard may use engineering or institutional controls as part of the response action. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/15/2008
Date Data Arrived at EDR: 05/16/2008
Date Made Active in Reports: 06/12/2008
Number of Days to Update: 27

Source: Department of Environmental Protection
Telephone: 717-783-9470
Last EDR Contact: 10/16/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: No Update Planned

AUL: Environmental Covenants Listing

A listing of sites with environmental covenants.

Date of Government Version: 10/16/2018
Date Data Arrived at EDR: 10/17/2018
Date Made Active in Reports: 11/27/2018
Number of Days to Update: 41

Source: Department of Environmental Protection
Telephone: 717-783-7509
Last EDR Contact: 10/17/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Program Sites

The VCP listings included Completed Sites, Sites in Progress and Act 2 Non-Use Aquifer Determinations Sites. Formerly known as the Act 2, the Land Recycling Program encourages the voluntary cleanup and reuse of contaminated commercial and industrial sites.

Date of Government Version: 10/09/2018
Date Data Arrived at EDR: 10/11/2018
Date Made Active in Reports: 10/22/2018
Number of Days to Update: 11
Source: Department of Environmental Protection
Telephone: 717-783-2388
Last EDR Contact: 10/11/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142
Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 09/24/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27
Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Sites
Brownfields are generally defined as abandoned or underused industrial or commercial properties where redevelopment is complicated by actual or perceived environmental contamination. Brownfields vary in size, location, age and past use. They can range from a small, abandoned corner gas station to a large, multi-acre former manufacturing plant that has been closed for years.

Date of Government Version: 10/16/2018
Date Data Arrived at EDR: 10/17/2018
Date Made Active in Reports: 11/28/2018
Number of Days to Update: 42
Source: Department of Environmental Protection
Telephone: 717-783-1566
Last EDR Contact: 10/17/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/18/2018
Date Data Arrived at EDR: 09/18/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 52
Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/18/2018
Next Scheduled EDR Contact: 12/31/2018
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

HIST LF INVENTORY: Facility Inventory

A listing of solid waste facilities. This listing is no longer updated or maintained by the Department of Environmental Protection. At the time the listing was available, the DEP?s name was the Department of Environmental Resources.

Date of Government Version: 06/02/1999
Date Data Arrived at EDR: 07/12/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 30

Source: Department of Environmental Protection
Telephone: 717-787-7381
Last EDR Contact: 09/19/2005
Next Scheduled EDR Contact: 12/19/2005
Data Release Frequency: No Update Planned

HIST LF INACTIVE: Inactive Facilities List

A listing of inactive non-hazardous facilities (10000 & 300000 series). This listing is no longer updated or maintained by the Department of Environmental Protection. At the time the listing was available, the DEP?s name was the Department of Environmental Resources.

Date of Government Version: 12/20/1994
Date Data Arrived at EDR: 07/12/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 30

Source: Department of Environmental Protection
Telephone: 717-787-7381
Last EDR Contact: 06/21/2005
Next Scheduled EDR Contact: 12/19/2005
Data Release Frequency: No Update Planned

HIST LF ALI: Abandoned Landfill Inventory

The report provides facility information recorded in the Pennsylvania Department of Environmental Protection ALI database. Some of this information has been abstracted from old records and may not accurately reflect the current conditions and status at these facilities

Date of Government Version: 01/04/2005
Date Data Arrived at EDR: 01/04/2005
Date Made Active in Reports: 02/04/2005
Number of Days to Update: 31

Source: Department of Environmental Protection
Telephone: 717-787-7564
Last EDR Contact: 11/26/2012
Next Scheduled EDR Contact: 03/11/2013
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 10/25/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 10/22/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 11/02/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 09/21/2018
Date Data Arrived at EDR: 09/21/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 49

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/26/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: No Update Planned

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/21/2018
Date Data Arrived at EDR: 09/21/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 49

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/26/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

ARCHIVE UST: Archived Underground Storage Tank Sites

The list includes tanks storing highly hazardous substances that were removed from the DEP's Storage Tank Information database because of the Department's policy on sensitive information. The list also may include tanks that are removed or permanently closed.

Date of Government Version: 09/04/2018
Date Data Arrived at EDR: 09/13/2018
Date Made Active in Reports: 09/27/2018
Number of Days to Update: 14

Source: Department of Environmental Protection
Telephone: 717-772-5599
Last EDR Contact: 09/13/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Varies

ARCHIVE AST: Archived Aboveground Storage Tank Sites

The list includes aboveground tanks with a capacity greater than 21,000 gallons that were removed from the DEP's Storage Tank Information database because of the Department's policy on sensitive information. The list also may include tanks that are removed or permanently closed.

Date of Government Version: 09/04/2018
Date Data Arrived at EDR: 09/13/2018
Date Made Active in Reports: 09/27/2018
Number of Days to Update: 14

Source: Department of Environmental Protection
Telephone: 717-772-5599
Last EDR Contact: 09/13/2018
Next Scheduled EDR Contact: 12/24/2018
Data Release Frequency: Varies

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/16/2018
Number of Days to Update: 43

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 11/27/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Semi-Annually

ACT 2-DEED: Act 2-Deed Acknowledgment Sites

This listing pertains to sites where the Department has approved a cleanup requiring a deed acknowledgment under Act 2. This list includes sites remediated to a non-residential Statewide health standard (Section 303(g)); all sites demonstrating attainment of a Site-specific standard (Section 304(m)); and sites being remediated as a special industrial area (Section 305(g)). Persons who remediated a site to a standard that requires a deed acknowledgment shall comply with the requirements of the Solid Waste Management Act or the Hazardous Sites Cleanup Act, as referenced in Act 2. These statutes require a property description section in the deed concerning the hazardous substance disposal on the site. The location of disposed hazardous substances and a description of the type of hazardous substances disposed on the site shall be included in the deed acknowledgment. A deed acknowledgment is required at the time of conveyance of the property.

Date of Government Version: 04/23/2010
Date Data Arrived at EDR: 04/28/2010
Date Made Active in Reports: 04/30/2010
Number of Days to Update: 2

Source: Department of Environmental Protection
Telephone: 717-783-9470
Last EDR Contact: 07/22/2011
Next Scheduled EDR Contact: 11/07/2011
Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/26/2018
Date Data Arrived at EDR: 03/27/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 73

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 09/25/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

SPILLS: State spills

A listing of hazardous material incidents.

Date of Government Version: 07/01/2018
Date Data Arrived at EDR: 07/10/2018
Date Made Active in Reports: 08/15/2018
Number of Days to Update: 36

Source: DEP, Emergency Response
Telephone: 717-787-5715
Last EDR Contact: 11/05/2018
Next Scheduled EDR Contact: 10/22/2018
Data Release Frequency: Semi-Annually

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 800-438-2474
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 11/19/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/12/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/12/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/16/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 08/31/2018
Date Data Arrived at EDR: 09/25/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 45

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 09/25/2018
Next Scheduled EDR Contact: 01/07/2019
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 11/05/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 11/09/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/21/2018
Next Scheduled EDR Contact: 12/31/2018
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/16/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/24/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/16/2018
Number of Days to Update: 43

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 11/27/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 08/01/2018
Date Data Arrived at EDR: 08/22/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 10/23/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 36

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 10/04/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/14/2018
Date Data Arrived at EDR: 10/11/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 57

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 10/11/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 10/09/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 10/11/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 12/05/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 12/03/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 10/26/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 10/02/2018
Date Data Arrived at EDR: 10/03/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 10/03/2018
Next Scheduled EDR Contact: 01/14/2019
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 10/30/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2018
Date Data Arrived at EDR: 10/12/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 56

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 10/01/2018
Next Scheduled EDR Contact: 12/31/2018
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 11/21/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 10/09/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 11/01/2018
Next Scheduled EDR Contact: 02/18/2019
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/16/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/16/2018
Number of Days to Update: 43

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 11/27/2018
Next Scheduled EDR Contact: 01/14/2019
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/01/2018
Date Data Arrived at EDR: 08/29/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 37

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/10/2018
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 12/06/2018
Next Scheduled EDR Contact: 03/25/2019
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 08/07/2018
Date Data Arrived at EDR: 09/05/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 30

Source: EPA
Telephone: (215) 814-5000
Last EDR Contact: 12/05/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 06/19/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 87

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 10/15/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/02/2018
Date Data Arrived at EDR: 09/05/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 9

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 12/31/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/11/2019
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 08/22/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 44

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 11/19/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Quarterly

AIRS: Permit and Emissions Inventory Data

Permit and emissions inventory data.

Date of Government Version: 09/18/2018
Date Data Arrived at EDR: 09/19/2018
Date Made Active in Reports: 10/22/2018
Number of Days to Update: 33

Source: Department of Environmental Protection
Telephone: 717-787-9702
Last EDR Contact: 09/19/2018
Next Scheduled EDR Contact: 12/31/2018
Data Release Frequency: Annually

ASBESTOS: Asbestos Notification Listing
Asbestos sites

Date of Government Version: 09/20/2018
Date Data Arrived at EDR: 09/20/2018
Date Made Active in Reports: 10/22/2018
Number of Days to Update: 32

Source: Department of Labor & Industry
Telephone: 717-703-1092
Last EDR Contact: 11/30/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Varies

DRYCLEANERS: Drycleaner Facility Locations
A listing of drycleaner facility locations.

Date of Government Version: 09/18/2018
Date Data Arrived at EDR: 09/19/2018
Date Made Active in Reports: 10/22/2018
Number of Days to Update: 33

Source: Department of Environmental Protection
Telephone: 717-787-9702
Last EDR Contact: 09/19/2018
Next Scheduled EDR Contact: 12/31/2018
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 10/23/2018
Date Made Active in Reports: 11/27/2018
Number of Days to Update: 35

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/15/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Annually

MINES: Abandoned Mine Land Inventory
This data set portrays the approximate location of Abandoned Mine Land Problem Areas containing public health, safety, and public welfare problems created by past coal mining.

Date of Government Version: 10/03/2018
Date Data Arrived at EDR: 10/24/2018
Date Made Active in Reports: 11/27/2018
Number of Days to Update: 34

Source: PASDA
Telephone: 814-863-0104
Last EDR Contact: 10/24/2018
Next Scheduled EDR Contact: 02/04/2019
Data Release Frequency: Semi-Annually

NPDES: NPDES Permit Listing
A listing of facilities with an NPDES permit.

Date of Government Version: 09/19/2017
Date Data Arrived at EDR: 09/21/2017
Date Made Active in Reports: 10/09/2017
Number of Days to Update: 18

Source: Department of Environmental Protection
Telephone: 717-787-9642
Last EDR Contact: 12/07/2018
Next Scheduled EDR Contact: 03/18/2019
Data Release Frequency: Varies

UIC: Underground Injection Wells
A listing of underground injection well locations.

Date of Government Version: 09/18/2018
Date Data Arrived at EDR: 09/19/2018
Date Made Active in Reports: 10/22/2018
Number of Days to Update: 33

Source: Department of Environmental Protection
Telephone: 717-783-7209
Last EDR Contact: 09/19/2018
Next Scheduled EDR Contact: 12/31/2018
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department Environmental Protection in Pennsylvania.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department Environmental Protection in Pennsylvania.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department Environmental Protection in Pennsylvania.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department Environmental Protection
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/04/2018
Number of Days to Update: 20

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/14/2018
Next Scheduled EDR Contact: 02/25/2019
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 07/13/2018
Date Made Active in Reports: 08/01/2018
Number of Days to Update: 19

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 10/09/2018
Next Scheduled EDR Contact: 01/21/2019
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 07/01/2018
Date Data Arrived at EDR: 08/01/2018
Date Made Active in Reports: 08/31/2018
Number of Days to Update: 30

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/31/2018
Next Scheduled EDR Contact: 02/11/2019
Data Release Frequency: Quarterly

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 04/09/2018
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 11/16/2018
Next Scheduled EDR Contact: 03/04/2019
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 08/23/2018
Date Data Arrived at EDR: 08/23/2018
Date Made Active in Reports: 09/18/2018
Number of Days to Update: 26

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 10/15/2018
Next Scheduled EDR Contact: 01/28/2019
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/15/2018
Date Made Active in Reports: 07/09/2018
Number of Days to Update: 24

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 12/07/2018
Next Scheduled EDR Contact: 03/25/2019
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association’s annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics’ primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics’ primary database on private school locations in the United States.

Daycare Centers: Child Care Facility List
Source: Department of Public Welfare
Telephone: 717-783-3856

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory

Source: Pennsylvania Spatial Data Access
Telephone: 610-344-6105

Current USGS 7.5 Minute Topographic Map

Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

BAKER RESIDENTIAL
320 ADAMS DRIVE
COATESVILLE, PA 19320

TARGET PROPERTY COORDINATES

Latitude (North):	39.988125 - 39° 59' 17.25''
Longitude (West):	75.821408 - 75° 49' 17.07''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	429870.4
UTM Y (Meters):	4426552.5
Elevation:	483 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5947569 COATESVILLE, PA
Version Date:	2013
North Map:	5948171 WAGONTOWN, PA
Version Date:	2013

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SSE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
42029C0190F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
42029C0135F	FEMA FIRM Flood data
42029C0140F	FEMA FIRM Flood data
42029C0195F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
COATESVILLE	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
D9	1/4 - 1/2 Mile SE	Not Reported
I28	1/2 - 1 Mile ESE	SE
1G	1/2 - 1 Mile ESE	SE
2G	1/4 - 1/2 Mile SE	Not Reported

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Paleozoic
System:	Ordovician
Series:	Ordovician
Code:	O *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name:	HAGERSTOWN
Soil Surface Texture:	silt loam
Hydrologic Group:	Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.
Soil Drainage Class:	Well drained. Soils have intermediate water holding capacity. Depth to water table is more than 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel:	MODERATE
Depth to Bedrock Min:	> 60 inches
Depth to Bedrock Max:	> 80 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	8 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 6.00 Min: 0.60	Max: 6.50 Min: 4.50
2	8 inches	20 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 2.00 Min: 0.60	Max: 7.30 Min: 4.50
3	20 inches	72 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 2.00 Min: 0.60	Max: 7.30 Min: 5.10

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silty clay loam

Surficial Soil Types: silty clay loam

Shallow Soil Types: silt loam

Deeper Soil Types: channery - silt loam
stratified
loam
unweathered bedrock

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
B5	USGS40001004110	1/4 - 1/2 Mile South
C8	USGS40001004428	1/4 - 1/2 Mile ENE
D11	USGS40001004161	1/4 - 1/2 Mile SE
G17	USGS40001004608	1/2 - 1 Mile NNW
F21	USGS40001004645	1/2 - 1 Mile NNE
G22	USGS40001004618	1/2 - 1 Mile NNW
H25	USGS40001004503	1/2 - 1 Mile NW
J29	USGS40001004320	1/2 - 1 Mile West
K30	USGS40001004043	1/2 - 1 Mile SSW
J33	USGS40001004321	1/2 - 1 Mile West
J35	USGS40001004333	1/2 - 1 Mile West
L36	USGS40001003990	1/2 - 1 Mile SSW
M39	USGS40001004122	1/2 - 1 Mile WSW
N40	USGS40001004525	1/2 - 1 Mile WNW
P44	USGS40001004725	1/2 - 1 Mile NNW
P48	USGS40001004726	1/2 - 1 Mile NNW
R52	USGS40001004376	1/2 - 1 Mile West
U66	USGS40001004319	1/2 - 1 Mile East
73	USGS40001004679	1/2 - 1 Mile NW
U78	USGS40001004343	1/2 - 1 Mile East
Z79	USGS40001004477	1/2 - 1 Mile WNW
AA80	USGS40001004322	1/2 - 1 Mile West
X82	USGS40001004524	1/2 - 1 Mile ENE
U83	USGS40001004306	1/2 - 1 Mile East
Y84	USGS40001004633	1/2 - 1 Mile ENE
AA86	USGS40001004288	1/2 - 1 Mile West
93	USGS40001003853	1/2 - 1 Mile SSW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	PASI50000409262	1/4 - 1/2 Mile SSW

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	PASI50000409320	1/4 - 1/2 Mile SSW
A3	PASI50000409300	1/4 - 1/2 Mile SSW
4	PASI50000404468	1/4 - 1/2 Mile SSW
B6	PASI50000010511	1/4 - 1/2 Mile South
C7	PASI50000043029	1/4 - 1/2 Mile ENE
D10	PASI50000010528	1/4 - 1/2 Mile SE
12	PASI50000389845	1/4 - 1/2 Mile ENE
E13	PASI50000388208	1/4 - 1/2 Mile South
E14	PASI50000388209	1/2 - 1 Mile South
F15	PASI50000043038	1/2 - 1 Mile NNE
E16	PASI50000388210	1/2 - 1 Mile South
G18	PASI50000012800	1/2 - 1 Mile NW
E19	PASI50000388824	1/2 - 1 Mile South
E20	PASI50000405074	1/2 - 1 Mile South
E23	PASI50000388825	1/2 - 1 Mile South
G24	PASI50000010668	1/2 - 1 Mile NNW
I26	PASI50000420160	1/2 - 1 Mile ESE
H27	PASI50000010639	1/2 - 1 Mile WNW
K31	PASI50000010484	1/2 - 1 Mile SSW
J32	PASI50000043016	1/2 - 1 Mile West
J34	PASI50000043017	1/2 - 1 Mile West
37	PASI50000010583	1/2 - 1 Mile West
L38	PASI50000010469	1/2 - 1 Mile SSW
M41	PASI50000010515	1/2 - 1 Mile WSW
N42	PASI50000010642	1/2 - 1 Mile WNW
O43	PASI50000400621	1/2 - 1 Mile SW
P45	PASI50000010713	1/2 - 1 Mile NNW
Q46	SPAW0063114	1/2 - 1 Mile WNW
Q47	SPAW0063115	1/2 - 1 Mile WNW
Q49	PASI50000107573	1/2 - 1 Mile WNW
Q50	PASI50000107574	1/2 - 1 Mile WNW
P51	PASI50000043044	1/2 - 1 Mile NW
O53	PASI50000382250	1/2 - 1 Mile SW
O54	PASI50000421337	1/2 - 1 Mile SW
R55	PASI50000043025	1/2 - 1 Mile West
R56	SPAW0063117	1/2 - 1 Mile West
R57	PASI50000107576	1/2 - 1 Mile West
S58	SPAW0063116	1/2 - 1 Mile WNW
T59	SPAW0055930	1/2 - 1 Mile WSW
S60	PASI50000107575	1/2 - 1 Mile WNW
T61	PASI50000100391	1/2 - 1 Mile WSW
U62	PASI50000010579	1/2 - 1 Mile East
V63	PASI50000388087	1/2 - 1 Mile East
V64	PASI50000388086	1/2 - 1 Mile East
U65	PASI50000010588	1/2 - 1 Mile East
W67	SPAW0063113	1/2 - 1 Mile NNW
V68	PASI50000387212	1/2 - 1 Mile East
X69	PASI50000010641	1/2 - 1 Mile ENE
V70	PASI50000387209	1/2 - 1 Mile East
W71	PASI50000107572	1/2 - 1 Mile NNW
V72	PASI50000388085	1/2 - 1 Mile East
U74	PASI50000010574	1/2 - 1 Mile East

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
V75	PASI50000387210	1/2 - 1 Mile East
Y76	PASI50000043036	1/2 - 1 Mile ENE
V77	PASI50000387211	1/2 - 1 Mile East
81	PASI50000392277	1/2 - 1 Mile NW
Z85	PASI50000043033	1/2 - 1 Mile WNW
AA87	PASI50000043018	1/2 - 1 Mile West
88	PASP50000001230	1/2 - 1 Mile ENE
89	PASI50000012789	1/2 - 1 Mile ESE
AA90	PASI50000010570	1/2 - 1 Mile West
X91	PASI50000107564	1/2 - 1 Mile ENE
92	SPAW0063105	1/2 - 1 Mile ENE
AB94	PASI50000411613	1/2 - 1 Mile SSW
AB95	PASI50000411614	1/2 - 1 Mile SSW

PHYSICAL SETTING SOURCE MAP - 5509910.2s



0 1/4 1/2 1 Miles

- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Oil, gas or related wells

SITE NAME:	Baker Residential	CLIENT:	Whitman
ADDRESS:	320 Adams Drive Coatesville PA 19320	CONTACT:	Sheila Innella
		INQUIRY #:	5509910.2s
LAT/LONG:	39.988125 / 75.821408	DATE:	December 12, 2018 12:02 pm

Copyright © 2018 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
SSW
1/4 - 1/2 Mile
Lower

PA WELLS **PASI50000409262**

Objectid:	409262	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	45	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	17-OCT-12	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	Not Reported	Latitudedd:	39.98466
Longitudedd:	-75.82332	Welladdress:	139 Chestnut Street, Coatesville, PA
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	1	Saltwaterzone:	0
Datedrilled:	15-OCT-12	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M006728
Latestowner:	7472705	Driller scoordme:	3
Latestproduction:	0	Latestwelluse:	7834596
Site id:	PASI50000409262		

A2
SSW
1/4 - 1/2 Mile
Lower

PA WELLS **PASI50000409320**

Objectid:	409320	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	40	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	17-OCT-12	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	Not Reported	Latitudedd:	39.984589
Longitudedd:	-75.82344	Welladdress:	139 Chestnut Street, Coatesville, PA
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	05-OCT-12	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M006726
Latestowner:	7472706	Driller scoordme:	3
Latestproduction:	0	Latestwelluse:	7834597
Site id:	PASI50000409320		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A3
SSW
1/4 - 1/2 Mile
Lower

PA WELLS **PASI50000409300**

Objectid:	409300	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	40	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	17-OCT-12	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	Not Reported	Latitudedd:	39.98445
Longitudedd:	-75.82336	Welladdress:	139 Chestnut Street, Coatesville, PA
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	05-OCT-12	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M006726
Latestowner:	7472707	Driller scoordme:	3
Latestproduction:	0	Latestwelluse:	7834598
Site id:	PASI50000409300		

4
SSW
1/4 - 1/2 Mile
Lower

PA WELLS **PASI50000404468**

Objectid:	404468	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	180	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	19-OCT-10	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	Not Reported	Latitudedd:	39.983161
Longitudedd:	-75.82383	Welladdress:	119 Shepard Way
Wellzipcode:	19320	Depthtobedrock:	15
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	11-OCT-10	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	069247
Latestowner:	7450060	Driller scoordme:	1
Latestproduction:	4481520	Latestwelluse:	7328241
Site id:	PASI50000404468		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B5
South
1/4 - 1/2 Mile
Lower

FED USGS **USGS40001004110**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 918	Type:	Well
Description:	NOW A PARKING LOT (1984)	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge carbonate-rock aquifers		
Formation Type:	Ledger Formation	Aquifer Type:	Not Reported
Construction Date:	19550101	Well Depth:	97
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

B6
South
1/4 - 1/2 Mile
Lower

PA WELLS **PASI50000010511**

Objectid:	10511	Depcounter:	-1
Siteid:	395856075491901	Transactioncount:	1
Localwellnumber:	CH 918	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377LDGR	Topographycode:	V
Welldepth:	97	Elevation:	330
Elevmethodcode:	M	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15001	Latitudedd:	39.9822222222222
Longitudedd:	-75.8219444444444	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-55	Pagwis id:	10512
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10512	Driller scoordme:	0
Latestproduction:	7590	Latestwelluse:	10512
Site id:	PASI50000010511		

C7
ENE
1/4 - 1/2 Mile
Higher

PA WELLS **PASI50000043029**

Objectid:	43029	Depcounter:	-1
Siteid:	395927075485101	Transactioncount:	3
Localwellnumber:	CH 4307	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377AMHP	Topographycode:	S
Welldepth:	0	Elevation:	570
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W

Datecreated:	28-JUN-96	Dateupdated:	13-AUG-96
Datareliabilityc:	C	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.9902777777778
Longitudedd:	-75.8141666666667	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	43030
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	42694	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	43030
Site id:	PASI50000043029		

C8
ENE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40001004428**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 4307	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Antietam Formation	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1992-06-11
Feet below surface:	26.6	Feet to sea level:	Not Reported
Note:	Not Reported		

D9
SE
1/4 - 1/2 Mile
Lower

AQUIFLOW **31495**

Site ID:	Not Reported
Groundwater Flow:	Not Reported
Shallowest Water Table Depth:	10.6
Deepest Water Table Depth:	Not Reported
Average Water Table Depth:	Not Reported
Date:	12/17/1992

D10
SE
1/4 - 1/2 Mile
Lower

PA WELLS **PASI50000010528**

Objectid:	10528	Depcounter:	-1
Siteid:	395900075483001	Transactioncount:	1
Localwellnumber:	CH 415	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377LDGR	Topographycode:	S
Welldepth:	360	Elevation:	320
Elevmethodcode:	M	Accuracyofelevat:	5
Hydrologicunit:	02040205	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15001	Latitudedd:	39.9833333333333
Longitudedd:	-75.8155555555555	Welladdress:	Not Reported

Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	10529
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10530	Driller scoordme:	0
Latestproduction:	7603	Latestwelluse:	10529
Site id:	PASI50000010528		

D11
SE **FED USGS** **USGS40001004161**
1/4 - 1/2 Mile
Lower

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 415	Type:	Well
Description:	WELL HAS BEEN DESTROYED	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge carbonate-rock aquifers		
Formation Type:	Ledger Formation	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	360
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

12
ENE **PA WELLS** **PASI50000389845**
1/4 - 1/2 Mile
Higher

Objectid:	389845	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	307	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	19-APR-10	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.990853
Longitudedd:	-75.812706	Welladdress:	75 Jamie Lane Coatesville, Pa
Wellzipcode:	19320	Depthtobedrock:	26
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	15-APR-10	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	068025
Latestowner:	7457051	Driller scoordme:	3
Latestproduction:	4483561	Latestwelluse:	9920666
Site id:	PASI50000389845		

E13
South **PA WELLS** **PASI50000388208**
1/4 - 1/2 Mile
Lower

Objectid:	388208	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0

Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	30	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	04-NOV-11	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.9809
Longitudedd:	-75.8211	Welladdress:	99 South First Ave., Coatesville, PA
Wellzipcode:	19320	Depthtobedrock:	24
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-NOV-11	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008912
Latestowner:	7465329	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7180900
Site id:	PASI50000388208		

E14
South
1/2 - 1 Mile
Lower

PA WELLS **PASI50000388209**

Objectid:	388209	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	30	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	04-NOV-11	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.9807
Longitudedd:	-75.821	Welladdress:	99 South First Ave., Coatesville, PA
Wellzipcode:	19320	Depthtobedrock:	22
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-NOV-11	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008913
Latestowner:	7456840	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7171246
Site id:	PASI50000388209		

F15
NNE
1/2 - 1 Mile
Higher

PA WELLS **PASI50000043038**

Objectid:	43038	Depcounter:	-1
Siteid:	395943075490701	Transactioncount:	3
Localwellnumber:	CH 4329	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FCIGA	Topographycode:	S
Welldepth:	205	Elevation:	501
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	11-AUG-97	Dateupdated:	12-AUG-97

Datareliabilityc:	C	Sourcedepthdatac:	D
Municipalitycode:	15956	Latitudedd:	39.9952777777778
Longitudedd:	-75.8186111111111	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	43039
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	42704	Driller scoordme:	0
Latestproduction:	44910	Latestwelluse:	43039
Site id:	PASI50000043038		

E16
South
1/2 - 1 Mile
Lower

PA WELLS **PASI50000388210**

Objectid:	388210	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	30	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	04-NOV-11	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.9806
Longitudedd:	-75.821	Welladdress:	99 South First Ave., Coatesville, PA
Wellzipcode:	19320	Depthtobedrock:	18
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-NOV-11	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008914
Latestowner:	7451614	Driller scoordme:	1
Latestproduction:	4482470	Latestwelluse:	7191105
Site id:	PASI50000388210		

G17
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40001004608**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 2416	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Intermediate Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G18
NW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000012800**

Objectid:	12800	Depcounter:	-1
Siteid:	395940075493701	Transactioncount:	1
Localwellnumber:	CH 2416	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FCIGA	Topographycode:	S
Welldepth:	0	Elevation:	350
Elevmethodcode:	M	Accuracyofelevat:	5
Hydrologicunit:	02040205	Latlongaccuracyc:	S
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-JAN-84	Dateupdated:	28-JUN-94
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15956	Latitudedd:	39.9944444444444
Longitudedd:	-75.8269444444444	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	12801
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	12885	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	12801
Site id:	PASI50000012800		

E19
South
1/2 - 1 Mile
Lower

PA WELLS **PASI50000388824**

Objectid:	388824	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	28	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	04-NOV-11	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.9805
Longitudedd:	-75.8211	Welladdress:	99 South First Ave., Coatesville, PA
Wellzipcode:	19320	Depthtobedrock:	24
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	31-OCT-11	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008910
Latestowner:	7466798	Driller scoordme:	1
Latestproduction:	4490513	Latestwelluse:	7183822
Site id:	PASI50000388824		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E20
South
1/2 - 1 Mile
Lower

PA WELLS **PASI50000405074**

Objectid:	405074	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	17	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	16-MAR-12	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.9805
Longitudedd:	-75.8209	Welladdress:	99 South First Ave., Coatesville, PA
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	15-MAR-12	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008919
Latestowner:	7468546	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7278092
Site id:	PASI50000405074		

F21
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40001004645**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 4329	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Intermediate Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	205	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	2	Level reading date:	1992-06-11
Feet below surface:	13.9	Feet to sea level:	Not Reported
Note:	Not Reported		

Level reading date:	1992-06-11	Feet below surface:	13.9
Feet to sea level:	Not Reported	Note:	Not Reported

G22
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40001004618**

Organization ID:	USGS-PA
Organization Name:	USGS Pennsylvania Water Science Center

Monitor Location:	CH 920	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Intermediate Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	19530101
Well Depth:	68	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1963-11-15
Feet below surface:	0.00	Feet to sea level:	Not Reported
Note:	Not Reported		

E23
South
1/2 - 1 Mile
Lower

PA WELLS **PASI50000388825**

Objectid:	388825	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	30	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	04-NOV-11	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.9804
Longitudedd:	-75.8211	Welladdress:	99 South First Ave., Coatesville, PA
Wellzipcode:	19320	Depthtobedrock:	19
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	31-OCT-11	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008911
Latestowner:	7456920	Driller scoordme:	1
Latestproduction:	4484921	Latestwelluse:	7171485
Site id:	PASI50000388825		

G24
NNW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010668**

Objectid:	10668	Depcounter:	-1
Siteid:	395941075493601	Transactioncount:	1
Localwellnumber:	CH 920	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FCIGA	Topographycode:	S
Welldepth:	68	Elevation:	350
Elevmethodcode:	M	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15956	Latitudedd:	39.9947222222222
Longitudedd:	-75.8266666666667	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0

Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-53	Pagwis id:	10669
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10678	Driller scoordme:	0
Latestproduction:	35251	Latestwelluse:	10669
Site id:	PASI50000010668		

H25
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40001004503**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 921	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Intermediate Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	16	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1963-11-15
Feet below surface:	13.24	Feet to sea level:	Not Reported
Note:	Not Reported		

I26
ESE
1/2 - 1 Mile
Lower

PA WELLS **PASI50000420160**

Objectid:	420160	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	260	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	09-MAY-14	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.985431
Longitudedd:	-75.811763	Welladdress:	641 E LINCOLN HWY
Wellzipcode:	19320	Depthtobedrock:	30
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	28-APR-14	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	069614
Latestowner:	7483509	Driller scoordme:	3
Latestproduction:	4508603	Latestwelluse:	9917524
Site id:	PASI50000420160		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H27
WNW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010639**

Objectid:	10639	Depcounter:	-1
Siteid:	395933075494801	Transactioncount:	1
Localwellnumber:	CH 921	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FCIGA	Topographycode:	V
Welldepth:	16	Elevation:	340
Elevmethodcode:	M	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15956	Latitudedd:	39.9925
Longitudedd:	-75.83	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	10640
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10647	Driller scoordme:	0
Latestproduction:	35239	Latestwelluse:	10640
Site id:	PASI50000010639		

I28
ESE
1/2 - 1 Mile
Lower

AQUIFLOW **31405**

Site ID:	15-23149
Groundwater Flow:	SE
Shallowest Water Table Depth:	6.31
Deepest Water Table Depth:	10.73
Average Water Table Depth:	Not Reported
Date:	04/28/1997

J29
West
1/2 - 1 Mile
Lower

FED USGS **USGS40001004320**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 4336	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Chickies Formation	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1992-08-13
Feet below surface:	21.8	Feet to sea level:	Not Reported
Note:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K30
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40001004043**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 2810	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge carbonate-rock aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	1966	Well Depth:	25
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1966
Feet below surface:	7	Feet to sea level:	Not Reported
Note:	Not Reported		

K31
SSW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010484**

Objectid:	10484	Depcounter:	-1
Siteid:	395849075493501	Transactioncount:	1
Localwellnumber:	CH 2810	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377LDGR	Topographycode:	V
Welldepth:	25	Elevation:	309.299987792969
Elevmethodcode:	L	Accuracyofelevat:	.1
Hydrologicunit:	02040205	Latlongaccuracyc:	S
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	08-AUG-86	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	O
Municipalitycode:	15001	Latitudedd:	39.9802777777778
Longitudedd:	-75.8263888888889	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-66	Pagwis id:	10485
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10485	Driller scoordme:	0
Latestproduction:	35173	Latestwelluse:	10485
Site id:	PASI50000010484		

J32
West
1/2 - 1 Mile
Lower

PA WELLS **PASI50000043016**

Objectid:	43016	Depcounter:	-1
Siteid:	395917075495801	Transactioncount:	3
Localwellnumber:	CH 4336	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377CCKS	Topographycode:	S

Welldepth:	0	Elevation:	420
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	12-JAN-96	Dateupdated:	12-JAN-96
Datareliabilityc:	C	Sourcedepthdatac:	Not Reported
Municipalitycode:	15956	Latitudedd:	39.9880555555556
Longitudedd:	-75.8327777777778	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	43017
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	42681	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	43017
Site id:	PASI50000043016		

J33
West
1/2 - 1 Mile
Lower

FED USGS **USGS40001004321**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 4335	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Chickies Formation	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1992-08-13
Feet below surface:	40.9	Feet to sea level:	Not Reported
Note:	Not Reported		

J34
West
1/2 - 1 Mile
Lower

PA WELLS **PASI50000043017**

Objectid:	43017	Depcounter:	-1
Siteid:	395917075500001	Transactioncount:	3
Localwellnumber:	CH 4335	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377CCKS	Topographycode:	S
Welldepth:	0	Elevation:	440
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	12-JAN-96	Dateupdated:	12-JAN-96
Datareliabilityc:	C	Sourcedepthdatac:	Not Reported
Municipalitycode:	15956	Latitudedd:	39.9880555555556
Longitudedd:	-75.8333333333333	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	43018
Sourcesitedataco:	1	Localpermit:	Not Reported

Latestowner:	42682	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	43018
Site id:	PASI50000043017		

J35
West
1/2 - 1 Mile
Lower

FED USGS **USGS40001004333**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 945	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Chickies Formation	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	80
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1963-11-14
Feet below surface:	36.06	Feet to sea level:	Not Reported
Note:	Not Reported		

L36
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40001003990**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 2808	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge carbonate-rock aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	1966	Well Depth:	21
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1966
Feet below surface:	10.25	Feet to sea level:	Not Reported
Note:	Not Reported		

37
West
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010583**

Objectid:	10583	Depcounter:	-1
Siteid:	395918075500201	Transactioncount:	1
Localwellnumber:	CH 945	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377CCKS	Topographycode:	S
Welldepth:	80	Elevation:	480

Elevmethodcode:	M	Accuracyofelevat:	20
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15956	Latitudedd:	39.9883333333333
Longitudedd:	-75.8338888888889	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	10584
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10588	Driller scoordme:	0
Latestproduction:	35212	Latestwelluse:	10584
Site id:	PASI50000010583		

L38
SSW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010469**

Objectid:	10469	Depcounter:	-1
Siteid:	395844075493201	Transactioncount:	1
Localwellnumber:	CH 2808	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	367CNSG	Topographycode:	V
Welldepth:	21	Elevation:	308
Elevmethodcode:	L	Accuracyofelevat:	.01
Hydrologicunit:	02040205	Latlongaccuracyc:	S
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	08-AUG-86	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	O
Municipalitycode:	15001	Latitudedd:	39.9788888888889
Longitudedd:	-75.8255555555556	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-66	Pagwis id:	10470
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10470	Driller scoordme:	0
Latestproduction:	35165	Latestwelluse:	10470
Site id:	PASI50000010469		

M39
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40001004122**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 2818	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19810204	Well Depth:	79
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1984-11-09

Feet below surface:	35.85	Feet to sea level:	Not Reported
Note:	Not Reported		

N40
WNW **FED USGS** **USGS40001004525**
1/2 - 1 Mile
Lower

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 3054	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Intermediate Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	19730618
Well Depth:	220	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1973-06-18
Feet below surface:	87.00	Feet to sea level:	Not Reported
Note:	Not Reported		

M41
WSW **PA WELLS** **PASI50000010515**
1/2 - 1 Mile
Lower

Objectid:	10515	Depcounter:	-1
Siteid:	395857075495801	Transactioncount:	1
Localwellnumber:	CH 2818	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377AMHP	Topographycode:	S
Welldepth:	79	Elevation:	440
Elevmethodcode:	M	Accuracyofelevat:	5
Hydrologicunit:	02040205	Latlongaccuracyc:	S
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	08-AUG-86	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	D
Municipalitycode:	15001	Latitudedd:	39.9825
Longitudedd:	-75.8327777777778	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	04-FEB-81	Pagwis id:	10516
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10516	Driller scoordme:	0
Latestproduction:	35187	Latestwelluse:	10516
Site id:	PASI50000010515		

N42
WNW **PA WELLS** **PASI50000010642**
1/2 - 1 Mile
Lower

Objectid:	10642	Depcounter:	-1
Siteid:	395935075500001	Transactioncount:	1
Localwellnumber:	CH 3054	Countycode:	029

Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FCIGA	Topographycode:	S
Welldepth:	220	Elevation:	0
Elevmethodcode:	1	Accuracyofelevat:	Not Reported
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	10-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15956	Latitudedd:	39.9930555555556
Longitudedd:	-75.8333333333333	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	18-JUN-73	Pagwis id:	10643
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10650	Driller scoordme:	0
Latestproduction:	35240	Latestwelluse:	10643
Site id:	PASI50000010642		

O43
SW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000400621**

Objectid:	400621	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	40	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	17-NOV-11	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	Not Reported	Latitudedd:	39.98093
Longitudedd:	-75.83208	Welladdress:	339 Lincold Highway, Coatesville, PA
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	11-NOV-11	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008384
Latestowner:	7447400	Driller scoordme:	3
Latestproduction:	0	Latestwelluse:	7175619
Site id:	PASI50000400621		

P44
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40001004725**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 922	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Intermediate Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	19630101
Well Depth:	93	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

P45
NNW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010713**

Objectid:	10713	Depcounter:	-1
Siteid:	395951075494401	Transactioncount:	1
Localwellnumber:	CH 922	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FCIGA	Topographycode:	H
Welldepth:	93	Elevation:	480
Elevmethodcode:	M	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15956	Latitudedd:	39.9975
Longitudedd:	-75.8288888888889	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-63	Pagwis id:	10714
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10725	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	10714
Site id:	PASI50000010713		

Q46
WNW
1/2 - 1 Mile
Lower

PA WELLS **SPAW0063114**

Well ID:	X 3399		
County:	029		
Owner Name:	GRAY HAROLD	Latitude:	395939
Longitude:	755002		
Lat/Long Accuracy:	M		
Quadrangle:	COATESVILLE		
Topographic Setting:	Not Reported		
Hydrologic Unit:	Not Reported		
Water Usage:	H		
Site Usage:	W		
Finish:	X		
Well Depth:	123	Casing 1:	34
Casing1 Diameter(inches):	6	Casing2:	Not Reported
Casing2 Diameter(inches):	Not Reported	Grouted:	Not Reported
Date Drilled:	00-00-00	Static Water Level:	50
Production WL:	Not Reported	Yield (gpm):	10
Yield Measurement Method:	1	Drawdown:	72
Test Time:	1	Bedrock:	30
Driller:	0248	Water Bearing Zone 1:	106
Water Bearing Zone 2:	Not Reported		
Lithology:	Not Reported		
Water Bearing Zone 3:	Not Reported		
Municipality:	15956		
Remark:	1939		
Aquifer:	400BLMR		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q47
WNW
1/2 - 1 Mile
Lower

PA WELLS **SPAW0063115**

Well ID:	X 3400		
County:	029		
Owner Name:	CHAPMAN JACOB	Latitude:	395939
Longitude:	755002		
Lat/Long Accuracy:	M		
Quadrangle:	COATESVILLE		
Topographic Setting:	Not Reported		
Hydrologic Unit:	Not Reported		
Water Usage:	H		
Site Usage:	W		
Finish:	X		
Well Depth:	213	Casing 1:	42
Casing1 Diameter(inches):	6	Casing2:	Not Reported
Casing2 Diameter(inches):	Not Reported	Grouted:	Not Reported
Date Drilled:	00-00-00	Static Water Level:	Not Reported
Production WL:	Not Reported	Yield (gpm):	3
Yield Measurement Method:	Not Reported	Drawdown:	Not Reported
Test Time:	Not Reported	Bedrock:	20
Driller:	0308	Water Bearing Zone 1:	60
Water Bearing Zone 2:	90		
Lithology:	GN		
Water Bearing Zone 3:	Not Reported		
Municipality:	15956		
Remark:	1939		
Aquifer:	400BLMR		

P48
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS40001004726**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 4318	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Intermediate Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	503	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	2	Level reading date:	1992-06-26
Feet below surface:	30.34	Feet to sea level:	Not Reported
Note:	Not Reported		

Level reading date:	1992-06-26	Feet below surface:	30.34
Feet to sea level:	Not Reported	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q49
WNW
1/2 - 1 Mile
Higher

PA WELLS **PASI50000107573**

Objectid:	107573	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	X 3399	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400BLMR	Topographycode:	Not Reported
Welldepth:	123	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-FEB-99	Dateupdated:	04-FEB-99
Datareliabilityc:	L	Sourcedepthdatac:	D
Municipalitycode:	15956	Latitudedd:	39.9941666666667
Longitudedd:	-75.8338888888889	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	30
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	107676
Sourcesitedataco:	2	Localpermit:	Not Reported
Latestowner:	106957	Driller scoordme:	0
Latestproduction:	108200	Latestwelluse:	109877
Site id:	PASI50000107573		

Q50
WNW
1/2 - 1 Mile
Higher

PA WELLS **PASI50000107574**

Objectid:	107574	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	X 3400	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400BLMR	Topographycode:	Not Reported
Welldepth:	213	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-FEB-99	Dateupdated:	04-FEB-99
Datareliabilityc:	L	Sourcedepthdatac:	D
Municipalitycode:	15956	Latitudedd:	39.9941666666667
Longitudedd:	-75.8338888888889	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	20
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	107677
Sourcesitedataco:	2	Localpermit:	Not Reported
Latestowner:	106958	Driller scoordme:	0
Latestproduction:	108201	Latestwelluse:	109878
Site id:	PASI50000107574		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

P51
NW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000043044**

Objectid:	43044	Depcounter:	-1
Siteid:	395951075494701	Transactioncount:	3
Localwellnumber:	CH 4318	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FCIGA	Topographycode:	S
Welldepth:	503	Elevation:	470
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	10-MAR-97	Dateupdated:	10-MAR-97
Datareliabilityc:	C	Sourcedepthdatac:	O
Municipalitycode:	15956	Latitudedd:	39.9975
Longitudedd:	-75.8297222222222	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	43045
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	42710	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	43045
Site id:	PASI50000043044		

R52
West
1/2 - 1 Mile
Higher

FED USGS **USGS40001004376**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 4309	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Banded Mafic Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1992-06-12
Feet below surface:	8.7	Feet to sea level:	Not Reported
Note:	Not Reported		

O53
SW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000382250**

Objectid:	382250	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported

Welldepth:	330	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	05-JUL-11	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.98094
Longitudedd:	-75.8332	Welladdress:	401 WEST LINCOLN HIGHWAY
Wellzipcode:	19320	Depthtobedrock:	130
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	23-JUN-11	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	069704
Latestowner:	7452774	Driller scoordme:	3
Latestproduction:	4490979	Latestwelluse:	9908312
Site id:	PASI50000382250		

O54
SW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000421337**

Objectid:	421337	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	380	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	20-JUN-14	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.980272
Longitudedd:	-75.832738	Welladdress:	356 WEST LINCOLN HIGHWAY
Wellzipcode:	19320	Depthtobedrock:	70
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	30-MAY-14	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	070051
Latestowner:	7484712	Driller scoordme:	1
Latestproduction:	4509814	Latestwelluse:	9879423
Site id:	PASI50000421337		

R55
West
1/2 - 1 Mile
Higher

PA WELLS **PASI50000043025**

Objectid:	43025	Depcounter:	-1
Siteid:	395922075501201	Transactioncount:	3
Localwellnumber:	CH 4309	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400BMFGA	Topographycode:	S
Welldepth:	0	Elevation:	551
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	13-FEB-97	Dateupdated:	13-FEB-97
Datareliabilityc:	C	Sourcedepthdatac:	Not Reported
Municipalitycode:	15956	Latitudedd:	39.9894444444444
Longitudedd:	-75.8366666666667	Welladdress:	Not Reported

Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	43026
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	42690	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	43026
Site id:	PASI50000043025		

R56
West
1/2 - 1 Mile
Higher

PA WELLS **SPAW0063117**

Well ID:	X 3402		
County:	029		
Owner Name:	PATWIL INC	Latitude:	395922
Longitude:	755014		
Lat/Long Accuracy:	M		
Quadrangle:	COATESVILLE		
Topographic Setting:	Not Reported		
Hydrologic Unit:	Not Reported		
Water Usage:	H		
Site Usage:	W		
Finish:	X		
Well Depth:	95	Casing 1:	24
Casing1 Diameter(inches):	6	Casing2:	Not Reported
Casing2 Diameter(inches):	Not Reported	Grouted:	Not Reported
Date Drilled:	00-00-00	Static Water Level:	Not Reported
Production WL:	Not Reported	Yield (gpm):	30
Yield Measurement Method:	Not Reported	Drawdown:	Not Reported
Test Time:	Not Reported	Bedrock:	19
Driller:	1290	Water Bearing Zone 1:	35
Water Bearing Zone 2:	65		
Lithology:	GN		
Water Bearing Zone 3:	Not Reported		
Municipality:	15956		
Remark:	1939		
Aquifer:	000GBBR		

R57
West
1/2 - 1 Mile
Higher

PA WELLS **PASI50000107576**

Objectid:	107576	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	X 3402	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	000GBBR	Topographycode:	Not Reported
Welldepth:	95	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-FEB-99	Dateupdated:	04-FEB-99
Datareliabilityc:	L	Sourcedepthdatac:	D
Municipalitycode:	15956	Latitudedd:	39.9894444444444
Longitudedd:	-75.8372222222222	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	19
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	107679
Sourcesitedataco:	2	Localpermit:	Not Reported

Latestowner:	106960	Driller scoordme:	0
Latestproduction:	108203	Latestwelluse:	109880
Site id:	PASI50000107576		

S58
WNW **PA WELLS** **SPAW0063116**
1/2 - 1 Mile
Lower

Well ID:	X 3401		
County:	029		
Owner Name:	MILLER ALFRED	Latitude:	395932
Longitude:	755012		
Lat/Long Accuracy:	M		
Quadrangle:	COATESVILLE		
Topographic Setting:	Not Reported		
Hydrologic Unit:	Not Reported		
Water Usage:	H		
Site Usage:	W		
Finish:	X		
Well Depth:	220	Casing 1:	29
Casing1 Diameter(inches):	6	Casing2:	Not Reported
Casing2 Diameter(inches):	Not Reported	Grouted:	Not Reported
Date Drilled:	00-00-00	Static Water Level:	87
Production WL:	Not Reported	Yield (gpm):	Not Reported
Yield Measurement Method:	1	Drawdown:	142
Test Time:	1	Bedrock:	25
Driller:	0248	Water Bearing Zone 1:	Not Reported
Water Bearing Zone 2:	Not Reported		
Lithology:	O		
Water Bearing Zone 3:	Not Reported		
Municipality:	15956		
Remark:	1939		
Aquifer:	400BLMR		

T59
WSW **PA WELLS** **SPAW0055930**
1/2 - 1 Mile
Lower

Well ID:	7006N		
County:	029		
Owner Name:	ENVIRONMENTAL RES.	Latitude:	395853
Longitude:	755007		
Lat/Long Accuracy:	M		
Quadrangle:	COATESVILLE		
Topographic Setting:	S		
Hydrologic Unit:	02040205		
Water Usage:	Not Reported		
Site Usage:	Not Reported		
Finish:	X		
Well Depth:	79	Casing 1:	35
Casing1 Diameter(inches):	6	Casing2:	Not Reported
Casing2 Diameter(inches):	Not Reported	Grouted:	Not Reported
Date Drilled:	02-00-81	Static Water Level:	42
Production WL:	75	Yield (gpm):	4
Yield Measurement Method:	V	Drawdown:	33
Test Time:	0.5	Bedrock:	35
Driller:	308	Water Bearing Zone 1:	50
Water Bearing Zone 2:	75		
Lithology:	SCH		

Water Bearing Zone 3:	Not Reported
Municipality:	15001
Remark:	Not Reported
Aquifer:	377ANTM

S60
WNW
1/2 - 1 Mile
Higher

PA WELLS **PASI50000107575**

Objectid:	107575	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	X 3401	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400BLMR	Topographycode:	Not Reported
Welldepth:	220	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-FEB-99	Dateupdated:	04-FEB-99
Datareliabilityc:	L	Sourcedepthdatac:	D
Municipalitycode:	15956	Latitudedd:	39.9922222222222
Longitudedd:	-75.8366666666667	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	25
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	107678
Sourcesitedataco:	2	Localpermit:	Not Reported
Latestowner:	106959	Driller scoordme:	0
Latestproduction:	108202	Latestwelluse:	109879
Site id:	PASI50000107575		

T61
WSW
1/2 - 1 Mile
Higher

PA WELLS **PASI50000100391**

Objectid:	100391	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	7006N	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377ANTM	Topographycode:	S
Welldepth:	79	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	02040205	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-FEB-99	Dateupdated:	04-FEB-99
Datareliabilityc:	L	Sourcedepthdatac:	D
Municipalitycode:	15001	Latitudedd:	39.9813888888889
Longitudedd:	-75.8352777777778	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	35
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-FEB-81	Pagwis id:	100494
Sourcesitedataco:	2	Localpermit:	Not Reported
Latestowner:	99782	Driller scoordme:	0
Latestproduction:	101037	Latestwelluse:	0
Site id:	PASI50000100391		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

U62
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010579**

Objectid:	10579	Depcounter:	-1
Siteid:	395917075481801	Transactioncount:	1
Localwellnumber:	CH 905	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377LDGR	Topographycode:	V
Welldepth:	128	Elevation:	360
Elevmethodcode:	M	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15001	Latitudedd:	39.9880555555556
Longitudedd:	-75.805	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-54	Pagwis id:	10580
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10584	Driller scoordme:	0
Latestproduction:	7634	Latestwelluse:	10580
Site id:	PASI50000010579		

V63
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000388087**

Objectid:	388087	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	12	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	26-AUG-09	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.98623
Longitudedd:	-75.80515	Welladdress:	1014 East Lincoln Hwy., Coatesville, Pa
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	29-JUL-09	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	N/A
Latestowner:	7459356	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7171202
Site id:	PASI50000388087		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

V64
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000388086**

Objectid:	388086	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	12	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	26-AUG-09	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.986
Longitudedd:	-75.80495	Welladdress:	1014 East Lincoln Hwy., Coatesville, Pa
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	29-JUL-09	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	N/A
Latestowner:	7453185	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7183941
Site id:	PASI50000388086		

U65
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010588**

Objectid:	10588	Depcounter:	-1
Siteid:	395919075481701	Transactioncount:	1
Localwellnumber:	CH 907	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377LDGR	Topographycode:	V
Welldepth:	250	Elevation:	360
Elevmethodcode:	M	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15912	Latitudedd:	39.9886111111111
Longitudedd:	-75.8047222222222	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-56	Pagwis id:	10589
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10594	Driller scoordme:	0
Latestproduction:	7637	Latestwelluse:	10589
Site id:	PASI50000010588		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

U66
East
1/2 - 1 Mile
Lower

FED USGS **USGS40001004319**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 905	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge carbonate-rock aquifers		
Formation Type:	Ledger Formation	Aquifer Type:	Not Reported
Construction Date:	19540101	Well Depth:	128
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1976-05-19
Feet below surface:	26	Feet to sea level:	Not Reported
Note:	Not Reported		

W67
NNW
1/2 - 1 Mile
Higher

PA WELLS **SPAW0063113**

Well ID:	X 3398		
County:	029		
Owner Name:	VOELOKER J W	Latitude:	395958
Longitude:	754947		
Lat/Long Accuracy:	M		
Quadrangle:	COATESVILLE		
Topographic Setting:	Not Reported		
Hydrologic Unit:	Not Reported		
Water Usage:	H		
Site Usage:	W		
Finish:	X		
Well Depth:	128	Casing 1:	42
Casing1 Diameter(inches):	6	Casing2:	Not Reported
Casing2 Diameter(inches):	Not Reported	Grouted:	Not Reported
Date Drilled:	00-00-00	Static Water Level:	51
Production WL:	Not Reported	Yield (gpm):	5
Yield Measurement Method:	Not Reported	Drawdown:	Not Reported
Test Time:	Not Reported	Bedrock:	37
Driller:	1308	Water Bearing Zone 1:	60
Water Bearing Zone 2:	Not Reported		
Lithology:	Not Reported		
Water Bearing Zone 3:	Not Reported		
Municipality:	15956		
Remark:	1939		
Aquifer:	400BLMR		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

V68
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000387212**

Objectid:	387212	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	12	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	26-AUG-09	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.98611
Longitudedd:	-75.80481	Welladdress:	1014 East Lincoln Hwy., Coatesville, Pa
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	29-JUL-09	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	N/A
Latestowner:	7445122	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7170964
Site id:	PASI50000387212		

X69
ENE
1/2 - 1 Mile
Higher

PA WELLS **PASI50000010641**

Objectid:	10641	Depcounter:	-1
Siteid:	395935075482101	Transactioncount:	1
Localwellnumber:	CH 413	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377HRPR	Topographycode:	S
Welldepth:	160	Elevation:	460
Elevmethodcode:	M	Accuracyofelevat:	5
Hydrologicunit:	02040205	Latlongaccuracyc:	S
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-JUL-84	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15912	Latitudedd:	39.9930555555556
Longitudedd:	-75.8058333333333	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	10642
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10649	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	10642
Site id:	PASI50000010641		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

V70
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000387209**

Objectid:	387209	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	20	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	26-AUG-09	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.98625
Longitudedd:	-75.8047	Welladdress:	1014 East Lincoln Hwy., Coatesville, Pa
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	29-JUL-09	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	060493
Latestowner:	7445121	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7170963
Site id:	PASI50000387209		

W71
NNW
1/2 - 1 Mile
Higher

PA WELLS **PASI50000107572**

Objectid:	107572	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	X 3398	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400BLMR	Topographycode:	Not Reported
Welldepth:	128	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-FEB-99	Dateupdated:	04-FEB-99
Datareliabilityc:	L	Sourcedepthdatac:	D
Municipalitycode:	15956	Latitudedd:	39.9994444444444
Longitudedd:	-75.8297222222222	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	37
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	107675
Sourcesitedataco:	2	Localpermit:	Not Reported
Latestowner:	106956	Driller scoordme:	0
Latestproduction:	108199	Latestwelluse:	109876
Site id:	PASI50000107572		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

V72
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000388085**

Objectid:	388085	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	32	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	26-AUG-09	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.98626
Longitudedd:	-75.80465	Welladdress:	1014 East Lincoln Hwy., Coatesville, Pa
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	29-JUL-09	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	060492
Latestowner:	7462904	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7179049
Site id:	PASI50000388085		

73
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40001004679**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 408	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Banded Mafic Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	19340101
Well Depth:	50	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	2	Level reading date:	1951-07-11
Feet below surface:	30	Feet to sea level:	Not Reported
Note:	Not Reported		

Level reading date:	1951-07-11	Feet below surface:	30
Feet to sea level:	Not Reported	Note:	Not Reported

U74
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000010574**

Objectid:	10574	Depcounter:	-1
Siteid:	395916075481601	Transactioncount:	1

Localwellnumber:	CH 906	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377LDGR	Topographycode:	V
Welldepth:	400	Elevation:	360
Elevmethodcode:	M	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15001	Latitudedd:	39.9877777777778
Longitudedd:	-75.8044444444444	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-55	Pagwis id:	10575
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10578	Driller scoordme:	0
Latestproduction:	7632	Latestwelluse:	10575
Site id:	PASI50000010574		

V75
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000387210**

Objectid:	387210	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	20	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	26-AUG-09	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.9862
Longitudedd:	-75.80461	Welladdress:	1014 East Lincoln Hwy., Coatesville, Pa
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	29-JUL-09	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	060494
Latestowner:	7454764	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7187029
Site id:	PASI50000387210		

Y76
ENE
1/2 - 1 Mile
Higher

PA WELLS **PASI50000043036**

Objectid:	43036	Depcounter:	-1
Siteid:	395942075482501	Transactioncount:	3
Localwellnumber:	CH 4305	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377CCKS	Topographycode:	S
Welldepth:	16	Elevation:	620
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	28-JUN-96	Dateupdated:	28-JUN-96

Datareliabilityc:	C	Sourcedepthdatac:	O
Municipalitycode:	15912	Latitudedd:	39.995
Longitudedd:	-75.8069444444444	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	43037
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	42702	Driller scoordme:	0
Latestproduction:	44909	Latestwelluse:	43037
Site id:	PASI50000043036		

V77
East
1/2 - 1 Mile
Lower

PA WELLS **PASI50000387211**

Objectid:	387211	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	18	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	26-AUG-09	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15001	Latitudedd:	39.98608
Longitudedd:	-75.8046	Welladdress:	1014 East Lincoln Hwy., Coatesville, Pa
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	29-JUL-09	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M009790
Latestowner:	7461336	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	7179050
Site id:	PASI50000387211		

U78
East
1/2 - 1 Mile
Lower

FED USGS **USGS40001004343**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 907	Type:	Well
Description:	DESTROYED, 05-19-1984	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge carbonate-rock aquifers		
Formation Type:	Ledger Formation	Aquifer Type:	Not Reported
Construction Date:	19560101	Well Depth:	250
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1963-09-30
Feet below surface:	33.03	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Z79
WNW
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40001004477**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 4310	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Intermediate Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	75	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1992-06-12
Feet below surface:	39.52	Feet to sea level:	Not Reported
Note:	Not Reported		

AA80
West
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40001004322**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 4333	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Banded Mafic Gneiss, Amphibolite Facies		
Aquifer Type:	Not Reported	Construction Date:	1965
Well Depth:	70	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1992-08-13
Feet below surface:	39.95	Feet to sea level:	Not Reported
Note:	Not Reported		

81
NW
1/2 - 1 Mile
Lower | **PA WELLS** | **PASI50000392277**

Objectid:	392277	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	300	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W

Datecreated:	16-JUN-10	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15961	Latitudedd:	39.99775
Longitudedd:	-75.83317	Welladdress:	100 Birchview Drive
Wellzipcode:	19320	Depthtobedrock:	50
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	07-JUN-10	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	067624
Latestowner:	7465574	Driller scoordme:	1
Latestproduction:	4489965	Latestwelluse:	9905300
Site id:	PASI50000392277		

X82
ENE **FED USGS** **USGS40001004524**
1/2 - 1 Mile
Higher

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 413	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Harpers Formation	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	160
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

U83
East **FED USGS** **USGS40001004306**
1/2 - 1 Mile
Lower

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 906	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge carbonate-rock aquifers		
Formation Type:	Ledger Formation	Aquifer Type:	Not Reported
Construction Date:	19550101	Well Depth:	400
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1984-05-18
Feet below surface:	15.16	Feet to sea level:	Not Reported
Note:	Not Reported		

Y84
ENE **FED USGS** **USGS40001004633**
1/2 - 1 Mile
Higher

Organization ID:	USGS-PA
Organization Name:	USGS Pennsylvania Water Science Center

Monitor Location:	CH 4305	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Chickies Formation	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	16
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	2	Level reading date:	1992-05-20
Feet below surface:	11	Feet to sea level:	Not Reported
Note:	Not Reported		

Level reading date:	1992-05-20	Feet below surface:	11
Feet to sea level:	Not Reported	Note:	Not Reported

Z85
WNW
1/2 - 1 Mile
Higher

PA WELLS **PASI50000043033**

Objectid:	43033	Depcounter:	-1
Siteid:	395931075501701	Transactioncount:	3
Localwellnumber:	CH 4310	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FCIGA	Topographycode:	S
Welldepth:	75	Elevation:	529
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	13-FEB-97	Dateupdated:	13-FEB-97
Datareliabilityc:	C	Sourcedepthdatac:	D
Municipalitycode:	15956	Latitudedd:	39.9919444444444
Longitudedd:	-75.8380555555556	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	43034
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	42699	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	43034
Site id:	PASI50000043033		

AA86
West
1/2 - 1 Mile
Higher

FED USGS **USGS40001004288**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 944	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Felsic and Mafic Gneiss	Aquifer Type:	Not Reported
Construction Date:	19631114	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels,Number of Measurements:	1	Level reading date:	1963-11-14
Feet below surface:	67.00	Feet to sea level:	Not Reported
Note:	Not Reported		

AA87
West
1/2 - 1 Mile
Higher

PA WELLS **PASI50000043018**

Objectid:	43018	Depcounter:	-1
Siteid:	395917075502001	Transactioncount:	3
Localwellnumber:	CH 4333	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400BMFGA	Topographycode:	S
Welldepth:	70	Elevation:	565
Elevmethodcode:	Not Reported	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	Not Reported
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	12-JAN-96	Dateupdated:	12-JAN-96
Datareliabilityc:	C	Sourcedepthdatac:	O
Municipalitycode:	15956	Latitudedd:	39.9880555555556
Longitudedd:	-75.8388888888889	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-65	Pagwis id:	43019
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	42683	Driller scoordme:	0
Latestproduction:	0	Latestwelluse:	43019
Site id:	PASI50000043018		

88
ENE
1/2 - 1 Mile
Lower

PA WELLS **PASP50000001230**

Fid:	1230	Springgenc:	1234
Siteid:	395928075481701	Transactio:	1
Localwelln:	SP-40	Countycode:	029
Quad:	COATESVILLE	Quadcode:	1939
Topography:	S	Elevation:	410
Elevmethod:	M	Elevaccura:	5
Hydrologic:	02040205	Latlongacc:	S
Typeofsite:	S	Formation:	Not Reported
Datareliab:	C	Springname:	Not Reported
Springtype:	Not Reported	Permanence:	Not Reported
Sphereofdi:	Not Reported	Improvemen:	Not Reported
Numofopeni:	Not Reported	Flowvariab:	Not Reported
Accuracyof:	Not Reported	Municipali:	15956
Datecreate:	04-DEC-91	Dateupdate:	06-MAR-92
Latitudedd:	39.9911111111	Longituded:	-75.8047222222
Sourcesite:	1	Pagwis id:	221170
Site id:	PASP50000001230	Edr lat:	39.9912172542
Edr lon:	-75.804390786		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

89
ESE
1/2 - 1 Mile
Lower

PA WELLS **PASI50000012789**

Objectid:	12789	Depcounter:	-1
Siteid:	395900075480001	Transactioncount:	1
Localwellnumber:	CH 414	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	367CNSG	Topographycode:	V
Welldepth:	225	Elevation:	420
Elevmethodcode:	M	Accuracyofelevat:	20
Hydrologicunit:	02040205	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	28-JUN-94
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15001	Latitudedd:	39.9844444444444
Longitudedd:	-75.8044444444444	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	Not Reported	Pagwis id:	12790
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	12872	Driller scoordme:	0
Latestproduction:	9114	Latestwelluse:	12790
Site id:	PASI50000012789		

AA90
West
1/2 - 1 Mile
Higher

PA WELLS **PASI50000010570**

Objectid:	10570	Depcounter:	-1
Siteid:	395914075502101	Transactioncount:	1
Localwellnumber:	CH 944	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	400FMFG	Topographycode:	S
Welldepth:	0	Elevation:	590
Elevmethodcode:	M	Accuracyofelevat:	10
Hydrologicunit:	02040205	Latlongaccuracyc:	1
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	06-DEC-76	Dateupdated:	03-MAR-90
Datareliabilityc:	C	Sourcedepthdatac:	Z
Municipalitycode:	15001	Latitudedd:	39.9872222222222
Longitudedd:	-75.8391666666667	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	14-NOV-63	Pagwis id:	10571
Sourcesitedataco:	1	Localpermit:	Not Reported
Latestowner:	10573	Driller scoordme:	0
Latestproduction:	35204	Latestwelluse:	10571
Site id:	PASI50000010570		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

X91
ENE
1/2 - 1 Mile
Higher

PA WELLS **PASI50000107564**

Objectid:	107564	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	X 1435	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	377CCKS	Topographycode:	S
Welldepth:	80	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	M
Quadcode:	1939	Typeofsitecode:	W
Datecreated:	03-FEB-99	Dateupdated:	04-FEB-99
Datareliabilityc:	L	Sourcedepthdatac:	D
Municipalitycode:	15956	Latitudedd:	39.9936111111111
Longitudedd:	-75.805	Welladdress:	Not Reported
Wellzipcode:	Not Reported	Depthtobedrock:	25
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	01-JAN-70	Pagwis id:	107667
Sourcesitedataco:	2	Localpermit:	Not Reported
Latestowner:	106948	Driller scoordme:	0
Latestproduction:	108191	Latestwelluse:	109868
Site id:	PASI50000107564		

92
ENE
1/2 - 1 Mile
Higher

PA WELLS **SPAW0063105**

Well ID:	X 1435		
County:	029		
Owner Name:	CHESTNUT JOHN	Latitude:	395937
Longitude:	754818		
Lat/Long Accuracy:	M		
Quadrangle:	COATESVILLE		
Topographic Setting:	S		
Hydrologic Unit:	Not Reported		
Water Usage:	H		
Site Usage:	W		
Finish:	X		
Well Depth:	80	Casing 1:	25
Casing1 Diameter(inches):	6	Casing2:	Not Reported
Casing2 Diameter(inches):	Not Reported	Grouted:	Not Reported
Date Drilled:	00-00-70	Static Water Level:	30
Production WL:	Not Reported	Yield (gpm):	15
Yield Measurement Method:	3	Drawdown:	Not Reported
Test Time:	1	Bedrock:	25
Driller:	0154	Water Bearing Zone 1:	45
Water Bearing Zone 2:	70		
Lithology:	SS		
Water Bearing Zone 3:	Not Reported		
Municipality:	15956		
Remark:	1939		
Aquifer:	377CCKS		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

93
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40001003853**

Organization ID:	USGS-PA		
Organization Name:	USGS Pennsylvania Water Science Center		
Monitor Location:	CH 917	Type:	Well
Description:	Not Reported	HUC:	02040205
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Piedmont and Blue Ridge crystalline-rock aquifers		
Formation Type:	Wissahickon Formation, Albite Chlorite Schist		
Aquifer Type:	Not Reported	Construction Date:	19570609
Well Depth:	120	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Ground water levels,Number of Measurements:	1	Level reading date:	1984-11-07
Feet below surface:	21.5	Feet to sea level:	Not Reported
Note:	Not Reported		

AB94
SSW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000411613**

Objectid:	411613	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported
Welldepth:	38	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	07-FEB-13	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15956	Latitudedd:	39.9754
Longitudedd:	-75.8297	Welladdress:	300 Strode Ave., Coatesville, PA
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	30-JUN-10	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008342
Latestowner:	7474997	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	8163490
Site id:	PASI50000411613		

AB95
SSW
1/2 - 1 Mile
Lower

PA WELLS **PASI50000411614**

Objectid:	411614	Depcounter:	-1
Siteid:	Not Reported	Transactioncount:	0
Localwellnumber:	Not Reported	Countycode:	029
Latitude:	Not Reported	Longitude:	Not Reported
Aapgcode:	Not Reported	Topographycode:	Not Reported

Welldepth:	45	Elevation:	0
Elevmethodcode:	Not Reported	Accuracyofelevat:	Not Reported
Hydrologicunit:	Not Reported	Latlongaccuracyc:	Not Reported
Quadcode:	0	Typeofsitecode:	W
Datecreated:	07-FEB-13	Dateupdated:	Not Reported
Datareliabilityc:	Not Reported	Sourcedepthdatac:	Not Reported
Municipalitycode:	15956	Latitudedd:	39.9754
Longitudedd:	-75.83	Welladdress:	300 Strode Ave., Coatesville, PA
Wellzipcode:	19320	Depthtobedrock:	0
Bedrocknotreache:	0	Saltwaterzone:	0
Datedrilled:	30-JUN-10	Pagwis id:	0
Sourcesitedataco:	3	Localpermit:	M008344
Latestowner:	7474998	Driller scoordme:	1
Latestproduction:	0	Latestwelluse:	8163491
Site id:	PASI50000411614		

1G
ESE
1/2 - 1 Mile
Lower

Site ID:	15-23149
Groundwater Flow:	SE
Shallowest Water Table Depth:	6.31
Deepest Water Table Depth:	10.73
Average Water Table Depth:	Not Reported
Date:	04/28/1997

AQUIFLOW **31405**

2G
SE
1/4 - 1/2 Mile
Lower

Site ID:	Not Reported
Groundwater Flow:	Not Reported
Shallowest Water Table Depth:	10.6
Deepest Water Table Depth:	Not Reported
Average Water Table Depth:	Not Reported
Date:	12/17/1992

AQUIFLOW **31495**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: PA Radon

Radon Test Results

Zipcode	Num Tests	Min pCi/L	Max pCi/L	Avg pCi/L
19320	5368	0.1	1669	12.1

EPA Region 3 Statistical Summary Readings for Zip Code: 19320

Number of sites tested: 992.

Maximum Radon Level: 999.9 pCi/L.
Minimum Radon Level: 0.5 pCi/L.

pCi/L <4	pCi/L 4-10	pCi/L 10-20	pCi/L 20-50	pCi/L 50-100	pCi/L >100
422 (42.54%)	270 (27.22%)	149 (15.02%)	95 (9.58%)	36 (3.63%)	20 (2.02%)

Federal EPA Radon Zone for CHESTER County: 1

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory
Source: Pennsylvania Spatial Data Access
Telephone: 610-344-6105

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Pennsylvania Public Water Supply Wells
Source: Pennsylvania Department of Environmental Resources Bureau of Water Supply
Telephone: 717-787-5017

Pennsylvania Groundwater Information System
Source: Department of Conservation and Natural Resources
Telephone: 717-702-2045

OTHER STATE DATABASE INFORMATION

Pennsylvania Oil and Gas Locations
Source: Pennsylvania Department of Environmental Protection
Telephone: 814-863-0104
An Oil and Gas Location is a DEP primary facility type related to the Oil & Gas Program. The sub-facility types related to Oil and Gas that are included in this layer are:Land Application -- An area where drilling cuttings or waste are disposed by land application; Well-- A well associated with oil and/or gas production; Pit -- An approved pit that is used for storage of oil and gas well fluids. Some sub facility types are not included in this layer due to security policies.

RADON

State Database: PA Radon
Source: Department of Environmental Protection
Telephone: 717-783-3594
Radon Test Results Statistics by Zip Code

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

EPA Region 3 Statistical Summary Readings
Source: Region 3 EPA
Telephone: 215-814-2082
Radon readings for Delaware, D.C., Maryland, Pennsylvania, Virginia and West Virginia.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX B:

User Questionnaire(s)

PHASE I ENVIRONMENTAL SITE ASSESSMENT
USER QUESTIONNAIRE

Pursuant to the American Society for Testing and Materials E 1527-13 *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM E 1527-13), in order to qualify for one of the Landowner Liability Protections (LLPs) offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the "Brownfields Amendments"), the **User** must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. These inquiries must also be conducted by EPA Brownfield Assessment and Characterization grantees. The User should provide the following information to the environmental professional. Failure to conduct these inquiries could result in a determination that "all appropriate inquiries" is not complete.

The "**User**" is defined in the ASTM E 1527-13 standard as *the party seeking to use Practice E 1527 to complete an environmental site assessment of the Site. A User may include, without limitation, a potential purchaser of property, a potential tenant of property, an owner of property, a lender, or a property manager.*

In completing this questionnaire, please be as specific as reasonably feasible, and answer in good faith and to the extent of your knowledge.

Thank you for taking the time to complete this questionnaire.

If you have any questions, please call our office at (732) 390-5858.

Site Name & Address:	Route 82 Property Coatesville, PA
Date	12-10-18
Name	John Dolan
Company Name	Baker Residential Limited Partnership
Company Address	One Westbrook Ln, White Plains, NY 10604
Contact Telephone No.	914 461-9326
Contact e-mail Address	JDolan@BakerResidential.com
Signature	John Dolan

1) Purpose of ASTM Phase I (potential purchase, potential sale, re-finance, update the environmental condition of the Site, lease termination or initiation, etc.) (40 CFR 312.29)
Potential Sale

WHITMAN

2) Environmental cleanup liens that are filed or recorded against the Site (40 CFR 312.29)	YES	NO
Did a search of recorded land title records (or judicial records where appropriate, see Note 1 below) identify any environmental liens filed or recorded against the Site under federal, tribal, state or local law?		✓
If Yes, please describe:		

NOTE 1 — In certain jurisdictions, federal, tribal, state, or local statutes, or regulations specify that environmental liens and AULs be filed in judicial records rather than in land title records. In such cases judicial records must be searched for environmental liens and activity and land use limitations (AULs).

3) Activity and land use limitations (AULs) that are in place on the Site or that have been filed or recorded against the Site (40 CFR 312.26(a)(1)(v) and vi))	YES	NO
Did a search of recorded land title records (or judicial records where appropriate, see Note 1 above) identify any AULs, such as engineering controls, land use restrictions or institutional controls that are in place at the Site and/or have been filed or recorded against the Site under federal, tribal, state or local law?		✓
If Yes, please describe:		

4) Specialized knowledge or experience of the person seeking to qualify for the *Landowner Liability Protection* (LLP) (40 CFR 312.28)	YES	NO
Do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?		✓
If Yes, please describe:		

5) Relationship of the purchase price to the fair market value of the Site property (40 CFR 312.29)	YES	NO
Does the purchase price being paid for the Site property reasonably reflect the fair market value of the property? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property? (a real estate appraisal does not need to be obtained exclusively to answer this question)	✓	
If No, please describe:		

6) *Commonly known* or *reasonably ascertainable* information regarding the Site property (40 CFR 312.30)	YES	NO
Are you aware of commonly known or reasonably ascertainable information about the Site that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, (a) Can you provide any information regarding the past uses of the Site? (b) Can you provide any information regarding specific chemicals that are present or once were present at the Site? (c) Can you provide any information regarding spills or other chemical releases that have occurred at the Site? (d) Can you provide any information regarding any environmental cleanups that have occurred at the Site?		✓ ✓ ✓ ✓
If Yes, please describe:		

7) The degree of obviousness of the presence or likely presence of contamination at the Site, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31)	YES	NO
Based on your knowledge and experience related to the Site, are there any obvious indicators that point to the presence or likely presence of releases at the Site?		✓

If Yes, please describe:

8) Proceedings Involving the Site (ASTM E1527-13 Section 10.9)	YES	NO
Are you aware of:		
(1) any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the Site;		✓
(2) any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on or from the Site; and		✓
(3) any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products at the Site?		✓

If Yes, please describe:

PHASE I ENVIRONMENTAL SITE ASSESSMENT
USER QUESTIONNAIRE

(9) Questions Regarding Helpful Documents (ASTM E1527-13 Section 10.8)	YES	NO
Are you aware of the presence of any of the documents listed below and, if so, whether copies can and will be provided to Whitman within reasonable time and cost constraints?		
Environment site assessment reports *	✓	
Environment compliance audit reports		✓
Environmental permits (e.g., solid waste disposal permits; hazardous waste disposal permits; wastewater permits; National Pollutant Discharge Elimination System [NPDES] permits; or underground injection permits)		✓
Registrations for underground and aboveground storage tanks		✓
Registrations for underground injection systems		✓
Safety Data Sheets (SDSs)		✓
Community Right-To-Know plan(s)		✓
Safety plans; preparedness and prevention plans; spill prevention, countermeasure, and control plans; etc.		✓
Reports regarding hydrogeologic conditions at the Site and surrounding area		✓
Notices or other correspondence from any government agency regarding current or previous violations of environmental laws with respect to the Site or relating to environmental liens encumbering the Site property		✓
Hazardous waste generator notices or reports		✓
Geotechnical studies **	✓	
Risk assessments		✓
Recorded AULs		✓

* Copy of Phase I Environmental Site Assessment prepared by Vollmer Associates LLP, dated April 5, 2004 - Provided to Whitman.

** Geotechnical Investigation prepared by Advanced GeoServices Corp dated June 11, 2004 Provided to Whitman

WHITMAN

APPENDIX C:

Historical Research Documentation

Baker Residential
320 Adams Drive
Coatesville, PA 19320

Inquiry Number: 5509910.5
December 17, 2018

The EDR-City Directory Image Report

Environmental Data Resources Inc
6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.



RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2014	☑	☑	EDR Digital Archive
2010	☑	☑	EDR Digital Archive
2005	☑	☑	EDR Digital Archive
2000	☑	☑	EDR Digital Archive
1995	☑	☑	EDR Digital Archive
1992	☑	☑	EDR Digital Archive
1987	☑	☑	Cole Criss-Cross Directory
1982	☑	☑	Cole Criss-Cross Directory
1977	☑	☑	Cole Criss-Cross Directory
1972	☐	☐	Cole Criss-Cross Directory

FINDINGS

TARGET PROPERTY STREET

320 Adams Drive
Coatesville, PA 19320

Year	*CD Image*	*Source*	
ADAMS DR			
2014	pg A1	EDR Digital Archive	
2010	pg A5	EDR Digital Archive	
2005	pg A9	EDR Digital Archive	
2000	pg A14	EDR Digital Archive	
1995	pg A18	EDR Digital Archive	
1992	pg A23	EDR Digital Archive	
1987	pg A28	Cole Criss-Cross Directory	
1982	pg A33	Cole Criss-Cross Directory	
1977	pg A37	Cole Criss-Cross Directory	
1972	-	Cole Criss-Cross Directory	Street not listed in Source

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*	
FLEETWOOD ST			
2014	pg. A2	EDR Digital Archive	
2010	pg. A6	EDR Digital Archive	
2005	pg. A10	EDR Digital Archive	
2000	pg. A15	EDR Digital Archive	
1995	pg. A19	EDR Digital Archive	
1992	pg. A24	EDR Digital Archive	
1987	pg. A29	Cole Criss-Cross Directory	
1982	pg. A34	Cole Criss-Cross Directory	
1977	pg. A38	Cole Criss-Cross Directory	
1972	-	Cole Criss-Cross Directory	Street not listed in Source
MANOR RD			
2014	pg. A3	EDR Digital Archive	
2010	pg. A7	EDR Digital Archive	
2005	pg. A12	EDR Digital Archive	
2000	pg. A16	EDR Digital Archive	
1995	pg. A21	EDR Digital Archive	
1992	pg. A25	EDR Digital Archive	
1987	pg. A30	Cole Criss-Cross Directory	
1982	pg. A35	Cole Criss-Cross Directory	
1977	pg. A39	Cole Criss-Cross Directory	
1972	-	Cole Criss-Cross Directory	Street not listed in Source
N FIRST AVE			
1992	pg. A26	EDR Digital Archive	
1987	pg. A31	Cole Criss-Cross Directory	
1982	pg. A36	Cole Criss-Cross Directory	
1977	pg. A40	Cole Criss-Cross Directory	
1972	-	Cole Criss-Cross Directory	Street not listed in Source

FINDINGS

Year	***CD Image***	***Source***	
WAGONTOWN RD			
2014	pg. A4	EDR Digital Archive	
2010	pg. A8	EDR Digital Archive	
2005	pg. A13	EDR Digital Archive	
2000	pg. A17	EDR Digital Archive	
1995	pg. A22	EDR Digital Archive	
1992	pg. A27	EDR Digital Archive	
1987	pg. A32	Cole Criss-Cross Directory	
1982	-	Cole Criss-Cross Directory	Target and Adjoining not listed in Source
1977	-	Cole Criss-Cross Directory	Target and Adjoining not listed in Source
1972	-	Cole Criss-Cross Directory	Street not listed in Source

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

ADAMS DR 2014

1	WILLIAMS, JULIE R
3	WASHINGTON, JEFFREY A
5	PINKNEY, ARRON N
46	TAYLOR, GISSELLE
300	BRIGITTE TASTE OF HOME LLC
	PAYLOR, GARY M
301	LEAPHART, EARL E
302	MCQUEEN, GLENN B
303	ELLIOTTE, ALBERT E
304	DEVEAUX, DELLINAH
305	LITTLE, BRYANT E
306	WALKER, JAMES A
307	FOLKS, HARVEY
308	HOLMES, REGINALD B
309	FAUST, EUGENE R
310	NIXON, TERRY A
311	BETHALA, SOLOMON M
312	HURST, INA B
314	OCCUPANT UNKNOWN,
315	SMITH, KEVIN J
316	SAMPLE, MONTERO
319	MANN, JASON
321	WRIGHT, GORDON L
323	SHOUSE, LATADRA Y
	UMAMI CATTERING
325	WIENCZEK, AMY L
359	WALKER, MINDI R
360	TAMBURRI, FRANK D
361	KATSIGEORGIS, MICHAEL
366	HOLMES, REGINALD
368	MEYERS, TAMEKA Y
372	BOWMAN, HENRY L

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

FLEETWOOD ST 2014

206	BLACKWELL, PAUL
208	HOGAN, DAWN M
210	OCCUPANT UNKNOWN,
212	SPADA, BRIANA
214	COATES, LEWIS O
216	MILLER, TONYA M
218	REEVES, LAWANDA
220	DOBIE, JUSTINA M
222	YOUNG, ROSE A
224	HOOD, AYESHA
226	GIST, HARVEY E
228	ABBOTT, GREGORY G
230	GIBBS, CURTIS N
232	OCCUPANT UNKNOWN,
234	GREENE, LARRY A
236	BRUNSON, TINA D
238	ORTIZ, RADAMES
240	BOWMAN, TAMARA E
242	STYER, TODD F
244	JOSEPH, SHYRA
246	BOWMAN, TIM B
248	STANLEY, RONALD L
250	DURNELL, KRISTEN V
252	ROBINSON, MICHELE A
254	JACOBS, ANTOINE
256	TERRY, CHONG Y
258	OCCUPANT UNKNOWN,
312	DALY-MYERS, KATHLEEN
330	OCCUPANT UNKNOWN,
332	SOTOL, JORGE
334	OCCUPANT UNKNOWN,
336	OCCUPANT UNKNOWN,
338	BOOKMAN, BRYAN
	ROBINSON & MITCHELL INC
340	ACOPPO, MIGUEL
342	MCMULLEN, ERNEST D
344	REEVES, DENNIS
348	LEE, LENETTA A
356	SCOTT, ROBIN D
366	HICKMAN, JANE M
368	RHOMAS, A
370	THOMAS, GENEVA M
372	WEISS, RACHEL
376	OCCUPANT UNKNOWN,
378	SALGADO, JOSE
400	TS AUTOMOTIVE SERVICE CENTER

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

MANOR RD 2014

600	COATESVILLE INN ASSOCIATES
	COURTYARD BY MARRIOTT
990	WEISER, MICHAEL
1003	CLARK, ERIC J
1004	TRICE, MARY E
1005	BUTLER, KELLY L
1007	SCHMIDT, JOHN F
1009	OCCUPANT UNKNOWN,
1015	BODDY, ANETRA L
	BODDY, DORIS A
	MCKIM, SHERRON
1021	JENKINS, JAMIE
1025	OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

WAGONTOWN RD 2014

921	PITTMAN, ANN C
923	QUINN, CAITLYN
	REITER, WILLIAM
925	THOMPSON, BRIANDA R
927	ALSTON, STANLEY R
929	OCCUPANT UNKNOWN,
1004	LAZAIMA, ROSADA
	MCKENNA, JACOB
	THOMPSON, KEVIN
	WESLEY, WENDELL W
	WRIGHT, JESSICA

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

ADAMS DR 2010

1	WILLIAMS, JUDITH R
3	WASHINGTON, J A
5	PINKNEY, LOUISE
38	OXENDINE, NECHELLE L
300	PAYLOR, GARY M
301	LEAPHART, EARL E
302	MCQUEEN ANDREA
	MCQUEEN, ANDREA J
303	CLINTON, CASAUNDRA
304	DEVEAUX, DELLINAH
305	LITTLE, EUGENE T
307	FOLKS, HARVEY
308	BOOKMAN, VICTORIA L
309	FAUST, EUGENE R
310	NIXON, ARTHUR E
312	HURST, INA B
313	BOWMAN, TIM B
315	EMANSKI, LAUREN
319	MANN, ELIZABETH
321	WRIGHT, GORDON L
323	UMAMI CATTERING
325	WALTON, CHRISTOPHER J
	WIENCZEK AMY
355	RUCKER, BARBARA J
357	MANN, JASON
359	WALKER, MINDI
360	TAMBURRI, SKOT A
361	KATSIGEORGIS, MICHAEL
365	BETHALA, SOLOMON M
366	HOLMES, REGINALD
368	WALKER, CHRIS
372	BOWMAN, HENRY L

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

FLEETWOOD ST 2010

208	HOPE, H
214	COATES, LEWIS O
216	BUTLER, ANGELA
218	REEVES, RATANYA L
220	DOBIE, JUSTINA M
222	EDWARDS, LOUISE
224	ADAMS, MONIQUE
226	EAGLES EYE JANITORIAL
	GIST, HARVEY E
228	VAUGHN, DARIUS
230	GIBBS, CURTIS N
234	RAGSDALE, LUTRICIA
236	BRUNSON, TINA D
238	JONES, CAROL
240	BOWMAN, JOHN C
242	STYER, TODD F
244	DIXON, SHAQUAIA
246	SHORT, SHAMERA
248	STANLEY, DAMON
250	ALLEN, TERRESE E
252	ROBINSON, MICHELE A
254	FERREYRA, MARIA
256	CHONG, TERRY
258	MULHOLLAN, LARRY
312	DALY, KATHY D
	WILLIAM LIBSTONE ASSOC COMFORT
334	JAMES, PATRICIA E
338	ROBINSON & MITCHELL INC
342	RIVERA, BEVERLY
346	THOMAS, C
348	SCHOOLS, JUDITH L
356	SCOTT, ROBIN
358	MACON, TARINA
360	DEVAULT, DESARAE M
366	HICKMAN, JANE M
370	THOMAS, JOHN B
376	RICKS, TAMIR
378	SILVA, EVA
399	G & Z FABRICATIONS
400	TS AUTOMOTIVE SERVICE CENTER

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

MANOR RD 2010

990	WEISER, LESLIE K
1003	CLARK, ERIC J
1004	TRICE, DAVID P
1005	BUTLER, TAMMY L
1007	SCHMIDT, AMANDA
1009	MYERS, GARY S
1010	AHRENS, QUINN
1015	VERGULDI, THOMAS
1021	HENRY, JOAN F
1023	BROWN, AARON W
1025	CAMPOS, TERESA M

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

WAGONTOWN RD 2010

921	PITTMAN, CLIFFORD
925	THOMPSON, BRIANDA
927	GIBBS, MARIE
1004	ERNAY, ADRANIH F
	FAUST, LINDA A
1053	KAPLAN, RICHARD P

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

ADAMS DR 2005

1	WILLIAMS, JUDITH R
5	PINKNEY, LOUISE
38	OXENDINE, NECHELLE L
44	HURST, INA B
46	NORRIS, BRIDGET G
301	LEAPHART, EARL E
303	ELLIOTTE, ALBERT E
305	LITTLE, EUGENE T
307	FOLKS, HARVEY
309	FAUST, EUGENE
313	BOWMAN, JAMES E

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

FLEETWOOD ST 2005

206	JORDANS CHAR DELI
208	HOPE, H
214	COATES, LEWIS O
216	FLAMER, RUSSELL
218	REEVES, RATANYA
220	BOYD, ROBIN L
222	YOUNG, ROSE A
226	EAGLES EYE JANITORIAL
	GIST, HARVEY E
228	CAMPOS, ERNEST E
230	GIBBS, CURTIS N
234	GREENE, LARRY E
236	WANNER, THOMAS J
238	BOOKMAN, NATHAN R
240	TINSLEY, RACHEL A
244	TALTOAN, CONWAY
246	MURRAY, CASSANDRA N
250	KENNEDY, JAMES H
252	ROBINSON, MICHELE A
254	BRICKUS, ROBERT W
256	TERRY, DAVID W
258	MULHOLLAN, LARRY
312	COMFORT CARE TEXTILES INC
	FISHER H BRADLEY INC
	LEWJAN TEXTILE CORP
330	REILLY, LAURA
332	ORTIZ, REGINA
334	JAMES, PATRICIA E
336	CURRY, CRAIG A
338	LAWRENCE, CHARLENE G
340	ALSTON, DAVID
	GONZALES, RUBEN
	HAMPTON, SAMUEL G
	THOMPSON, TIANA
	WATSON, BLAINE
346	BURGOS, KENNETH
348	LEE, LENETTA A
350	MULLEN, RICARDO M
352	WILLIAMS, REBA N
354	DICKENS, NANCY C
358	CORNISH, KEVIN J
360	CORNISH, KEVIN J
362	BOWMAN, RICK T
366	HICKMAN, JANIE M
368	THOMAS, JOHN F
370	THOMAS, JOHN B
372	PIPER, DAVID W
399	ALL DAY EMERGENCY LOCKSMITH
	BDV MOVING CO
	LOUS AUTO

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

FLEETWOOD ST 2005 (Cont'd)

400 TS AUTOMOTIVE SERVICE CENTER

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

MANOR RD 2005

990	WEISER, MICHAEL
1001	MYERS, GARY S
1002	BUTLER, TAMMY L
1004	TRICE, DAVID P
1005	BUTLER, KELLY L
1006	LACLAIR, JOSEPH W
1007	CORNELL, JAMIE L
1010	HAGGERTY, VICKI A
1021	SCARBOROUGH, MICHAEL H
1027	MCCULLEY, ELLA M

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

WAGONTOWN RD 2005

921	PITTMAN, CLIFFORD
923	SALAS, LUIS
925	THOMPSON, BRIANDA
927	GIBBS, GREGORY L
1004	ERNAY, ADRANIH F
1038	DELAHOY, RONALD L
1053	KAPLAN, RICHARD P
1055	ALSTON, LORETTA W

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

ADAMS DR 2000

1	WILLIAMS, JUDITH
3	WASHINGTON, WILLIAM V
301	LEAPHART, EARL E
305	LITTLE, BRYANT
307	FOLKS, TRAVIS H

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

FLEETWOOD ST 2000

210	GREENLY, TERESA
214	COATES, NANCY L
216	RHODES, KENNETH
220	BRICKUS, MARIE
222	YOUNG, ROSE A
226	STEWART, R L
230	BIRCKETT, SHARON
234	GREENE, LARRY
	JACKSON, SALOME
238	MYERS, C R
240	LUMPKIN, MAJA
250	BROWN, OSCAR S
252	ROBINSON, K
254	PARKER, DONNA M
312	COMFORT CARE TEXTILES INC
	FISHER H BRADLEY
	LEWJAN TEXTILE CORP
330	REILLY, JAMES F
334	JAMES, P E
338	LAWRENCE, C
340	CORTEZ, RAYMOND J
342	HUGGINS, MONICA E
346	HUGGINS, MONICA
348	LEE, LENETTA
350	MULLEN, BARBARA C
354	RIGGINS, CALVIN
356	GAFFNEY, F G
362	BOWMAN, KATHRYN
368	THOMAS, JOHN
370	THOMAS, GENEVA
372	LONG, DARLENE
378	JACKSON, TANISHA
	LOVE, TYRONE
399	LOUS AUTO
	TUTTLE & MANET COMPANY INC
400	TS AUTOMOTIVE SERVICE CEN

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

MANOR RD 2000

1000	KINKA, ANTHONY
1004	TRICE, DAVID P
1010	KINKA, NICHOLA
1021	DOYLE, RICHARD A
1035	BAKER, LAURA
	BUTCHER, TAMIKA

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

WAGONTOWN RD 2000

752	REDIFER, JOHN
1038	DELAHOY, R
1039	MIDDLETON, WILLARD B
1043	ROWLANDWYLIE, B
1046	ROBINSON, MICHAEL
1047	DANTZLER, DENNIS
1049	TAYLOR, GEORGE E
1050	OLIVER, ERIC L
1052	PITTMAN, C
1053	MASON, M
1055	GIBBS, GREGORY
1056	GIBBS, LORETTA W
1059	FAIRBANKS, T H

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

ADAMS DR 1995

1	WILLIAMS, JUDITH
3	WASHINGTON, WILLIAM V
5	PINKNEY, JAMES
15	OCCUPANT UNKNOWNN
301	LEAPHART, EARL E
302	DAVIES, HUGH W
303	ELLIOTTE, ALBERT E
304	RAYSON, VICTORI
306	WANSINK, MELISSA J
307	FOLKS, TRAVIS H
308	MARCH, ROBERT JR
309	OCCUPANT UNKNOWNN
310	ROHRMAN, PAUL
312	MOORE, EDWARD
313	BOWMAN, TIM B
314	OCCUPANT UNKNOWNN
316	MARIANI, GLEN R
322	WALL, GREGORY F
326	OCCUPANT UNKNOWNN
328	OCCUPANT UNKNOWNN
330	FINE, DAVID
332	OCCUPANT UNKNOWNN
334	OCCUPANT UNKNOWNN
336	OCCUPANT UNKNOWNN
351	OCCUPANT UNKNOWNN
353	POWELL, L
355	OCCUPANT UNKNOWNN
357	GRAVES, MERRITT
359	OCCUPANT UNKNOWNN
361	RAMBO, A M
363	OCCUPANT UNKNOWNN
365	GILL, ROBERT
375	OCCUPANT UNKNOWNN
377	OCCUPANT UNKNOWNN

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

FLEETWOOD ST 1995

208	GARBER, WILLIAM
210	STOKES, C
212	OCCUPANT UNKNOWNN
214	COATES, NANCY L
216	RHODES, KENNETH
218	DUNCAN, SARITA D
222	YOUNG, ROSE A
224	LOMBARDO, FRANK J
226	STEWART, R L
228	SUTTON, GARY J
230	OCCUPANT UNKNOWNN
232	OCCUPANT UNKNOWNN
236	OCCUPANT UNKNOWNN
238	OCCUPANT UNKNOWNN
240	OCCUPANT UNKNOWNN
242	OCCUPANT UNKNOWNN
244	TROWERY, TAMARA
250	OCCUPANT UNKNOWNN
252	ROBINSON, K
254	PARKER, DONNA M
256	OCCUPANT UNKNOWNN
258	MARCH, ROBERT
301	FISHER REALTY MINI STORAGE
312	BRAFIS INDUSTRIES
	LEWJAN TEXTILE CORP
	SMITH EVA
330	JORDAN, EDWARD
332	KRAJEWSKI, PHILIP J
334	OCCUPANT UNKNOWNN
336	OCCUPANT UNKNOWNN
338	ROBINSON, HARRY E JR
340	OCCUPANT UNKNOWNN
342	OLIVER, CYNTHIA
344	OCCUPANT UNKNOWNN
346	OCCUPANT UNKNOWNN
348	LEVENITE, WALTER J
350	MULLEN, BARBARA C
352	GARDNER, CRYSTAL
354	BYRD, DAVID
358	OCCUPANT UNKNOWNN
360	BRAKE, M
362	JOHNSON, V
364	OCCUPANT UNKNOWNN
368	WASHINGTON, DONNA
370	THOMAS, JOHN B JR
372	MCNAMARA, J
374	OCCUPANT UNKNOWNN
376	CLARK, WALTER H
378	PARKER, DANA
399	TUTTLE & MANET COMPANY INC

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

FLEETWOOD ST 1995 (Cont'd)

400 HARLEY, TYRONE

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

MANOR RD 1995

227	NASS, HERBERT F JR
990	HINES, DORIS
1000	KINKA, ANTHONY JR
1001	MYERS, GARY
1002	BUTLER, KELLY
1004	TRICE, JAMES S
1005	OCCUPANT UNKNOWNN
1006	LACLAIR, M
1007	SCARBOROUGH, MICHAEL
1008	MCCULLEY, REUBEN
1010	KINKA, N
	LAURENTO, L P III
1022	DONKEWICZ, M
1023	OCCUPANT UNKNOWNN

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

WAGONTOWN RD 1995

150	MAMMARELLA, ELENA
	MCCURDY, JOHN
1059	FAIRBANKS, THEO H
1064	DIBERARDINIS, SCOTT

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

ADAMS DR 1992

1	WILLIAMS, JUDITH
3	WASHINGTON, WILLIAM V
5	PINKNEY, JAMES
307	FOLKS, TRAVIS H
310	ROHRMAN, PAUL
312	PATTON, L
313	BOWMAN, JANE
316	MARIANI, GLEN R
322	WALL, GREGORY G
330	FINE, DAVID
353	POWELL, L
355	MOLLOY, WILLIAM J
357	GRAVES, MERRITT
361	RAMBO, A M
365	GILL, ROBERT

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

FLEETWOOD ST 1992

208	GARBER, WILLIAM
212	MALPASS, SCOTT
214	COATES, N L
218	STEEN, EDWARD G
222	YOUNG, SHARON
224	LOMBARDO, FRANK J
226	STEWART, R L
234	MCCAUGHEY, RICHARD C
242	TORRES, CYNTHIA
258	MARCH, ROBERT
301	FISHER REALTY MINI STORAGE
312	BRAFIS INDUSTRIES
	GOLDSTEIN ROSE
	SMITH EVA
332	KRAJEWSKI, PHILIP J
348	LEVENITE, WALTER J
364	ANDERSON, KAREN
370	THOMAS, JOHN B JR
374	RUBINCAM, BARBARA J
376	CLARK, WALTER H
378	REECE, MARVIN JR
3123	MARTINEZ, LUIS

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

MANOR RD 1992

227	NASS, HERBERT F JR
1000	KINKA, ANTHONY JR
1001	MYERS, GARY
1008	MCCULLEY, REUBEN
1010	KINKA, N
1022	DONKEWICZ, M
1023	HARRIS, ELZENIA

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

N FIRST AVE 1992

101 LAMB PAUL H

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

WAGONTOWN RD 1992

1059 FAIRBANKS, T H
1064 DIBERARDINIS, SCOTT

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

ADAMS DR 1987

ADAMS DR 19320

Coatesville PO

1- 499 CT3055 $D..B22

1	Eug W Williams Jr	62	384-4606
3	Iris Washington	82	383-6279
	Wm V Washington	73	383-5687
5	James Pinkney	79	384-5456
302	Frank Pfanders	¤	383-6433
303		NP	
304	Victoria Rayson	84	384-2103
307	L Folks	¤	383-0394
	Travis H Folks	77	383-4783
308	A Edwards	-	384-4367
	P Edwards	-	384-4367
313	J Bowman	66	383-6788
316	Franklin McCann	¤	384-2038
322	Gregory G Wall	¤	384-7730
326	Robert C Potter Jr	-	384-9133
328	M J Harbuck	-	383-5581
334	Edwin Manbeck	-	383-0718
336	David Lyons	¤	384-1646
351	Robert E Blei	-	384-8604
353	L Powell	¤	383-9711
357	Merritt Graves	-	383-9967
359	Patrick K Fullam	-	383-7713
361	A M Rambo	¤	384-6636
363	M J Rodgers	¤	383-9992
365	Anthony P Knerr	-	384-2525
	Lynne D Weer	-	384-2525
371	Jan Christner	-	384-9604
	Jos E Christner	¤	384-9388
375	Francis X McKenna	-	384-6818
377	Jeffrey Waterhouse	-	383-0430
408	Curtis Edgerton	¤	383-9148
	31 RESIDENCE		

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

FLEETWOOD ST 1987

228	. . . . .	NP	
230	Gloria Hardy	81	384-2213
232	Graham Seachrist	54	384-8349
238	240 242 246 . . .	NP	
248	. . . . .	NP	
250	Oscar S Brown	85	383-7318
252	254 256	NP	
258	C O Titus Jr	82	383-5735
312★	**Brafis Industries . . .**	**85**	**384-7207**
	James Cannon	84	383-1086
	C M Parker	85	383-4582
330	Florence Draper	82	383-1323
332	Philip J Krajewski . . .	57	384-8329
334	336 338	NP	
340	James E Myers Jr . . .	¤	384-4973
342	Judith M Thomas . . .	¤	383-5899
	Phillip Thomas	-	383-5899
344	M E Monteith	80	384-1520
346	. . . . .	NP	
348	Walter J Levenite . . .	54	384-1531
350	. . . . .	NP	
352	Robyn G Coleman . . .	82	383-6492
354	356	NP	
358	Linda Coafou	¤	383-0921
360	J Harnish	¤	383-6043
362	364 366 368 . . .	NP	
370	Stephanie Bowman . . .	¤	384-2608

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

MANOR RD 1987



19320

MANOR RD

Coatesville PO

1– 3399 CT3052 $B..C24

9	H S Gilman Jr	85	942-3348
99	A Bosquez	77	384-4065
103	106 108 109A	NP	
110		NP	
190	David R Dodds	79	384-2910
194	196	NP	
1000	Anthony Kinka Jr	70	384-9278
1001	1003 1006 1007	NP	
1008	Reuben McCulley	77	384-8683
1010		NP	
1022	George Donkewicz	82	384-7852
1023	1024 1025 1026	NP	
1027	Kenneth Collins	82	384-5356
1029		NP	
1030	Louis J Gregor	73	384-9619
1032½	1033 1035	NP	
1036	Bonnie S Rogala		¤ 383-5836
	Ralph Schmidt		¤ 383-5836
1038	Rev Jas Christmas	81	383-4130
1103	Harold L Root		383-1995
1115	V B Hess	82	384-6506
		81	384-2402

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

N FIRST AVE 1987



1ST AVE N 19320

Coatesville PO

1– 299 CT3055 $D..B22

19 ★ Eagles Home 384-1828
225 Ralph J Henry 80 383-1645
NO # ★ P J Devitt Hardwar . . 77 384-0810
1 RESIDENCE 2 BUSINESS

1ST AVE S 19320

Coatesville PO

1– 499 CT3056 $D..B22
500– 1099 CT3058 $D..B22

53 ★ City Hall 84 384-0300
★ City Manager 84 384-0300
★ Cotsvle Main St . . . – 383-0584
★ Cty Non Emergency . . 85 384-4684
71 ★ Blind Chstr Co Asn . . 384-2767
★ Chester Cty Assn . . . 384-2767
72 . . . . . NP
73 ★ VFW Post 287 . . . . 85 384-2360
76 78 . . . . . NP
99 ★ Barnetts Serv Sta . . 384-3242
102 ★ Fnncl Excg Co Pa . . . 85 383-4504

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

WAGONTOWN RD 1987



WAGONTOWN RD
Coatesville PO

RD 1 19320
1– END CT3052 $B..C24

191	Rip Breuninger	84		384-8067
	Robt H Breuninger	84		384-8067
NO #	Wm H Breitenbach	73		384-2361
NO #	Matthew Capriotti		¤	384-8473
NO #	Robert W Clifton			384-7041
NO #	Jas E Cunningham		¤	384-5514
NO #	Scott Diberardinis	84		384-8569
NO #	Solomon Drawhorn	64		384-4195
NO #	H Spencer Dunlap			384-7552
NO #	Donald H Hannum	75		384-2249
NO #	J W Inslee	78		384-5518
NO #	Crystal Kuhn		¤	383-4830
NO #	Richard A Maggio	75		384-3694
NO #	Larry E Myers	85		384-6366
NO # ★	**Puseys Auto Repair**	**85**		**383-1696**
NO #	R Sack	84		384-5518

15 RESIDENCE 1 BUSINESS

WAGON WHEEL LN 18901
Doylestown PO

1– END CT1046.04 $A..E44

26		NP	
39	James F McLean	84	348-3330

2 RESIDENCE

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

ADAMS DR 1982

ADAMS DR **COATSVL**

19320

1- 399 TZ3055 $E..C31

007110

1	Eug W Williams Jr		384-4606
3	Wm V Washington	.73	383-5687
5	James Pinkney	.79	384-5456
303	304	.NP	
307	Travis H Folks	.77	383-4783
313	J Bowman	.66	383-6788

7 Residence

ADAMS DR **FRLS HL**

19030

100- 199 TZ105802 $B..D17

007120

116	John Hamilton	.68	949-3664
117	Charles E Shaw	.73	943-8256
118		.NP	
119	Thomas Winters	.79	945-7647
120	J E Moyer	.73	945-6341
121		.NP	
122	Lee R Saunders	.80	547-3105
123		.NP	
124	E L Sundermeter	.80	949-3227
126	James A Gould	.79	949-1735

10 Residence

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

FLEETWOOD ST 1982

226	R L Stewart	.–	383-6762
228	Billy M Giles	.¤	383-1999
230	Gloria Hardy	.¤	384-2213
232	Graham Seachrist		384-8349
238	240 242	.NP	
246	J E Bradford	.80	384-8998
248	V Henderson	.79	383-7393
250	B ODonnell	.74	384-8754
252	254	.NP	
256	D Hall	.¤	383-1029
258		.NP	
312	Wanda Baxter	.80	384-3144
	J L Boyd	.79	383-7568
	★Edj Packaging Comp		384-7208
	★Mr Cutting Inc		384-7207
323	★Head Start		384-4882
330		.NP	
332	Philip J Krajewski		384-8329
334		.NP	
336	B Stewart	.–	384-8539
338	John Jacoby		384-3176
340	L Trammell	.¤	383-5877
342	Joseph Thomas		383-1838
344	M E Monteith	.80	384-1520
346		.NP	

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

MANOR RD 1982

103	106 108	.NP	
109A	Marion Bowlan	.78	383-4650
190	David R Dodds	.79	384-2910
194	196	.NP	
1000	Anthony Kinka Jr		384-9278
1001	1003 1006	.NP	
1007	Clyde H Swisher Sr		384-4367
1008	Reuben McCulley	.77	384-8683
1010	David W Weaver	.76	384-3937
1023	Lemmy L Rokins		383-4187
1024	1026 1027 1029	.NP	
1030	Louis J Gregor	.73	384-9619
1032½	1033 1035 1036	.NP	
1038	Rev Jas Christmas	.¤	383-4130
1103	Harold L Root		383-1995
1115		.NP	
1117	Roger Keith	.–	384-2402
1123	James E Pullen	.79	384-7362
1125	H Richard Miller	.79	384-7145
1127	Kenneth J Profeto	.73	384-1887
	Thomas Profeto	.78	383-7471
	Allan R Wilgis	.79	384-8278
1131		.NP	

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

N FIRST AVE 1982



1ST AVE N COATSVL

. 19320

1- 299 TZ3055 $E..C31

000290

19★Eagles Home 384-9941

★Eagles Home 384-1828

225 Ralph J Henry 80 383-1645

No #★P J Devitt Hardwar 384-0810

1 Residence 3 Business

1ST AVE S COATSVL

. 19320

1- 499 TZ3056 $E..C31

500- 1099 TZ3058 $E..C31

000300

53★Coatesvle City Hll 384-0800

★City Water Dept 384-0263

★City Mayor 384-0300

★Coatsvl Vist Nurse 384-4200

★Visiting Nurse 384-4200

64★Coatsvl YMCA 384-5085

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

ADAMS DR 1977



ADAMS DR — **COATSVL 19320**

1 - 399 TZ 3055 — **$E..C31**

1	Eug W Williams Jr		384-4606
3	Wm V Washington	3	383-5687
5	Gary B Cleveland		384-0886
303	Ronald L Malippa	4	383-4693
304	E Lawson McMullen	4	383-5827
307	David S Pryce	4	383-1337
313	C J Satchell	5	384-6344

7 RESIDENCE

ADAMS DR — **FRLS HL 19030**

100 - 199 TZ 105802 — **$B..D17**

116	John Hamilton	8	949-3664
117	Charles E Shaw	3	943-8256
118		NP	
119	V Lappan	0	943-9435
120	J E Moyer	3	945-6341
121		NP	
122		NP	
123	C H Sanders	2	949-1572
124	Robert Stabinsky	□	547-7232
126	M A Ritter	2	943-7636

10 RESIDENCE

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

FLEETWOOD ST 1977

232	Graham Seachrist		384-8349
238	B ODonnell	4	384-8754
240		NP	
242	Marino Yannetti		384-7318
248		NP	
250		NP	
252		NP	
254	J R Depaolantonio		384-0901
256		NP	
258	Walter S Ross	3	383-5291
312	★ **Coatesville Garmnt**		**384-7207**
	★ **Mr Cutting Inc**		**384-7207**
330		NP	
332	Philip J Krajewski		384-8329
334		NP	
336	Lloyd A Kimes		384-8622
338	John Jacoby		384-3176
340	★ **D L Porter Pntng**		**384-7209**
342	Joseph Thomas		383-1838
344	Thomas Monteith		384-1520
346	Terry B Baker		384-1052
348	Walter J Levenite		384-1531
350	Paul J Bryson		384-5777
352	Donald Markward		384-4359

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

MANOR RD 1977



MANOR RD — COATSVL

------R D 1------ 19320

100 - 3399 TZ 3052 $C..C31

106	John Wolfrey	5	383-5014
108	Richard Massi	-	384-7811
	Gregory E Osborne	5	383-1686
	Jay W Trace	4	384-3837
109A	Parke E Morrison	3	384-1820
190	David W Meissner	4	384-9614
194	Ron M Cozzone	5	384-8712
	Paul Levin	□	384-8787
196	Walter E Osborn		383-1681

------R D 2------ 19320

1000	Anthony Kinka Jr		384-9278
1001	Michael A Kinka	□	383-1215
1003	Steve Suchak		383-1310
1007	Margt K Clifford		384-4367
	Clyde H Swisher Sr		384-4367

---------- 19320

1010	David W Weaver	-	384-3937
1023	Lemmy L Rokins		383-4187
1024	John C Reese		384-6704
1026		NP	
1027		NP	
1029	George E Taylor	3	384-6787

Target Street	Cross Street	Source
-	✓	Cole Criss-Cross Directory

N FIRST AVE 1977

1ST AVE N COATSVL

19320

1 - 299 TZ 3055 $E..C31

19 ★ Eagles Home 384-9941

★ Eagles Home 384-1828

225 Fred F Phillips 384-9229

1 RESIDENCE 2 BUSINESS

1ST AVE S COATSVL

19320

TZ 3056 $E..C31

TZ 3058 $E..C31

26 ★ P J Devitt Hardwre... 384-0810

53 ★ Coatsvl City Hall 384-0300

★ Coatsvl Water Dept .. 384-0263

★ Coatsvl Cty Treas 384-0840

★ Coatsvl Mayors OFC . 384-0300

★ Coatsvl Vist Nurse ... 384-0357

★ Visiting Nurse 384-0357

64 ..... NP

71 ★ Blind Chstr Co Asn... 384-2767

★ Chester Cty Assn 384-2767

72 ..... NP

Baker Residential

320 Adams Drive

Coatesville, PA 19320

Inquiry Number: 5509910.3

December 12, 2018

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

12/12/18

Site Name:

Baker Residential
320 Adams Drive
Coatesville, PA 19320
EDR Inquiry # 5509910.3

Client Name:

Whitman
7 Pleasant Hill Rd
Cranbury, NJ 08512
Contact: Sheila Innella

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Whitman were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 2863-4B51-996B

PO # 39680

Project NA

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: 2863-4B51-996B

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Whitman (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

APPENDIX D:

Photograph Log

Appendix D
Phase I ESA Photograph Log

Photo 1: Typical Site conditions in northern portion of Site, facing southwest.

Photo 2: Typical Site conditions in western portion of Site, facing southeast.

Photo 3: Stormwater drainage pipe in western portion of Site.

Photo 4: Gravel-covered parking and storage area in southern portion of Site, facing southwest.

Photo 5: Stockpiled soil and rock in central portion of Site, facing northeast.

Photo 6: Concrete piles on central portion of Site.

Appendix D
Phase I ESA Photograph Log

Photo 7: Automotive parts located on central portion of Site.

Photo 8: Concrete piles located on central portion of Site.

Photo 9: Tires located on northern portion of Site.

Photo 10: Hot tub located on northern portion of Site.

Photo 11: Piles of potentially asbestos containing floor tiles and shingles located on northern portion of Site.

Photo 12: Piles of potentially asbestos containing shingles located on northern portion of Site.

Appendix D
Phase I ESA Photograph Log

Photo 13: Piles of concrete and tires located on northern portion of Site.

Photo 14: Piles of concrete and wood window frame located on northern portion of Site.

Photo 15: Tires, wood, and plastic household waste located on southern portion of Site.

Photo 16: Pile of asphalt millings located on southern portion of Site.

Photo 17: Approximate area in which the tank was formerly located.

Photo 18: Typical adjoining single-family residence.

Appendix D
Phase I ESA Photograph Log

 Photo 19: Southern-adjoining Amtrak rail line.	

APPENDIX E:

Other Reference Information

Phase I – Environmental Site Assessment

Prepared for:

Route 82 Property,
City of Coatesville, Chester County, PA

April 5, 2004

Prepared by:

VOLLMER ASSOCIATES LLP

TABLE OF CONTENTS

Environmental Site Assessment

Route 82 Property

City of Coatesville

Introduction	1-2
■ Purpose	1
■ Limitations	1-2
Existing Site Information	2-4
■ Site Description	2
■ Delaware County Deeds	3-4
■ Environmental Geographic Database Report	4
■ Delaware County Aerial Photographs	4
■ Interviews	4
■ Pennsylvania Department of Environmental Protection (DEP) Environmental Records	4
Site Reconnaissance	5-7
■ Soils	5-6
■ Geology	6-7
■ Wetlands	7
■ Flood Plain	7
■ Site Visit	7
Findings and Conclusions	8
Site Photographs	9-20
Appendix I (Maps)	
Appendix II (EDR Report)	

VOLLMER

INTRODUCTION

Purpose

VOLLMER ASSOCIATES, LLP has conducted a Phase I Environmental Site Assessment (ESA) for the property herein referred to as Route 82 Property in the City of Coatesville, Chester County, Commonwealth of Pennsylvania. The site is located at the eastern side of Route 82, north of the Conrail Railroad. The purpose of the ESA is to identify recognized environmental conditions in connection with the property.

The following sources of information were reviewed to evaluate the site:

1. Deeds
2. Environmental Geographic Database Report
3. Chester County Aerial Photographs
4. National Flood Insurance Program-Flood Insurance Rate Map – Panel 42029C 0302 D - Chester County, PA
5. National Wetlands Inventory Map, Coatesville Quadrangle
6. Soil Survey for Chester County
7. Geology Survey for Chester County
8. Site Visit
9. Interviews
10. Records Review - PA Department of Environmental Protection

Limitations

1. This assessment has been conducted in accordance with good customary practice to identify recognized environmental conditions. Recognized environmental conditions mean the presence or likely presence of any hazardous substances or petroleum products visually and physically observed on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property; and does not include de minimis conditions that generally do not present a material risk of harm to public health or the environment.

2. This assessment does not include any testing or sampling of materials on or beneath the site, not limited to soil, water, air, etc. Any additional services, not limited to a broader scope of assessment, more detailed conclusions, liability/risk evaluations, recommendations for Phase II testing, remediation techniques, etc. are beyond the scope of this ESA.

This report is site-specific in that it relates to assessment of environmental conditions on the subject property (16-001-0014, 38-003-0038.01, 38-03J-0010.01, and 38-03J-0015.00) only and does not address existing or potential off-site environmental liabilities. This is a confidential report that has been prepared for the use of our client and the Iacobucci Homes and Iacobucci Homes agents and assigns only.

3. Accuracy and completeness of record information from all sources is not guaranteed. A reasonable effort has been made to identify, obtain, and review only record information that is reasonably ascertainable from standard sources. This includes information that is publicly available, obtainable from its source within reasonable time and cost constraints, and practically reviewable.

4. This report is not intended to be a claim, warranty, guarantee, nor any form of assurance of existing or future environmental conditions or liabilities.

EXISTING SITE INFORMATION

Site Description

The site is located at the eastern side of Route 82, north of the Conrail Railroad. This ESA involves the aforementioned parcels only. The site is currently vacant with no buildings or structures within it. The property consists of approximately 90 + acres total. The site is mostly wooded area with some steep slopes. A large area of rock fill was observed near the center of the property. This is thought to be rock excavated from the construction of Route 82 through Coatesville. Also, numerous of debris and trash were observed during the site visit.

Chester County Deeds

Parcel No. 16-001-0014

	Deed Bk/Pg.	Owner	Deed Date
	178/566	Tarlecky Enterprises Corp.	12/18/1987
Part	W27/180	Miller-Hill Corp.	12/6/1955
	S25-615/122	Paul L. A. Keiser	3/20/1953
Part	T28/139	Miller-Hill Corp.	10/17/1956
Part	H28/492	Miller-Hill Corp.	9/22/1955
	E21-502/251	David S. & Edith C. Landis	7/14/1944
Part	W30/184	Miller-Hill Corp.	2/12/1959
	X18-445/172	George D. & Elizabeth Spackman	5/13/1932

Parcel No. 38-003-0038.01

	Deed Bk/Pg.	Owner	Deed Date
	4814-2021	Kathryn M. & Victoria A. Haggerty	8/8/2000
	A60/196	Nichols Kinka	3/19/1982

Parcel No. 38-03J-0010.01

	Deed Bk/Pg.	Owner	Deed Date
	S60/57	Leonard E. Scarborough	11/24/1982
Part	R22-539/10	Clyde H. Swisher	8/25/1945
Part	M32/121	Clyde H. Swisher	11/9/1960

Parcel No. 38-03J-0015.00

Deed Bk/Pg.	Owner	Deed Date
4814-2021	Kathryn M. & Victoria A. Haggerty	9/8/2000
A60/196	Nichols Kinka	3/19/1982

Environmental Geographic Database Report

Attached is a copy of the results of an environmental records search performed by Environmental Data Resources, Inc. The report did not reveal any evidence of known environmental conditions in connection with the subject site.

Chester County Aerial Photographs

We have reviewed aerial photographs for the years 1985 and 2000. There was very little visible change on the site or surrounding properties throughout the time period reviewed. In the 1985 photograph the residential subdivision to the south of the property in the City of Coatesville was visible. Route 82 was visible in both of the aerials reviewed. In the 2000 photograph there is no discernable change on the subject property from the 1985 photograph.

Interviews

The current owner of the large parcel, Mr. Bob Tarlecky, was interviewed by telephone on Friday March 26, 2004. He was asked if he was aware of any environmental conditions in connection with the property, and more specifically, if he was aware of any underground storage tanks on the subject property. He indicated that he was not aware of any environmental conditions on the property. He was also asked about the large tank (see site photographs) on the adjacent property to the north. He indicated that the tank was owned by a previous owner of that parcel and had been intended to be used as an oil storage tank, however, the owner died prior to its installation.

Pennsylvania Department of Environmental Protection (DEP) Environmental Records

PA DEP was contacted to schedule a file review for the site. PA DEP does not have any files specific to the site.

SITE RECONNAISSANCE

Soils

According to the United States Department of Agriculture (USDA) Soil Conservation Service (SCS) "Soil Survey for Chester and Delaware Counties, Pennsylvania". Soils on the site are mapped as Edgemont channery loam (EcB), (EcB2), (EcC2), (EcD2), (EcD3), (EcE2), (EdF) and Manor loam and channery loam (MhE3).

The Edgemont series consists of moderately deep, well-drained soils on uplands. The soils formed mainly in materials weathered from quartzite, but partly in materials weathered from quartz schist. They have a dark grayish-brown surface layer and a yellowish-brown or strong-brown subsoil. The native vegetation was white oak, red oak, black oak, tulip-poplar, hickory, and beech. These soils are on the lower slopes of the Piedmont Plateau. They are mainly north of the Great Valley in Chester County. The principal areas are Barren Hill, near Compass; Welsh Mountains and Thomas Hill, east and west of Elverson in the northwestern part of the county; and north Valley Hills, adjacent to the Great Valley.

The Edgemont soils are near the Glenelg, Chester, Glenville, and Worsham soils. The profile of the Edgemont soils is lighter textured and lighter colored than the profiles of the Glenelg and Chester soils. The Edgemont soils are better drained than the Glenville and Worsham soils. The Glenville soils are moderately well drained, and the Worsham soils are poorly drained.

The texture of the surface layer ranges from loam to silt loam. The texture of the subsoil ranges from silty clay loam to loam. These soils have low available moisture capacity. Permeability is moderately rapid to rapid. The soils are low in fertility. Most of the areas are wooded.

The Manor series consists of shallow, well-drained soils of uplands. The soils occur in both Chester and Delaware Counties, but in Chester County they are more common south of Chester Valley. The parent material of these soils is mostly mica, schist, and gneiss. The schist is fairly soft and weathers easily. The soils formed on schist appear to be deep, but actually, they have little development in the B-horizon. The soils formed on gneiss are shallow over bedrock in many places.

The Manor soils have a dark-brown surface layer. Their subsoil is yellowish red or yellowish brown and is micaceous. In many places the soil has a slippery or greasy feeling caused mainly by the abundance of mica that it contains. The native forest consisted mostly of red oak, white oak, chestnut, hickory, black oak, tulip-poplar, and beech.

The Manor soils are near the deep, well-drained Chester soils and the moderately deep, well-drained Glenelg soils. They are also near the Glenville and Worsham soils, but they are shallower and better drained than those soils.

The texture of the surface layer is loam or light silt loam. The color of the surface layer ranges from pale brown to dark grayish brown, and that of the subsoil, from yellowish brown to reddish brown. Depth to bedrock ranges from 15 inches in some places that are underlaine by gneiss to between 8 and 10 feet in soils that are underlain by mica schist. In most places the subsoil is very micaceous and is underlain by highly weathered mica schist. The mica schist is interspersed with partially disintegrated fragments of rock. In some areas near South Valley Hills, where the underlying rocks are albite-chlorite schist, 40 to 60 percent of the profile, by volume, consist of fragments of schist. The fragments vary in size. They are as much as 3 or 4 inches across and ½ inch to 2 inches thick.

Geology

Chickies Formation (Cch) underlies the majority of the subject site. This formation is light gray, hard quartzite and quartz schist; thin, interbedded, dark slate at top, conglomerate at base. The topography of this formation is rough mountains of medium to high relief; natural slopes are steep and stable. This formation has good stability in very steep cuts. Blasting is required for this formation, slow drilling rates with rotary equipment, in part, due to many quartz veins that exceed 12 inches in width may be required. The foundation stability is good to excellent quality foundation for heavy structures.

Harpers Formation (Ch) underlies a small portion on the south of the subject site. This formation is dark greenish-gray phyllite and schist with quartzite layers. The topography of this formation is undulating hills of low relief, also natural slopes are moderately steep and stable. This formation has poor to fair cut slope stability. Excavation is moderately easy with heavy power equipment, un-weathered rock may require blasting. The foundation stability is good quality foundation for heavy structures.

Vintage Formation (Cv) underlies a very small portion near the southern property line of the subject site. This formation is dark gray, knotty, argillaceous dolomite with impure, light-gray marble at the base of the formation. The topography of this formation is undulating valley of low to medium relief; also natural slopes are gentle to moderately steep and stable. This formation has good cut slope stability. Blasting is required for this formation; moderate-drilling rates with rotary equipment may be required. The foundation stability is good to excellent quality foundation for medium-weight structures.

Chickies Formation hellam conglomerate (Chc) underlies a very small portion to the north of the subject site. This formation is a hellam conglomerate of the Chickies formation.

Wetlands

According to the U.S. Department of the Interior, Fish and Wildlife Service National Wetlands Inventory Maps, Coatesville Quadrangle, there are no mapped wetlands on the subject site. This was confirmed during our site visit.

Floodplain

The Federal Emergency Management Agency's National Flood Insurance Program, Flood Insurance Rate Map for Chester County, Pennsylvania Map Number 42029C 0302 D, effective date November 20, 1996, has been examined for this site. The site is mapped as Zone X, areas outside the 500-year flood. There are no areas on the subject property identified as flood way or flood hazard area.

Site Visit

A site visit was conducted on March 25, 2004 on the subject site. The 90 + acre site is presently vacant (Photo 1-3). The site is located at the eastern side of Route 82, north of the Conrail Railroad. The site is bounded to the east by residential properties (Photo 4), to the north and west by Route 82 (Photo 5-6), and to the south by residential properties (Photo 7).

Numerous pile of debris and trash were observed during the site visit (Photos 8-12). Numerous piles of tires were also observed on the site (Photos 13-15). A large storage tank was observed on the northern portion of the property (Photo 16-18). The tank appeared to be empty and there was no visible sign of contents leaking from it. In several locations 55-gallon drums were observed (Photo19-20). There was no indication of the drums leaking, however these drums were sealed and the contents could not be observed. There are numerous piles of fill on the site ranging in height (Photo 21-22). Also a large area of rock fill was observed near the center of the property (Photo 23-24). This is thought to be rock excavated from the construction of Route 82 through Coatesville.

Other than the presence of the debris, trash, and tire piles on the site, the site visit did not reveal any evidence of environmental conditions in connection with the subject site.

FINDINGS AND CONCLUSIONS

We have performed a Phase I Environmental Site Assessment in accordance with ASTM standards, the scope of our contract, and with good customary practice for the project known as Baker Properties. This ESA is subject to the Limitations in the INTRODUCTION of this report.

In conclusion, this assessment has not revealed the probability of environmental conditions on this site other than those items listed below. We do not recommend any further investigation in the form of a Phase II on the subject site. Three items, however, are noted for the information of our client. First, the presence of the existing tank on the northern portion of the property is of potential concern. While there is no indication of leakage from the tank, we advise that tank be removed form the property in a proper manner and if any contents inside the tank are present they should discarded in a proper manner. Secondly, any tires on the site should be removed and disposed of in a proper fashion. Finally, all the debris and any storage drums on the site should be should be removed and properly disposed of.

Photo 1. View, generally east, of property and neighboring property.

Photo 2. View, generally south, of the northwest portion of the property.

Photo 3. View, generally southeast, in the southeastern portion of the property.

Photo 4. View, generally east, of neighboring residential property.

Photo 5. View, generally south along Rt. 82 north of the property.

Photo 6. View, generally east of Rt. 82 north of the property.

Photo 7. View, generally west, of residential development south of the site.

Photo 8. View, generally northwest, of debris on subject site, south of Rt. 82.

Photo 9. View, generally northwest, of debris on subject site, south of Rt. 82.

Photo 10. View, generally north, of debris on subject site, south of Rt. 82.

Photo 11. View, generally east, of debris on subject site, south of Rt. 82.

Photo 12. View, generally east, of debris on southeastern portion of the subject site.

Photo 13. View, generally northwest, of debris on subject site, south of Rt. 82.

Photo 14. View, generally east of tires near central portion of the property.

Photo 15. View, generally south of trail through the property, west of new residential development.

Photo 16. View, generally north, of tank on the northern portion of the property.

Photo 17. View, generally north, of tank on the northern portion of the property.

Photo 18. View of the inside of the tank on the northern portion of the property.

Photo 19. View, generally north, of a 55-gallon drum on the property.

Photo 20. View, generally north, of a 55-gallon drum on the property.

Photo 21. View, generally northeast, of a mound of fill near center of the property.

Photo 22. View, generally northeast, of a mound of fill near the center of property.

Photo 23. View, generally northeast, of rock fill pile near center of property.

Photo 24. View, generally northeast, of rock fill pile near center of property.

APPENDIX I
MAPS

U.S.G.S. Map
Coatesville Quadrangle

Name: COATESVILLE
Date: 3/12/2004
Scale: 1 inch equals 2000 feet

Location: 039° 59' 22.8" N 075° 49' 29.0" W
Caption: Baker Properties
City of Coatesville
Chester County, PA

Copyright (C) 1997, Maptech, Inc.

Soils Map

Coatesville
South Coatesville
Youngsburg
BRANDYWINE
BRANCH
PENNSYLVANIA
CEMETERY
Scale 1:20,000
0
½
1 Mile

TED STATES
NT OF THE INTERIOR
OLOGICAL SURVEY

CHESTER COUNTY, PENN

AREAL

Geology Map

Flood Plain Map



NATIONAL W
UNITED STATES

Wetlands Map
Coatesville Quadrangle

APPENDIX II
EDR REPORT

The EDR Radius Map
with GeoCheck®

Baker Properties
City of Coatesville
Coatsville, PA 19320

Inquiry Number: 01147135.1r

March 15, 2004

The Standard in Environmental Risk Management Information

440 Wheelers Farms Road
Milford, Connecticut 06460

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

FORM-ARB

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	6
Orphan Summary	9
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	A-54

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.** It can not be concluded from this report that coverage information for the target and surrounding properties does not exist from other sources. Any analyses, estimates, ratings or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Any liability on the part of EDR is strictly limited to a refund of the amount paid for this report.

Copyright 2004 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR). The report meets the government records search requirements of ASTM Standard Practice for Environmental Site Assessments, E 1527-00. Search distances are per ASTM standard or custom distances requested by the user.

TARGET PROPERTY INFORMATION

ADDRESS

CITY OF COATESVILLE
COATSVILLE, PA 19320

COORDINATES

Latitude (North):	39.989740 - 39° 59' 23.1"
Longitude (West):	75.820700 - 75° 49' 14.5"
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	429932.6
UTM Y (Meters):	4426731.0
Elevation:	589 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property:	39075-H7 COATESVILLE, PA
Source:	USGS 7.5 min quad index

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the ASTM E 1527-00 search radius around the target property for the following databases:

FEDERAL ASTM STANDARD

NPL	National Priority List
Proposed NPL	Proposed National Priority List Sites
CERCLIS	Comprehensive Environmental Response, Compensation, and Liability Information System
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
CORRACTS	Corrective Action Report
RCRIS-TSD	Resource Conservation and Recovery Information System
RCRIS-LQG	Resource Conservation and Recovery Information System
RCRIS-SQG	Resource Conservation and Recovery Information System
ERNS	Emergency Response Notification System

STATE ASTM STANDARD

SHWS	Hazardous Sites Cleanup Act Site List

EXECUTIVE SUMMARY

SWF/LF ..... Solid Waste Facility Inventory/Transfer Stations
UST ..... Listing of Pennsylvania Regulated Underground Storage Tanks
VCP ..... Voluntary Cleanup Program Sites
ARCHIVE UST ..... Archived Underground Storage Tank Sites

FEDERAL ASTM SUPPLEMENTAL

CONSENT ..... Superfund (CERCLA) Consent Decrees
ROD ..... Records Of Decision
Delisted NPL ..... National Priority List Deletions
FINDS ..... Facility Index System/Facility Identification Initiative Program Summary Report
HMIRS ..... Hazardous Materials Information Reporting System
MLTS ..... Material Licensing Tracking System
MINES ..... Mines Master Index File
NPL Liens ..... Federal Superfund Liens
PADS ..... PCB Activity Database System
US BROWNFIELDS ..... A Listing of Brownfields Sites
DOD ..... Department of Defense Sites
RAATS ..... RCRA Administrative Action Tracking System
TRIS ..... Toxic Chemical Release Inventory System
TSCA ..... Toxic Substances Control Act
SSTS ..... Section 7 Tracking Systems
FTTS INSP ..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

STATE OR LOCAL ASTM SUPPLEMENTAL

AST ..... Listing of Pennsylvania Regulated Aboveground Storage Tanks
LAST ..... Storage Tank Release Sites
ACT 2-DEED ..... Act 2-Deed Acknowledgment Sites
HIST LF ..... Abandoned Landfill Inventory
ARCHIVE AST ..... Archived Aboveground Storage Tank Sites

BROWNFIELDS DATABASES

US BROWNFIELDS ..... A Listing of Brownfields Sites
Inst Control ..... Engineering and Institutional Controls at Act 2 Sites
VCP ..... Voluntary Cleanup Program Sites
BROWNFIELDS ..... Brownfields Sites

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STATE ASTM STANDARD

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Resources' List of Confirmed Releases.

A review of the LUST list, as provided by EDR, and dated 01/08/2004 has revealed that there are 4 LUST sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
COATESVILLE CTL OFC	*500 CHESTNUT ST*	*1/4 - 1/2 SE*	*1*	*6*
JEROME H RHOADS INC	356 W MAIN ST	1/4 - 1/2 SSE	2	6
NEWLIN BROS	340 HARMONY ST	1/4 - 1/2 SSE	4	8
CARL O BENNER ELEM SCH	545 E LINCOLN HWY	1/4 - 1/2 SE	5	8

STATE OR LOCAL ASTM SUPPLEMENTAL

UNREG LTANKS: Leaking storage tank cases from unregulated storage tanks.

A review of the UNREG LTANKS list, as provided by EDR, and dated 04/12/2002 has revealed that there is 1 UNREG LTANKS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
LAMBS AUTO SVC	*101 E CHESTNUT ST*	*1/4 - 1/2 SSW*	*3*	*7*

PROPRIETARY DATABASES

Former Manufactured Gas (Coal Gas) Sites:
The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative

A review of the Coal Gas list, as provided by EDR, has revealed that there are 2 Coal Gas sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
COATSVILLE GAS CO.	WEST MAIN STREET	1/2 - 1 SSW	6	8
CLUTLER & HELLER TANNERY	WEST MAIN STREET	1/2 - 1 SW	7	8

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped:

Site Name	Database(s)
LUKENS STEEL CO	CERCLIS, FINDS, RCRIS-LQG, TRIS, RCRIS-TSD, UST, CORRACTS, AST, LAST, UNREG LTANKS, ARCHIVE AST
SEAT PROPERTY	CERCLIS, FINDS
HILL FARM	VCP
AD + SOIL, INC-DAVIDSON FARM SITE	SWF/LF
ANDY KUPERSTEIN	LUST
UNION CARBIDE CORP LINDE DIVISION	RCRIS-SQG, FINDS
G.O. CARLSON, INC.	RCRIS-SQG
BLOSENSKI LANDFILL SITE	FINDS, RCRIS-LQG
PARCEL 16-5-18, LUKENS STEEL COMPANY	US BROWNFIELDS

OVERVIEW MAP - 01147135.1r - Vollmer Associates

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Coal Gasification Sites
- National Priority List Sites
- Landfill Sites
- Dept. Defense Sites
- Power transmission lines
- Oil & Gas pipelines
- 100-year flood zone
- 500-year flood zone
- Federal Wetlands

TARGET PROPERTY:	Baker Properties	CUSTOMER:	Vollmer Associates
ADDRESS:	City of Coatesville	CONTACT:	Tia Stevenson
CITY/STATE/ZIP:	Coatsville PA 19320	INQUIRY #:	01147135.1r
LAT/LONG:	39.9897 / 75.8207	DATE:	March 15, 2004 7:40 pm

Copyright © 2003 EDR, Inc. © 2003 GDT, Inc. Rel: 07/2003 All Rights Reserved.

DETAIL MAP - 01147135.1r - Vollmer Associates

- ★ Target Property
- ▲ Sites at elevations higher than or equal to the target property
- ◆ Sites at elevations lower than the target property
- Coal Gasification Sites
- Sensitive Receptors
- National Priority List Sites
- Landfill Sites
- Dept. Defense Sites
- Power transmission lines
- Oil & Gas pipelines
- 100-year flood zone
- 500-year flood zone

TARGET PROPERTY:	Baker Properties	CUSTOMER:	Vollmer Associates
ADDRESS:	City of Coatesville	CONTACT:	Tia Stevenson
CITY/STATE/ZIP:	Coatsville PA 19320	INQUIRY #:	01147135.1r
LAT/LONG:	39.9897 / 75.8207	DATE:	March 15, 2004 7:40 pm

Copyright © 2003 EDR, Inc. © 2003 GDT, Inc. Rel 07/2003 All Rights Reserved

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL ASTM STANDARD								
NPL		1.000	0	0	0	0	NR	0
Proposed NPL		1.000	0	0	0	0	NR	0
CERCLIS		0.500	0	0	0	NR	NR	0
CERC-NFRAP		0.250	0	0	NR	NR	NR	0
CORRACTS		1.000	0	0	0	0	NR	0
RCRIS-TSD		0.500	0	0	0	NR	NR	0
RCRIS Lg. Quan. Gen.		0.250	0	0	NR	NR	NR	0
RCRIS Sm. Quan. Gen.		0.250	0	0	NR	NR	NR	0
ERNS		TP	NR	NR	NR	NR	NR	0
STATE ASTM STANDARD								
State Haz. Waste		1.000	0	0	0	0	NR	0
State Landfill		0.500	0	0	0	NR	NR	0
LUST		0.500	0	0	4	NR	NR	4
UST		0.250	0	0	NR	NR	NR	0
VCP		0.500	0	0	0	NR	NR	0
ARCHIVE UST		0.250	0	0	NR	NR	NR	0
FEDERAL ASTM SUPPLEMENTAL								
CONSENT		1.000	0	0	0	0	NR	0
ROD		1.000	0	0	0	0	NR	0
Delisted NPL		1.000	0	0	0	0	NR	0
FINDS		TP	NR	NR	NR	NR	NR	0
HMIRS		TP	NR	NR	NR	NR	NR	0
MLTS		TP	NR	NR	NR	NR	NR	0
MINES		0.250	0	0	NR	NR	NR	0
NPL Liens		TP	NR	NR	NR	NR	NR	0
PADS		TP	NR	NR	NR	NR	NR	0
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
DOD		1.000	0	0	0	0	NR	0
RAATS		TP	NR	NR	NR	NR	NR	0
TRIS		TP	NR	NR	NR	NR	NR	0
TSCA		TP	NR	NR	NR	NR	NR	0
SSTS		TP	NR	NR	NR	NR	NR	0
FTTS		TP	NR	NR	NR	NR	NR	0
STATE OR LOCAL ASTM SUPPLEMENTAL								
AST		TP	NR	NR	NR	NR	NR	0
LAST		TP	NR	NR	NR	NR	NR	0
ACT 2-DEED		0.500	0	0	0	NR	NR	0
HIST LF		0.500	0	0	0	NR	NR	0
ARCHIVE AST		TP	NR	NR	NR	NR	NR	0
UNREG LTANKS		0.500	0	0	1	NR	NR	1

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
EDR PROPRIETARY HISTORICAL DATABASES								
Coal Gas		1.000	0	0	0	2	NR	2
BROWNFIELDS DATABASES								
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
Inst Control		0.250	0	0	NR	NR	NR	0
VCP		0.500	0	0	0	NR	NR	0
BROWNFIELDS		0.500	0	0	0	NR	NR	0

NOTES:

AQUIFLOW - see EDR Physical Setting Source Addendum

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

1
SE
1/4-1/2
2031 ft.

COATESVILLE CTL OFC
500 CHESTNUT ST
COATESVILLE, PA 19320

LUST **S102733885**
AST **N/A**

Relative:
Lower

Actual:
345 ft.

LUST:

Facility Id:	15-17725
Facility Address 2:	Not reported
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	Interim Remedial Actions Initiated or Completed
Status Date:	/ /
Description :	BELL COATESVILLE CTL OFC 21016
Release Date:	08/06/1994
Region:	SE-1

AST:

Facility ID:	569240
Tank Status:	Currently in Use
Tank Sequence Number:	001A
Date Installed:	01/01/1993
Chemical:	DIESL
Tank Capacity:	1500
Municipality Name :	Coatesville
Client Id Number :	87568
Mailing Name :	VERIZON INC
Mailing Address:	966 S MATLACK ST WEST CHESTER, PA 19380
Other Id :	15-17725
Secondary Facility Address	Not reported
Region Code Name :	SE REGIONAL OFFICE, CONSHOHOCKEN
Regulated Expiration Dt:	02/04/2004
Tank Code :	AST
Inspection Code :	Not reported
Tank Last Dt Inspected :	Not reported
Status Code End Date :	Not reported
Tank Substance Date End :	Not reported
Region Code :	4100

2
SSE
1/4-1/2
2292 ft.

JEROME H RHOADS INC
356 W MAIN ST
COATESVILLE, PA

LUST **S102733886**
N/A

Relative:
Lower

Actual:
341 ft.

LUST:

Facility Id:	15-25526
Facility Address 2:	Not reported
Facility Type:	Underground Storage Tank Containing Petroleum
Facility Status:	Cleanup Completed
Status Date:	07/06/1995
Description :	JEROME H RHOADS INC
Release Date:	08/05/1989
Region:	SE-1

3
SSW
1/4-1/2
2394 ft.

LAMBS AUTO SVC
101 E CHESTNUT ST
COATESVILLE, PA 19320

UST **U002317717**
UNREG LTANKS **N/A**

Relative:
Lower

Actual:
323 ft.

UNREG LTANKS:
Region : South East
Class : Cleanup of Tanks using authorities other than Act 32
Closed : Not reported
Contaminant : Not reported

UST:
Facility ID: 569125
Capacity: 10000
Date Installed: 12/14/1994
Tank Seq No: 009
Chemical: GAS
Tank Status: Currently in Use
Municipality Name : Coatesville
Client Id Number : 179531
Mailing Name : PAUL H LAMB JR
Mailing Address: 101 E CHESTNUT ST
COATESVILLE, PA 19320
Other Id : 15-06586
Secondary Facility Address Not reported
Region Code Name : SE REGIONAL OFFICE, CONSHOHOCKEN
Regulated Expiration Dt: 02/04/2004
Tank Code : UST
Inspection Code : FOI
Tank Last Dt Inspected : 23-Jan-02
Status Code End Date : Not reported
Tank Substance Date End : Not reported
Region Code : 4100

Facility ID: 569125
Capacity: 10000
Date Installed: 12/14/1994
Tank Seq No: 010
Chemical: GAS
Tank Status: Currently in Use
Municipality Name : Coatesville
Client Id Number : 179531
Mailing Name : PAUL H LAMB JR
Mailing Address: 101 E CHESTNUT ST
COATESVILLE, PA 19320
Other Id : 15-06586
Secondary Facility Address Not reported
Region Code Name : SE REGIONAL OFFICE, CONSHOHOCKEN
Regulated Expiration Dt: 02/04/2004
Tank Code : UST
Inspection Code : FOI
Tank Last Dt Inspected : 23-Jan-02
Status Code End Date : Not reported
Tank Substance Date End : Not reported
Region Code : 4100

Map ID / Direction / Distance / Distance (ft.) / Elevation	Site	Database(s)	EDR ID Number / EPA ID Number
4 SSE 1/4-1/2 2472 ft.	**NEWLIN BROS** **340 HARMONY ST** **COATESVILLE, PA**	LUST	S105800118 N/A

Relative: Lower
Actual: 342 ft.

LUST:

Facility Id:		15-10149
Facility Address 2:		Not reported
Facility Type:		Underground Storage Tank Containing Petroleum
Facility Status:		Inactive
Status Date:		12/31/2001
Description :	NEWLINS AUTO SVC	
Release Date:		08/05/1989
Region:		SE-1

---

5 SE 1/4-1/2 2574 ft.	**CARL O BENNER ELEM SCH** **545 E LINCOLN HWY** **COATESVILLE, PA**	LUST	S105145063 N/A

Relative: Lower
Actual: 338 ft.

LUST:

Facility Id:		15-40559
Facility Address 2:		Not reported
Facility Type:		Underground Storage Tank Containing Petroleum
Facility Status:		Cleanup Completed
Status Date:		03/25/1992
Description :	CARL O BENNER ELEM SCH	
Release Date:		08/05/1989
Region:		SE-1

---

6 SSW 1/2-1 3293 ft.	**COATSVILLE GAS CO.** **WEST MAIN STREET** **COATSVILLE, PA 19320**	Coal Gas	G000000065 N/A

Relative: Lower
Actual: 305 ft.

COAL GAS SITE DESCRIPTION:
Site is on the south side of West Main Street west of Brandywine Creek. Site is to the southeast of the end of former Bridge Street's intersection with West Main Street. Site also called Philadelphia Suburban Gas Co.

©Copyright 1993 Real Property Scan, Inc.

---

7 SW 1/2-1 3470 ft.	**CLUTLER & HELLER TANNERY** **WEST MAIN STREET** **COASTVILLE, PA 19320**	Coal Gas	G000000066 N/A

Relative: Lower
Actual: 336 ft.

COAL GAS SITE DESCRIPTION:
Site is on the northern side of West Main St., east of Church St., across from the Coastville Gas Co.

©Copyright 1993 Real Property Scan, Inc.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
COATESVILLE	1000335685	UNION CARBIDE CORP LINDE DIVISION	S 1ST AVE	19320	RCRIS-SQG, FINDS
COATESVILLE	S105423505	HILL FARM	BLACKHORSE HILL RD	19320	VCP
COATESVILLE	1000208280	LUKENS STEEL CO	50 S FIRST AVE	19320	CERCLIS, FINDS, RCRIS-LQG, TRIS, RCRIS-TSD, UST, CORRACTS, AST, LAST, UNREG LTANKS, ARCHIVE AS
COATESVILLE	1007113649	G.O. CARLSON, INC.	WEST LINCOLN HIGHWAY	19320	RCRIS-SQG
COATESVILLE	1006881794	PARCEL 16-5-18, LUKENS STEEL COMPANY	NORTHWEST OF LINCOLN HIGHWAY	19320	US BROWNFIELDS
COATSVILLE	1001126465	SEAT PROPERTY	159 BARON HILL ROAD	19320	CERCLIS, FINDS
COATSVILLE	S105800046	ANDY KUPERSTEIN	305 W LINCOLN HWY		LUST
WEST CALN TOWNSHIP	1000572305	BLOSENSKI LANDFILL SITE	RTE 340	19320	FINDS, RCRIS-LQG
WEST MARLBOROUGH	S103595725	AD + SOIL, INC-DAVIDSON FARM SITE	APPLE GROVE ROAD	19320	SWF/LF

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM STANDARD RECORDS

NPL: National Priority List
Source: EPA
Telephone: N/A
National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/29/04
Date Made Active at EDR: 02/27/04
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 02/06/04
Elapsed ASTM days: 21
Date of Last EDR Contact: 02/06/04

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 8
Telephone: 303-312-6774

EPA Region 4
Telephone 404-562-8033

Proposed NPL: Proposed National Priority List Sites
Source: EPA
Telephone: N/A

Date of Government Version: 01/07/04
Date Made Active at EDR: 02/27/04
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 02/06/04
Elapsed ASTM days: 21
Date of Last EDR Contact: 02/06/04

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System
Source: EPA
Telephone: 703-413-0223
CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 11/17/03
Date Made Active at EDR: 02/02/04
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 12/22/03
Elapsed ASTM days: 42
Date of Last EDR Contact: 12/22/03

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned
Source: EPA
Telephone: 703-413-0223
As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

Date of Government Version: 11/17/03
Date Made Active at EDR: 02/02/04
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 12/22/03
Elapsed ASTM days: 42
Date of Last EDR Contact: 12/22/03

CORRACTS: Corrective Action Report
Source: EPA
Telephone: 800-424-9346
CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/18/03
Date Made Active at EDR: 02/02/04
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 12/26/03
Elapsed ASTM days: 38
Date of Last EDR Contact: 12/08/03

RCRIS: Resource Conservation and Recovery Information System
Source: EPA
Telephone: 800-424-9346
Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs): generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs): generate between 100 kg and 1,000 kg of hazardous waste per month. Large quantity generators (LQGs): generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator off-site to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 01/12/04
Date Made Active at EDR: 02/10/04
Database Release Frequency: Varies

Date of Data Arrival at EDR: 01/19/04
Elapsed ASTM days: 22
Date of Last EDR Contact: 01/19/04

ERNS: Emergency Response Notification System
Source: National Response Center, United States Coast Guard
Telephone: 202-260-2342
Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/03
Date Made Active at EDR: 03/12/04
Database Release Frequency: Annually

Date of Data Arrival at EDR: 01/26/04
Elapsed ASTM days: 46
Date of Last EDR Contact: 01/26/04

FEDERAL ASTM SUPPLEMENTAL RECORDS

BRS: Biennial Reporting System
Source: EPA/NTIS
Telephone: 800-424-9346
The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/01/01
Database Release Frequency: Biennially

Date of Last EDR Contact: 12/16/03
Date of Next Scheduled EDR Contact: 03/15/04

CONSENT: Superfund (CERCLA) Consent Decrees
Source: EPA Regional Offices
Telephone: Varies
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: N/A
Database Release Frequency: Varies

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ROD: Records Of Decision
Source: EPA
Telephone: 703-416-0223
Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/09/04
Database Release Frequency: Annually

Date of Last EDR Contact: 01/06/04
Date of Next Scheduled EDR Contact: 04/05/04

DELISTED NPL: National Priority List Deletions
Source: EPA
Telephone: N/A
The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 01/29/04
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/06/04
Date of Next Scheduled EDR Contact: 05/01/04

FINDS: Facility Index System/Facility Identification Initiative Program Summary Report
Source: EPA
Telephone: N/A
Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/09/04
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/06/04
Date of Next Scheduled EDR Contact: 04/05/04

HMIRS: Hazardous Materials Information Reporting System
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/18/03
Database Release Frequency: Annually

Date of Last EDR Contact: 01/19/04
Date of Next Scheduled EDR Contact: 04/19/04

MLTS: Material Licensing Tracking System
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 01/15/04
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/06/04
Date of Next Scheduled EDR Contact: 04/05/04

MINES: Mines Master Index File
Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959

Date of Government Version: 11/25/03
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 12/29/03
Date of Next Scheduled EDR Contact: 03/29/04

NPL LIENS: Federal Superfund Liens
Source: EPA
Telephone: 202-564-4267
Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 11/21/03
Date of Next Scheduled EDR Contact: 02/23/04

PADS: PCB Activity Database System
Source: EPA
Telephone: 202-564-3887
PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 12/30/03
Database Release Frequency: Annually

Date of Last EDR Contact: 02/09/04
Date of Next Scheduled EDR Contact: 05/10/04

DOD: Department of Defense Sites
Source: USGS
Telephone: 703-648-5423
This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 10/01/03
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/02/04
Date of Next Scheduled EDR Contact: 05/10/04

STORMWATER: Storm Water General Permits
Source: Environmental Protection Agency
Telephone: 202 564-0746
A listing of all facilities with Storm Water General Permits.

Date of Government Version: N/A
Database Release Frequency: Quarterly

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

US BROWNFIELDS: A Listing of Brownfields Sites
Source: Environmental Protection Agency
Telephone: 202-566-2777
Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become BCRLF cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 07/15/03
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 12/17/03
Date of Next Scheduled EDR Contact: 03/15/04

RMP: Risk Management Plans
Source: Environmental Protection Agency
Telephone: 202-564-8600
When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: N/A
Database Release Frequency: N/A

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

RAATS: RCRA Administrative Action Tracking System
Source: EPA
Telephone: 202-564-4104
RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/95
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 12/08/03
Date of Next Scheduled EDR Contact: 03/08/04

TRIS: Toxic Chemical Release Inventory System
Source: EPA
Telephone: 202-566-0250
Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/01
Database Release Frequency: Annually

Date of Last EDR Contact: 12/22/03
Date of Next Scheduled EDR Contact: 03/22/04

TSCA: Toxic Substances Control Act
Source: EPA
Telephone: 202-260-5521
Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/02
Database Release Frequency: Every 4 Years

Date of Last EDR Contact: 12/08/03
Date of Next Scheduled EDR Contact: 03/08/04

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
Source: EPA
Telephone: 202-564-2501

Date of Government Version: 01/21/04
Database Release Frequency: Quarterly

Date of Last EDR Contact: 12/22/03
Date of Next Scheduled EDR Contact: 03/22/04

SSTS: Section 7 Tracking Systems
Source: EPA
Telephone: 202-564-5008
Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/01
Database Release Frequency: Annually

Date of Last EDR Contact: 01/19/04
Date of Next Scheduled EDR Contact: 04/19/04

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-564-2501
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 01/30/04
Database Release Frequency: Quarterly

Date of Last EDR Contact: 12/22/03
Date of Next Scheduled EDR Contact: 03/22/04

STATE OF PENNSYLVANIA ASTM STANDARD RECORDS

SHWS: Hazardous Sites Cleanup Act Site List
Source: Department Environmental Protection
Telephone: 717-783-7816
The Hazardous Sites Cleanup Act Site List includes sites listed on PA Priority List, sites delisted from PA Priority List, Interim Response Completed sites, and Sites Being Studied or Response Being Planned.

Date of Government Version: 07/08/03
Date Made Active at EDR: 10/14/03
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 09/25/03
Elapsed ASTM days: 19
Date of Last EDR Contact: 02/17/04

PA SWF/LF:

SWF/LF: Solid Waste Facility Inventory/Transfer Stations
Source: Department of Environmental Protection
Telephone: 717-783-9258
Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites. Database addresses may represent a sites locational and/or mailing address.

Date of Government Version: 07/21/03
Date Made Active at EDR: 10/07/03
Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 09/24/03
Elapsed ASTM days: 13
Date of Last EDR Contact: 12/22/03

SWF/LF: Operating Facilities
Source: Department of Environmental Protection
Telephone: 717-787-7564

Date of Government Version: 10/29/03
Date Made Active at EDR: 01/09/04
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 12/22/03
Elapsed ASTM days: 18
Date of Last EDR Contact: 12/22/03

SWF/LF: Transfer Stations
Source: Department of Environmental Protection
Telephone: 717-787-7564
A listing of transfer stations.

Date of Government Version: 03/01/99
Date Made Active at EDR: 04/19/02
Database Release Frequency: Varies

Date of Data Arrival at EDR: 03/29/02
Elapsed ASTM days: 21
Date of Last EDR Contact: 12/22/03

SWF/LF: Inactive Solid Waste Landfill
Source: Department of Environmental Protection
Telephone: 717-783-9258
Inactive Solid Waste Facilities. This listing is no longer updated by the state.

Date of Government Version: 12/20/94
Date Made Active at EDR: 06/30/99
Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 06/08/99
Elapsed ASTM days: 22
Date of Last EDR Contact: 12/22/03

LUST: Storage Tank Release Sites
Source: Department of Environmental Protection
Telephone: 717-783-7509
Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 01/08/04
Date Made Active at EDR: 01/26/04
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 01/12/04
Elapsed ASTM days: 14
Date of Last EDR Contact: 01/12/04

UST: Listing of Pennsylvania Regulated Underground Storage Tanks
Source: Department of Environmental Protection
Telephone: 717-772-5599
Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 01/02/04
Date Made Active at EDR: 01/27/04
Database Release Frequency: Varies

Date of Data Arrival at EDR: 01/13/04
Elapsed ASTM days: 14
Date of Last EDR Contact: 01/13/04

VCP: Voluntary Cleanup Program Sites
Source: Department of Environmental Protection
Telephone: 717-783-2388
Sites involved in the Voluntary Cleanup Program

Date of Government Version: 02/17/04
Date Made Active at EDR: 03/15/04
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 02/17/04
Elapsed ASTM days: 27
Date of Last EDR Contact: 02/17/04

ARCHIVE UST: Archived Underground Storage Tank Sites
Source: Department of Environmental Protection
Telephone: 717-772-5599
The list includes tanks storing highly hazardous substances that were removed from the DEP's Storage Tank Information database because of the Department's policy on sensitive information. The list also may include tanks that are removed or permanently closed.

Date of Government Version: 10/01/03
Date Made Active at EDR: 01/30/04
Database Release Frequency: Varies

Date of Data Arrival at EDR: 01/13/04
Elapsed ASTM days: 17
Date of Last EDR Contact: 01/13/04

STATE OF PENNSYLVANIA ASTM SUPPLEMENTAL RECORDS

AST: Listing of Pennsylvania Regulated Aboveground Storage Tanks
Source: Department of Environmental Protection
Telephone: 717-772-5599
Registered Aboveground Storage Tanks.

Date of Government Version: 01/02/04
Database Release Frequency: Varies

Date of Last EDR Contact: 01/13/04
Date of Next Scheduled EDR Contact: 04/12/04

LAST: Storage Tank Release Sites
Source: Department of Environmental Protection
Telephone: 717-783-7509
Leaking Aboveground Storage Tank Incident Reports.

Date of Government Version: 01/08/04
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/12/04
Date of Next Scheduled EDR Contact: 04/12/04

ACT 2-DEED: Act 2-Deed Acknowledgment Sites
Source: Department of Environmental Protection
Telephone: 717-783-9470
This listing pertains to sites where the Department has approved a cleanup requiring a deed acknowledgment under Act 2. This list includes sites remediated to a non-residential Statewide health standard (Section 303(g)); all sites demonstrating attainment of a Site-specific standard (Section 304(m)); and sites being remediated as a special industrial area (Section 305(g)). Persons who remediated a site to a standard that requires a deed acknowledgment shall comply with the requirements of the Solid Waste Management Act or the Hazardous Sites Cleanup Act, as referenced in Act 2. These statutes require a property description section in the deed concerning the hazardous substance disposal on the site. The location of disposed hazardous substances and a description of the type of hazardous substances disposed on the site shall be included in the deed acknowledgment. A deed acknowledgment is required at the time of conveyance of the property.

Date of Government Version: 02/17/04
Database Release Frequency: Varies

Date of Last EDR Contact: 02/17/04
Date of Next Scheduled EDR Contact: 05/17/04

UNREG LTANKS: Unregulated Tank Cases
Source: Department of Environmental Protection
Telephone: 717-783-7509
Leaking storage tank cases from unregulated storage tanks.

Date of Government Version: 04/12/02
Database Release Frequency: No Update Planned

Date of Last EDR Contact: 08/14/03
Date of Next Scheduled EDR Contact: N/A

HIST LF: Abandoned Landfill Inventory
Source: Department of Environmental Protection
Telephone: 717-787-7564
The report provides facility information recorded in the Pennsylvania Department of Environmental Protection ALI database. Some of this information has been abstracted from old records and may not accurately reflect the current conditions and status at these facilities

Date of Government Version: 12/23/03
Database Release Frequency: Varies

Date of Last EDR Contact: 12/22/03
Date of Next Scheduled EDR Contact: 03/22/04

ARCHIVE AST: Archived Aboveground Storage Tank Sites
Source: Department of Environmental Protection
Telephone: 717-772-5599
The list includes aboveground tanks with a capacity greater than 21,000 gallons that were removed from the DEP's Storage Tank Information database because of the Department's policy on sensitive information. The list also may include tanks that are removed or permanently closed.

Date of Government Version: 10/01/03
Database Release Frequency: Varies

Date of Last EDR Contact: 01/13/04
Date of Next Scheduled EDR Contact: 04/12/04

EDR PROPRIETARY HISTORICAL DATABASES

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

BROWNFIELDS DATABASES

Inst Control: Engineering and Institutional Controls at Act 2 Sites
Source: Department of Environmental Protection
Telephone: 717-783-9470
Under Act 2 and the accompanying regulations, Administration of Land Recycling Program, persons who perform a site cleanup using a site-specific standard or affect a special industrial area cleanup may use engineering or institutional controls to attain the cleanup. The sites listed had either an engineering control and/or an instituitional control used in the remediation of the site.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/10/04
Database Release Frequency: Varies

Date of Last EDR Contact: 02/17/04
Date of Next Scheduled EDR Contact: 05/17/04

VCP: Voluntary Cleanup Program Sites
Source: Department of Environmental Protection
Telephone: 717-783-2388
Sites involved in the Voluntary Cleanup Program

Date of Government Version: 02/17/04
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 02/17/04
Date of Next Scheduled EDR Contact: 05/17/04

BROWNFIELDS: Brownfields Sites
Source: Department of Environmental Protection
Telephone: 717-783-7509

Date of Government Version: 07/01/03
Database Release Frequency: Varies

Date of Last EDR Contact: 02/17/04
Date of Next Scheduled EDR Contact: 05/17/04

US BROWNFIELDS: A Listing of Brownfields Sites
Source: Environmental Protection Agency
Telephone: 202-566-2777
Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become BCRLF cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: N/A
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data
Source: PennWell Corporation
Telephone: (800) 823-6277
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Child Care Facility List
Source: Department of Public Welfare
Telephone: 717-783-3856

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

STREET AND ADDRESS INFORMATION

© 2003 Geographic Data Technology, Inc., Rel. 07/2003. This product contains proprietary and confidential property of Geographic Data Technology, Inc. Unauthorized use, including copying for other than testing and standard backup procedures, of this product is expressly prohibited.

GEOCHECK®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

BAKER PROPERTIES
CITY OF COATESVILLE
COATSVILLE, PA 19320

TARGET PROPERTY COORDINATES

Latitude (North):	39.989738 - 39° 59' 23.1"
Longitude (West):	75.820702 - 75° 49' 14.5"
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	429932.6
UTM Y (Meters):	4426731.0
Elevation:	589 ft. above sea level

EDR's GeoCheck Physical Setting Source Addendum has been developed to assist the environmental professional with the collection of physical setting source information in accordance with ASTM 1527-00, Section 7.2.3. Section 7.2.3 requires that a current USGS 7.5 Minute Topographic Map (or equivalent, such as the USGS Digital Elevation Model) be reviewed. It also requires that one or more additional physical setting sources be sought when (1) conditions have been identified in which hazardous substances or petroleum products are likely to migrate to or from the property, and (2) more information than is provided in the current USGS 7.5 Minute Topographic Map (or equivalent) is generally obtained, pursuant to local good commercial or customary practice, to assess the impact of migration of recognized environmental conditions in connection with the property. Such additional physical setting sources generally include information about the topographic, hydrologic, hydrogeologic, and geologic characteristics of a site, and wells in the area.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata. EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

USGS Topographic Map:	39075-H7 COATESVILLE, PA
General Topographic Gradient:	General SE
Source:	USGS 7.5 min quad index

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
CHESTER, PA	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 42029C0302D

Additional Panels in search area: 42029C0168D
42029C0164D
42029C0306D

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
COATESVILLE	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
D12	1/2 - 1 Mile SSE	Not Reported
15	1/2 - 1 Mile SE	SE

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Paleozoic
System:	Ordovician
Series:	Ordovician
Code:	O *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name:	HAGERSTOWN
Soil Surface Texture:	silt loam
Hydrologic Group:	Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.
Soil Drainage Class:	Well drained. Soils have intermediate water holding capacity. Depth to water table is more than 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel:	MODERATE
Depth to Bedrock Min:	> 60 inches
Depth to Bedrock Max:	> 80 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	8 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 6.00 Min: 0.60	Max: 6.50 Min: 4.50
2	8 inches	20 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 2.00 Min: 0.60	Max: 7.30 Min: 4.50
3	20 inches	72 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit 50% or more), Fat Clay.	Max: 2.00 Min: 0.60	Max: 7.30 Min: 5.10

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silty clay loam

Surficial Soil Types: silty clay loam

Shallow Soil Types: silt loam

Deeper Soil Types: channery - silt loam
stratified
loam
unweathered bedrock

ADDITIONAL ENVIRONMENTAL RECORD SOURCES

According to ASTM E 1527-00, Section 7.2.2, "one or more additional state or local sources of environmental records may be checked, in the discretion of the environmental professional, to enhance and supplement federal and state sources... Factors to consider in determining which local or additional state records, if any, should be checked include (1) whether they are reasonably ascertainable, (2) whether they are sufficiently useful, accurate, and complete in light of the objective of the records review (see 7.1.1), and (3) whether they are obtained, pursuant to local, good commercial or customary practice." One of the record sources listed in Section 7.2.2 is water well information. Water well information can be used to assist the environmental professional in assessing sources that may impact groundwater flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS0905716	1/4 - 1/2 Mile ENE
2	USGS0905669	1/4 - 1/2 Mile NNE
A3	USGS0905753	1/4 - 1/2 Mile NW
A6	USGS0905682	1/4 - 1/2 Mile NW
B8	USGS0905863	1/2 - 1 Mile South
C10	USGS0905696	1/2 - 1 Mile WNW
D13	USGS0905917	1/2 - 1 Mile SE
E16	USGS0905737	1/2 - 1 Mile West
E17	USGS0905808	1/2 - 1 Mile West
F18	USGS0905577	1/2 - 1 Mile NW
E20	USGS0905803	1/2 - 1 Mile West
G23	USGS0905692	1/2 - 1 Mile WNW
H25	USGS0905882	1/2 - 1 Mile SSW
F26	USGS0905576	1/2 - 1 Mile NW
J30	USGS0906036	1/2 - 1 Mile SSW
K31	USGS0905929	1/2 - 1 Mile SW
L34	USGS0905791	1/2 - 1 Mile West
35	USGS0905674	1/2 - 1 Mile ENE
M36	USGS0905693	1/2 - 1 Mile ENE
N40	USGS0905738	1/2 - 1 Mile East
O43	USGS0905592	1/2 - 1 Mile WNW
N44	USGS0905735	1/2 - 1 Mile East
46	USGS0905711	1/2 - 1 Mile East
N47	USGS0905809	1/2 - 1 Mile East
49	USGS0905607	1/2 - 1 Mile North
51	USGS0905771	1/2 - 1 Mile West
P53	USGS0905807	1/2 - 1 Mile West
P56	USGS0905817	1/2 - 1 Mile West
58	USGS0905543	1/2 - 1 Mile NNW
R59	USGS0905523	1/2 - 1 Mile North
Q63	USGS0905568	1/2 - 1 Mile NE
Q65	USGS0905578	1/2 - 1 Mile ENE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
7	PA1150363	1/4 - 1/2 Mile SSW

Note: PWS System location is not always the same as well location.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A4	DPA00006216	1/4 - 1/2 Mile NW
A5	DPA00006224	1/4 - 1/2 Mile NW
C9	DPA00006113	1/2 - 1 Mile WNW
B11	DPA00005785	1/2 - 1 Mile South
D14	DPA00005825	1/2 - 1 Mile SSE
F19	DPA00006316	1/2 - 1 Mile NW
E21	DPA00005976	1/2 - 1 Mile West
G22	DPA00006141	1/2 - 1 Mile WNW
H24	DPA00005724	1/2 - 1 Mile SSW
I27	SPAW0063115	1/2 - 1 Mile WNW
I28	SPAW0063114	1/2 - 1 Mile WNW
J29	DPA00005682	1/2 - 1 Mile SSW
K32	DPA00005792	1/2 - 1 Mile SW
33	SPAW0063113	1/2 - 1 Mile NW
M37	DPA00006142	1/2 - 1 Mile ENE
38	SPAW0063116	1/2 - 1 Mile WNW
N39	DPA00005966	1/2 - 1 Mile East
L41	SPAW0063117	1/2 - 1 Mile West
O42	DPA00006282	1/2 - 1 Mile WNW
N45	DPA00005986	1/2 - 1 Mile East
N48	DPA00005957	1/2 - 1 Mile East
M50	SPAW0063105	1/2 - 1 Mile ENE
52	SPAW0055930	1/2 - 1 Mile SW
Q54	SPAW0056180	1/2 - 1 Mile NE
Q55	SPAW0056181	1/2 - 1 Mile NE
P57	DPA00005939	1/2 - 1 Mile West
R60	DPA00006551	1/2 - 1 Mile North
61	SPAW0056039	1/2 - 1 Mile NE
R62	SPAW0063107	1/2 - 1 Mile North
Q64	DPA00006317	1/2 - 1 Mile ENE

PHYSICAL SETTING SOURCE MAP - 01147135.1r



County Boundary
Major Roads
Contour Lines
Earthquake epicenter, Richter 5 or greater
Water Wells
Public Water Supply Wells
Cluster of Multiple Icons

0 1/4 1/2 1 Miles

Groundwater Flow Direction
Indeterminate Groundwater Flow at Location
Groundwater Flow Varies at Location

N

TARGET PROPERTY:	Baker Properties	CUSTOMER:	Vollmer Associates
ADDRESS:	City of Coatesville	CONTACT:	Tia Stevenson
CITY/STATE/ZIP:	Coatsville PA 19320	INQUIRY #:	01147135.1r
LAT/LONG:	39.9897 / 75.8207	DATE:	March 15, 2004 7:41 pm

Copyright © 2003 EDR, Inc. © 2003 GDT, Inc. Rel. 07/2003. All Rights Reserved.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
1		
ENE	**FED USGS**	**USGS0905716**
1/4 - 1/2 Mile		
Higher		

Agency:	USGS	Site ID:	395927075485101
Site Name:	CH 4307		
Dec. Latitude:	39.99094		
Dec. Longitude:	-75.81384		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	570		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	19950517
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377ANTM		
Aquifer type:	Not Reported		
Well depth:	Not Reported		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-06-11	26.6	

	Database	EDR ID Number
2		
NNE	**FED USGS**	**USGS0905669**
1/4 - 1/2 Mile		
Lower		

Agency:	USGS	Site ID:	395943075490701
Site Name:	CH 4329		
Dec. Latitude:	39.99538		
Dec. Longitude:	-75.81828		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	501		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	19950517
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	205		
Hole depth:	Not Reported	Source:	driller
Project no:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-06-11	13.9	

A3
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS0905753**

Agency:	USGS	Site ID:	395940075493701
Site Name:	CH 2416		
Dec. Latitude:	39.99455		
Dec. Longitude:	-75.82661		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	350		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	Not Reported		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 0

A4
NW
1/4 - 1/2 Mile
Lower

PA WELLS **DPA00006216**

Site ID:	395940075493701		
Local well #:	2416	Type of Site:	well
Well Depth:	Not Reported	Date Drilled:	Not Reported
Latitude:	395940	Longitude:	0754937
Lat/Long Accuracy:	ACCURATE TO +1 SECOND	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	400FCIGA	Topography:	HILLSIDE
Elevation Accuracy:	5	Elevation Method:	interpolated from topographic map
Elevation:	350	Quadrangle:	COATESVILLE
Date Record Created:	01/03/1984	Data Reliability:	field checked by reporting agency
Date Record Updated:	06/28/1994	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	IRWIN, ROBERT		
Date of Ownership:	08/18/1980	Zip Code:	Not Reported

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	GNEISS
Formation Code:	400FCIGA		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

Hydrogeologist Visits Information:

Date of Visit:	08/18/1980	Name of Visitor:	DAVIS D K

Water Quality Information:

Date of Measurement:	08/27/1980	Formation Sampled:	400PCKG
Code:	00010	Value:	14
Date of Measurement:	08/27/1980	Formation Sampled:	400PCKG
Code:	00095	Value:	395
Date of Measurement:	08/27/1980	Formation Sampled:	400PCKG
Code:	00400	Value:	5.8
Date of Measurement:	08/27/1980	Formation Sampled:	400PCKG
Code:	00900	Value:	200

A5
NW
1/4 - 1/2 Mile
Lower

PA WELLS **DPA00006224**

Site ID:	395941075493601		
Local well #:	920	Type of Site:	well
Well Depth:	68	Date Drilled:	01/01/1953
Latitude:	395941	Longitude:	0754936
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	400FCIGA	Topography:	HILLSIDE
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	350	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	TAYLOR, GEORGE		
Date of Ownership:	12/31/1953	Zip Code:	Not Reported

Construction Information:

Construction Date:	1953	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	OTHER/UNKNOWN
Driller:	WOMBLE, HOPE		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	METAMORPHIC (UNDIFFERENTIATED)
Formation Code:	400FCIGA		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Opening Information:

Top opening interval:	64	Bottom opening interval:	Not Reported
Interval Yield:	Not Reported	Type of Packing:	Not Reported
Opening Material:	UNKNOWN	Type of Opening:	fractured rock

Aquifer Test Information:

Discharge Date:	11/15/1963	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	.00
WL Data Source:	UNKNOWN		
WL Measurement Method:	UNKNOWN		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	F		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

Water Quality Information:

Date of Measurement:	11/15/1963	Formation Sampled:	000GRGS
Code:	00095	Value:	350
Date of Measurement:	11/15/1963	Formation Sampled:	000GRGS
Code:	00900	Value:	85

A6
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS0905682**

Agency:	USGS	Site ID:	395941075493601
Site Name:	CH 920		
Dec. Latitude:	39.99483		
Dec. Longitude:	-75.82634		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	350		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	19530101	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	68		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1963-11-15	0.00	

7
SSW
1/4 - 1/2 Mile
Lower

FRDS PWS **PA1150363**

PWS ID:	PA1150363	PWS Status:	Active
Date Initiated:	Not Reported	Date Deactivated:	Not Reported
PWS Name:	RAINBOW CAFE 1106 W LINCOLN HIGHWAY COATESVILLE, PA 19320		
Addressee / Facility:	Mailing RAINBOW CAFE ALEX CZIRJAK 1106 WEST LINCOLN HIGHWAY COATESVILLE, PA 19320		
Facility Latitude:	39 58 59	Facility Longitude:	075 49 27
City Served:	Not Reported		
Treatment Class:	Untreated	Population:	00000050

PWS currently has or had major violation(s) or enforcement: No

---

B8
South
1/2 - 1 Mile
Lower

FED USGS **USGS0905863**

Agency:	USGS	Site ID:	395856075491901
Site Name:	CH 918		
Dec. Latitude:	39.98233		
Dec. Longitude:	-75.82161		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	328		
Hydrologic code:	02040205		
Topographic:	Valley flat		
Site Type:	Ground-water other than Spring		
Const Date:	19550101	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377LDGR		
Aquifer type:	Not Reported		
Well depth:	97.0		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 0

C9
WNW
1/2 - 1 Mile
Lower

PA WELLS **DPA00006113**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Site ID:	395933075494801		
Local well #:	921	Type of Site:	well
Well Depth:	16	Date Drilled:	Not Reported
Latitude:	395933	Longitude:	0754948
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	400FCIGA	Topography:	VALLEY FLAT
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	340	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	RUCZHAK, ANN		
Date of Ownership:	11/15/1963	Zip Code:	Not Reported

Construction Information:

Construction Date:	Not Reported	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	DUG
Driller:	Not Reported		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	METAMORPHIC (UNDIFFERENTIATED)
Formation Code:	400FCIGA		

Aquifer Test Information:

Discharge Date:	11/15/1963	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	13.20
WL Data Source:	USGS OR PAGS		
WL Measurement Method:	STEEL TAPE		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	1		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

Water Quality Information:

Date of Measurement:	11/15/1963	Formation Sampled:	377CCKS
Code:	00095	Value:	100
Date of Measurement:	11/15/1963	Formation Sampled:	377CCKS
Code:	00900	Value:	34

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
C10 **WNW** **1/2 - 1 Mile** **Lower**	**FED USGS**	**USGS0905696**

Agency:	USGS	Site ID:	395933075494801
Site Name:	CH 921		
Dec. Latitude:	39.99261		
Dec. Longitude:	-75.82967		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	340		
Hydrologic code:	02040205		
Topographic:	Valley flat		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	16.0		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1963-11-15	13.24	

	Database	EDR ID Number
B11 **South** **1/2 - 1 Mile** **Lower**	**PA WELLS**	**DPA00005785**

Site ID:	395856075491901		
Local well #:	918	Type of Site:	well
Well Depth:	97	Date Drilled:	01/01/1955
Latitude:	395856	Longitude:	0754919
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	377LDGR	Topography:	VALLEY FLAT
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	330	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	HAINES, HERMAN		
Date of Ownership:	01/01/1955	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	5
Diameter:	6	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Construction Information:

Construction Date:	1955	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	OTHER/UNKNOWN
Driller:	MYERS, LEROY		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	DOLOMITE
Formation Code:	377LDGR		

Opening Information:

Top opening interval:	75	Bottom opening interval:	Not Reported
Interval Yield:	Not Reported	Type of Packing:	Not Reported
Opening Material:	UNKNOWN	Type of Opening:	fractured rock

Aquifer Test Information:

Discharge Date:	Not Reported	Discharge Type:	PUMPED
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	10	SWL:	Not Reported
WL Data Source:	Not Reported		
WL Measurement Method:	Not Reported		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	Not Reported		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	DESTROYED		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

D12
SSE
1/2 - 1 Mile
Lower

Site ID:	Not Reported
Groundwater Flow:	Not Reported
Shallowest Water Table Depth:	10.6
Deepest Water Table Depth:	Not Reported
Average Water Table Depth:	Not Reported
Date:	12/17/1992

AQUIFLOW **31495**

D13
SE
1/2 - 1 Mile
Lower

FED USGS **USGS0905917**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Agency:	USGS	Site ID:	395900075483001
Site Name:	CH 415		
Dec. Latitude:	39.98344		
Dec. Longitude:	-75.81522		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	320		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377LDGR		
Aquifer type:	Not Reported		
Well depth:	360		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 0

D14
SSE
1/2 - 1 Mile
Lower

PA WELLS **DPA00005825**

Site ID:	395900075483001		
Local well #:	415	Type of Site:	well
Well Depth:	360	Date Drilled:	Not Reported
Latitude:	395900	Longitude:	0754856
Lat/Long Accuracy:	ACCURATE TO +1 MINUTE	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	377LDGR	Topography:	HILLSIDE
Elevation Accuracy:	5	Elevation Method:	interpolated from topographic map
Elevation:	320	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	KIRK ICE CO		
Date of Ownership:	01/01/1925	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	10
Diameter:	10	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

Construction Information:

Construction Date:	Not Reported	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	CABLE TOOL
Driller:	Not Reported		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	DOLOMITE
Formation Code:	377LDGR		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Aquifer Test Information:

Discharge Date:	Not Reported	Discharge Type:	PUMPED
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	8	SWL:	Not Reported
WL Data Source:	Not Reported		
WL Measurement Method:	Not Reported		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	Not Reported		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	DESTROYED		

Water Use Information:

Use Date:	Not Reported	Use:	INDUSTRIAL

15
SE
1/2 - 1 Mile
Lower

Site ID:	15-23149
Groundwater Flow:	SE
Shallowest Water Table Depth:	6.31
Deepest Water Table Depth:	10.73
Average Water Table Depth:	Not Reported
Date:	04/28/1997

AQUIFLOW **31405**

E16
West
1/2 - 1 Mile
Lower

FED USGS **USGS0905737**

Agency:	USGS	Site ID:	395917075495801
Site Name:	CH 4336		
Dec. Latitude:	39.98816		
Dec. Longitude:	-75.83245		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	420		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	19950518
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377CCKS		
Aquifer type:	Not Reported		
Well depth:	Not Reported		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-08-13	21.8	

E17
West
1/2 - 1 Mile
Lower

FED USGS **USGS0905808**

Agency:	USGS	Site ID:	395917075500001
Site Name:	CH 4335		
Dec. Latitude:	39.98816		
Dec. Longitude:	-75.833		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	440		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	19950518
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377CCKS		
Aquifer type:	Not Reported		
Well depth:	Not Reported		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-08-13	40.9	

F18
NW
1/2 - 1 Mile
Lower

FED USGS **USGS0905577**

Agency:	USGS	Site ID:	395951075494401
Site Name:	CH 922		
Dec. Latitude:	39.99761		
Dec. Longitude:	-75.82856		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	480		
Hydrologic code:	02040205		
Topographic:	Hilltop		
Site Type:	Ground-water other than Spring		
Const Date:	19630101	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	93		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database	EDR ID Number
PA WELLS	DPA00006316

F19
NW
1/2 - 1 Mile
Lower

Site ID:	395951075494401		
Local well #:	922	Type of Site:	well
Well Depth:	93	Date Drilled:	01/01/1963
Latitude:	395951	Longitude:	0754944
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	400FCIGA	Topography:	HILLTOP
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	480	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	BROWN, L		
Date of Ownership:	12/31/1963	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	60
Diameter:	6	Casing Wall Thickness:	Not Reported
Casing Material:	STEEL		

Construction Information:

Construction Date:	1963	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	OTHER/UNKNOWN
Driller:	MYERS, LEROY		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	METAMORPHIC (UNDIFFERENTIATED)
Formation Code:	400FCIGA		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

Water Quality Information:

Date of Measurement:	11/15/1963	Formation Sampled:	000GRGS
Code:	00010	Value:	13.5
Date of Measurement:	11/15/1963	Formation Sampled:	000GRGS
Code:	00095	Value:	300

Date of Measurement:	11/15/1963	Formation Sampled:	000GRGS
Code:	00900	Value:	100

E20
West
1/2 - 1 Mile
Lower

FED USGS **USGS0905803**

Agency:	USGS	Site ID:	395918075500201
Site Name:	CH 945		
Dec. Latitude:	39.98844		
Dec. Longitude:	-75.83356		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	470		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377CCKS		
Aquifer type:	Not Reported		
Well depth:	80.0		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1963-11-14	36.06	

E21
West
1/2 - 1 Mile
Lower

PA WELLS **DPA00005976**

Site ID:	395918075500201		
Local well #:	945	Type of Site:	well
Well Depth:	80	Date Drilled:	Not Reported
Latitude:	395918	Longitude:	0755002
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	377CCKS	Topography:	HILLSIDE
Elevation Accuracy:	20	Elevation Method:	interpolated from topographic map
Elevation:	480	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	HINES, NORMAN		
Date of Ownership:	12/31/1963	Zip Code:	Not Reported

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	CONGLOMERATE
Formation Code:	377CCKS		

Aquifer Test Information:

Discharge Date:	11/14/1963	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	36.10
WL Data Source:	USGS OR PAGS		
WL Measurement Method:	STEEL TAPE		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	1		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

Water Quality Information:

Date of Measurement:	11/14/1963	Formation Sampled:	377CCKS
Code:	00010	Value:	14.5
Date of Measurement:	11/14/1963	Formation Sampled:	377CCKS
Code:	00095	Value:	80
Date of Measurement:	11/14/1963	Formation Sampled:	377CCKS
Code:	00400	Value:	5.1
Date of Measurement:	11/14/1963	Formation Sampled:	377CCKS
Code:	00900	Value:	34

G22
WNW
1/2 - 1 Mile
Lower

PA WELLS **DPA00006141**

Site ID:	395935075500001		
Local well #:	3054	Type of Site:	well
Well Depth:	220	Date Drilled:	06/18/1973
Latitude:	395935	Longitude:	0755000
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	400FCIGA	Topography:	HILLSIDE
Elevation Accuracy:	Not Reported	Elevation Method:	unknown
Elevation:	Not Reported	Quadrangle:	COATESVILLE
Date Record Created:	12/10/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	MILLER, ALFRED		
Date of Ownership:	06/18/1973	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	29
Diameter:	6	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Construction Information:

Construction Date:	06/18/1973	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	AIR ROTARY
Driller:	KEYES, THOMAS		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	IGNEOUS (UNDIFFERENTIATED)
Formation Code:	400FCIGA		

Aquifer Test Information:

Discharge Date:	06/18/1973	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	87.00
WL Data Source:	USGS OR PAGS		
WL Measurement Method:	REPORTED, METHOD NOT KNOWN		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	1		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

G23
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS0905692**

Agency:	USGS	Site ID:	395935075500001
Site Name:	CH 3054		
Dec. Latitude:	39.99316		
Dec. Longitude:	-75.833		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	Not Reported		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	19730618	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	220		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1973-06-18	87.00	

H24
SSW
1/2 - 1 Mile
Lower

PA WELLS **DPA00005724**

Site ID:	395849075493501		
Local well #:	2810	Type of Site:	well
Well Depth:	25	Date Drilled:	1966
Latitude:	395849	Longitude:	0754935
Lat/Long Accuracy:	ACCURATE TO +1 SECOND	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	1	Topography:	VALLEY FLAT
Elevation Accuracy:	.1	Elevation Method:	level or other surveying method
Elevation:	309.3	Quadrangle:	COATESVILLE
Date Record Created:	08/08/1986	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	WELL OWNER
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	LUKENS STEEL CO		
Date of Ownership:	1966	Zip Code:	Not Reported

Other Owner Identification Information:

Other Identifier:	26	ID Assigner:	OWNER PA

Casing Information:

Casing Top:	0	Casing Bottom:	25
Diameter:	1.5	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

Construction Information:

Construction Date:	196602	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	BORED OR AUGERED
Driller:	SPRAGUE & HENWOOD INC		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	DOLOMITE
Formation Code:	377LDGR		

Hole Information:

Top of the Hole:	0	Bottom of the Hole:	25
Diameter:	4		

Aquifer Test Information:

Discharge Date:	1966	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	7.00
WL Data Source:	WELL OWNER		
WL Measurement Method:	REPORTED, METHOD NOT KNOWN		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	1		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	DESTROYED		

Water Use Information:

Use Date:	Not Reported	Use:	UNUSED

Hydrogeologist Visits Information:

Date of Visit:	11/07/1984	Name of Visitor:	WOOD, C R

H25
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS0905882**

Agency:	USGS	Site ID:	395849075493501
Site Name:	CH 2810		
Dec. Latitude:	39.98038		
Dec. Longitude:	-75.82606		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	309.3		
Hydrologic code:	02040205		
Topographic:	Valley flat		
Site Type:	Ground-water other than Spring		
Const Date:	1966	Inven Date:	1966
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	Not Reported		
Aquifer type:	Not Reported		
Well depth:	25		
Hole depth:	Not Reported	Source:	owner
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
0000-00	7	

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
F26 **NW** **1/2 - 1 Mile** **Lower**	**FED USGS**	**USGS0905576**

Agency:	USGS	Site ID:	395951075494701
Site Name:	CH 4318		
Dec. Latitude:	39.99761		
Dec. Longitude:	-75.82939		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	470		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	19950517
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	503		
Hole depth:	Not Reported	Source:	owner
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-06-26	30.34	

	Database	EDR ID Number
I27 **WNW** **1/2 - 1 Mile** **Lower**	**PA WELLS**	**SPAW0063115**

Well ID:	X 3400		
Owner's Name:	CHAPMAN JACOB	County	CHESTER
Latitude:	395939	Longitude:	755002
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	Not Reported	Topographic Setting:	Not Reported
Water Usage:	DOMESTIC	Site Usage:	WITHDRAWAL
Well Depth:	213	Finish:	OPEN HOLE
Casing 1:	42	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	00-00-00
Static Water Level:	Not Reported	Production WL:	Not Reported
Yield (gpm):	3	Yield Measurement Method:	Not Reported
Drawdown:	Not Reported	Test Time:	Not Reported
Bedrock:	20	Driller:	0308
Water Bearing Zone 1:	60	Water Bearing Zone 2:	90
Water Bearing Zone 3:	Not Reported	Lithology:	GRANITE
Municipality:	VALLEY	Remark:	1939
Aquifer:	BALTIMORE GNEISS		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
I28 **WNW** **1/2 - 1 Mile** **Lower**	**PA WELLS**	**SPAW0063114**

Well ID:	X 3399		
Owner's Name:	GRAY HAROLD	County	CHESTER
Latitude:	395939	Longitude:	755002
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	Not Reported	Topographic Setting:	Not Reported
Water Usage:	DOMESTIC	Site Usage:	WITHDRAWAL
Well Depth:	123	Finish:	OPEN HOLE
Casing 1:	34	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	00-00-00
Static Water Level:	50	Production WL:	Not Reported
Yield (gpm):	10	Yield Measurement Method:	1
Drawdown:	72	Test Time:	1
Bedrock:	30	Driller:	0248
Water Bearing Zone 1:	106	Water Bearing Zone 2:	Not Reported
Water Bearing Zone 3:	Not Reported	Lithology:	Not Reported
Municipality:	VALLEY	Remark:	1939
Aquifer:	BALTIMORE GNEISS		

	Database	EDR ID Number
J29 **SSW** **1/2 - 1 Mile** **Lower**	**PA WELLS**	**DPA00005682**

Site ID:	395844075493201		
Local well #:	2808	Type of Site:	well
Well Depth:	21	Date Drilled:	1966
Latitude:	395844	Longitude:	0754932
Lat/Long Accuracy:	ACCURATE TO +1 SECOND	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	1	Topography:	VALLEY FLAT
Elevation Accuracy:	.01	Elevation Method:	level or other surveying method
Elevation:	308	Quadrangle:	COATESVILLE
Date Record Created:	08/08/1986	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	WELL OWNER
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	LUKENS STEEL CO		
Date of Ownership:	12/31/1966	Zip Code:	Not Reported

Other Owner Identification Information:

Other Identifier:	17	ID Assigner:	OWNER PA

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	LIMESTONE
Formation Code:	367CNSG		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Aquifer Test Information:

Discharge Date:	1966	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	10.20
WL Data Source:	WELL OWNER		
WL Measurement Method:	REPORTED, METHOD NOT KNOWN		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	1		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	DESTROYED		

Water Use Information:

Use Date:	Not Reported	Use:	UNUSED

Hydrogeologist Visits Information:

Date of Visit:	11/07/1984	Name of Visitor:	WOOD, C R

J30
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS0906036**

Agency:	USGS	Site ID:	395844075493201
Site Name:	CH 2808		
Dec. Latitude:	39.97899		
Dec. Longitude:	-75.82522		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	308.04		
Hydrologic code:	02040205		
Topographic:	Valley flat		
Site Type:	Ground-water other than Spring		
Const Date:	1966	Inven Date:	1966
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	Not Reported		
Aquifer type:	Not Reported		
Well depth:	21		
Hole depth:	Not Reported	Source:	owner
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
0000-00	10.25	

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
K31 **SW** **1/2 - 1 Mile** **Lower**	**FED USGS**	**USGS0905929**

Agency:	USGS	Site ID:	395857075495801
Site Name:	CH 2818		
Dec. Latitude:	39.98261		
Dec. Longitude:	-75.83245		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	440		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	19810204	Inven Date:	19810204
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	Not Reported		
Aquifer type:	Not Reported		
Well depth:	79		
Hole depth:	Not Reported	Source:	driller
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1984-11-09	35.85	

	Database	EDR ID Number
K32 **SW** **1/2 - 1 Mile** **Lower**	**PA WELLS**	**DPA00005792**

Site ID:	395857075495801		
Local well #:	2818	Type of Site:	well
Well Depth:	79	Date Drilled:	02/04/1981
Latitude:	395857	Longitude:	0754958
Lat/Long Accuracy:	ACCURATE TO +1 SECOND	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	1	Topography:	HILLSIDE
Elevation Accuracy:	5	Elevation Method:	interpolated from topographic map
Elevation:	440	Quadrangle:	COATESVILLE
Date Record Created:	08/08/1986	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	DRILLER
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	CITY OF COATESVILLE		
Date of Ownership:	198102	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	35
Diameter:	6	Casing Wall Thickness:	Not Reported
Casing Material:	STEEL		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Construction Information:

Construction Date:	02/04/1981	Finish:	Not Reported
Const. Data Source:	DRILLER	Construction Method:	AIR ROTARY
Driller:	PETERSHEIM BROS		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	SCHIST
Formation Code:	377HRPR		

Hole Information:

Top of the Hole:	0	Bottom of the Hole:	79
Diameter:	6		

Aquifer Test Information:

Discharge Date:	02/04/1981	Discharge Type:	PUMPED
Data Source:	DRILLER		
Measurement Method:	REPORTED, METHOD NOT KNOWN		
Discharge:	4	SWL:	54.10
WL Data Source:	Not Reported		
WL Measurement Method:	Not Reported		
Production WL:	75	Drawdown:	33
Spec. Cap.:	0.12	Test Length:	0.5
Status during measurement:	Not Reported		
Discharge Date:	11/09/1984	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	35.80
WL Data Source:	USGS OR PAGS		
WL Measurement Method:	STEEL TAPE		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	1		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	UNUSED		

Water Use Information:

Use Date:	Not Reported	Use:	UNUSED

Hydrogeologist Visits Information:

Date of Visit:	11/07/1984	Name of Visitor:	WOOD, C R

33
NW
1/2 - 1 Mile
Lower

PA WELLS **SPAW0063113**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Well ID:	X 3398		
Owner's Name:	VOELOKER J W	County	CHESTER
Latitude:	395958	Longitude:	754947
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	Not Reported	Topographic Setting:	Not Reported
Water Usage:	DOMESTIC	Site Usage:	WITHDRAWAL
Well Depth:	128	Finish:	OPEN HOLE
Casing 1:	42	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	00-00-00
Static Water Level:	51	Production WL:	Not Reported
Yield (gpm):	5	Yield Measurement Method:	Not Reported
Drawdown:	Not Reported	Test Time:	Not Reported
Bedrock:	37	Driller:	1308
Water Bearing Zone 1:	60	Water Bearing Zone 2:	Not Reported
Water Bearing Zone 3:	Not Reported	Lithology:	Not Reported
Municipality:	VALLEY	Remark:	1939
Aquifer:	BALTIMORE GNEISS		

L34
West
1/2 - 1 Mile
Lower

FED USGS **USGS0905791**

Agency:	USGS	Site ID:	395922075501201
Site Name:	CH 4309		
Dec. Latitude:	39.98955		
Dec. Longitude:	-75.83634		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	551		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	19950517
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400BMFGA		
Aquifer type:	Not Reported		
Well depth:	Not Reported		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-06-12	8.7	

35
ENE
1/2 - 1 Mile
Higher

FED USGS **USGS0905674**

Agency:	USGS	Site ID:	395942075482501
Site Name:	CH 4305		
Dec. Latitude:	39.99511		
Dec. Longitude:	-75.80661		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	620		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	19950517
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377CCKS		
Aquifer type:	Not Reported		
Well depth:	16		
Hole depth:	Not Reported	Source:	owner
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-05-20	11	

M36
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS0905693**

Agency:	USGS	Site ID:	395935075482101
Site Name:	CH 413		
Dec. Latitude:	39.99316		
Dec. Longitude:	-75.8055		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	460		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377HRPR		
Aquifer type:	Not Reported		
Well depth:	160		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 0

M37
ENE
1/2 - 1 Mile
Lower

PA WELLS **DPA00006142**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Site ID:	395935075482101		
Local well #:	413	Type of Site:	well
Well Depth:	160	Date Drilled:	Not Reported
Latitude:	395935	Longitude:	0754821
Lat/Long Accuracy:	ACCURATE TO +1 SECOND	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	377HRPR	Topography:	HILLSIDE
Elevation Accuracy:	5	Elevation Method:	interpolated from topographic map
Elevation:	460	Quadrangle:	COATESVILLE
Date Record Created:	07/03/1984	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	BROWN'S GREENHOUSE		
Date of Ownership:	Not Reported	Zip Code:	Not Reported

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	METAMORPHIC (UNDIFFERENTIATED)
Formation Code:	377HRPR		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	DESTROYED		

Water Use Information:

Use Date:	Not Reported	Use:	UNUSED

38
WNW
1/2 - 1 Mile
Lower

PA WELLS **SPAW0063116**

Well ID:	X 3401		
Owner's Name:	MILLER ALFRED	County	CHESTER
Latitude:	395932	Longitude:	755012
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	Not Reported	Topographic Setting:	Not Reported
Water Usage:	DOMESTIC	Site Usage:	WITHDRAWAL
Well Depth:	220	Finish:	OPEN HOLE
Casing 1:	29	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	00-00-00
Static Water Level:	87	Production WL:	Not Reported
Yield (gpm):	Not Reported	Yield Measurement Method:	1
Drawdown:	142	Test Time:	1
Bedrock:	25	Driller:	0248
Water Bearing Zone 1:	Not Reported	Water Bearing Zone 2:	Not Reported
Water Bearing Zone 3:	Not Reported	Lithology:	OTHER
Municipality:	VALLEY	Remark:	1939
Aquifer:	BALTIMORE GNEISS		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
N39 **East** **1/2 - 1 Mile** **Lower**	**PA WELLS**	**DPA00005966**

Site ID:	395917075481801		
Local well #:	905	Type of Site:	well
Well Depth:	128	Date Drilled:	01/01/1954
Latitude:	395917	Longitude:	0754818
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	377LDGR	Topography:	VALLEY FLAT
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	360	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	PRODUCERS COOP EXCHANGE		
Date of Ownership:	12/31/1954	Zip Code:	Not Reported
Owner:	KALLMAN CO		
Date of Ownership:	05/19/1984	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	60
Diameter:	12	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

Construction Information:

Construction Date:	1954	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	OTHER/UNKNOWN
Driller:	MYERS, LEROY		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	DOLOMITE
Formation Code:	377LDGR		

Aquifer Test Information:

Discharge Date:	05/19/1976	Discharge Type:	PUMPED
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	150	SWL:	26.00
WL Data Source:	Not Reported		
WL Measurement Method:	Not Reported		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	Not Reported		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Water Use Information:

Use Date:	Not Reported	Use:	AIR CONDITIONING

N40
East
1/2 - 1 Mile
Lower

FED USGS **USGS0905738**

Agency:	USGS	Site ID:	395917075481801
Site Name:	CH 905		
Dec. Latitude:	39.98816		
Dec. Longitude:	-75.80467		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	360		
Hydrologic code:	02040205		
Topographic:	Valley flat		
Site Type:	Ground-water other than Spring		
Const Date:	19540101	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377LDGR		
Aquifer type:	Not Reported		
Well depth:	128		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1976-05-19	26	

L41
West
1/2 - 1 Mile
Lower

PA WELLS **SPAW0063117**

Well ID:	X 3402		
Owner's Name:	PATWIL INC	County	CHESTER
Latitude:	395922	Longitude:	755014
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	Not Reported	Topographic Setting:	Not Reported
Water Usage:	DOMESTIC	Site Usage:	WITHDRAWAL
Well Depth:	95	Finish:	OPEN HOLE
Casing 1:	24	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	00-00-00
Static Water Level:	Not Reported	Production WL:	Not Reported
Yield (gpm):	30	Yield Measurement Method:	Not Reported
Drawdown:	Not Reported	Test Time:	Not Reported
Bedrock:	19	Driller:	1290
Water Bearing Zone 1:	35	Water Bearing Zone 2:	65
Water Bearing Zone 3:	Not Reported	Lithology:	GRANITE
Municipality:	VALLEY	Remark:	1939
Aquifer:	GABBRO/GABBROIC GNEISS		

GEOCHECK®- PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
O42 **WNW** **1/2 - 1 Mile** **Lower**	**PA WELLS**	**DPA00006282**

Site ID:	395947075500501		
Local well #:	408	Type of Site:	well
Well Depth:	50	Date Drilled:	01/01/1934
Latitude:	395947	Longitude:	0755005
Lat/Long Accuracy:	ACCURATE TO +1 SECOND	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	400BMFGA	Topography:	HILLSIDE
Elevation Accuracy:	5	Elevation Method:	interpolated from topographic map
Elevation:	405	Quadrangle:	COATESVILLE
Date Record Created:	08/08/1986	Data Reliability:	not fld checked, rprting agency considers it ok
Date Record Updated:	03/03/1990	Depth Data Source:	USGS OR PAGS
Agency use of site:	Inventory Data Site Only		

Casing Information:

Casing Top:	0	Casing Bottom:	10
Diameter:	6	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

Construction Information:

Construction Date:	Not Reported	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	CABLE TOOL
Driller:	Not Reported		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	DIORITE
Formation Code:	400BMFGA		

Hole Information:

Top of the Hole:	0	Bottom of the Hole:	50
Diameter:	6		

Opening Information:

Top opening interval:	30	Bottom opening interval:	Not Reported
Interval Yield:	Not Reported	Type of Packing:	Not Reported
Opening Material:	UNKNOWN	Type of Opening:	fractured rock

Aquifer Test Information:

Discharge Date:	1934	Discharge Type:	PUMPED
Data Source:	USGS OR PAGS		
Measurement Method:	Not Reported		
Discharge:	2	SWL:	Not Reported
WL Data Source:	Not Reported		
WL Measurement Method:	Not Reported		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	Not Reported		

Discharge Date:	07/11/1951	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	30.00
WL Data Source:	UNKNOWN		
WL Measurement Method:	UNKNOWN		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	1		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

O43
WNW
1/2 - 1 Mile
Lower

FED USGS **USGS0905592**

Agency:	USGS	Site ID:	395947075500501
Site Name:	CH 408		
Dec. Latitude:	39.99649		
Dec. Longitude:	-75.83439		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	405		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	19340101	Inven Date:	19510711
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400BMFGA		
Aquifer type:	Not Reported		
Well depth:	50		
Hole depth:	Not Reported	Source:	reporting agency (generally USGS)
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1951-07-11	30	

N44
East
1/2 - 1 Mile
Lower

FED USGS **USGS0905735**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Agency:	USGS	Site ID:	395919075481701
Site Name:	CH 907		
Dec. Latitude:	39.98872		
Dec. Longitude:	-75.80439		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	360		
Hydrologic code:	02040205		
Topographic:	Valley flat		
Site Type:	Ground-water other than Spring		
Const Date:	19560101	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377LDGR		
Aquifer type:	Not Reported		
Well depth:	250		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1963-09-30	33.03	

N45
East
1/2 - 1 Mile
Lower

PA WELLS **DPA00005986**

Site ID:	395919075481701		
Local well #:	907	Type of Site:	well
Well Depth:	250	Date Drilled:	01/01/1956
Latitude:	395919	Longitude:	0754817
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	377LDGR	Topography:	VALLEY FLAT
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	360	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	PRODUCERS COOP EXCHANGE		
Date of Ownership:	12/31/1956	Zip Code:	Not Reported
Owner:	KALLMAN CO		
Date of Ownership:	05/18/1984	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	Not Reported
Diameter:	8	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

Construction Information:

Construction Date:	1956	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	OTHER/UNKNOWN
Driller:	MYERS, LEROY		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	DOLOMITE
Formation Code:	377LDGR		

Aquifer Test Information:

Discharge Date:	09/30/1963	Discharge Type:	PUMPED
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	15	SWL:	33.00
WL Data Source:	USGS OR PAGS		
WL Measurement Method:	STEEL TAPE		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	Not Reported		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	DESTROYED		

Water Use Information:

Use Date:	Not Reported	Use:	UNUSED

46
East
1/2 - 1 Mile
Lower

FED USGS **USGS0905711**

Agency:	USGS	Site ID:	395928075481701
Site Name:	CH SP40		
Dec. Latitude:	39.99122		
Dec. Longitude:	-75.80439		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	410		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Spring		
Const Date:	Not Reported	Inven Date:	19900720
Well Type:	Spring		
Primary Aquifer:	377AMHP		
Aquifer type:	Not Reported		
Well depth:	Not Reported		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 0

N47
East
1/2 - 1 Mile
Lower

FED USGS **USGS0905809**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Agency:	USGS	Site ID:	395916075481601
Site Name:	CH 906		
Dec. Latitude:	39.98788		
Dec. Longitude:	-75.80411		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	360		
Hydrologic code:	02040205		
Topographic:	Valley flat		
Site Type:	Ground-water other than Spring		
Const Date:	19550101	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	377LDGR		
Aquifer type:	Not Reported		
Well depth:	400		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1984-05-18	15.16	

N48
East
1/2 - 1 Mile
Lower

PA WELLS **DPA00005957**

Site ID:	395916075481601		
Local well #:	906	Type of Site:	well
Well Depth:	400	Date Drilled:	01/01/1955
Latitude:	395916	Longitude:	0754816
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	COATESVILLE
Formation:	377LDGR	Topography:	VALLEY FLAT
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	360	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	PRODUCERS COOP EXCHANGE		
Date of Ownership:	12/31/1955	Zip Code:	Not Reported
Owner:	KALLMAN CO		
Date of Ownership:	05/18/1984	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	100
Diameter:	8	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

Construction Information:

Construction Date:	1955	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	OTHER/UNKNOWN
Driller:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	DOLOMITE
Formation Code:	377LDGR		

Opening Information:

Top opening interval:	150	Bottom opening interval:	Not Reported
Interval Yield:	Not Reported	Type of Packing:	Not Reported
Opening Material:	UNKNOWN	Type of Opening:	fractured rock

Aquifer Test Information:

Discharge Date:	05/18/1984	Discharge Type:	PUMPED
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	60	SWL:	15.20
WL Data Source:	USGS OR PAGS		
WL Measurement Method:	STEEL TAPE		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	Not Reported		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	UNUSED		

Water Use Information:

Use Date:	Not Reported	Use:	UNUSED

Water Quality Information:

Date of Measurement:	09/30/1963	Formation Sampled:	377LDGR
Code:	00095	Value:	510
Date of Measurement:	09/30/1963	Formation Sampled:	377LDGR
Code:	00400	Value:	7.1
Date of Measurement:	09/30/1963	Formation Sampled:	377LDGR
Code:	00900	Value:	260

49
North
1/2 - 1 Mile
Lower

FED USGS **USGS0905607**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Agency:	USGS	Site ID:	400009075491001
Site Name:	CH 4302		
Dec. Latitude:	40.00261		
Dec. Longitude:	-75.81911		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	520		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	19820422	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	120		
Hole depth:	Not Reported	Source:	driller
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-05-28	41.75	

M50
ENE
1/2 - 1 Mile
Higher

PA WELLS **SPAW0063105**

Well ID:	X 1435		
Owner's Name:	CHESTNUT JOHN	County	CHESTER
Latitude:	395937	Longitude:	754818
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	Not Reported	Topographic Setting:	HILLSIDE
Water Usage:	DOMESTIC	Site Usage:	WITHDRAWAL
Well Depth:	80	Finish:	OPEN HOLE
Casing 1:	25	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	00-00-70
Static Water Level:	30	Production WL:	Not Reported
Yield (gpm):	15	Yield Measurement Method:	3
Drawdown:	Not Reported	Test Time:	1
Bedrock:	25	Driller:	0154
Water Bearing Zone 1:	45	Water Bearing Zone 2:	70
Water Bearing Zone 3:	Not Reported	Lithology:	SANDSTONE
Municipality:	VALLEY	Remark:	1939
Aquifer:	CHICKIES FORMATION		

51
West
1/2 - 1 Mile
Lower

FED USGS **USGS0905771**

Agency:	USGS	Site ID:	395931075501701
Site Name:	CH 4310		
Dec. Latitude:	39.99205		
Dec. Longitude:	-75.83773		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	529		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	Not Reported	Inven Date:	19950517
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	75		
Hole depth:	Not Reported	Source:	driller
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-06-12	39.52	

52
SW
1/2 - 1 Mile
Lower

PA WELLS **SPAW0055930**

Well ID:	7006N		
Owner's Name:	ENVIRONMENTAL RES.	County	CHESTER
Latitude:	395853	Longitude:	755007
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	02040205	Topographic Setting:	HILLSIDE
Water Usage:	Not Reported	Site Usage:	Not Reported
Well Depth:	79	Finish:	OPEN HOLE
Casing 1:	35	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	02-00-81
Static Water Level:	42	Production WL:	75
Yield (gpm):	4	Yield Measurement Method:	V
Drawdown:	33	Test Time:	0.5
Bedrock:	35	Driller:	308
Water Bearing Zone 1:	50	Water Bearing Zone 2:	75
Water Bearing Zone 3:	Not Reported	Lithology:	SCHIST
Municipality:	COATESVILLE	Remark:	Not Reported
Aquifer:	ANTIETAM FORMATION		

P53
West
1/2 - 1 Mile
Lower

FED USGS **USGS0905807**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Agency:	USGS	Site ID:	395917075502001
Site Name:	CH 4333		
Dec. Latitude:	39.98816		
Dec. Longitude:	-75.83856		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	565		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	1965	Inven Date:	19950518
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400BMFGA		
Aquifer type:	Not Reported		
Well depth:	70		
Hole depth:	Not Reported	Source:	owner
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-08-13	39.95	

Q54
NE
1/2 - 1 Mile
Lower

PA WELLS **SPAW0056180**

Well ID:	X 3381		
Owner's Name:	Not Reported	County	CHESTER
Latitude:	395952	Longitude:	754822
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	Not Reported	Topographic Setting:	Not Reported
Water Usage:	DOMESTIC	Site Usage:	WITHDRAWAL
Well Depth:	120	Finish:	OPEN HOLE
Casing 1:	20	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	00-00-00
Static Water Level:	27	Production WL:	Not Reported
Yield (gpm):	5	Yield Measurement Method:	Not Reported
Drawdown:	Not Reported	Test Time:	1
Bedrock:	15	Driller:	1290
Water Bearing Zone 1:	75	Water Bearing Zone 2:	110
Water Bearing Zone 3:	Not Reported	Lithology:	GRANITE
Municipality:	CALN	Remark:	1939
Aquifer:	BALTIMORE GNEISS		

Q55
NE
1/2 - 1 Mile
Lower

PA WELLS **SPAW0056181**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Well ID:	X 3382		
Owner's Name:	DOUTRICH HOMES	County	CHESTER
Latitude:	395952	Longitude:	754822
Quadrangle:	COATESVILLE	Lat/Long Accuracy:	ACCURATE TO +1 MINUTE
Hydrologic Unit:	Not Reported	Topographic Setting:	Not Reported
Water Usage:	DOMESTIC	Site Usage:	WITHDRAWAL
Well Depth:	200	Finish:	OPEN HOLE
Casing 1:	40	Casing1 Diameter(inches):	6
Casing2:	Not Reported	Casing2 Diameter(inches):	Not Reported
Grouted:	Not Reported	Date Drilled:	00-00-00
Static Water Level:	Not Reported	Production WL:	Not Reported
Yield (gpm):	4	Yield Measurement Method:	Not Reported
Drawdown:	Not Reported	Test Time:	1
Bedrock:	35	Driller:	1290
Water Bearing Zone 1:	125	Water Bearing Zone 2:	185
Water Bearing Zone 3:	Not Reported	Lithology:	GRANITE
Municipality:	CALN	Remark:	1939
Aquifer:	BALTIMORE GNEISS		

P56
West
1/2 - 1 Mile
Lower

FED USGS **USGS0905817**

Agency:	USGS	Site ID:	395914075502101
Site Name:	CH 944		
Dec. Latitude:	39.98733		
Dec. Longitude:	-75.83884		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	585		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	19631114	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FMFG		
Aquifer type:	Not Reported		
Well depth:	Not Reported		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1963-11-14	67.00	

P57
West
1/2 - 1 Mile
Lower

PA WELLS **DPA00005939**

GEOCHECK®- PHYSICAL SETTING SOURCE MAP FINDINGS

Site ID:	395914075502101		
Local well #:	944	Type of Site:	well
Well Depth:	Not Reported	Date Drilled:	11/14/1963
Latitude:	395914	Longitude:	0755021
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	400FMFG	Topography:	HILLSIDE
Elevation Accuracy:	10	Elevation Method:	Interpolated from topographic map
Elevation:	590	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	SCOTT, BEN		
Date of Ownership:	11/14/1963	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	Not Reported
Diameter:	6	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

Construction Information:

Construction Date:	Not Reported	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	OTHER/UNKNOWN
Driller:	Not Reported		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	METAMORPHIC (UNDIFFERENTIATED)
Formation Code:	400FMFG		

Aquifer Test Information:

Discharge Date:	11/14/1963	Discharge Type:	Not Reported
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	Not Reported	SWL:	67.00
WL Data Source:	USGS OR PAGS		
WL Measurement Method:	STEEL TAPE		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	Not Reported	Test Length:	Not Reported
Status during measurement:	1		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

Water Quality Information:

Date of Measurement:	11/14/1963	Formation Sampled:	000GRGS
Code:	00095	Value:	220

Date of Measurement:	11/14/1963	Formation Sampled:	000GRGS
Code:	00900	Value:	68

58
NNW
1/2 - 1 Mile
Lower

FED USGS **USGS0905543**

Agency:	USGS	Site ID:	400006075495101
Site Name:	CH 4301		
Dec. Latitude:	40.00177		
Dec. Longitude:	-75.8305		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	540		
Hydrologic code:	02040205		
Topographic:	Hilltop		
Site Type:	Ground-water other than Spring		
Const Date:	1984	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400BMFGA		
Aquifer type:	Not Reported		
Well depth:	300		
Hole depth:	Not Reported	Source:	owner
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1992-05-28	59.8	

R59
North
1/2 - 1 Mile
Lower

FED USGS **USGS0905523**

Agency:	USGS	Site ID:	400014075491801
Site Name:	CH 3081		
Dec. Latitude:	40.00399		
Dec. Longitude:	-75.82134		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	360		
Hydrologic code:	02040205		
Topographic:	Valley flat		
Site Type:	Ground-water other than Spring		
Const Date:	19870414	Inven Date:	19870729
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	Not Reported		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
R60 **North** **1/2 - 1 Mile** **Lower**	**PA WELLS**	**DPA00006551**

Site ID:	400014075491801		
Local well #:	3081	Type of Site:	well
Well Depth:	Not Reported	Date Drilled:	04/14/1987
Latitude:	400014	Longitude:	0754918
Lat/Long Accuracy:	ACCURATE TO +1 SECOND	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	VALLEY
Formation:	400FCIGA	Topography:	VALLEY FLAT
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	360	Quadrangle:	WAGONTOWN
Date Record Created:	08/03/1987	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	TURKEY HILL MINI-MART		
Date of Ownership:	04/14/1987	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	Not Reported
Diameter:	6	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

Construction Information:

Construction Date:	04/14/1987	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	AIR ROTARY
Driller:	E J MYERS & SONS		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	UNKNOWN
Formation Code:	400FCIGA		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	COMMERCIAL

Hydrogeologist Visits Information:

Date of Visit:	07/28/1987	Name of Visitor:	VOGEL

Water Quality Information:

Date of Measurement:	07/28/1987	Formation Sampled:	000GRDR
Code:	00010	Value:	14

GEOCHECK®- PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
Q63 **NE** **1/2 - 1 Mile** **Lower**	**FED USGS**	**USGS0905568**

Agency:	USGS	Site ID:	395954075482201
Site Name:	CH 4534		
Dec. Latitude:	39.99844		
Dec. Longitude:	-75.80578		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	550		
Hydrologic code:	02040205		
Topographic:	Hillside (slope)		
Site Type:	Ground-water other than Spring		
Const Date:	199101	Inven Date:	19950523
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	396		
Hole depth:	Not Reported	Source:	driller
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1993-08-02	16.06	

Q64 **ENE** **1/2 - 1 Mile** **Lower**		**PA WELLS**	**DPA00006317**
Site ID:	395951075481901		
Local well #:	904	Type of Site:	well
Well Depth:	120	Date Drilled:	03/26/1962
Latitude:	395951	Longitude:	0754819
Lat/Long Accuracy:	UNKNOWN	Hydrologic Unit:	02040205
County:	CHESTER	Municipality:	CALN
Formation:	400FCIGA	Topography:	UPLAND DRAW
Elevation Accuracy:	10	Elevation Method:	interpolated from topographic map
Elevation:	600	Quadrangle:	COATESVILLE
Date Record Created:	12/06/1976	Data Reliability:	field checked by reporting agency
Date Record Updated:	03/03/1990	Depth Data Source:	UNKNOWN
Agency use of site:	Inventory Data Site Only		

Owner Information:

Owner:	MAHAM, CECIL		
Date of Ownership:	03/26/1962	Zip Code:	Not Reported

Casing Information:

Casing Top:	0	Casing Bottom:	21
Diameter:	6	Casing Wall Thickness:	Not Reported
Casing Material:	UNKNOWN		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Construction Information:

Construction Date:	1962	Finish:	Not Reported
Const. Data Source:	UNKNOWN	Construction Method:	OTHER/UNKNOWN
Driller:	MYERS, LEROY		

Geohydrologic Information:

Top of Interval:	Not Reported	Bottom of Interval:	Not Reported
Contributing Unit:	PRIMARY	Lithology:	METAMORPHIC (UNDIFFERENTIATED)
Formation Code:	400FCIGA		

Aquifer Test Information:

Discharge Date:	06/06/1963	Discharge Type:	PUMPED
Data Source:	Not Reported		
Measurement Method:	Not Reported		
Discharge:	13	SWL:	34.00
WL Data Source:	USGS OR PAGS		
WL Measurement Method:	STEEL TAPE		
Production WL:	Not Reported	Drawdown:	Not Reported
Spec. Cap.:	0.6	Test Length:	Not Reported
Status during measurement:	Not Reported		

Site Use Information:

Date of Use:	Not Reported	Note:	Not Reported
Site Use:	WITHDRAWAL		

Water Use Information:

Use Date:	Not Reported	Use:	DOMESTIC

Water Quality Information:

Date of Measurement:	04/10/1963	Formation Sampled:	000GRGS
Code:	00095	Value:	75
Date of Measurement:	04/10/1963	Formation Sampled:	000GRGS
Code:	00400	Value:	6
Date of Measurement:	04/10/1963	Formation Sampled:	000GRGS
Code:	00900	Value:	34

Q65
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS0905578**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Agency:	USGS	Site ID:	395951075481901
Site Name:	CH 904		
Dec. Latitude:	39.99761		
Dec. Longitude:	-75.80495		
Coord Sys:	NAD83		
State:	PA		
County:	Chester County		
Altitude:	600		
Hydrologic code:	02040205		
Topographic:	Upland draw		
Site Type:	Ground-water other than Spring		
Const Date:	19620326	Inven Date:	Not Reported
Well Type:	Single well, other than collector or Ranney type		
Primary Aquifer:	400FCIGA		
Aquifer type:	Not Reported		
Well depth:	120		
Hole depth:	Not Reported	Source:	Not Reported
Project no:	Not Reported		

Ground-water levels, Number of Measurements: 1

Date	Feet below Surface	Feet to Sealevel
1963-06-06	34.00	

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: PA Radon

Test Result Statistics

Zip	Total Sites	Min pCi/L	Max pCi/L	Avg pCi/L
19320	1863	.1	2601	13.8

EPA Region 3 Statistical Summary Readings for Zip Code: 19320

Number of sites tested: 992.

Maximum Radon Level: 999.9 pCi/L.
Minimum Radon Level: 0.5 pCi/L.

pCi/L <4	pCi/L 4-10	pCi/L 10-20	pCi/L 20-50	pCi/L 50-100	pCi/L >100
422 (42.54%)	270 (27.22%)	149 (15.02%)	95 (9.58%)	36 (3.63%)	20 (2.02%)

Federal EPA Radon Zone for CHESTER County: 1

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STATE RECORDS

Pennsylvania Public Water Supply Wells
Source: Pennsylvania Department of Environmental Resources Bureau of Water Supply
Telephone: 717-787-5017

Pennsylvania Groundwater Information System
Source: Department of Conservation and Natural Resources
Telephone: 717-783-7258

RADON

State Database: PA Radon
Source: Department of Environmental Protection
Telephone: 717-783-3594
Radon Test Results Statistics by Zip Code

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

EPA Region 3 Statistical Summary Readings
Source: Region 3 EPA
Telephone: 215-814-2082
Radon readings for Delaware, D.C., Maryland, Pennsylvania, Virginia and West Virginia.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

ADVANCED GEOSERVICES CORP. *"Engineering for the Environment"℠*

1055 Andrew Drive, Suite A
West Chester, PA 19380-4293
(610) 840-9100 Fax (610) 840-9199
www.agcinfo.com

June 11, 2004 2004-1207-01

Baker Residential of Pennsylvania, LLC.
2 Raymond Drive
Havertown, PA 19083

Attention: Mr. Ray Iacobucci

GEOTECHNICAL INVESTIGATION
ROUTE 82 SITE
COATESVILLE, PENNSYLVANIA

Gentlemen:

Advanced GeoServices Corp. (AGC) is pleased to present this report of a geotechnical investigation performed to assist in the design and construction of the proposed development at your site located along Route 82 in Coatesville, Pennsylvania as shown on the Site Location Map, Figure 1. This geotechnical investigation was performed in accordance with our proposal No. 2004-P-062-G, dated May 4, 2004.

The scope of this geotechnical investigation included a site reconnaissance to identify features that reflect subsurface conditions; the excavation of thirty (30) test pits; laboratory testing of selected representative soil samples; appropriate engineering analyses; and the issue of this report.

SITE DESCRIPTION

The site is predominantly woods consisting of dense mature trees and is bordered by Route 82 to the north and west and residential properties to the south and east. The topography of the site is relatively flat in the central portion of the site (plateau area) and slopes steeply downward to the north, west, and south. The base of the slopes to the north and west are steep (on the order of 1:1 (horizontal:vertical)) and appear to have been formed from blasting activities performed during the construction of Route 82. The grade of these slopes above the 1:1 base portion is on the order of 2:1 to 2.5:1.

A soil/rock fill slope is located at the northern edge of the plateau area. This feature is thought to have been formed during the construction of Rout 82, by dumping the removed roadway soil/rock over the previous sloped ground surface. The face of the existing soil/rock fill is distinctly visible on the topographical plan as approximately a 1.3:1 (horizontal:vertical) slope and is generally covered with cobbles, boulders, brush, small diameter trees, and decomposed organic matter (leaves). The ground surface at the top of the slope is generally soil covered with small diameter trees, but boulder and soil piles are visible throughout the top of the fill mass.

PROJECT DESCRIPTION

We understand that the development scheme for the site has not been finalized but will consist of residential housing and possibly a section of commercial buildings (located north of the rock/fill slope). We also understand that a winding entrance drive is planned along the face of the soil/rock fill slope as shown on the conceptual sketch plans provided with your request for proposal. Conceptual grading for the entrance drive shows the placement of embankment fill (potentially as much as 40 feet) against the face of the existing soil/rock fill slope.

SUBSURFACE CONDITIONS

The shallow subsurface conditions at the site were investigated by the excavation of thirty (30) test pits located as shown on Figure 2. The original scope of work proposed the excavation of twenty-six (26) test pits. However, five (5) supplemental test pits were excavated in order to better define the horizontal and vertical limits of the soil/rock fill. The scheduled test pit TP-19 was eliminated due to adverse weather conditions (lightning) experienced at the end of the last day of the field investigation. The logs of the test pits are provided in the Appendix. In addition, laboratory testing was conducted on representative grab and bulk soil samples collected from the test pits. The results of this testing are shown on the test pit logs and in the Appendix.

Geologically, the region is located in the Piedmont Physiographic Province. The bedrock beneath the site is a light gray to white quartzite and quartzite schist of the Chickies Formation. The weathering profile of this formation is typically characterized by horizons of completely weathered residual soil underlain by partially weathered decomposed rock which transitions into a less weathered altered rock and eventually into completely unweathered intact rock. The transitioning from residual soil to intact rock is typically gradual, with an increasing strength and frequency of rock fragments with depth. The subsurface conditions encountered in the test pits are summarized below.

TOPSOIL

Topsoil was encountered in 28 of the 30 test pits to an average depth of 6 inches below the ground surface. The topsoil generally consists of a dark brown organic silt with varying amounts of roots and partially decomposed vegetative material. In test pit TP-16, the topsoil was mixed with trash.

SOIL/ROCK FILL SLOPE

The soil/rock fill slope is located at the northern edge of the plateau area of the site. Nine (9) test pits (TP-8, TP-11, TP-12, TP-16, TP-17, TP-20, TP-22, TP-30, and TP-31) were excavated within this fill area. The fill material encountered in the test pits generally consists of gray cobbles and boulders with a brown silty gravelly sand matrix. The boulders range from about 12 inches to 5 feet in diameter, but generally average about 2 to 3 feet in diameter.

The fill material observed in the test pits was in a loose state and generally caved in as the test pits were excavated. The original topsoil was encountered below the fill in test pits TP-17, TP-20, TP-22, and TP- 30. The total depth of the fill at test pits TP-11, TP-12, and TP-16 could not be determined as the test pits were terminated in the fill. In order to estimate the depths and horizontal extent of the fill, the original ground surface contours beneath the soil/rock fill mass were interpolated/inferred from the existing topography and from the bottom of fill data obtained from test pits TP-17, TP-20, TP-22, and TP- 30. The inferred bottom of fill contours are shown on Figure 3.

The face of the soil/rock fill slope is generally covered with cobbles, boulders, brush, small diameter trees, and decomposed organic matter (leaves). The cobbles and boulders at the surface of the slope face appear to be loose. The exposed boulders and lack of surface vegetation suggest that the face of the fill slope is composed of predominantly rock fill; this is common as the larger rubble is typically pushed to the edge of the fill mass during placement. In addition, at a 1.3:1 slope, soil typically erodes/sloughs; no noticeable surface sloughing of soil was observed. It is likely that any soil located at the edge of the mass during fill placement has washed down the slope or into the voids in the rock fill.

RESIDUAL SOIL

Residual soil results from the complete weathering of the underlying bedrock and was encountered beneath the fill and/or topsoil in 20 of the 30 test pits. The residual soil generally consists of a medium dense brown to light brown and orange brown silty sand with varying amounts of gravel. In some of the test pits trace amounts of cobbles were encountered. Twelve (12) samples of the residual soil were tested for moisture content. The moisture ranges from 7.7 to 27.0 percent and averages about 16.4 percent. In addition, a representative bulk sample of the residual soil was

obtained for Modified Proctor testing (ASTM D 1557). The results of this testing are included in the Appendix.

DECOMPOSED ROCK

The residual soil grades with depth to a less weathered decomposed rock material characterized by a relic rock structure. The decomposed rock material was encountered in 20 of the 30 test pits and generally consists of a medium dense to dense gray to brown coarse to fine sand and gravel with varying amounts of cobbles and boulders. Some of the cobble-size decomposed rock material was friable; this friability decreased with depth. Fourteen (14) samples of the decomposed rock material were tested for moisture content. The moisture content ranges from 6.0 to 21.6 percent and averages about 11.4 percent.

ALTERED/INTACT ROCK

Intact rock as indicated by practical refusal of a Komatsu 228 excavator was encountered in 15 of the 30 test pits at depths ranging from 8.7 to 14.5 feet. Directly above the intact rock, altered rock consisting of slightly weathered fractured bedrock with soil seams was encountered in 7 of the 30 test pits. The altered rock horizon was difficult to excavate with a Komatsu 228 excavator and where excavatable, it was removed in cobble- to boulder-size fragments with varying amounts of sand and gravel.

GROUNDWATER

Groundwater was not encountered in any of the test pits during our field investigation.

DEVELOPMENT CONDITIONS

Based on the conditions encountered during our field study, we offer the following conclusions.

EARTHWORKS

Site Excavations

Although final grades have not been established for this development, it is anticipated that excavation of the soil/rock fill, residual soil, and decomposed rock will be required for both mass excavations and utility/foundation construction. The excavation of these materials can be accomplished with conventional earth moving equipment; however, special handling procedures will likely be required to remove the larger boulders within the soil/rock fill area.

Altered/intact rock was defined in this report by practical refusal of a Komatsu 228 excavator. In confined excavations like trenches, the level of intact rock as shown in the test pit logs and on Figure 2 represents the elevation at which rock removal methods (breaking and/or blasting) will most likely be required. In mass cuts, however, it may be possible to excavate into the altered and intact rock to greater depths using more powerful excavation equipment such as a large dozer equipped with a ripper tooth.

Site Fills

With the present topography, it is anticipated that significant filling will be required to achieve design grades. The average moisture content of the residual soils and decomposed rock materials are 16.4 percent and 11.4 percent, respectively. Based on the results of the Modified Proctor test performed on a representative sample, the optimum moisture content of the residual soil is about 11.5 percent. Therefore, some drying of the residual soils will likely be required in order to achieve the compaction criteria recommended in this report. The residual soils may also be mixed with gravel- and cobble-size rock fragments to reduce their moisture contents to acceptable levels.

Excavation of the decomposed rock and altered rock materials will result in "blocky" fill materials. Portions of the decomposed rock material may be friable and should break down to sand- and gravel-size particles under heavy construction equipment. The majority of the decomposed rock material should be suitable in its present state for use as fill. However, deep excavations within the decomposed and altered rock will result in large non-friable materials. In addition, the soil/rock fill contains boulders as large as 5 feet in diameter. Special placement procedures as described in the "Recommendations" section of this report will be required for the use of fill materials larger than 8 inches in diameter. Depending on the final earthwork balance and quantity of the rock to be removed from the soil/rock fill area, crushing and screening of the rock particles for use as fill or as aggregate base course may be feasible.

STABILITY OF EXISTING SOIL/ROCK FILL SLOPE

We understand that a winding entrance drive is planned along the face of the existing soil/rock fill slope and that the construction of this roadway will include the placement of load-bearing fill against the base of the slope face. Load-bearing fill placed against the base of this slope face will increase the global stability of the existing soil/rock fill mass. The higher the elevation and larger the width of the roadway embankment, the greater will be the increase in global stability of the existing soil/rock fill mass.

Although the soil/rock fill mass appears to be globally stable and the placement of load-bearing fill against the base of the slope will increase its stability, the exposed face of the 1.3:1 slope (i.e., the slope that remains above future fill areas and/or in future non-graded areas, etc.) may be vulnerable to surface slip failures and the sliding of any loose surface rock fill. Therefore, the exposed face of the existing 1.3:1 soil/rock fill slope should be cut back to a slope of 2:1 or shallower. A conceptual cross-section of the re-graded rock/fill slope is depicted on Figure 4.

Excavating the existing soil/rock fill slope to 2:1 or shallower will increase the stability of the surface materials by decreasing the surface grade and allowing these materials to be compacted. If any loose rock fill remains following compaction, these materials should be stabilized with rock netting or other appropriate methods. If soil is present at the surface of the slope following excavation, vegetation should be established on the new slope with an appropriate seed mixture and erosion mat.

SUPPORT CONDITIONS FOR FOUNDATIONS, ONGRADE SLABS, AND PAVEMENT

Support Capability of Natural Materials and Newly-Placed Load-Bearing Fill

Conventional shallow foundations and ongrade floor/basement slabs of the proposed houses and commercial buildings as well as the associated roadway/parking area pavements can be safely supported on the natural soils and on newly-placed load-bearing fill. The foundations should consist of shallow-based spread/wall footing systems proportioned for an allowable net bearing pressure of 3,000 pounds per square foot (psf).

Support Capability of Existing Soil/Rock Fill Mass

The soil/rock fill observed in the test pits was loose and caved during excavation. It is likely that during its placement the soil/rock fill was not compacted but only spread with a dozer. Due to the loose nature of the fill materials and the unknown placement and compaction procedures, it is our opinion that the existing soil/rock fill is not capable of direct foundation support without the potential for excessive settlements. However, it is believed that the existing soil/rock fill is capable of direct support of roadways and landscape areas following the removal of the discrete piles of soil and rock located on the ground surface within this area.

The presence of large rubble will likely prohibit the installation of deep foundations (i.e., driven piles, drilled piles, etc.). Undercutting to the underlying natural materials and backfilling with load-bearing fill will present the least risk for settlement and is preferable; however, this option may require substantially deep undercuts or a significantly reduced available building area. Considering the relatively light loadings of conventional residential housing, it appears that undercutting the

existing soil/rock fill within the house footprint and foundation support zone (i.e., a line extending outward and downward at a 1:1 slope from the edge of the footing) 12 feet below the design foundation bearing level and backfilling the undercut area with load-bearing fill may be feasible to support shallow foundations for houses. However, this foundation support scheme is not considered appropriate for commercial structures and commercial structures should not be constructed on the soil/rock fill mass. The shallow foundations for houses constructed above the soil/rock fill mass should be proportioned for an allowable net bearing pressure of 1,500 pounds per square foot (psf).

As discussed previously, the exposed face of the 1.3:1 slope (i.e., the slope that remains above future fill areas and/or in future non-graded areas, etc.) should be cut back to 2:1 or shallower. Considering the unknown placement and compaction procedures used to construct the existing soil/rock fill mass, the houses and roadways should not be located near the top of the new slope. For planning purposes, a minimum 50-feet development setback from the top of the new slope should be implemented. A conceptual cross-section of this scheme with a 2:1 slope grade is depicted on Figure 4.

RECOMMENDATIONS

Recommendations relating to the design and construction of the proposed development are provided below.

DEVELOPMENT SETBACKS

The perimeter of the site to the north and west is bordered by a natural slope ranging in grade from about a 1:1 (horizontal:vertical) at the base to about a 2:1 toward the top of the slope. It is recommended that a minimum 20-feet building setback line from the top of the 2:1 slope be provided.

As discussed in the "Development Conditions" section of this report, it is recommended that all development (including houses and roadways) be set back a minimum of 50 feet from the top of the new soil/rock fill slope (formed by cutting back the existing 1.3:1 soil/rock fill slope).

SITE PREPARATION

All trees, vegetation, surface topsoil/root mat, soil/rock piles, and all other debris and unsuitable materials should be stripped/removed from the proposed development area and from any areas to receive load-bearing fill. After clearing/removal, the existing subgrades that will receive load-bearing fill should be proof-rolled with a large, smooth-drum vibratory roller under the observation of a geotechnical engineer/technician to densify the surficial soils and to delineate any soft/unstable areas.

Soft/unstable areas observed by the geotechnical engineer/technician during the proof-rolling which cannot be densified by additional compaction should be undercut to stable material and the undercut area backfilled in accordance with the "Load-Bearing Fill" section of this report.

LOAD-BEARING FILL

All fill proposed to support features that will be adversely affected by settlement are considered load-bearing fill. Materials used as load-bearing fill should be free of degradable trash/rubble, organic inclusions, frozen materials, and excess moisture. Recommendations for acceptable particle sizes for load-bearing fill are discussed below.

Moisture Control

Portions of the site residual soils will likely require aerating and drying in order to achieve the compaction criteria recommended in this report. These procedures can be performed during dryer, warmer months (late spring and summer) but are generally difficult to achieve during wetter, cooler periods (autumn, winter, and early spring). In addition, it should be noted that the onsite soils are sensitive to moisture. Therefore, fill construction should be planned during the drier periods of the year (late spring to early fall). Alternatively, the wetter portions of the residual soils can be mixed with gravel- and cobble-size fragments to reduce their moisture content to acceptable limits.

Fill Placement Procedures and Compaction Criteria

Excavation of the decomposed rock and altered rock materials will result in "blocky" fill materials. Portions of the decomposed rock material may be friable; these friable materials will likely break down to sand- and gravel- size particles under heavy construction equipment. However, deep excavations within the decomposed and altered rock will result in large non-friable materials. In addition, the soil/rock fill contains boulders as large as 5 feet in diameter.

It is recommended that the residual soils and the more friable decomposed rock material be used in the upper portions of large fill areas and to backfill utilities and foundation elements. The rock fill and non-friable rock fragments larger than 8 inches should be placed at the bottom of large fill areas outside of the foundation support zone of the proposed houses and commercial structures. The foundation support zone extends outward and downward at a 1:1 slope from the edges of the footing. In addition, the rock fill/fragments should not be placed within 4 feet of the final subgrade elevation nor in areas of proposed utilities. The rock fill/fragments should be placed in such a manner as to minimize void spaces between adjacent rock pieces. Any remaining void spaces in each lift should be filled with soil.

Load-bearing soil fill should be placed in horizontal lifts with a maximum loose thickness of 10 inches (for area fills) or 8 inches (for backfill in confined areas). Load-bearing soil fill placed over large areas should be compacted by repeated passes of a large, smooth-drum vibratory roller. Backfill place in confined areas should be compacted by repeated passes of hand-manipulated compaction equipment (i.e., jumping jack-type tampers, etc.)

It is believed that the "blocky" nature of portions of the decomposed and altered rock material will restrict the use of conventional in-place density testing which depends upon small samples to represent large fill volumes. The adequacy of compaction of this material should be evaluated by a performance-based monitoring system as judged by an experienced geotechnical engineer/technician. It is believed that the degree of compaction of the residual soils and the more friable portions of the decomposed rock material may be monitored by the use of conventional in-place density testing procedures. In areas where conventional in-place density testing is appropriate, the following compaction criteria should be adopted.

- Load-bearing fill placed for the support of foundations should be compacted to at least 95% of the maximum modified dry density as determined by the Modified Proctor test (ASTM D 1557).

- Load-bearing fill placed for support of floor slabs, sidewalks, and pavements should be compacted to at least 92 percent of the maximum dry density as determined by the Modified Proctor test (ASTM D 1557).

In addition, all compacted fills should be stable, with no appreciable movement beneath the compaction equipment.

FOUNDATIONS

Foundations for the proposed houses and commercial structures should consist of shallow-based spread/wall footings bearing on natural soils and/or on newly-placed load-bearing fill. Footings that will be subject to frost action should be based at least 36 inches below the adjacent exterior grade. Footings located adjacent to underground structures, existing foundations, or utilities should be based such that a line extending outward and downward at a 1:1 slope from the edge of the footing passes beneath the structure/foundation/utility.

All footing excavations should be monitored by a geotechnical engineer/technician to assure that the bearing conditions are consistent with those presented in this report. If unsuitable or less competent materials are encountered at the bearing level, the footing should be lowered to bear on more competent materials.

Commercial Structures/Residential Housing Located Outside of Soil/Rock Fill Area

Footings for structures located outside of the soil/rock fill area should be proportioned for a maximum allowable net bearing pressure of 3,000 pounds per square foot (psf). A minimum wall footing width of 24 inches and a minimum lateral column footing dimension of 36 inches are recommended to prevent edge shear conditions.

Residential Housing Located Within Soil/Rock Fill Area

Residential housing located within the soil/rock fill area should be supported on a shallow foundation system consisting of column/wall footings proportioned for a maximum allowable net bearing pressure of 1,500 psf. The foundation support zone of each house should be constructed in accordance with the following procedures. A minimum wall footing width of 18 inches and a minimum lateral column footing dimension of 36 inches are recommended to prevent edge shear conditions.

- Undercut the soil/rock fill a minimum of 12 feet below the design foundation bearing elevation. The undercut should be performed within the entire house footprint and extended 12 feet laterally in all directions beyond the house footprint.
- Proof-roll/compact the undercut subgrade with a large, smooth-drum vibratory roller (minimum10 tons) to densify the existing fill materials. Loose/unstable areas observed by the geotechnical engineer/technician during the proof-rolling which cannot be densified by additional compaction should be stabilized as directed by the geotechnical engineer/technician.
- Place a woven geotextile fabric (Mirafi 500X, or the equivalent) on the undercut subgrade.
- Backfill the undercut area with load-bearing fill compacted to at least 95% of the maximum modified dry density as determined by the Modified Proctor test (ASTM D 1557). The load-bearing fill should not contain particles larger than 8 inches.

It is recommended that the above preparation procedures be monitored by a geotechnical engineer/technician to verify that the bearing conditions are compatible with the design criteria.

ONGRADE SLABS

The ground floor/basement slabs should be supported on grade. Immediately prior to slab construction, the subgrade should be proof-rolled as described under the "Site Preparation" section of this report to densify any areas disturbed by adverse weather or previous construction activities. Any unstable areas observed during the proof-rolling should be undercut to stable material and the undercut area backfilled with load-bearing fill compacted to at least 92 percent of the maximum dry density as determined by the Modified Proctor test (ASTM D 1557).

To preclude uneven curing, a 4-inch thick, well compacted granular base course should be placed beneath the slab. This base course should consist of freely-draining material similar in gradation to AASHTO Course Aggregate No. 57.

PAVEMENTS

It is recommended that the following pavement section be installed on a compacted, stable subgrade.

RECOMMENDED MINIMUM PAVEMENT SECTION

PAVEMENT ELEMENT	ELEMENT THICKNESS (1)
Bituminous Concrete Wearing Course, PaDOT ID-2	1-1/2"
Bituminous Concrete Binder Course, PaDOT ID-2	2-1/2"
Aggregate Base Course (2)	8"
Improved Subgrade (3)	12"

1. These recommendations are predicated on the assumption that pavement usage will generally be limited to light-duty (automobile) traffic.

2. Base Course should be 3A Modified Coarse Aggregate with less than ten percent finer than the No. 200 sieve, and all fines should be non-plastic (PI=0).

3. Subgrade should be compacted just prior to base course placement such that no appreciable movement is observed beneath the compaction equipment.

This recommended pavement design should be re-evaluated during construction and modified commensurate with the actual subgrade conditions encountered. Exposed soils are susceptible to deterioration and the subgrade stability will depend on the weather conditions and the maintenance, particularly drainage control, exercised by the contractor.

This pavement design may not be suitable for the heavy traffic loads associated with the construction of this development. If the full pavement section or selected elements of this pavement section are installed during the construction period, it may be necessary to repair and/or reconstruct the pavement when the construction is completed.

LIMITATIONS

All provisions and recommendations presented in this report are predicated on the assumption that subsurface conditions do not deviate appreciably from those disclosed by the test pits. These conclusions and recommendations are subject to confirmation or revision upon our review of the final plans and specifications for the proposed development. Conclusions and recommendations are also based on the premise that competent geotechnical field decisions will be provided during construction.

The scope of this geotechnical investigation was limited to an evaluation of the load-carrying capabilities and stability of the subsurface materials. Oil, hazardous waste, radon, radioactivity, irritants, pollutants, or other dangerous substances and conditions were not the subject of this report or this geotechnical investigation.

Statements and conclusions regarding the impact of geotechnical conditions on the design and construction of the proposed development as stated in this report are unique. Findings, conclusions, and recommendations are not transferable to other development schemes, site arrangements, or structural systems.

We appreciate this opportunity to be of service to you. If you have any questions concerning the contents of this report, or if we may be of further service, please contact us.

Very truly yours,

ADVANCED GEOSERVICES CORP.

Todd D. Trotman, P.E.
Associate Project Consultant

Paul F. Marano, P.E.
Senior Project Consultant

TDT:PFM:kk



ROUTE 82 SITE
COATESVILLE, PENNSYLVANIA

Scale: AS SHOWN	CONCEPTUAL CROSS SECTION
Originated By: T.D.T.	
Drawn By: P.S.G.	
Checked By: T.D.T.	
Project Mgr: T.D.T.	
Dwg No. 2004-207-01-04	
Issued:	Project no. 2004-1207-01 — FIGURE : 4

Advanced GeoServices Corp.
1055 Andrew Drive Suite A
West Chester, Pennsylvania 19380
(610) 840-9100
FAX: (610) 840-9199

J:\Route 82 Site\2004-1207-01\2004-207-01-04

FIGURES



ROUTE 82 SITE

COATESVILLE, PENNSYLVANIA

SITE LOCATION MAP

Advanced GeoServices Corp.
1055 Andrew Drive, Suite A
West Chester, Pennsylvania 19380
(610) 840-9100
FAX: (610) 840-9199

FIGURE: 1

APPENDIX

Subsurface conditions at the site were explored by the excavation of thirty (30) test pits located as shown on Figure 2. The test pits were excavated by P.J. Reilly Contracting Co., Inc. under the technical supervision of Advanced GeoServices Corp. (AGC) personnel. The field locations and ground surface elevations of test pits TP-1 through TP-26 were provided by Vollmer Associates LLP. The locations of test pits TP-27 through TP-31 were determined by AGC in the field. The ground surface elevations at these test pit locations were interpolated from the site plan provided by Vollmer Associates LLP. on June 1, 2004.

Soil samples were obtained for identification and classification purposes via grab and bulk samples in the test pits. Logs of the test pits are presented in this appendix with descriptions of the various soil horizons encountered. Upon completion, the test pits were backfilled with the excavation spoils to the surrounding surface elevation.

A limited laboratory investigation was conducted on representative soil samples to assist with soil classification and to provide an indication of soil behavior. This testing consisted of determinations of moisture content, grain size analysis, and the moisture-density relationship (Modified Proctor). The tests were conducted according to ASTM standards. The moisture content results are shown on the test pit logs adjacent to the samples tested, and the results of the grain size analysis and Modified Proctor testing are included at the end of this appendix. The performance of the grain size analysis testing is denoted in the "Other Test" column on the test pit logs as "GS".

LOG OF TEST PIT
TP-1

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 599.4 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 599.4 / 0.5 / 598.9		
		(TOPSOIL) *Medium dense, moist, orange-brown silty fine SAND with gravel, trace cobbles.* 5.0 / 594.4		
		(RESIDUAL SOIL) *Dense, moist, gray-brown coarse to fine SAND, GRAVEL and blocky COBBLES.* *(DECOMPOSED ROCK)* 11.0 / 588.4		
		Completion Depth = 11 feet *PRACTICAL REFUSAL*		

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-2

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 518.5 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with forrest cover and roots. 518.5 / 0.5 / 518		
		(TOPSOIL)	27.0	G.S.
		Medium dense, moist, brown sandy gravelly SILT, trace cobbles, occasional boulder.		
		(RESIDUAL SOIL) 6.0 / 512.5		
		Dense, moist, brown coarse to fine sandy GRAVEL and blocky COBBLES.		
		(DECOMPOSED ROCK)		
		14.0 / 504.5		
		Completion Depth = 14 feet *PRACTICAL REFUSAL*		

LOG OF TEST PIT
TP-3

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 574.5 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with forrest cover and roots. 574.5 / 0.5 / 574		
		(TOPSOIL)	22.3	
		Medium dense, moist, brown silty fine SAND with friable and non-friable gravel, trace friable cobbles. 6.0 / 568.5		
		(RESIDUAL SOIL)		
		Dense, moist, sandy GRAVEL, COBBLES and small BOULDERS.		
		(DECOMPOSED ROCK)		
		14.0 / 560.5		
		Completion Depth = 14 feet *END OF TEST PIT*		

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-4

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 506.0 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
506		*Dark brown organic SILT with roots.*		
505.6 (0.4)		*(TOPSOIL)*		
504 (2.0)		*Medium dense, moist, silty fine SAND, trace gravel.*		
		(RESIDUAL SOIL)	17.1	
		Dense, moist, brown silty SAND, GRAVEL, and platey COBBLES. Rock content increasing with depth.		
497 (9.0)		*(DECOMPOSED ROCK)*		
		Very dense, fractured rock with soil seams. Excavates into cobbles and small boulders.		
491.5 (14.5)		*(ALTERED ROCK)*		
		Completion Depth = 14.5 feet *PRACTICAL REFUSAL*		

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-5

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 562.7 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT, trace roots. 562.7		
		0.5 562.2		
		(TOPSOIL)		
		Medium dense, moist, orange-brown silty fine SAND, trace gravel. 3.0 559.7		
		(RESIDUAL SOIL) 6.0 556.7	10.5	
		Medium dense, moist, gray-brown silty SAND and GRAVEL, trace cobbles.		
		(DECOMPOSED ROCK)		
		Dense, moist, brown blocky COBBLES and BOULDERS with sand and gravel.		
		13.0 549.7		
		(DECOMPOSED ROCK)		
		Completion Depth = 13 feet *PRACTICAL REFUSAL*		

LOG OF TEST PIT
TP-6

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 565.9 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with forrest cover, trace roots. 565.9 / 0.4 / 565.5		
		(TOPSOIL) 3.0 / 562.9		
		Medium dense, moist, light brown silty SAND and GRAVEL.		
	S-1	*(RESIDUAL SOIL)*	8.9	
		Dense, moist, silty SAND and GRAVEL with cobbles. Rock content increasing with depth.		
		10.0 / 555.9		
		(DECOMPOSED ROCK)		
		Completion Depth = 10 feet *PRACTICAL REFUSAL*		

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-7

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 565.7 ft.
CHECKED BY: T. Trotman
INSPECTOR: S. Gardner
DATE: May 12, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 565.7 / 0.4 / 565.3		
		(TOPSOIL)		
		Medium dense, moist, brown to orange-brown silty fine SAND, trace gravel. 4.0 / 561.7		
		(RESIDUAL SOIL)	6.0	
		Dense to very dense silty SAND, GRAVEL and COBBLES, occasional boulder. Rock content increasing with depth.		
		(DECOMPOSED ROCK)		
		12.0 / 553.7		
		Completion Depth = 12 feet *PRACTICAL REFUSAL*		

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-8

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 586.0 ft.
CHECKED BY: T. Trotman
INSPECTOR: S. Gardner
DATE: May 12, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 586		
		0.6 585.4		
		(TOPSOIL)		
		Loose, moist, gray COBBLES and BOULDERS in a matrix of brown silty sand.		
		(FILL)		
		7.0 579		
	S-1	*Medium dense to dense, moist, brown silty fine SAND with gravel and cobbles. Rock content increases with depth.*	7.7	
		(DECOMPOSED ROCK)		
		14.0 572		
		Completion Depth = 14 feet *PRACTICAL REFUSAL*		

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-9

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 597.7 ft.
CHECKED BY: T. Trotman
INSPECTOR: S. Gardner
DATE: May 12, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 597.7		
		0.4 597.3		
		(TOPSOIL)	12.7	
		Medium dense, moist, brown silty fine SAND, trace gravel. 3.0 594.7		
		(RESIDUAL SOIL)		
		Dense, moist, brown silty coarse to fine SAND and GRAVEL, trace to some cobbles.		
		10.0 587.7		
		(DECOMPOSED ROCK)		
		Very dense, blocky COBBLES and BOULDERS with soil seams. 11.5 586.2		
		(ALTERED ROCK)		
		Completion Depth = 11.5 feet		
		PRACTICAL REFUSAL		

LOG OF TEST PIT
TP-10

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 494.2 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with forrest cover and roots. 494.2 / 0.4 / 493.8		
		(TOPSOIL)		
		Medium dense, moist, brown silty fine SAND with gravel, trace cobbles. 3.5 / 490.7	12.4	
		(RESIDUAL SOIL)		
		Dense, moist, gray, light brown silty fine SAND with gravel. Relic rock structure is apparent. 7.0 / 487.2		
		(DECOMPOSED ROCK)		
		Very dense, sandy blocky COBBLES, trace boulders. Rock content increasing with depth.		
		12.5 / 481.7		
		(DECOMPOSED ROCK)		
		Completion Depth = 12.5 feet *PRACTICAL REFUSAL*		

LOG OF TEST PIT
TP-11

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 582.0 ft.
CHECKED BY: T. Trotman
INSPECTOR: S. Gardner
DATE: May 12, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 582 / 0.4 / 581.6	7.3	
		(TOPSOIL) *Loose, moist, gray COBBLES and BOULDERS in a matrix of silty sand.* *(FILL)* 15.0 / 567		
		Completion Depth = 15 feet *END OF TEST PIT*		

LOG OF TEST PIT
TP-12

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 590.0 ft.
CHECKED BY: T. Trotman
INSPECTOR: S. Gardner
DATE: May 12, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 590 0.3 589.7		
		(TOPSOIL)		
		Loose, moist, gray coarse to fine COBBLES and BOULDERS in a matrix of gravelly sand.	3.7	
		(FILL)		
		18.0 572		
		Completion Depth = 18 feet *END OF TEST PIT*		

LOG OF TEST PIT
TP-13

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 592.9 ft.
CHECKED BY: T. Trotman
INSPECTOR: S. Gardner
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 592.9		
		0.8 592.1		
		(TOPSOIL)		
		Medium dense to dense orange-brown to brown silty fine SAND with elongated gravel, trace to some cobbles.	7.7	
		6.0 586.9		
		(RESIDUAL SOIL)		
		Very dense, moist, brown COBBLES and BOULDERS with soil seams.		
		8.7 584.2		
		(ALTERED ROCK)		
		Completion Depth = 8.7 feet		
		PRACTICAL REFUSAL		

LOG OF TEST PIT
TP-14

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 580.9 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 580.9		
		0.3 580.6		
		(TOPSOIL) *Medium dense, moist, brown silty fine SAND, trace gravel.*		
		3.5 577.4		
	S-1	5.0 575.9	8.3	
		(RESIDUAL SOIL) *Medium dense, moist, gray silty SAND and GRAVEL, trace cobbles.*		
		(DECOMPOSED ROCK) *Dense, moist, brown silty SAND, GRAVEL and COBBLES. Rock content increasing with depth.*		
		(DECOMPOSED ROCK) 14.5 566.4		
		Completion Depth = 14.5 feet *PRACTICAL REFUSAL*		

LOG OF TEST PIT
TP-15

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 490.4 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with forrest cover and roots. 490.4 / 0.7 / 489.7		
		(TOPSOIL)		
		Medium dense to dense, moist, light brown silty fine SAND, trace gravel and cobbles.	14.3	G.S.
		(RESIDUAL SOIL)		
		9.0 / 481.4		
		Very dense, moist, blocky COBBLES with sand, trace boulders.		
		11.5 / 478.9		
		(ALTERED ROCK)		
		Completion Depth = 11.5 feet *PRACTICAL REFUSAL*		

LOG OF TEST PIT
TP-16

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 583.4 ft.
CHECKED BY: T. Trotman
INSPECTOR: S. Gardner
DATE: May 12, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Loose organic SILT with plastic glass and metal debris. 583.4 / 0.9 / 582.5		
		(TOPSOIL/FILL) 4.0		
		Medium dense, moist, brown silty SAND with gravel. 579.4	5.8	
		(FILL)		
		Loose, moist, gray COBBLES and BOULDERS with silty fine sand.		
		(FILL)		
		17.0		
		Completion Depth = 17 feet 566.4 *END OF TEST PIT*		

LOG OF TEST PIT
TP-17

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 592.4 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with fine roots. 592.4		
		0.3 592.1		
		(TOPSOIL)		
		Loose, moist, gray and brown COBBLES and BOULDER in a matrix of silty sand.		
		(FILL)		
		10.7 581.7		
		Original topsoil. 11.0		
	S-1	*Medium dense, moist, brown silty fine SAND, trace gravel.* 581.4	18.6	
		13.5 578.9		
		(RESIDUAL SOIL)		
		Dense to very dense, silty SAND, GRAVEL and COBBLES. Rock content increases with depth.		
		17.0 575.4		
		(DECOMPOSED ROCK)		
		Completion Depth = 17 feet		
		END OF TEST PIT		

LOG OF TEST PIT
TP-18

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 600.2 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT, trace fine roots. 600.2 / 0.4 / 599.8		
		(TOPSOIL)		
		Medium dense to dense, moist, orange-brown to brown silty fine SAND and COBBLES, occasional small boulders.		
		(DECOMPOSED ROCK)	7.9	
		8.0 / 592.2		
		Very dense, moist, brown, blocky COBBLES and BOULDERS with sand and gravel.		
		(ALTERED ROCK)		
		13.0 / 587.2		
		Completion Depth = 13 feet *PRACTICAL REFUSAL*		

LOG OF TEST PIT
TP-19

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION:
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004

ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
0		Completion Depth = 0 feet		
		TEST PIT WAS NOT PERFORMED		
5				
10				
15				
20				
25				
30				
35				

LOG OF TEST PIT
TP-20

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 596.6 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
0		*Dark brown organic SILT with roots.* 596.6		
		0.3 596.3 *(TOPSOIL)*		
		Loose, moist, brown sandy COBBLES and small BOULDERS. 3.0 593.6		
		3.2 593.4 *(FILL)*	14.4	
		6.0 590.6 *Original topsoil.* *Medium dense, moist, brown silty fine SAND, trace gravel, occasional cobbles.*		
		(RESIDUAL SOIL)	13.7	
		Medium dense to dense, moist, gray-brown silty SAND, GRAVEL and COBBLES. Rock content increased with depth. 12.0 584.6		
		13.0 583.6 *(DECOMPOSED ROCK)* *Fractured, blocky rock with soil seams.* *(ALTERED ROCK)*		
		Completion Depth = 13 feet *PRACTICAL REFUSAL*		

LOG OF TEST PIT
TP-21

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 453.2 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 453.2 0.9 452.3 *(TOPSOIL)* *Medium dense to dense, brown to orange-brown silty fine SAND, trace gravel and cobbles.*	10.3	
		(RESIDUAL SOIL)	23.2	
		18.0 Completion Depth = 18 feet 435.2 *END OF TEST PIT*		

LOG OF TEST PIT
TP-22

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 593.3 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT, trace roots. 593.3 / 0.4 / 592.9		
		(TOPSOIL)		
		Loosely arranged COBBLES and BOULDERS in a matrix of sand and gravel.		
		(FILL)	7.3	
		13.0 / 580.3		
		Original topsoil. 13.3 / 580		
		Medium dense to dense, moist brown silty fine SAND and GRAVEL, trace to some cobbles.		
		(DECOMPOSED ROCK)	11.3	
		18.0 / 575.3		
		Completion Depth = 18 feet		
		END OF TEST PIT		

LOG OF TEST PIT
TP-23

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 587.8 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT. 587.8 0.3 587.5 *(TOPSOIL)*		
		Medium dense to dense, moist, brown silty fine SAND with gravel, trace to some cobbles.	15.0	
		(DECOMPOSED ROCK)		
		19.0	14.2	
		Completion Depth = 19 feet 568.8 *END OF TEST PIT*		

LOG OF TEST PIT
TP-24

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 575.6 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with dense roots. 575.6 0.8 574.8		
		(TOPSOIL) *Medium dense to dense, moist, light brown to orange-brown silty fine SAND with gravel, trace cobbles.*	20.9	
		(RESIDUAL SOIL)		
		9.0 566.6 *Medium dense, moist, orange-brown silty fine SAND with gravel and cobbles.*		
		(DECOMPOSED ROCK)	21.6	
		15.0 560.6 Completion Depth = 15 feet *END OF TEST PIT*		

LOG OF TEST PIT
TP-25

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 572.5 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT with roots. 572.5 0.5 572 *(TOPSOIL)* *Medium dense to dense, moist, brown to light brown silty fine SAND with gravel, trace to some friable and non-friable cobbles.* *(DECOMPOSED ROCK)*	11.9	G.S.
		18.0 554.5 Completion Depth = 18 feet *END OF TEST PIT*		

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-26

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 546.1 ft.
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 14, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description		Moisture (%)	Other Tests
		Dark brown organic SILT with forrest cover and roots.	546.1 0.4 545.7		
		(TOPSOIL) *Dense, moist, brown silty sandy GRAVEL with cobbles, trace boulders.*	4.0 542.1	15.6	
		(DECOMPOSED ROCK) *Very dense black COBBLES and BOULDERS with sand and gravel.*	9.0 537.1		
		(ALTERED ROCK) Completion Depth = 9 feet *PRACTICAL REFUSAL*			

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-27

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 590.0
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
590 / 0		*Brown organic SILT.*		
589.7 / 0.3		*(TOPSOIL)*		
587 / 3.0		*Medium dense, silty fine SAND with gravel.*		
585 / 5.0		*(RESIDUAL SOIL)*		
		Dense, moist, brown sandy COBBLES.		
		(DECOMPOSED ROCK)		
		Completion Depth = 5 feet		
		END OF TEST PIT		

ADVANCED GEOSERVICES CORP.

LOG OF TEST PIT
TP-28

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 589.0
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Medium dense, moist, brown silty fine SAND, trace gravel. 589		
		(RESIDUAL SOIL) 4.0		
		Completion Depth = 4 feet 585 *END OF TEST PIT*		

LOG OF TEST PIT
TP-29

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 588.0
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT. 588 0.4		
		(TOPSOIL) 587.6 3.0		
		Medium dense, moist, brown silty fine SAND, trace gravel. 585		
		(RESIDUAL SOIL)		
		Completion Depth = 3 feet		
		END OF TEST PIT		

LOG OF TEST PIT
TP-30

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 591.0
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Loose, moist, coarse to fine COBBLES and BOULDERS with silty sand. 591		
		(FILL)		
		6.5		
		Original topsoil. 584.5		
		6.7		
		Medium dense, brown silty fine SAND. 584.3		
		8.0		
		(RESIDUAL SOIL) 583		
		Completion Depth = 8 feet		
		END OF TEST PIT		

LOG OF TEST PIT
TP-31

PROJECT: Route 82 Site - Coatesville, PA
TEST PIT LOCATION: See Figure 2
EXCAVATION METHOD: Komatsu 228
EXCAVATION COMPANY: P.J. Reilly
WATER ENCOUNTERED AT: None Encountered

PROJECT NO.: 2004-1201-01
SURFACE ELEVATION: 597.5
CHECKED BY: T. Trotman
INSPECTOR: M. Simonds
DATE: May 15, 2004



ELEVATION / DEPTH	SOIL SYMBOLS SAMPLER SYMBOLS BLOWS PER 6 INCHES	Soil Description	Moisture (%)	Other Tests
		Dark brown organic SILT. 597.5		
		0.3 597.2		
		(TOPSOIL) *Loose, moist brown COBBLES and BOULDERS with sand and gravel.*		
		4.5 593		
		(FILL) *Medium dense, moist, brown silty fine SAND, trace gravel.*		
		7.0 590.5		
		(RESIDUAL SOIL)		
		Completion Depth = 7 feet *END OF TEST PIT*		

GeoSystems Consultants,inc

Fort Washington, Pa 19034

Job No. 2003G318
Date 19-May-04
File No. 2003g318-12

Job Name: AGC: Route 82 Site
Reviewed By ENM(GSC) Todd Trotman (AGC)
Ref. M:\Lab\ASSIGN\2004\[2003318ls-12.xls]97027LS1

Laboratory Testing Assignment & Data Summary

Boring	Sample	Depth	Water	Atterberg Limits	Specific Gravity		Sieve	Hydro.	Compact.	Carbon-	k	K	Consol.	Uc	UU	CIU	pH
No.	No	ft.	Content,%	liquid/plastic						nate	Test	Test	Test	Test	Test	Test	
			ASTMD	ASTMD	ASTMD	ASTMC	ASTMD		ASTMD	ASTMD	ASTMD	ASTMD	ASTMD	ASTMD	ASTMD	ASTMD	
			2216	4318	854	127			1557	3042	5084	2434	2435	2166	2850	4767	
TP-2	S-1	2.0	27.0				X										
TP-3	S-1	2.0	22.3														
TP-4	S-1	4.0	17.1														
TP-5	S-1	6.0	10.5														
TP-6	S-1	6.0	8.9														
TP-7	S-1	6.0	6.0														
TP-8	S-1	08.0-09.0	7.7														
TP-9	S-1	02.0-03.0	12.7														
TP-10	S-1	3.0	12.4														
TP-11	S-1	01.0-02.0	7.3														
TP-12	S-1	04.0-05.0	3.7														
TP-13	S-1	03.0-04.0	7.7														
TP-14	S-1	5.0	8.3														
TP-15	S-1	3.0	14.3				X										
TP-16	S-1	04.0-05.0	5.8														
TP-17	S-1	12.0-	18.6														
TP-18	S-1	6.0	7.9														
TP-20	S-1	5.0	14.4														
	S-2	9.0	13.7														
TP-21	S-1	4.0	10.3														
	S-2	9	23.2														
TP-22	S-1	8	7.3														
	S-2	16.0	11.3														
TP-23	S-1	4.0	15														
	S-2	18.0	14.2														
TP-24	S-1	3.0	20.9														
	S-2	14.0	21.6														
TP-25	S-1	9.0	11.9				X										
TP-26	S-1	3.0	15.6														
TP-14A		00.0-03.0	12.9		2.76	2.65	X		X								
File No	M:\Lab\ASSIGN\2004\[2003318ls-12.xls]97027LS1																

GeoSystems Consultants Inc.

Fort Washington , Pa.

Job No.	2003g318	Date	24-May-04
File No.	2003318c-33	Specific Gravity(-10 Sieve Mat.)	2.76
Job Name:	AGC; Route#82 site	Specific Gravity(+#4 Sieve Mat.)	2.65
Boring No./Sple No.	Buckets	Average Specific Gravity	2.74
Description	Brown SILTY SAND (SM)	Maximum Dry Density, pcf	121.1
Liquid Limit	Not Requested	Optimum Water Content, %	11.5
Plastic Limit		Corrected Max. Dry Density, pcf	126.0
Plastic Index		Corrected Optimum Water Content, %	10.6
As-Received Water Content,%	12.9	N.C-Not Corrected	
Ref. No.	M:\Lab\COMPACT\2004 compact\[2003G318C-33.XLS]014C-1	Asmd- Assumed	





Complaint Information

4100 - EP SE Rgnl Off Norristown

Complaint Id: 234314
Related Complaint Id:
County: Chester
Municipality: Coatesville City
Entered By: THOMAS B NEWMYER
After Hours (Y/N): Y
Source: Phone Call
ER Related (Y/N): Y
Date Received: 06/11/2003
Date Acknowledged:
Abbreviated Description: Truck spills hydrallic oil to pavement
Long Description: A BROKEN HYDRALLIC LINE ON A TRUCK SPILLS 100 GALLONS OF HYDRALLIC OIL TO THE PAVEMENT. THE CLEAN IS UNDERWAY AND THE SPILL WAS CONTAINED TO PAVEMENT ONLY.
Site Location: CHESTER ADC MAP 28, GRID H-6.

Complainant Information

Name: Ray Adjolly
Seq #: 1
Company:
Home Phone: 610-383-2097
Confidential (Y/N):
Work Phone:
Ext:
Email:
Mobile Phone:
Address:
Date/Time Received: 06/11/2003

Responsible Party Information

Name: RAY ADJOLLY
Home Phone: 610-383-2097
Company: ISG PLATE, INC. (FORMERLY BETHLEHEM STEEL)
Work Phone:
Ext:
Permit #:
Mobile Phone:
County:
Municipality:
Address: MODENA ROAD
COATESVILLE, PA 19320

Response Information

Priority: 1
# of Documents: 0
Program: Waste Management
Complaint Type: Land Contamination
Date Referred: 06/13/2003
Date Response Assigned: 06/11/2003
Referred To: Paul Jardel
Date Reponse Due: 06/11/2003
Date Resolved: 06/11/2003
Date First Response: 06/11/2003
Inspector:
Supervisor:
Comments: This one came in Wednesday night, not an emergency contained and cleanup underway.

Investigation Information

Date Assigned:
Date Investigated:
Type: Other
Inspector:
Violation (Y/N):
eFACTS Inspection Id:
Investigation Id:
Investigation Description:

APPENDIX F:

Whitman Staff and Environmental Professional Qualifications/Resumes

Sheila Innella

Senior Scientist I

Responsibility

Ms. Innella joined Whitman in June 2016. As a Senior Scientist I with over 10 years of environmental consulting experience, Ms. Innella's responsibilities include the preparation and management of due diligence-related tasks such as ASTM Phase I and Phase II Environmental Site Assessments and New Jersey Department of Environmental Protection (NJDEP) Preliminary Assessments. Activities performed as part of each assessment include site inspections, historical source reviews, and file document reviews.

Additional responsibilities include oversight of geophysical surveys, logging soil stratigraphy, and air, soil, and groundwater sampling. Ms. Innella also completes reports associated with these assessments and investigations.

Ms. Innella assists with child daycare/education facility environmental assessment services, including Indoor Environmental Health Assessments, regulatory process applications, desktop environmental reviews, and property file reviews.

Other responsibilities include proposal writing, budgeting, coordination with clients, attorneys, and regulatory authorities, project coordination, field coordination, and task delegation associated with Phase II Environmental Site Assessments, and Site and Remedial Investigations.

Professional Registrations / Certifications

- Completed 40 Hour OSHA Training Course and Annual Refreshers
- 8 Hour OSHA HAZWOPER Supervisor Training
- 3-Day AHERA Asbestos Building Inspector Program and Annual Refreshers
- Adult and Pediatric First Aid / CPR / AED
- Transportation Worker Identification Credentials

Education

M.S. Plant and Soil Science
University of Delaware – 2010

B.S. Agronomy
Minor in Animal Science
Texas Tech University – 2004

Alexa Fiumarelli

Staff Scientist

Responsibility

Ms. Fiumarelli joined Whitman in January 2018. As a Staff Scientist, Ms. Fiumarelli's responsibilities include environmental compliance including, but not limited to, General Air Permits, Spill Prevention, Containment & Control (SPCC) Plans, Stormwater Pollution Prevention Plans (SPPP), and various New Jersey Department of Environmental Protection (NJDEP) permits. Additional compliance activities include Right-to-Know inventories and reporting, as well as training.

Ms. Fiumarelli also assists in the collection of environmental samples including, but not limited to, groundwater, indoor & sub-slab air, and sediment samples, as well as environmental sample data entry, preparation of regulatory reports and other relevant tasks. Additionally, Ms. Fiumarelli is proficient in sampling for indoor/outdoor air quality issues, mold and radon and has assisted on numerous projects.

As a Licensed Registered Environmental Health Specialist (REHS), Ms. Fiumarelli also performs health inspections for food manufacturing facilities, enforcing local, state, and federal regulations that pertain to the sanitation of food and water, the handling of hazardous and infectious wastes, and the cleanliness and safety of the facilities.

Professional Registrations / Certifications

- Licensed Registered Environmental Health Specialist (REHS)
- Completed 40 Hour OSHA Hazardous Site Worker Course

Project Experience

Asbestos Projects

- AHERA 6-month evaluations at several schools – NJ, Statewide
- Post-abatement testing at Newark Schools

Mold Projects

- Mercer County Community College
- Colts Neck Schools
- C.R. Bard, Inc.
- Highland Park Schools
- Newark Schools
- Millburn Schools
- Monmouth County Vo-Tech

Education

B.S. Public Health
Minor in Environmental Science
William Paterson University - 2017

Professional Associations

- Member of the New Jersey Environmental Health Association
- Member of the New Jersey Chapter of the Society of Women Environmental Professionals

APPENDIX G:

Environmental Professional Statement

DEFINITION OF ENVIRONMENTAL PROFESSIONAL AND RELEVANT EXPERIENCE THERETO PURSUANT TO 40 CFR 312

(1) a person who possesses sufficient specific education, training, and experience necessary to exercise professional judgment to develop opinions and conclusions regarding conditions indicative of releases or threatened releases (see §312.1(c)) on, at, in, or to a property, sufficient to meet the objectives and performance factors in §312.20(e) and (f).

(2) Such a person must: (i) hold a current Professional Engineer's or Professional Geologist's license or registration from a state, tribe, or U.S. territory (or the Commonwealth of Puerto Rico) and have the equivalent of three (3) years of full-time relevant experience; or (ii) be licensed or certified by the federal government, a state, tribe, or U.S. territory (or the Commonwealth of Puerto Rico) to perform environmental inquiries as defined in §312.21 and have the equivalent of three (3) years of full-time relevant experience; or (iii) have a Baccalaureate or higher degree from an accredited institution of higher education in a discipline of engineering or science and the equivalent of five (5) years of full-time relevant experience; or (iv) have the equivalent of ten (10) years of full-time relevant experience.

(3) An environmental professional should remain current in his or her field through participation in continuing education or other activities.

(4) The definition of environmental professional provided above does not preempt state professional licensing or registration requirements such as those for a professional geologist, engineer, or site remediation professional. Before commencing work, a person should determine the applicability of state professional licensing or registration laws to the activities to be undertaken as part of the inquiry identified in §312.21(b).

(5) A person who does not qualify as an environmental professional under the foregoing definition may assist in the conduct of all appropriate inquiries in accordance with this part if such person is under the supervision or responsible charge of a person meeting the definition of an environmental professional provided above when conducting such activities.

Relevant experience, as used in the definition of environmental professional in this section, means: participation in the performance of all appropriate inquiries investigations, environmental site assessments, or other site investigations that may include environmental analyses, investigations, and remediation which involve the understanding of surface and subsurface environmental conditions and the processes used to evaluate these conditions and for which professional judgment was used to develop opinions regarding conditions indicative of releases or threatened releases (see §312.1(c)) to the Site. Whitman personnel resume(s) are included in **Appendix F**.

I declare that, to the best of my professional knowledge and belief, I meet the definition of environmental professional as defined in §312.10 of 40 CFR 312.

I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Signature of Environmental Professional: Shala Innella Date: 12/21/18